

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHF3R
 Ref. No : TAX/07/18/2032
 Reg. Date : 03/11/2017
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS4
 Name of Driver : SOH LAI KIM
 Type of Accident : SIDE SWIPE
 Date / Time of Accident : 09/07/2018 12:10:00 PM
 Accident Reported Date / Time : 09/07/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024096919
 Special Instruction to ARC, if any :
 SKQ2230U
 Prepared Date : 09/07/2018 03:09:55 PM



Sathya Sai
 10/7/2018

3 days.

- Part by Part Repair
- Question mark item photo
- Photo before paint.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKB3FU903573735

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 676.00	0.00
Total Spray Painting Charges	: 1,116.00	0.00
Total Material Charges	: 2,539.92	2,539.92
Other Charges	: 700.00	0.00
TOTAL	: 5,031.92	0.00
Lum Sum Total	: 0.00	0.00
No. of Repair Days	: 5.00	0.00 3 days
Prepared / Adjusted By	:	
Arc / Surveyor Sign Off Date	: 09/07/2018 07:21:47 PM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 09/07/2018 07:21:47 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount : 0.00	Prepared Date : 7/9/2018 7:23:52 PM

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR LH REAR PORTION	676.00	0.00 400
Total Labour	676.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR FENDER LH	378.00	0.00 200
TO RESPRAY RIM	180.00	0.00 100
TO REPSRAY REAR BUMPER	378.00	0.00 200
TO RESPRAY FILLER RR BUMPER LH	180.00	0.00 100
Total Spray Painting & Panel Beating	1,116.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 40
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 50
TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0.00 60
TO REPLACE SUNDRY PARTS	100.00	0.00 20
TO WASH AND VACUUM	60.00	0.00 X
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	0.00 50
TO REMOVE AND REFIT TYRE	120.00	0.00 50
Total Other Costs	700.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
6160247160			PANEL SUB-ASSY, FENDER REAR LH <i>R</i>	1	824.80	25.00	618.60	Replace	Replace	No
4261147450			WHEEL, DISC <i>R</i>	1	1,555.10	25.00	1,166.32	Replace	Replace	No
			TYRE <i>X</i>	1	126.74	0.00	126.74	Replace	Replace	No
5215947913			COVER, RR BUMPER ASSY <i>R</i>	1	423.90	25.00	317.92	Replace	Replace	No
			PIXEL STICKER <i>✓NEC</i>	2	60.00	0.00	120.00	Replace	Replace	No
5256647900			FILLER, RR BUMPER, LH <i>R</i>	1	119.90	25.00	89.92	Replace	Replace	No
5257647040			RETAINER, RR BUMPER, LH <i>?</i>	1	111.50	25.00	83.62	Replace	Replace	No
5246247030			PAD, RR BUMPER, RH & LH, 1 <i>?</i>	1	3.80	25.00	2.85	Replace	Replace	No
5246247020			PAD, RR BUMPER, RH & LH, 2 <i>?</i>	1	3.80	25.00	2.85	Replace	Replace	No
5246247010			PAD, RR BUMPER, RH & LH, 3 <i>?</i>	1	3.80	25.00	2.85	Replace	Replace	No
5219147030			SEAL, RR BUMPER ARM, RH & LH <i>?</i>	1	11.00	25.00	8.25	Replace	Replace	No
TOTAL MATERIALS								2,539.94	2,539.92	
TOTAL MATERIALS(Discounted)								2,539.92	2,539.92	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									