

BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636

Tel: 6559 8944 / Fax: 6269 2404

AIG Asia Pacific Insurance Pte. Ltd
 AIG Building
 78 Shenton Way #08-16
 Singapore (079120)
 ATTN: MOTOR CLAIM DEPARTMENT
 Tel : 6419 3000 Fax : 6835 7416

*Not Notified
 1-B.1
 Resony Bepain
 6 days*

ACCIDENT REPAIR ON : SLV5197A
MODEL : TOYOTA VOXY HYBRID
POLICY NO : GA310149
CHASSIS NO : ZWR800283845
MANUFACTURING YEAR : 2017
DATE / TIME OF ACCIDENT: 09/07/2018 Time: 0820Hrs ALONG PIE EXIT 4A TO SIMEI AVE
THIRD PARTY VEHICLE NO : SLM8926R

Date: 20/06/2018
 Page : 1 of 2

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

Replacement Of Parts

S/N	Quantity	Unit Price S\$	Condition	Amount S\$
1				
2				
3				
4				
5				
6				
7				
8				
9				
10				
11				
12				
13				
14				
15				
16				
17				
18				
19				
20				
21				
22				
23				
24				
25				
26				

Sub-Total: _____ -
 Less Discount 25% -
Total Parts: -

Special Nett Items

1	Anti-rust coating	3	80.00	240.00
2	Rear Bumper Clips	10		-

60.00

ma - ✓

3	Rear Windscreen Sealant	1	100.00
4	Rear Number plate	1	50.00

Mr 405N
50.00 X
Total Parts: 390.00

Labour Charges For Rear Portion

1	Provide skill labour to remove all damaged parts, panel beat, cut & weld if necessary and align all panel and reinstall all damaged parts.		<i>700</i> 1,800.00
2	Provide skill labour & material to putty all damaged parts & panel & to respray with 2K paint with oven spray booth facilities		<i>660</i> 1,800.00
3	Provide skill labour to disconnect and check electrical wiring		<i>20</i> 30.00
4	Remove and refit rear end panel lining and garnish to facilitate repair		<i>60</i> 100.00
5	Remove and replace bumper sensors		<i>50</i> 100.00
6	Realign Exhaust Pipe		50.00 ?
7	Remove and replace exhaust pipe/system to facilitate repair recommended specification		120.00 ?
8	Remove and refit rear windscreen		<i>120</i> 200.00
9	Dismantle and transfer tailgate fittings and mechanism to new tailgate to new tailgate/facilitate repair		<i>60</i> 80.00
Total Labour:			4,200.00

Total Parts & Labour: 4,590.00
GST 7% 321.30
Grand Total: 4,911.30

Estimate Repair Duration

10 days
6 days

ACCIDENT VEHICLE OF : SLV5197A

Page : 2 of 2

Remark: Supplementary estimate will be raised in the event additional damaged parts are found in the course of repair.

Yours sincerely,

ESTIMATOR: ANTHONY

Survey attended by:

Name : *Kenneth*
Company : *LKK*
Date : *17/7/18*
Time : *10.30am*
Contact No: *96910663*
Email : _____

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: