



ComfortDelGro Engineering

205 Braddell Road S(579701)

ACCIDENT REPAIR ESTIMATE

Our Ref:

Type of Claim : TPVehicle No. : SLB5435TMake & Model : HONDA VEZEL 1.5X HYBRIDYear of Manufacture : 2015Chassis No. : RU31120706Ins Company : AIG / AXA

Engine No. : _____

Excess : _____

Policy No. : _____

Date of Accident : 07/07/2018

Time of Accident : _____

Suggested Days of Repair : _____

In-house Vehicle Assessor**Repair Estimate**Case Owner : Andrew

Signature : _____

Parts (a) Cost / List Price Items \$ 3,345.20Plus/Less 20% \$ 669.04Total of Cost / List \$ 2,676.16(b) Nett Price Items \$ -

Less _____

Total of Nett Item _____

(c) Special Nett Items \$ 325.00Total Parts Cost (Appendix A) \$ 3,001.16Labour (Appendix B) \$ 3,570.00Total Repair Cost \$ 6,571.16

Contact No

Frt Counter Operation

6383 7466 - Patrick Tia

6383 7730 - Brenda Ng

6383 7890 - Rohani

braddell_cr@sparkcarcare.com**Workshop Operation**

63837656 - Ngo Toh Wee

63837362 - Andrew Goh

63838115 - William Wang

braddell_operation@sparkcarcare.com

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Eno Q. Amy - 82880282Company : UKKSurvey conducted on : 12/7/18 at _____**Remarks By Surveyor**

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 4 day(s)(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : _____ Date: _____

part by part.
before paint photos.

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax: 62844284, 62815767

Spare Parts

Vehicle No : SLB5435T Case Owner : Andrew

Make & Model : HONDA VEZEL 1.5X HYBI Year Manufacture : 2015

Chassis No : RU24420706 Engine No : 0

Sales Order : _____ Supplier : _____

Order By : _____ Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	Rear bumper <i>see</i>	1		\$ 762.60	/		
2	Rear bumper side retainer LH <i>X GNA</i>	1		\$ 18.90	X		
3	Rear bumper side retainer RH <i>X GNA</i>	1		\$ 18.90	X		
4	Rear bumper clips <i>see</i>	10		\$ 30.00	/		
5	Rear bumper reflector LH <i>X GNA</i>	1		\$ 151.80	X		
6	Rear bumper reflector RH <i>X GNA</i>	1		\$ 151.80	X		
7	Tailgate <i>see</i>	1		\$ 982.80	/		
8	Tailgate windscreen glass moulding upper	1		\$ 28.60	/		
9	Tailgate windscreen glass moulding lower	1		\$ 28.60	/		
10	Tailgate windscreen glass moulding LH <i>see</i>	1		\$ 29.30	/		
11	Tailgate windscreen glass moulding RH <i>see</i>	1		\$ 29.30	/		
12	Tailgate lamp LH <i>X GNA</i>	1		\$ 443.00	X		
13	Tailgate lamp RH <i>X GNA</i>	1		\$ 443.00	X		
14	Tailgate emblem logo H <i>see</i>	1		\$ 28.70	/		
15	Tailgate emblem VEZEL <i>see</i>	1		\$ 38.90	/		
16	Tailgate emblem HYBRID <i>see</i>	1		\$ 57.40	/		
17	Rear end panel top garnish <i>?</i>	1		\$ 101.60	X		
18	Reverse sensor <i>?</i>	1				\$ 280.00	X
19	Rear number plate with casing <i>X NN</i>	1				\$ 45.00	X
20	0	0					
21	0	0					
22	0	0					
23	0	0					
24	0	0					
25	0	0					
26	0	0					
27	0	0					
28	0	0					
29	0	0					
30	0	0					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

2016.2
209,1612.96

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax:62844284,62815767

Labour

Vehicle No. : SLB5435T Case Owner : Andrew
Make & Model : ONDA VEZEL 1.5X HYBRID Year of Manufacture : 2015

S/No	Labour Description	Estimated Price	Adjusted Price
1	To remove and replace rear windscreen.	\$120.00	100
2	To remove and refit cushions and upholstery to facilitate repairs	\$250.00	60
3	To transfer tailgate parts and mechanisms to new tailgate	\$250.00	60
4	To remove, reinstall Hybrid Electronic Module connection and to reset and sychronization the electronic system	\$550.00	?
5	Labor charges to repair and replace rear portion damages	\$960.00	480
6	To check wiring functions	\$120.00	X N/A
7	To install reverse sensor	\$120.00	40
8	To putty and spray paint rear bumper, tailgate, rear end panel and all affected areas	\$1,000.00	500
9	To apply rust proofing on replaced and repaired panels	\$200.00	60
			1300
<div> <p>KKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer Signature: Date:</p> </div>			

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

29/2/96