



ComfortDelGro Engineering

205 Braddell Road S(579701)

ACCIDENT REPAIR ESTIMATE

Our Ref:

Type of Claim : TPVehicle No. : SLB5435TMake & Model : HONDA VEZEL 1.5X HYBRIDYear of Manufacture : 2015Chassis No. : RU31120706Ins Company : AIG / AXA

Engine No. : _____

Excess : _____

Policy No. : _____

Date of Accident : 07/07/2018

Time of Accident : _____

Suggested Days of Repair : _____

In-house Vehicle Assessor**Repair Estimate**Case Owner : Andrew

Signature : _____

Parts (a) Cost / List Price Items \$ 3,345.20Plus/Less 20% \$ 669.04Total of Cost / List \$ 2,676.16(b) Nett Price Items \$ -

Less _____

Total of Nett Item _____

(c) Special Nett Items \$ 325.00Total Parts Cost (Appendix A) \$ 3,001.16Labour (Appendix B) \$ 3,570.00Total Repair Cost \$ 6,571.16

Contact No

Frt Counter Operation

6383 7466 - Patrick Tia

6383 7730 - Brenda Ng

6383 7890 - Rohani

braddell_cr@sparkcarcare.com**Workshop Operation**

63837656 - Ngo Toh Wee

63837362 - Andrew Goh

63838115 - William Wang

braddell_operation@sparkcarcare.com*The above total will be subjected to 7% G.S.T.*

Name of Surveyor : _____

Company : _____

Survey conducted on : _____ at _____

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : _____ day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : _____ Date: _____

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax:62844284,62815767

Spare Parts

Vehicle No : SLB5435T Case Owner : Andrew

Make & Model : HONDA VEZEL 1.5X HYB Year Manufacture : 2015

Chassis No : RU31120706 Engine No : 0

Sales Order : _____ Supplier : _____

Order By : _____ Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	Rear bumper	1		\$ 762.60			
2	Rear bumper side retainer LH	1		\$ 18.90			
3	Rear bumper side retainer RH	1		\$ 18.90			
4	Rear bumper clips	10		\$ 30.00			
5	Rear bumper reflector LH	1		\$ 151.80			
6	Rear bumper reflector RH	1		\$ 151.80			
7	Tailgate	1		\$ 982.80			
8	Tailgate windscreen glass moulding upper	1		\$ 28.60			
9	Tailgate windscreen glass moulding lower	1		\$ 28.60			
10	Tailgate windscreen glass moulding LH	1		\$ 29.30			
11	Tailgate windscreen glass moulding RH	1		\$ 29.30			
12	Tailgate lamp LH	1		\$ 443.00			
13	Tailgate lamp RH	1		\$ 443.00			
14	Tailgate emblem logo H	1		\$ 28.70			
15	Tailgate emblem VEZEL	1		\$ 38.90			
16	Tailgate emblem HYBRID	1		\$ 57.40			
17	Rear end panel top garnish	1		\$ 101.60			
18	Reverse sensor	1				\$ 280.00	
19	Rear number plate with casing	1				\$ 45.00	
20	0	0					
21	0	0					
22	0	0					
23	0	0					
24	0	0					
25	0	0					
26	0	0					
27	0	0					
28	0	0					
29	0	0					
30	0	0					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Tel: 63837168 / 63837466 Fax:62844284,62815767

Year of Manufacture : 2015

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.