

ASS. REC. BY:

REP

CS/CTI18012624/Kvd3ⁿ²

Special Instruction:

Survivor:

Kenneth

ASSIGNMENT (Office)

From (Person):

Irene Tay

of

CTI

Date/Time:

11/7/18 @ 248pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SIF 2098G

Insured:

SLS 9110P

at Workshop in/s

Hui Yang Motor

Tel:

9047 3466

of

Blk 176 Sin Ming Drive #04-02

Policy No:

DMPCSN3093971700

Claim No:

SNM18D013361C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

05/07/2018

CA / REV / REP. / REV 24 HRS

up

H.O.D. Endorsement:

Date/Time:

2:57pm @ 11/7/18

Person Contacted:

Belle

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SIF 2098G - X

SLS 9110P - X

18/7/18

@ 233pm final fig \$300 confirmed with Belle (Rad 1775.77, 8690)
(Mc LS)

ASS. REC. BY:

REF: CT21

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / QD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 01 days Res.: Yes or No

Lum Sum: 1.31 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLF 20986 Yr Regn: 09, 09

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy wish C.C. 1797

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading 171467 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 86820 0011882

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/65R15 R: Yulco

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal. 4 mm

L/Bal. 4 mm

D.O.A. 517418

Rear

R/Bal. 5 mm

L/Bal. 5 mm

D.O.I. 16/7/18

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

17/7 File pass to Catherine
83006

Labour Only

RECEIVED 17 JUL 2018

18/7/2018

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

18/7 - typist

Days Of Repair: 1

Resurvey No. of Trip: -

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

) \$ + RS. \$

) Fictos

) Others

Report Format:

Lump Sum / I.B.I. (\$) 300

merimen

TOTAL

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Jul 2018		12 Jul 2018 10:27 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	LOH YUEN MENG, ID: S7087123H		
Main Claimant:	HYMS CAR LEASING PTE LTD		
Vehicle Reg. No.:	SLF2098G	Date of Loss:	05/07/2018 00:00 - :59
Claim Type:	TP / SNM18D03361C02	Policy/Cover Note No.:	DMPCSN3093971700 (Comprehensive)
Vehicle Reg. No. (Insured):	SLS9110P	Policy No. (Claimant):	
		Excess:	\$0.00
Repairer:	Hui Yang Motor Pte Ltd (HQ) 176 Sin Ming Drive #04-02, Sin Ming AutoCare, 575721 Sin Ming - Tel: 64515752		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 23/07/2018]		
Adj Asg. Remarks:	EST \$2075.77, CASE WITH SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Irene Tay <irene.tay@sg.cntaiping.com>
Sent: Wednesday, 11 July 2018 2:48 PM
To: hui_yang_motor@hotmail.com; assignments@lkkauto.com
Cc: Jowyn Tay; Lucas Lee
Subject: CTP REF NO. SNM18D013361C02 HY REF NO. SLF2098G - ACCIDENT INVOLVING SLS9110P AND SLF9110P ON 05 JULY 2018
Attachments: 11072018144531.pdf

Dear Sir/Mdm,

We refer to the above captioned matter and your email dated 10 July 2018.

As spoken, you are agreeable to let us appoint **LKK** to survey your client's vehicle.

Aside to LKK,

Please contact BEL @ 90473466 to conduct survey asap.

Note. Ms Jowyn is the claim handle for this case.

Thank You.

Regards,

Irene Tay
Executive
Claims Department (Motor Division)

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
Direct (65) 6389 6192
Fax (65) 62247478/62247175
Email: claimsdept@sg.cntaiping.com
www.sg.cntaiping.com



Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

Evon Char

18 | 3361 | 0

From: Hui Yang Motor <hui_yang_motor@hotmail.com>
Sent: Tuesday, July 10, 2018 3:42 PM
To: Claims Dept of CTI
Subject: TP Claim for SLF2098G against SLS9110P / DOA: 05/07/2018
Attachments: SKM_C28718071015440.pdf
Importance: High

Hi,

Please refer to attached and kindly advise us on when can we arrange our client to send down SLF2098G for survey.

Thank you & Regards,

Bel

p: 90473466

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

11 JUL 2018

輝陽汽車有限公司
HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

Reg No. 201629438M

05/07/2018

Owner: HYMS CAR LEASING PTE LTD

ESTIMATE TO REPAIR TOYOTA WISH - SLF2098G

1pc front RH door
1pc front RH door sticker

R \$ 985.85 X
ms \$ 181.85 X

less 25%

\$ 1,167.70
\$ 291.93
\$ 875.77

wiring
tuffkote
spray painting
labour charges
Total

ms \$ 50.00 X
\$ 50.00 X
\$ 600.00 200
\$ 500.00 100
\$ 2,075.77

Not Withheld
Revised After Pricing

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

Date:



LKK Auto Consultants Pte Ltd (Co Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT18012624/KVD3N2

Date: 19/07/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN3093971700
Claimant Vehicle No :	SLF2098G	Insured Vehicle No :	SLS9110P
Date of Loss:	05/07/2018	Nature of Claim:	TP
		Claim No:	SNM18D03361C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLF2098G	Engine No:	2ZR0432452
Make & Model:	TOYOTA WISH, 1.8 X (A)	Chassis No:	ZGE200011882
Reg. Date:	23/09/2009 (Man. Year: 2009)	Odometer:	171467 km
Colour:	White		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/65 R15	Rear Tyre Size:	205/65 R15
Front Left Side:	Linglong 4 mm	Rear Left Side:	Yokohama 5 mm
Front Right Side:	Linglong 4 mm	Rear Right Side:	Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	875.77	0.00	875.77	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,200.00	300.00	900.00	75.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	2,075.77	300.00	1,775.77	85.55
+ GST 7.00/7.00% (\$\$)	145.30	21.00	124.30	85.55
Nett Amount (\$\$)	2,221.07	321.00	1,900.07	85.55

INSPECTION

Date of Assignment:	12/07/2018	
Date Inspected:	16/07/2018	Inspected At:
		Hui Yang Motor Pte Ltd (HQ)
		176 Sin Ming Drive #04-02, Sin Ming
		AutoCare
		Singapore 575721

Estimated Period of Repair: 1.0 days**Adjuster:** KENNETH KONG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 19 Jul 2018)
Parts: M1-MPV	TOYOTA WISH 1.8 X (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLF2098G)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT RH DOOR	Repair	985.85 FL	*- FL
2	1		*FRONT RH DOOR STICKER	Not Necessary	181.85 FL	*- FL
F=Franchise part. L=ListItemDisc.						
Sub Total (S\$)					1,167.70	0.00
- List Item Discount on L Items 25.00/25.00% (S\$)					291.93	0.00
Total Parts (S\$)					875.77	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	WIRING	New	50.00	-
2	TUFFKOTE	New	50.00	-
3	SPRAY PAINTING	New	600.00	200.00
4	LABOUR CHARGES	New	500.00	100.00
Gross Labour Cost (\$\$)			1,200.00	300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >