ASS, REC, BY:	REF CS FC[180] 2626	71 +d3 Decial Instruction:
	Which Assignment (Of	
From (Person): Mau	1 chua of FCI	Date/Time:
Estimated Cost:	Bill to:	
	S/OD RES/EVA/INV/MV/CS	EHC 2022G
To Inspect Vehicle No:		Insured: SHC 2870G
	Wearnes Automotive	Tel: 9129 4556
of	249 Alexandru Road	
Policy No:	Claim	No: D18005139 MPSH
Sum Insured:	Exec	
Make of Veh: (Client's Record)		D.O.A = 20/06/2018
CA / REV / REP. /	REV 24 HRS COS	H.O.D. Endorsement:
Date/Time: 312pm 0	11718 Person Contacted: Mid	le Vehicle IN OUT
Date/Time Action/L	ostruction () Estimate	
SIF	9370 X-X	
SHC	2870 G-08/FCI17016187/R	29bn2 DOA: 17/08/2017
Part	by Part \$10.907 .98 (Red. 658 1.30 1.37%)

ASS. REC. BY:	
AS	SIGNMENT
From: Date: 16 07 2018	Veh No: 3 SLP9370X Yr Regn: 2017, Jul
Estimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD TP WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No: SID 9370 X	Males 111 2 V40
at Workshop m/s Weurnes- Automotive	D 1
of 249 Alexandra Rd	
Insured:	
Policy No.	Eng/No:
Claims No.	C/No:
Sum Insured: Excess:	Gen. Cond: Good / Fair / Poor / Burnt
(Client's Record)	Steering: Inorder / Jammed / Leaked / Burnt or
-hit thir	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh: owner waiting Michelle.	Modi: Nil / S/Rim / STD A/Rim or
(Boliou Condition)	Tyre Size: F: 05 55WUb
(Policy Condition) Remark: The veh had commenced its N/S O/S	R:
Remark: The veh had commenced its N/S O/S repair at the time of inspection.	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
	TOYO/YOKO or
Bal. or Market Value:	Front / Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. mm R/Bal. mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal mm L/Bal mm
Est. Repairs:days Res.: Yes or No	D.O.A. D.O.I. 16/7/18 0 15
Lum Sum: % 3 Val.: Yes or No	Survey held at Weames
CA / REV / REP. / 24 HRS (WP)	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Date: Person Contacted: Vehicle: IN / OUT	Et NS
	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	
=	
RECEIVED 2 7 AUG	2018
RECEIVED 1 1 SEP	2018 Edterd W
,	
ate/Time, File Pass to? : Preli. Report	Days Of Repair: 5
ITATUMEN TO	[VZ-10
ate/Time, File Return to?	Resurvey No. of Trip: Survey Fee: 170+ 105 Transportation: 50
Add Fee:	
Pin.	: Interview (\$) Photos (\$ 35
eport Format :	: Tech, Invs (\$
eport Format : H ump Sum / I.B.I; (\$ 10,907 98)	: Tech. Invs (\$) Others (\$)



MS First Capital Insurance Limited Co.Reg. No. 195000106C GST Reg. No. M2-0001676-9 6 Raffles Quay #21-00 Singapore 048580 Tel: (65) 6222 2311 Fax: (65) 6222 3547

Claims & Hotor Underwriting Dept: 36 Robinson Road #16-01 City House Singapore 068877 Tel: (65) 6507 3848 Fax: (65) 6507 3849 www.msfirstcapital.com.sg

MOTOR SURVEY ASSIGNMENT

Date

02-07-2018

Our Ref No. D18005139MFSH

Accident Date

29-06-2018

Claim Type. Third Party

Insured Vehicle

SHC2870G

Third Party Vehicle. SLP9370X

Survey Location

BODY AND PAINT DEPT 249 ALEXANDRA ROAD

Contact Person.

MICHELLE ONG

Contact No.

0/ 91294556

Fax No. 62647137

Survey Type

WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:

Appointed

Surveyor

LKK AUTO CONSULTANTS PTE LTD

Contact Person Contact Number.

NA NA

Fax No. 68416315

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc: Workshop

WEARNES AUTOMOTIVE

Attention. NIL

Cc: TP Solicitor

NA

TP Solicitor Fax No. NA

Officer Incharge

MAY CHUA

PTE LTD

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection. This is a computer generated letter, no signature required.

-Jon Dottulla/24 1907



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

-10	ST CAPITAL INSU		ernationale Des Experts En Autor		
EHE	ST CAPITAL INSC	JRANCE LTD	Ref : CS/FCI180126	26/T1td3	
	ROBINSON ROAD 3-01 CITY HOUSES	SINGAPORE 068877	Date: 11-07-2018		
			Code: FCI2		
1.			lars :- THIRD PARTY CLA	M	
	Insured Veh.	SHC 2870G	Veh. Inspected	SLP 9370X	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	D18005139MFSH	Excess (\$)	0.00	
	Assign From	CWS (MAY CHUA)	Assign Date	11/07/2018	
2.		Vehicle F	Particulars & Condition	CHANGE TO BE	
	Make & Model		c.c	0	
	Engine No.	HIDDEN	Year of Reg.		
	Chassis No.		Colour		
	Odometer -		Steering		
	Brakes		Modification		
	General				
3.		Co	nditions of Tyres		
		Size	Make	Balance	
	R/H Front Tyre			mm	
	L/H Front Tyre			mm	
	R/H Rear Tyre			mm	
	L/H Rear Tyre			mm	
١.		Desci	ription of Damages		
j.		Ger	neral Information		
	Accident Date	29/06/2018	Inspection Date		
	Survey held at	WEARNES AUTOMOTIVE			
		249 ALEXANDRA ROAD SINGAPORE 159935			
a.			Remarks		
	A)THE INSPECTIO	N WAS CONDUCTED ON A'	"WITHOUT PREJUDICE" BASI S, WE HAVE NOT AUTHORISE	S.	

MBHH18085941 / Ajax Mars Pte Ltd - Bukit Merah ENTRY DATE & TIME: 04/07/2018 03:08 SUBMITTED BY: Susan Neo

Your NCD will be affected due to late reporting Actual e-Filling Submission Date & Time: 04/07/2018 03:33

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

		ACCIDENT STATEMENT
Date Of Report		04/07/2018 03:08
Date Of Accident		29/06/2018 16:20
Exact Location Of Accident	2	OPEN CARPARK AT BLK 558 JURONG WEST STREET 42
Country/State of Loss		SINGAPORE
		DETAILS OF OWN VEHICLE

	DETAILS OF OWN VEHICL
to the table of the contract o	WALLES OF THE COLUMN TO A COLU

Vehicle Registration Number SLP9370X

Insured/Policyholder

Name Of Registered Owner NOORASHIKEEN BINTE KHAMIS

NRIC No S8310109A

Email Address NIKIE_ANGEL@HOTMAIL.COM

Mobile Phone No (LOCAL) +65-94502438

Alternative Phone No OFFICE-94502438

Vehicle Particulars

Manufacturer VOLVO
Model V40

Exact Purpose for which vehicle was being used at time of accident

PRIVATE

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

If No, Please state action to be taken THIRD PARTY
Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company SOMPO INSURANCE SINGAPORE PTE, LTD.

Type Of Coverage COMPREHENSIVE

Fleet Policy NO

Policy Number D18MTPV01011292

Cover Note Number N.A.

Driver

Name of Driver NOORASHIKEEN BINTE KHAMIS

 NRIC No
 \$8310109A

 Date Of Birth
 02/04/1983

 Occupation
 INDOOR

 Date Of Driving Pass
 19/05/2015

Driving Experience 3 YEARS AND 1 MONTH

Gender FEMALE

Mobile Number (LOCAL) +65-94502438

Fax Number

Contact Number OFFICE-94502438

EMail Address NIKIE_ANGEL@HOTMAIL.COM

Address

BLK 558 JURONG WEST STREET 42

#04-453

Postcode

640558

OWNER

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

FLOOD

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

ambulance?

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER TO POLICE REPORT NO:T/20180629/2191 LODGED AT MARINE PARADE NPP. ON 29/06/2018 AT ABOUT 1615HRS,I PARKED MY VEHICLE (SLP9370X) AT THE OPEN CARPARK OF BLK 558 JURONG WEST STREET. I WISH TO STATE THAT I DO NOT REMEMBER THE PARKING LOT NUMBER. AT ABOUT 1810HRS, I CAME BACK TO RETRIEVE MY VEHICLE. WHEN I ENTERED MY CAR, MY IN-CAR CAMERA PROMPTED ME THAT THERE WAS AN IMPACT DURING PARKING .I THEN VIEWED MY IN-CAR CAMERA FOOTAGE AND REALIZED THAT AT ABOUT 1621HRS, A BLUE COMFORT TAXI BEARING REGISTRATION PLATE NUMBER SHC2870G WAS REVERSING INTO THE PARKING LOT ON THE LEFT SIDE OF MY VEHICLE HOWEVER THE REAR OF THE TAXI KNOCKED INTO THE FRONT LEFT OF MY VEHICLE AND SUBSEQUENTLY IT LEFT THE LOCATION. I THEN ALIGHTED FROM MY VEHICLE TO ACCESS THE DAMAGE AND DISCOVERED THAT THERE ARE DENTS AND SCRATCH MARKS AT THE FRONT LEFT SIDE OF MY VEHICLE.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Remarks/ Reasons:

PENDING VIDEO FROM INSURED

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SHC2870G

Vehicle Make/Model/Colour

HYUNDA/I40 1.7 CRDLE/BLU

Details Of Properties

Vehicle Category

TAXI

Name of Driver


NRIC/Passport Number

Contact Number

Address

Postcode Insurance Company Name Nature Of Damage No. Of Passenger (Including Driver)

Sketch Plan



Common Statement

Refer to police report No.T/20180629/2	2191
	*
Tax: Voucher No	
ECLARATION	vided above are true in every aspect
ECLARATION Ve declare that the above particulars & information proventies by AJAX MARS REPORTING OFFICER	vided above are true in every aspect
ECLARATION We declare that the above particulars & information proving the property of the province of the pr	vided above are true in every aspect
ECLARATION We declare that the above particulars & information proving the state of the state o	vided above are true in every aspect
ECLARATION Ve declare that the above particulars & information proventies by AJAX MARS REPORTING OFFICER	rided above are true in every aspect
ECLARATION We declare that the above particulars & information proving the property of the province of the pr	vided above are true in every aspect
ECLARATION We declare that the above particulars & information proving declare that the above particulars & information proving declare that the above particulars & information proving declared by AJAX MARS REPORTING OFFICER - AIZAM BIN ATAN	Riegistered Owner or Driver's Signature





Police Station Of Origin: Marine Parade NPP 74 Marine Drive #01-35 SINGAPORE 440074 Tel No: 1800-4409999

1 of 3 Report No. T/20180629/2191

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 29/06/2018 22:01			Vide Report No.:	Station Diary No.:	
Informar	it's Partic	ulars		KAN TENEDONE	
	Informant: SHIKEEN I	BINTE KHAMIS	Address: APT BLK 558 JURONG WES SINGAPORE 640558	T STREET 42 #04-453	
ID Type / ID No.: NRIC NO / S8310109A Nationality:			Contact No.: Home/Office: Mobile: 94502438 Email:		
	ORE CITIZ	EN	Liliali.		
Sex: Age: Date of Birth: Female 35 02/04/1983			Type of Informant: Vehicle Owner		
Race: Malay		2	Language:	Institution / School Name:	
Occupation: HUMAN RESOURCE AND FINANCE			Driving Licence Information: Class:	Date of Expiry:	

General Infor	mation of the Accide	nt			Starte I
Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 29/06/2018 16:20	Car Park	Location:
	ST STREET 42 ARK OF BLOCK 558 J		ā	3	
Weather: Clear		Road Surface: Dry		Road Speed Li	imit: '
Traffic Flow:		Traffic Control:	7	Traffic Volume	:
Type of Collis Moving Vehic	ion: le Against - Parked Ve	hicle		Anyone convey ambulance:	yed by

Details of Vehicle Involved .						
Vehicle No.	Туре	Make	Model	Color	Condition	No of Passenger
SHC2870G	Car					0
SLP9370X	Car					0

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA





2 of 3

Report No. T/20180629/2191

Police Station Of Origin: Marine Parade NPP 74 Marine Drive #01-35 SINGAPORE 440074

Tel No: 1800-4409999

CONTINUATION OF REPORT

Vehicle Owner		Calledon Las		and the same			
Name	NOORASHIKEEN BINTE KHAMIS		ID No		S8310109A		
Related Vehicle	NIL		NIL		Conta	ct No.	94502438
Hospital/Clinic	NIL			Class Drivin Licen Expin	g	Class: NIL Date of Expiry: NIL	
Date Treatment	NIL Date Disc		harge	NIL			
No. of Days gran	ted Medical Leave	NIL	Degree o	f Injury	NIL		

Brief Details.

On 29/06/2018 at about 1615hrs, I parked my vehicle (SLP9370X) at the open carpark of Blk 558 Jurong West Street. I wish to state that I do not remember the parking lot number. At about 1810hrs, I came back to retrieve my vehicle. When I entered my car, my in-car camera prompted me that there was an impact during parking. I then viewed my in-car camera footage and realized that at about 1621hrs, a blue comfort taxi bearing registration plate number SHC2870G was reversing into the parking lot on the left side of my vehicle however the rear of the taxi knocked into the front left of my vehicle and subsequently it left the location. I then alighted from my vehicle to access the damage and discovered that there are dents and scratch marks at the front left side of my vehicle.





Police Station Of Origin: Marine Parade NPP 74 Marine Drive #01-35 SINGAPORE 440074 Tel No: 1800-4409999 3 of 3 Report No. T/20180629/2191

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report: G / Sgt 3 CHANG WEI LIANG, GLEN	Signature Of Informant:		
Signature Of Interpreter: Not applicable	Date/Time: 29/06/2018 22:01		
Officer In Charge Of Case: TP / HRT / Sr Staff Sgt ESTHER CHONG Contact No.: 65476368	Classification Of Case:		
Authentication Stamp			



SERVICE ESTIMATE

90117 - C00001 SL: SERVICE SALES - PC Ms Noorashikeen Binte Khamis GST Reg.No:M28920628X Blk 447-A Jalan Kayu Inv.No. . : B&P 0 Page 1 #03-364 Inv.date. : 10/07/2018 WIP No. . : 15301 Singapore 791447 Veh.In/Out: *Tel.No. . : Mobile: 94502438 Reg.No. . : SLP9370X Closed by : Michelle Ong Siew Be Reg.date .: 22/06/2017 Svc Consultant : Mileage ..: Chassis No: YV1MV28H0H2437641 Remarks : Ms Noorashikeen Bint Description Mech Qty Price Disc% Pkg Amount G Op. No 2400 . 3.200.00 S TO REPLACE FRONT LH FENDER. 3200.00 0 FRT BUMPER, FRT BRACKET, FRT 1400 LH HEADLAMP, .ETC 2,100.00 S TO PUTTY SPRAY PAINT ON FRT 2100.00 0 LH FENDER, FRT BUMPER, ETC 50.00 S TO REPLACE FRONT LH RIM 50.00 031 280.00 S 0 COMPUTERISED WHEEL ALIGMENT 280.00 0 10 150.00 S 280 TO FOCUS HEADLAMP 0 150.00 0 450.00 0 450.00 S /V TO CHECK WIRING INCLUDE 0 RESETTING OF ALL ELECTRICAL MODULES 895.30 S H- 80577 FENDER FRT LH V40 13 1.0 EA 895.30 1,186.50 S de 1067 35 54.30 S M 1357 1186.50 V039814150/BUMPER CO 1.0 EA BUMPER SEAL FRT V40 1.0 EA 54.30 88.70 SMC 7985 BUMPER BRACKET LHF V 1.0 EA 88.70 88.70 3 x An 88.70 BUMPER BRACKET RHF V 1.0 EA 88.70 Sauxun BUMPER BRACKET LHF V 1.0 EA 88.70

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanfilm 97-1957-19

NP

16/7/18@1600

Resurrey before points

Sure We ando-com



83.40 Suer 75.06

303.20 Sneet Lux. 272 3

500.00 SXM

SERVICE ESTIMATE

90117 - C00001 SL: SERVICE SALES - PC Ms Noorashikeen Binte Khamis GST Req.No:M28920628X Inv.No. . : B&P 0 Page 2 Blk 447-A Jalan Kavu #03-364 Inv.date.: 10/07/2018 WIP No. . : 15301 Veh. In/Out: Singapore 791447 *Tel.No. . : Mobile: 94502438 Reg.No. . : SLP9370X Closed by : Michelle Ong Siew Be Reg.date.: 22/06/2017 Mileage . : 0 Svc Consultant : Chassis No: YV1MV28H0H2437641 Remarks : Ms Noorashikeen Bint

ree 88.70 S * 79 83 BUMPER BRACKET RHF V 1.0 EA 88.70 1.0 EA 216.90 216.90 SXM4 BUMPER FOAM FRT V40 1.0 EA 559.70 559.70 S× nn RADIATOR GRILLE T2 V 1.0 EA 1707.10 1.707.10 SX ny FRAME PANEL FRT V40 1,232.80 SX 17 3,549.50 Sat 319455 1.0 EA 1232.80 BUMPER RAIL (BEAM) F 1.0 EA 3549.50 HEADLAMP LED LH T2 V 536.80 S cut 483.12 ALLOY RIM "Markeb" 7 1.0 EA 536.80 30.00 s me / 27 10.0 EA 3.00 BLIND RIVET 4.0*21MM 48.00 sne 43.70 10.0 EA 4.80 BUMPER CLIP

1.0 EA 83.40

1.0 EA 500.00

4.0 EA 75.80

Mech Qty Price Disc% Pkg Amount G

Gross Total. 17,488,30 Labour Total Net..... 17,488.30 6,230.00 Parts Total 11,258.30 GST @ 7.0% 1,224.18 18,712.50 Package Total 0.00 Total.... Paid.... 0.00 Please Pay.. 18,712.50 GST: S=StdRated; O=OutOfScope; Z=ZeroRated

Op.No

Description

BUMPER INSTALLING MT

NOISE DEADENING PAD

ADHESIVE TUBE CHEMIC



SERVICE ESTIMATE

	SERVICE	ESTIM			
0 -	F00003 SL: FIRST CAPITAL IN	SURANCE LTD			
FIRST CA	PITAL INSURANCE LTD			No:M28920628X	
36 ROBIN	ISON ROAD	Inv.No	: B&P	0 Page 1	
#16-01,	CITY HOUSE	Inv.date.	: 24/07/20.	18	
SINGAPOR		WIP No	: 15301		
Singapor	e 068877	Veh.In/Out	: 16/07/20	18 23/07/2018	
		*Tel.No	:		
		Reg.No	: SLP9370X		
Closed b	y : Michelle Ong Siew Be	Reg.date .	: 22/06/20	17	
Svc Cons	ultant : ACC	Mileage	: 21,919		
Remarks	: Ms Noorashikeen Bint	Chassis No	: YV1MV28H	0H2437641	
Op.No	Description	Mech Qty	Price Dis	c% Pkg Amount	G
					_
802	TO REPLACE FRONT LH FENDER,	0	2400.00	0 2,400.00	S
	R,FRT BRACKET,FRT				1
LH HEADLA					
800	TO PUTTY SPRAY PAINT ON FRT	0	1400.00	0 1,400.00	3/
LH FENDER	,FRT BUMPER,ETC				/
031	TO REPLACE FRONT LH RIM	0	50.00		
	COMPUTERISED WHEEL ALIGMENT	0	280.00	0 280.00	8/
280	TO FOCUS HEADLAMP	0		0 150.00	
280	TO CHECK WIRING INCLUDE	0	450.00	0 450.00	s/
RESETTING	OF ALL ELECTRICAL				
MODULES	6		005 70 10	005 77	0
	FENDER FRT LH V40 13			805.77	
	V039814150/BUMPER CO			1,067.85	
	BUMPER SEAL FRT V40		54.30 10		
	BUMPER BRACKET LHF V		88.70 10		
	MALADLAMP LED LH TZ V			3,194.55	
	(3) ALLOY RIM "Markeb" 7	1.0 EA	556.80 10	483.12	3



SERVICE ESTIMATE

Said than 17% Mr. All. Said than	. Home was II allo II II II	11 11 11				
0 - F00003 SL: FIRST CAPITAL IN	SURANLE L.L					
FIRST CAPITAL INSURANCE LTD		920628X				
36 ROBINSON ROAD	Inv.No :	B&P		0 1	Page _	
#16-01, CITY HOUSE	Inv.date. :	24/07	/2018			
SINGAPORE	WIP No :	15301				
Jingapore 068877	Veh.In/Out:	16/07	/2018	23/	07/2018	
01115440101011	*Tel.No :					
	Reg.No :	SLP93	70X			
Closed by : Michelle Ong Siew Be	Reg.date. :					
ove consultant : ACC	Mileage . :					
Remarks: Ms Noorashikeen Bint				2437	641	
op.No Description	Mech Qty	Price	Disc%	Pkg	Amount	G
BLIND RIVET 4.0*21MM	10.0 EA	3.00	10		27.00	S
BBUMPER CLIP	10.0 EA				43.20	
BBUMPER INSTALLING MT	1.0 EA	83.40	10		75.06	S
	4.0 EA				272.88	
BUMPER BRACKET LHF V	1.0 EA		10		79.83	S

			Gross Total.	10,907.96
Labour Parts Package	Total Total Total	4,730.00 6,177.96 0.00	Net GST @ 7.0% Total Paid Please Pay	10,907.96 763.56 11,671.52 0.00 11,671.52

GST: S=StdRated; O=OutOfScope; Z=ZeroRated



5b.

ESTIMATED NORMAL PERIOD FOR REPAIR:

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		ationale Des Experts En Automo				
IRST CAPITAL INSU	RANCE LTD	Ref : CS/FCI1801262	0/11(0362			
6 ROBINSON ROAD	SINGAPORE 068877	Date: 17-09-2018				
10-01-011-11-0-0-2-0		Code: FCI2				
	Policy Particula	ars :- THIRD PARTY CLAIR				
Insured Veh.	SHC 2870G	Veh. Inspected	SLP 9370X			
Policy No.	D-18088936MFSH	Coverage (\$)	0.00			
Claim No.	D18005139MFSH	Excess (\$)	0.00			
Assign From	MAY CHUA	Assign Date	11/07/2018			
2.	Vehicle Pa	articulars & Condition				
Make & Model	VOLVO V40	c.c	1498			
Engine No.	HIDDEN	Year of Reg.	2017			
Chassis No.	YV1MV28H0H2437641	Colour	RED			
Odometer	21904	Steering	IN ORDER			
Brakes	IN ORDER	Modification	SPORTS RIM			
General	GOOD					
3.	Cor	nditions of Tyres				
	Size	Make	Balance			
R/H Front Tyre	205/55 R16	MICHELIN	6 mm			
L/H Front Tyre		MICHELIN	6 mm			
R/H Rear Tyre		MICHELIN	6 mm			
L/H Rear Tyre		MICHELIN	6 mm			
4.	Desc	ription of Damages				
THE VEHICLE S	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.					
DAMAGES SEE	DETAILS.					
5.	Ge	neral Information				
Accident Date	29/06/2018	Inspection Date	16/07/2018			
Survey held a	TO THE PERSON OF	PTE LTD				
	249 ALEXANDRA ROAD SINGAPORE 159935					
5a.		Remarks				
A)DAMAGES C	ONSISTENT TO ACCIDENT R		ASIS. USED REPAIRS.			
C)IN ACCORDA	ANCE TO YOUR INSTRUCTION	mate Days of Repair				

Estimate Days of Repair

5 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLP 9370X

ty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)	
	REPLACEMENT OF PARTS			805.77	
	FENDER FRT LH V40 13 (SN)	BENT	895.30	1,067.85	
1000	V039814150/BUMPER CO (SN)	DEFORMED	1,186.50	48.87	
7.4	BUMPER SEAL FRT V40 (SN)	NECESSARY	54.30	79.85	
	BUMPER BRACKET LHF V (SN)	NECESSARY	88.70		
	BUMPER BRACKET RHF V (SN)	NOT NECESSARY	88.70		
	BUMPER BRACKET LHF V (SN)	NOT NECESSARY	88.70	== ==	
	BUMPER BRACKET RHF V (SN)	NECESSARY	88.70	Matabas	
	BUMPER FOAM FRT V40 (SN)	NOT NECESSARY	216.90		
	RADIATOR GRILLE T2 V (SN)	NOT NECESSARY	559.70		
	FRAME PANEL FRT V40 (SN)	NOT NECESSARY	1,707.10		
	BUMPER RAIL (BEAM) F (SN)	NOT NECESSARY	1,232.80	G899996497 4 Va	
	HEADLAMP LED LH T2 V (SN)	CUT	3,549.50		
	ALLOY RIM "MARKED" 7 (SN)	CUT	536.80		
	BLIND RIVET 4.0*21MM @\$3.00 (SN)	NECESSARY	30.00	-	
	BUMPER CLIP @\$4.80 (SN)	NECESSARY	48.0		
	BUMPER INSTALLING MT (SN)	NECESSARY	83.4		
	1 NOISE DEADENING PAD (SN)	NOT NECESSARY	0403400-000		
	4 ADHESIVE TUBE CHEMIC (SN)	NECESSARY	303.2		
	4 Abrilland		11,258.3	6,177.9	
	LABOUR		3,200.0	2,400.0	
	TO REPLACE FRONT LH FENDER, FRT BUMPER, FRT BRACKET, FRT LH HEADLAMP, ETC.		2,100.0	1,400.0	
	TO PUTTY SPRAY PAINT ON FRT LH FENDER, FRT BUMPER, ETC.		50.0		
	TO REPLACE FRONT LH RIM.		280.		
	COMPUTERISED WHEEL ALIGNMENT.		150.		
	TO FOCUS HEADLAMP.		450.		
	TO CHECK WIRING INCLUDE RESETTING OF ALL			00	
	ELECTRICAL MODULES.		6,230.		
	GRAND TOTAL		17,488.	30 10,907.	

Report Ref No. CS/FCI18012626/T1td3e2





RECOMMENDED COST OF REPAIRS

10,907.98

Report Ref No. CS/FCI18012626/T1td3e2

fourtim.

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.