

SME Motor Pte Ltd

1 Kaki Bukit Ave 6, #02-15 Autobay@KakiBukit Singapore 417883
TEL: 67476106 (6 lines) FAX: 67442368 Email: service@smemotor.com.sg
GST:201119451E RCB NO:201119451E

M/S: EQ INSURANCE COMPANY LTD

5 Maxwell Road #17-00
Tower Block MND Complex
singapore 069110

TEL: 6223 9433

FAX: 6224 3903

ATTN: Motor Claim Department

Your Ref No: 18/EQ/TP-139 (07)

Claim Type: Third Party

Accident Date: 06/07/2018

TP Veh Reg No: GBF214U

Estimate No: EST0004251

Date: 09 Jul 2018

Policy No: A28613664MKC

Veh Reg No: GX8592X

Make/Model: TOYOTA DYNA

Chasis No: JTFUF34YX03002779

Engine No: 5L5472403

Reg. Date: 12/10/2004

Estimate Repair Cost to Vehicle No :GX8592X

Description	Quantity	List Price	Amount
		SS	SS
List Price			
1 SIDE MIRROR LH ASSY	1 PC	685.00	
2 WIPER CORNER GARNISH LH	1 PC	135.00	
SIDE MIRROR TOP COVER LH - \$30 (MISSING)		820.00	
	Less 25%	205.00	615.00
Labour			
3 LABOUR CHARGE	1 UNIT	200.00	100
4 SPRAY PAINTING	1 UNIT	200.00	150
	250	400.00	400.00
Total			SS 1,015.00
Add GST @ 7%			71.05
Total Amount Payable			SS 1,086.05

TOTAL: SINGAPORE DOLLAR ONE THOUSAND EIGHTY SIX AND CENTS FIVE ONLY

For SME Motor Pte Ltd

List 850

-250

637.50

lc

250

887.50

not Allocat

24hr
the ph. after up
2 day
11/7/18

4/5

plp \$887.50

15/08/18

AUTHORISED SIGNATURE
LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

SME Motor Pte Ltd

1 Kaki Bukit Ave 6, #02-15 Autobay@KakiBukit Singapore 417883
TEL: 67476106 (6 lines) FAX: 67442368 Email: service@smemotor.com.sg
GST:201119451E RCB NO:201119451E

M/S : HONG SEAFOOD PTE LTD

Singapore

ATTN:

Your Ref No: 18/EQ/TP-139 (07)

Claim Type: Third Party

Accident Date: 06/07/2018

TP Veh Reg No: GBF214U

Estimate No: EST0004251

Date: 15 Aug 2018

Policy No: A28613664MKC

Veh Reg No: GX8592X

Make/Model: TOYOTA DYNA

Chasis No: JTFUF34YX03002779

Engine No: 5L5472403

Reg. Date: 12/10/2004

Estimate Repair Cost to Vehicle No :GX8592X

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
Supplementary Parts to Repair			
List Price			
1 SIDE MIRROR TOP COVER LH	1 PC	4.5 30.00	
		30.00	
	Less 25%	7.50	22.50
Total			S\$ 22.50
GST Amount			S\$ 1.58
Total Amount Payable			S\$ 24.08

For SME Motor Pte Ltd

AUTHORISED SIGNATURE

1-820
637.50
887.50