



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: EQ INSURANCE COMPANY LTD	Document No.	: SQT18002831	Page	1
	5 MAXWELL ROAD	Date	: 9. Jul 2018		
	#17-00 TOWER BLK MND BUILDING	Customer No.	: WZE011		
	SINGAPORE 069110	Svc Advisor	: ANIKKA LAI SWEE KAM		
Registration No	: SLW2387H	Engine No	: L15B33111785		
Chassis No	: JHMGK5850JX204040	Date Time	: 9. Jul 2018 8:55:38 PM		
Model	: JAZZ 1.5VTIR CVT 18YM (EURO 6)	Surveyor Name	:		
Owner's Name	: WONG SIN DUEN	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 7/7/2018				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: OWNER: WONG SIN DUEN OWNER INSURER: TOKIO MARINE ACC DATE: 7/7/18 SURVEYED BY: DATE: REF NO: TP INSURER: EQ INSURANCE TP VEH: XB6166X						
04715-T5B-J50ZZ	FACE,RR.BUMPER	1 <i>de</i>	492.60	25	369.45	25.86	395.31
71593-T5A-J50	SPACER,R.RR.BUMPER SIDE	1 <i>new</i>	16.60	25	12.45	0.87	13.32
71598-T5A-J50	SPACER,L.RR.BUMPER SIDE	1 <i>x</i>	16.60	25	12.45	0.87	13.32
91505-TM8-003	CLIPBUMPER	9 <i>per</i>	2.00	25	13.50	0.95	14.45
04636-TAS-300ZZ	PANEL SET,R.RR.OUTSIDE	1 <i>bt</i>	537.60	25	403.20	28.22	431.42
73525-SYY-000	RUBBERRR QTR W/SHIELD	2 <i>new</i>	9.50	25	14.25	1.00	15.25
91501-T5A-003	CLIPQUARTER WINDSHIELD A	1 <i>new</i>	3.60	25	2.70	0.19	2.89
91502-T5A-003	CLIPQUARTER WINDSHIELD B	1 <i>new</i>	3.60	25	2.70	0.19	2.89
91503-T5A-003	CLIPQUARTER WINDSHIELD C	1 <i>new</i>	2.40	25	1.80	0.13	1.93
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	1 <i>new</i>	60.00		60.00	4.20	64.20
42700-TAR-E91	DISK ALUMINIUM WHEEL,16X6	1 <i>new</i>	772.30	25	579.22	40.55	619.77
Sum Item					1471.72	103.03	1,574.75
BOSUN	SUNDRIES	1 <i>30</i>	100.00		100.00	7.00	107.00
BG52R	REPLACE RR. R QTR GLASS.(N)	1 <i>✓</i>	280.00		280.00	19.60	299.60
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1 <i>280</i>	650.00		650.00	45.50	695.50
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1 <i>100</i>	200.00		200.00	14.00	214.00
BA02R	REMOVE & INSTALL REVERSE SENSORS-4 PCS (N)	1 <i>✓</i>	160.00		160.00	11.20	171.20
BKFE22R	<i>560</i> CUT OFF & RENEW RR R FENDER & DAMAGE PARTS	1 <i>2800 3000</i>	2000.00		2000.00	140.00	2140.00
BP03R	<i>450</i> SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (3P)	1 <i>1350</i>	1500.00		1500.00	105.00	1605.00



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: EQ INSURANCE COMPANY LTD	Document No.	: SQT18002831	Page	2
	5 MAXWELL ROAD	Date	: 9. Jul 2018		
	#17-00 TOWER BLK MND BUILDING	Customer No.	: WZE011		
	SINGAPORE 069110	Svc Advisor	: ANIKKA LAI SWEE KAM		
Registration No	: SLW2387H	Engine No	: L15B33111785		
Chassis No	: JHMGK5850JX204040	Date Time	: 9. Jul 2018 8:55:38 PM		
Model	: JAZZ 1.5VTIR CVT 18YM (EURO 6)	Surveyor Name	:		
Owner's Name	: WONG SIN DUEN	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 7/7/2018				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
Sum Labor					4890.00	342.30	5,232.30

Survey By	<u>Tan Jiah 97495749</u>						
Date & Time	<u>13/7/18 @ 1730</u>	Total Amount	7	6,361.72	445.33	6,807.05	
Excess		Total (Inclusive of GST)				6,807.05	
Status	<u>WP</u>						
Signature	<u>[Signature]</u>						

sure lkkauto.com.
Resurvey before paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 12/7/2018 1:25:00 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)