

ASSIGNMENT

From: _____ Date: 11/07/2018

Estimated Cost: _____

OD ☒ TP ☒ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MV

To inspect Vehicle No: SJ41742G

at Workshop m/s K. Kim Hin Auto

of 160 Sin Ming Drive #02-20

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)



Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$16k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 24 days Res.: Yes or No

Lum Sum: 20% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS up

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SJU 1742G Yr Regn: 11, 09

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Avante c.c. 1591

Colour: 2. Black A/C: Insured / Std / NI / NA

Sp. Reading: 117265 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KM14DU41BMTU 897517

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: Hankook 215/45R17

R: Falken

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal. 8 mm

L/Bal. 8 mm

D.O.A. 6/7/118

Survey held at

Rear

R/Bal. 7 mm

L/Bal. 7 mm

D.O.I. 11/7/118

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

& R

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

12/7 K. Kim Hin to Catherine
Return Simon max 6/11/2011 @ 7200

(RSD: + 24,782.57 71%)

Date/Time, File Pass to?

☐ : Prel. Report☐ : Final Report

Date/Time, File Return to?

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS \$ _____

Photos

Others

TOTAL

Report Format:

ump Sum / I.B.I. (\$) _____

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

No. : 29883

Vehicle Insured : SKW 3598 X
Accident Date : 06-Jul-2018

Date : 09-Jul-2018

Our Ref : 180432 (ECICS) / SANDRA

PAGE : 1

WANG YIHONG (MR)
Singapore

Not Notified
1/1 Aug @ ?
Return After Paint
24 days

ESTIMATED COST OF REPAIR FOR HYUNDAI AVANTE 1.6 AT (2009) SJU1742G

1 pc	front bumper			<i>Bz</i>	461.46	—
2 pcs	front bumper side retainer (LH/RH)	@ S\$ 18.70		<i>CM</i>	37.40	—
10 pcs	front bumper clips	@ S\$ 2.00		<i>ru</i>	20.00	✓
2 pcs	front bumper foglamp assy (LH/RH)	@ S\$141.70	<i>all in</i>		283.40	✓
1 pc	front bumper lower centre grille			<i>Dir</i>	47.00	✓
1 pc	front bumper sponge			<i>CM</i>	113.40	—
1 pc	front bumper reinforcement			<i>Bz</i>	254.00	—
2 pcs	front bumper reinforcement bracket (LH/RH)	@ S\$ 29.80			59.60	<i>X/NH</i>
2 pcs	headlamp assy (LH/RH)	@ S\$480.00	<i>my Bz</i>		960.00	✓
2 pcs	headlamp lower bracket (LH/RH)	@ S\$ 29.80		<i>Bz</i>	59.60	✓
8 pcs	front grille clips	@ S\$ 2.00		<i>ru</i>	16.00	—
2 pcs	front fender (LH/RH)	@ S\$434.30		<i>Bz</i>	868.60	—
2 pcs	front fender "VVT" emblem (LH/RH)	@ S\$ 18.20		<i>ru</i>	36.40	—
2 pcs	front fender inner shield (LH/RH)	@ S\$ 48.00		<i>In</i>	96.00	<i>X</i>
18 pcs	front fender inner shield clip	@ S\$ 2.00		<i>ru</i>	36.00	<i>X</i>
1 pc	bonnet			<i>By</i>	1,792.40	✓
2 pcs	bonnet hinges (LH/RH)	@ S\$ 55.70		<i>ru</i>	111.40	<i>X</i>
1 pc	bonnet insulator			<i>Return</i>	230.10	✓
11 pcs	bonnet insulator clips	@ S\$ 2.00		<i>ru</i>	22.00	✓
2 pcs	bonnet rubber stopper	@ S\$ 6.70		<i>In</i>	13.40	<i>X</i>
1 pc	bonnet stay			<i>In</i>	18.90	<i>X</i>
1 pc	bonnet stay bush			<i>In</i>	7.00	<i>X</i>
1 pc	bonnet stay clip holder			<i>In</i>	7.00	<i>X</i>
1 pc	bonnet stay top protector				15.00	<i>X/NH</i>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Con't Page 2 ...



AUTO PTE LTD

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkinhin.com.sg

Vehicle Insured : SKW 3598 X
Our Ref : 180432

Page : 2
No. : 29883

1 pc	bonnet stay top protector rivet		MC	3.00	✓
1 pc	bonnet lock		MC	44.80	✓
1 pc	bonnet lock cover			8.00	X NH
1 pc	bonnet pull lock cabler-outer			24.20	X NH
1 pc	bonnet inner seal		CM	14.60	✓
1 pc	front support panel		CM	791.30	✓
2 pcs	horn (LH/RH)	@ S\$ 73.80		147.60	X NH
1 pc	aircon condenser			990.90	X NH
1 pc	aircon condenser liquid pipe			360.50	X NH
1 pc	aircon condenser discharge pipe			191.50	X NH
1 pc	aircon condenser suction pipe			200.20	X NH
1 pc	radiator			588.70	X NH
2 pcs	radiator air guide (LH/RH)	@ S\$ 15.00		30.00	X NH
2 pcs	radiator top bracket (LH/RH)	@ S\$ 14.70		29.40	X NH
2 pcs	radiator top bush (LH/RH)	@ S\$ 14.70		29.40	X NH
2 pcs	radiator bottom bush (LH/RH)	@ S\$ 14.70		29.40	X NH
1 pc	radiator top hose			41.50	X NH
1 pc	radiator bottom hose			41.90	X NH
1 pc	radiator spare tank		MC	30.20	✓
1 pc	radiator spare tank bypass hose			10.00	X NH
1 pc	radiator spare tank bypass pipe			17.50	X NH
1 pc	radiator fan assy		MC	567.50	X NH
1 pc	wiper washer tank			58.30	✓
1 pc	wiper washer tank	MC		54.70	X NH
1 pc	air intake duct	MC		96.80	X NH
1 pc	air cleaner box assy	MC		179.90	X NH
1 pc	air intake hose	MC		246.40	X NH
1 pc	throttle body assy	MC		732.50	X NH
1 pc	throttle body gasket	MC		10.00	X NH
1 pc	intake manifold	MC		406.10	X NH
1 pc	engine top cover	MC		202.90	✓
1 pc	battery tray			33.80	X NH
1 pc	front bumper under cover			43.20	X NH

Con't Page 3 ...



AUTO PTE LTD

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkinhin.com.sg

Vehicle Insured : SKW 3598 X
Our Ref : 180432

Page : 3
No. : 29883

2 pcs engine under cover (LH/RH)	@ S\$ 24.90	49.80	X
2 pcs engine under side cover (LH/RH)	@ S\$ 13.00	26.00	X
1 pc engine mounting-LH		285.70	X
1 pc engine mounting-RH		303.60	X
1 pc engine mounting-front		217.00	X
1 pc engine mounting-rear		261.10	X
1 pc alternator		743.40	X
2 pcs rear number plate lamp assy (LH/RH)	@ S\$ 62.10	124.20	X
1 pc rear bumper		489.10	—
3 pcs rear bumper lower bracket	@ S\$ 21.60	64.80	—
2 pcs rear bumper top bracket (LH/RH)	@ S\$ 24.00	48.00	X NH
1 pc rear bumper sponge		109.90	—
1 pc rear bumper reinforcement		270.00	—
2 pcs rear bumper reinforcement bracket (LH/RH)	@ S\$ 67.30	134.60	—
10 pcs rear bumper clips	@ S\$ 2.00	20.00	—
2 pcs taillamp assy (LH/RH)	@ S\$ 288.40	576.80	—
2 pcs taillamp clips	@ S\$ 5.00	10.00	—
2 pcs taillamp panel (LH/RH)	@ S\$ 175.70	351.40	—
2 pcs rear fender (LH/RH)	@ S\$ 1806.10	3,612.20	—
2 pcs rear fender inner shield (LH/RH)	@ S\$ 13.00	26.00	—
16 pcs rear fender inner shield clips	@ S\$ 2.00	32.00	—
2 pcs rear fender inner trim lining (LH/RH)	@ S\$ 163.00	326.00	X NH
20 pcs rear fender inner trim lining clips	@ S\$ 2.00	40.00	X NH
1 pc rear windscreen glass moulding		47.50	—
1 pc bootlid		985.90	—
2 pcs bootlid hinges (LH/RH)	@ S\$ 132.00	264.00	X
1 pc bootlid outer garnish		62.40	—
1 pc bootlid outer garnish chrome		70.70	—
1 pc bootlid outer garnish top seal		15.40	—
6 pcs bootlid outer garnish clips	@ S\$ 2.00	12.00	—
1 pc bootlid "AVANTE" emblem		31.20	—
1 pc bootlid logo		23.30	—

Con't Page 4 ...

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

Vehicle Insured : SKW 3598 X
Our Ref : 180432

Page : 4
No. : 29883

1 pc	bootlid "S" emblem			20.30	✓
1 pc	bootlid weatherstrip			79.30	✓
2 pcs	bootlid lamp assy (LH/RH)	@ S\$163.60		327.20	✓
1 pc	bootlid lock			118.30	✓
1 pc	bootlid lock catch			15.00	✓
1 pc	bootlid inner trim lining			151.10	✓
10 pcs	bootlid inner trim lining clip	@ S\$ 2.00		20.00	✓
2 pcs	bootlid rubber stopper	@ S\$ 4.00		8.00	x
1 pc	key cylinder set			238.80	✓
2 pcs	rear fender top 1/4 glass	@ S\$363.00		726.00	✓
1 pc	rear end panel			493.80	✓
1 pc	rear end panel top garnish			34.40	✓
1 pc	spare tyre panel			878.30	✓
1 pc	spare tyre panel top board			220.00	x
2 pcs	spare tyre panel extension panel (LH/RH)	@ S\$ 96.70		193.40	x
1 pc	spare tyre lock screw			8.00	x
1 pc	o/s rear chassis member			657.20	x
1 pc	rear exhaust muffler			711.20	x
2 pcs	rear exhaust muffler mounting	@ S\$ 50.20		100.40	x
1 pc	rear exhaust muffler gasket			16.00	x
1 pc	centre exhaust muffler			394.50	x
2 pcs	centre exhaust muffler mounting	@ S\$ 19.00		38.00	x
1 pc	centre exhaust muffler gasket			16.00	x
				26,921.96	
Less 20% :				-5,384.39	
				21,537.57	
1 pc	front number plate			40.00	sn ✓
1 pc	front bumper spoiler			480.00	sn ✓
1 pc	front grille (sport)			350.00	sn ✓
1 pc	radiator coolant			48.00	sn ✓
1 pc	battery			380.00	sn ✓
1 pc	rear number plate			40.00	sn ✓
1 pc	rear bumper spoiler			480.00	sn ✓

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkinhin.com.sg

Vehicle Insured : SKW 3598 X
Our Ref : 180432

Page : 5
No. : 29883

1 pc	reverse sensor	
1 pc	reverse camera	
1 pc	rear windscreen glass sealant	
1 pc	rear windscreen glass damping seal	
1 pc	bootlid top spoiler	
2 pcs	rear fender top 1/4 glass	@ S\$ 40.00
	sealant	
2 pcs	rear fender top 1/4 glass	@ S\$ 20.00
	damping seal	
1 pc	spare tyre	
1 pc	rear subwoofer	

<i>Shan</i>	220.00	sn	<i>2000</i>
<i>nu</i>	380.00	sn	<i>✓</i>
<i>nu</i>	40.00	sn	<i>—</i>
<i>nu</i>	20.00	sn	<i>—</i>
<i>sn</i>	450.00	sn	<i>X</i>
<i>nu</i>	80.00	sn	<i>6000</i>
<i>nu</i>	40.00	sn	<i>✓</i>
	380.00	sn	<i>2000</i>
	450.00	sn	<i>X</i>

To tow accident vehicle to workshop
by flatbed or Kings Dolly towing

(Bill) 200.00 *X*

To remove, cut out damaged parts,
panel beating, welding, align,
refix and to renew affected parts.

2200
2,400.00

To focus Headlamps and Taillamps.

To check front and rear lighting
operation and rewiring

60.00 *400*

To remove and refit rear windscreen
glass and conduct water leak test

120.00 *✓*

To remove and refit left rear
fender top glass and conduct water
leak test.

100.00 *400*

To remove and refit right rear
fender top glass and conduct water
leak test.

100.00 *400*

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkinhin.com.sg

Vehicle Insured : SKW 3598 X
Our Ref : 180432

Page : 6
No. : 29883

To remove and refit rear upholstery trimming, roof lining, seats, speaker board in order to facilitate repairing works	120.00 ✓
To remove aircon condenser, pipes and driers. Vaccum and recharge gas	100.00 ✓
To apply undersealing	180.00 ✓
To dismantle and check rear under-carriage. To replace affected portions.	240.00 220
To conduct rear wheel alignment test.	80.00 60
To check and realignment on chassis member.	350.00 250
To remove and refit petrol/diesel tank in order to facilitate repairing works.	220.00 60
To remove and renew exhaust silencer box	120.00 80
To remove and refit reverse sensor assy.	80.00 50
To putty and respray on affected portions.	2000
	2,100.00
Total :	S\$31,985.57
	=====

Singapore Dollars Thirty One Thousand Nine Hundred and Eighty Five and Cents Fifty Seven Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4237J
Vehicle Details	
Vehicle No.:	SJU1742G
Vehicle to be Exported:	No
Intended De-registration Date:	09 Jul 2018
Vehicle Make:	HYUNDAI
Vehicle Model:	AVANTE 1.6 AT ABS D/AB 2WD 4DR
Primary Colour:	Black
Manufacturing Year:	2009
Engine No.:	G4FC9U750364
Chassis No.:	KMH DU41BMAU897517
Maximum Power Output:	89.7 kW (120 bhp)
Open Market Value:	\$11,400.00
Original Registration Date:	21 Nov 2009
First Registration Date:	21 Nov 2009
Transfer Count:	1
Actual ARF Paid:	\$11,400.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Nov 2019
PARF Rebate Amount:	\$6,270.00
Intended COE Rebate Details	
COE Expiry Date:	20 Nov 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$17,189.00
COE Rebate Amount:	\$2,344.00
Total Rebate Amount:	\$8,614.00

The information contained herein is correct as at 09 Jul 2018

OK



Inchcape
Pre-Owned

**WIDE RANGE OF PRE-OWNED
TOYOTA AND OTHER MAKES
AVAILABLE**

VISIT OUR NEW SHOWROOM FOR A PREMIUM PRE-OWNED EXPERIENCE @ 2 PANDAN CRESCENT INCHCAPE CENTRE



LEARN
MORE
»

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Weekend Offer Free 2 Years Warranty/Service Package.



Call Now Before It Was Sold.
Sincere Trading

PRIME MOTOR & LEASING

BOHONG YONG CHENG ENTERPRISES PTE LTD GROUP OF COMPANIES

With over 200 units of vehicles
to choose from, ranging from
all European to Japanese Makes.

Post an Ad

Advertiser Login

Ways of Selling

Browse by Category

< Back (1 2 3) Next >

Sort by Date Posted

20 results/page

59 vehicles

Hyundai Avante

Advanced Search

Image	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Hyundai Avante	Any	Any	2009	Any	Any	Any	Available
	Hyundai Avante 1.6A S	\$11,800	\$8,100 /yr	14-May-2009	1,591 cc	-	Sedan	Available
Extremely Well Maintained Unit! Ideal For Short Term Drive Or COE Renewal! Call To View In Our Air-Conditioned Showroom Now!								
G5 Automobiles Pte Ltd								
Posted: 08-Jul-2018 Tags: 2009 Hyundai Avante, Hyundai Avante, Hyundai, Avante, Used Hyundai								
	Hyundai Avante 1.6A S	\$15,500	\$7,970 /yr	30-Sep-2009	1,591 cc	125,000 km	Sedan	Available
(S Model, 1 Owner Car) 100% Quality Buy! Low Mileage Unit 125,000km Done, Comes With 6 Months Engine And Gearbox Warranty, All Our Quality Preworn Car Are Selling At Low Depreciation Price. STA/VICOM...								
Car World Automobile								
Posted: 08-Jul-2018 Tags: 2009 Hyundai Avante, Hyundai Avante, Hyundai, Avante, Used Hyundai								
	Hyundai Avante 1.6A RS Sunroof	\$15,800	\$8,920 /yr	25-Aug-2009	1,591 cc	-	Sedan	Available
Sport Black Avante RS Comes With Sunroof And Only 1 In The Market! Well Maintained By Previous Owner And Well Maintained. Very Spacious And Big Boot Space. Ideal For Those Who Fancy Spacious And Comfo...								
Ka-Hup Vehicles Trading								
Posted: 07-Jul-2018 Tags: 2009 Hyundai Avante, Hyundai Avante, Hyundai, Avante, Used Hyundai								
	Hyundai Avante 1.6A	\$14,700	\$7,220 /yr	06-Oct-2009	1,591 cc	115,000 km	Sedan	Available
Elegant And Sporty Titanium Silver! Only 1 Owner! Very Well Maintained By Meticulous Owner! Zero Modification! Low Mileage Done! Buy With A Peace Of Mind From A Company With 30 Years Of Excellent Hist...								
Posted: 07-Jul-2018 Tags: 2009 Hyundai Avante, Hyundai Avante, Hyundai, Avante, Used Hyundai								
Car Buying	Car Selling	Car Ownership						
Car Aftermarket	On The Move	Lifestyle						
	Hyundai Avante 1.6A S	\$15,222	\$7,350 /yr	28-Oct-2009	1,591 cc	142,721 km	Sedan	Available
Priced For Quick Sales. Car In Full Working Condition. Well Maintained. Best For Short Term Drive. Quiet Ride. Call Now To View.								
Posted: 06-Jul-2018 Tags: 2009 Hyundai Avante, Hyundai Avante, Hyundai, Avante, Used Hyundai								
	Hyundai Avante 1.6M	\$12,600	\$6,100 /yr	28-Oct-2009	1,591 cc	112,018 km	Sedan	Available
Cheapest Avante With Only Depre \$5.9k! Free 1 Year Warranty! Flexible Loan And Insurance Packages. Low Interest Rate At 2.78%. Welcome All Kind Of Trade In. Welcome Workshop Or STA Evaluation. Act Fas...								
Posted: 06-Jul-2018 Tags: 2009 Hyundai Avante, Hyundai Avante, Hyundai, Avante, Used Hyundai								
	Hyundai Avante 1.6A S	\$16,800	\$7,770 /yr	18-Dec-2009	1,591 cc	-	Sedan	Available
GUARANTEE BUY BACK AT 7K! Cheapest In The Market! Quiet Engine And Undercarriage With Smooth Running Condition. Very Good Condition! Fuel Efficiency At 12Km/L! Easy To Drive And Maintain! Welcome Trade...								
Posted: 06-Jul-2018 Tags: 2009 Hyundai Avante, Hyundai Avante, Hyundai, Avante, Used Hyundai								
Compare	undai Avante 1.6M	\$10,000	\$5,480 /yr	22-Jun-2009	1,591 cc	95,000 km	Sedan	Available



Perfect Neutral Colour With The Least Maintenance Needed! Good Drive, Healthy Engine And Gearbox, Coupled With Our In-House 6 Months Warranty, STA Or Your Preferred Workshop For A Pre-purchase Inspect...

Posted: 05-Jul-2018 Tags: 2009 Hyundai Avante, Hyundai Avante, Hyundai, Avante, Used Hyundai



Hyundai Avante 1.6A R5 Sunroof

\$14,800

\$8,360 /yr

11-Aug-2009

1,591 cc

109,000 km

Sedan

Available

One Owner, Clean Interior, Well Maintained By Previous Owner, Spacious Yet Fuel Efficiently, Good For Short Term Drive, Act Now To Test Drive This White Beauty Avante!

Taxis

Posted: 04-Jul-2018 Tags: 2009 Hyundai Avante, Hyundai Avante, Hyundai, Avante, Used Hyundai



Hyundai Avante 1.6M

\$11,800

\$7,180 /yr

11-Jul-2009

1,591 cc

-

Sedan

Available

Welcome All Kind Of Trade In. Welcome Workshop Or STA Evaluation. Reliable Manual Transmission, Accident Free Unit! Viewing Strictly Via Appointment Only.

Posted: 03-Jul-2018 Tags: 2009 Hyundai Avante, Hyundai Avante, Hyundai, Avante, Used Hyundai



How much is your car really worth?

Find out how much your car can sell for, Quotz helps owners like you, sell their cars at the HIGHEST PRICE guaranteed! If we fail, you'll get \$100 CASH! Free valuation via phone/online. Absolutely No obligations!

Find out more!



Hyundai Avante 1.6M

\$11,600

\$5,650 /yr

29-Sep-2009

1,591 cc

-

Sedan

Available

Reliable Car, Can Easily Drive For Another 10 Years. Selling Only Because Of Work Assignment Overseas. Well-maintained By Single Owner, Regular Servicing, Fuel Efficient, Spacious Boot.

Posted: 03-Jul-2018 Tags: 2009 Hyundai Avante, Hyundai Avante, Hyundai, Avante, Used Hyundai

DIRECT OWNER



Hyundai Avante 1.6A

\$10,800

\$8,000 /yr

23-Feb-2009

1,591 cc

93,000 km

Sedan

Available

Full Agents Service Since Day 1, 1 Careful Owner, Low Mileage Done, All Wear And Tear Done Up! Suitable For Short Term Drive Or COE Renewal, Act Now To Test This Car Today!

Taxis

Posted: 02-Jul-2018 Tags: 2009 Hyundai Avante, Hyundai Avante, Hyundai, Avante, Used Hyundai



Hyundai Avante 1.6A S

\$12,998

\$12,300 /yr

11-Feb-2009

1,591 cc

220,000 km

Sedan

Available

Changed Recently Engine And Gearbox Oil Cum Filter, Spark Plugs, All Engine Mounting, Waterpump, Fan Belt, Battery, Suitable For Short Term Usage, Engine And Gearbox In Good Condition, Very Low Cost C...

Posted: 02-Jul-2018 Tags: 2009 Hyundai Avante, Hyundai Avante, Hyundai, Avante, Used Hyundai

DIRECT OWNER



Hyundai Avante 1.6A

\$15,800

\$7,890 /yr

20-Oct-2009

1,591 cc

169,100 km

Sedan

Available

Excellent Engine And Interior Condition.

Posted: 01-Jul-2018 Tags: 2009 Hyundai Avante, Hyundai Avante, Hyundai, Avante, Used Hyundai

DIRECT OWNER



Hyundai Avante 1.6A S

\$11,800

\$7,280 /yr

13-May-2009

1,591 cc

-

Sedan

Available

1 Owner Very Well Kept. Road Tax 11/2018. Monthly Only \$460 Depreciation, Guarantee Buy Back At \$6700 Upon Expire, Economical Car Great For Daily Usage, Car Still Look Presentable Despite Its Age, Pri...

Posted: 30-Jun-2018 Tags: 2009 Hyundai Avante, Hyundai Avante, Hyundai, Avante, Used Hyundai



Hyundai Avante 1.6A S

\$14,800

\$8,730 /yr

30-Jul-2009

1,591 cc

74,000 km

Sedan

Available

Well Maintained Interior And Exterior By Previous Owner! Spacious Cabin! Tip Top Condition With No Repairs Needed! Suitable For Short Term Ride And Renew Of COE In The Future! Buy With Assurance From ...

Ka-Hup Vehicles Trading

Posted: 30-Jun-2018 Tags: 2009 Hyundai Avante, Hyundai Avante, Hyundai, Avante, Used Hyundai

DEPRECIATION



Hyundai Avante 1.6A

\$14,000

\$7,350 /yr

02-Oct-2009

1,591 cc

157,208 km

Sedan

Available

Well Maintained By The Previous Owner. Smooth Drive From Point A To Point B.

Carro

Posted: 27-Jun-2018 Tags: 2009 Hyundai Avante, Hyundai Avante, Hyundai, Avante, Used Hyundai

DEPRECIATION



Hyundai Avante 1.6A S

\$16,800

\$8,700 /yr

19-Oct-2009

1,591 cc

129,000 km

Sedan

Available

(S Model, 1 Owner Car) 100% Quality Buy! Low Mileage Unit, Looks, Drive And Feels Like New. Perfectly Well Maintained, No Repairs Needed, All Our Quality Prowen Car Are Selling At Low Depreciation ...

Ka-Hup Vehicles Trading

Posted: 27-Jun-2018 Tags: 2009 Hyundai Avante, Hyundai Avante, Hyundai, Avante, Used Hyundai

DEPRECIATION



Hyundai Avante 1.6M **\$13,800** **\$7,040 /yr** **27-Oct-2009** **1,591 cc** **130,000 km** **Sedan** **Available**

Low Mileage! Beautiful Silver Sedan! Selling Due To Upgrading! Good Condition, Well Taken Care And Maintained By Owner. Road Tax Until November. Good For COE Renewal/Short Term Usage! Consignment Unit...

Consignment

Car Search

Posted: 26-Jun-2018 Tags: 2009 Hyundai Avante, Hyundai Avante, Hyundai, Avante, Used Hyundai



Hyundai Avante 1.6A **\$12,800** **\$7,120 /yr** **15-Jul-2009** **1,591 cc** **161,000 km** **Sedan** **Available**

Trade In All Available, Interested Please Call For Viewing, Viewing By Appointment Only.

Boeki Auto & Marine

Posted: 23-Jun-2018 Tags: 2009 Hyundai Avante, Hyundai Avante, Hyundai, Avante, Used Hyundai

Save this search criteria, to get email alerts whenever a match is found.

Model Price Depreciation Eng Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

= Back (1 2 3) Next =

20 results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & QPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used Hyundai Avante, Hyundai Avante Singapore, used Hyundai Avante Singapore, used Hyundai Avante, used vehicles Singapore or even buy used Hyundai Avante Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2018 sgCarMart. All rights reserved.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: ECICS Limited
7 Temasek Boulevard
#10-01 Suntec Tower One
Singapore 038987

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 13 Jul 2018

Preliminary Advice

Insured Vehicle No	: SKW3598X	Accident Date	: 06/07/2018
TP Vehicle No	: SJU1742G	Assignment Date	: 11/07/2018
Make	: HYUNDAI AVANTE	Est. Duration of Repair	: 24 days
Date of Inspection	: 11/07/2018		
Inspection At	: K Kim Hin Auto Pte Ltd (HQ) 160 Sin Ming Drive #02-20, Sin Ming AutoCity Singapore 575722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages ...front and rear.... portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	31,985.57
Revised Amount	:S\$	19,030.66
Check Items (Estimated)	:S\$	8,467.84
Total	:S\$	27,498.50

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	16,000.00
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	8,614.00
Salvage Value	:S\$	
Margin for Repair	:S\$	7,386.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : We have not authorized repairs.

Catherine Chong (LKK Auto)

From: motorsurvey <motorsurvey@ecics.com.sg>
Sent: Tuesday, 10 July, 2018 3:26 PM
To: admin1@kkimhin.com.sg; assignments@lkkauto.com
Cc: service@kkimhin.com.sg; sandrakhong@gmail.com; simon@kkimhin.com.sg; survey@kkimhin.com.sg; motorsurvey
Subject: RE: Accident involving SJU 1742 G and SKW 3598 X on 6/7/2018 ; Our claim no is DMPC1800280H.
Attachments: GIA REPORT BY LAIHUAT.PDF

Without Prejudice

Dear Shuman

Thank you for your email.
We will appoint LKK for the PRS.

Aside to LKK

Please assist to arrange TP PRS.

Thank you.

Regards,
Janice Goh
Claims Division
DID: +65 6303 0182
FAX: +65 6338 9267

ECICS Limited
7 Temasek Boulevard, #10-01 Suntec Tower One, Singapore 038987

WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to motorsurvey@ecics.com.sg directly.

Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. Thank you for your kind patience and understanding.

From: admin1@kkimhin.com.sg [mailto:admin1@kkimhin.com.sg]
Sent: Tuesday, 10 July, 2018 12:06 PM
To: motorsurvey
Cc: service@kkimhin.com.sg; sandrakhong@gmail.com; simon@kkimhin.com.sg; survey@kkimhin.com.sg
Subject: FW: Accident involving SJU 1742 G and SKW 3598 X on 6/7/2018

Dear all,

Kindly arrange for survey, vehicle is in.

Thank you.

Best Regards,
Shuman
K. Kim Hin Auto Pte Ltd
Tel: 6452 7018 Fax: 6458 3895

10/7/2018 @ 3:48pm
Shuman veh in

11.07.2018

From: admin1@kkimhin.com.sg [mailto:admin1@kkimhin.com.sg]
Sent: 09 July, 2018 2:00 PM
To: 'claims@ecics.com.sg'
Cc: 'service@kkimhin.com.sg'; 'sandrakhong@gmail.com'; 'simon@kkimhin.com.sg'; 'survey@kkimhin.com.sg' (survey@kkimhin.com.sg)
Subject: Accident involving SJU 1742 G and SKW 3598 X on 6/7/2018

Your ref: SKW 3598 X
Our ref: SJU 1742 G

Dear all,


Our client SJU 1742 G, who was hit by your insured SKW 3598 X, on 6/7/2018.

We will forward the GIA report later once ready.

Vehicle is in and working on the estimate, kindly appoint surveyor.

Thank you.

Best Regards,
Shuman
K. Kim Hin Auto Pte Ltd
Tel: 6452 7018 Fax: 6458 3895



This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

Asher Sng (LKKAuto)

From: Asher Sng (LKKAuto)
Sent: Wednesday, 1 August 2018 2:04 PM
To: 'PHOCKLEONG@GMAIL.COM'
Subject: ACCIDENT INVOLVING SKW 3598X & SJU 1742G AT / ALONG TPE TWDS SLE BESIDE TAMPINES AVE 10 EXIT ON 06/07/2018.

HI POH HOCK LEONG,

[Without Prejudice]

By Email Only

ACCIDENT INVOLVING SKW 3598X & SJU 1742G AT / ALONG TPE TWDS SLE BESIDE TAMPINES AVE 10 EXIT ON 06/07/2018.

We refer to the above accident matter.

As spoken, we are the loss adjusters acting on behalf of M/s ECICS Limited, the Motor Insurer of SKW 3598X on the reported accident on 06/07/2018.

Our Principal has received a Third Party property damage claim from the owner of SJU 1742G with regards to the above accident.

We will try our best to negotiate for an amicable settlement on best possible terms with Third Party under the terms and conditions of your motor policy. In this respect, the vehicle's premium/NCD may be affected as a result of the above claim.

In the event that you receive any letters/ court documents regards to the above accident matter, please do not reply or respond, you may forward to us directly for further handling and we will reply on your behalf.

Thank you.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Asher Sng (LKKAuto)

From: Asher Sng (LKKAuto)
Sent: Monday, 9 September 2019 4:25 PM
To: Desmond Lee Ker Wen (ECICS, Claims)
Cc: ECICS Claims
Subject: RE: Accident involving SJU 1742 G and SKW 3598 X on 6/7/2018 ; Our claim no is DMPC1800280H.
Attachments: [REMINDER] RE: ACCIDENT INVOLVING SJU 1742G AND SKW 3598X ON 06/07/2018

Hi Sir,

We refer to the above matter.

Third party claimant yet to send in the vehicle for repair till date.

In view on above, we will like to submit our w/p report due to no development.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Janice Goh Siew Geok (ECICS, Claims) [mailto:Janice_Goh@ecics.com.sg]

Sent: Tuesday, 10 July 2018 3:33 PM

To: assignments@lkkauto.com

Subject: FW: Accident involving SJU 1742 G and SKW 3598 X on 6/7/2018 ; Our claim no is DMPC1800280H.

Hi LKK

Please find the attached of insured report for your kind attention.

Thank you.

Regards,

Janice Goh

Claims Division

DID: +65 6303 0182

FAX: +65 6338 9267

ECICS Limited

7 Temasek Boulevard, #10-01 Suntec Tower One, Singapore 038987

WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to motorsurvey@ecics.com.sg directly.

Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. Thank you for your kind patience and understanding.

From: motorsurvey
Sent: Tuesday, 10 July, 2018 3:26 PM
To: 'admin1@kkimhin.com.sg'; 'assignments@lkkauto.com'
Cc: service@kkimhin.com.sg; sandrakhong@gmail.com; simon@kkimhin.com.sg; survey@kkimhin.com.sg; motorsurvey
Subject: RE: Accident involving SJU 1742 G and SKW 3598 X on 6/7/2018 ; Our claim no is DMPC1800280H.

Without Prejudice

Dear Shuman

Thank you for your email.
We will appoint LKK for the PRS.

Aside to LKK

Please assist to arrange TP PRS.

Thank you.

Regards,
Janice Goh
Claims Division
DID: +65 6303 0182
FAX: +65 6338 9267

ECICS Limited
7 Temasek Boulevard, #10-01 Suntec Tower One, Singapore 038987

WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to motorsurvey@ecics.com.sg directly.

Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. Thank you for your kind patience and understanding.

From: admin1@kkimhin.com.sg [mailto:admin1@kkimhin.com.sg]
Sent: Tuesday, 10 July, 2018 12:06 PM
To: motorsurvey
Cc: service@kkimhin.com.sg; sandrakhong@gmail.com; simon@kkimhin.com.sg; survey@kkimhin.com.sg
Subject: FW: Accident involving SJU 1742 G and SKW 3598 X on 6/7/2018

Dear all,

Kindly arrange for survey, vehicle is in.

Thank you.

Best Regards,
Shuman

K. Kim Hin Auto Pte Ltd
Tel: 6452 7018 Fax: 6458 3895

From: admin1@kkimhin.com.sg [mailto:admin1@kkimhin.com.sg]
Sent: 09 July, 2018 2:00 PM
To: 'claims@ecics.com.sg'
Cc: 'service@kkimhin.com.sg'; 'sandrakhong@gmail.com'; 'simon@kkimhin.com.sg'; 'survey@kkimhin.com.sg' (survey@kkimhin.com.sg)
Subject: Accident involving SJU 1742 G and SKW 3598 X on 6/7/2018

Your ref: SKW 3598 X
Our ref: SJU 1742 G

Dear all,

Our client SJU 1742 G, who was hit by your insured SKW 3598 X, on 6/7/2018.

We will forward the GIA report later once ready.

Vehicle is in and working on the estimate, kindly appoint surveyor.

Thank you.

Best Regards,
Shuman
K. Kim Hin Auto Pte Ltd
Tel: 6452 7018 Fax: 6458 3895

☐	☐	☐
--------------------------	--------------------------	--------------------------

This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Oct 2019 12:00 Edit Reg		10 Jul 2018 00:00 Edit Adj Rpt	S\$7,200.00 Edit Estimates	S\$7,200.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: POH HOCK LEONG , ID: S1417192D, Email: www.abcd.com.sg									
Main Claimant: WANG YIHONG , ID: S8624237J									
Vehicle Reg. No.: SJU1742G		Date of Loss: 06/07/2018 17:00 - :59 [103 Months and 15 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / DMPC1800280H		Policy/Cover Note No.: MPC17A00498402							
Vehicle Reg. No. (Insured): SKW3598X		Policy No. (Claimant): A0005503							
		Excess:							
Repairer: K Kim Hin Auto Pte Ltd (HQ) 160 Sin Ming Drive #02-20, Sin Ming AutoCity, S75722 Sin Ming - Tel: 64527018									
Handling Insurer: ECICS Limited (HQ) - Tel: 63374779 /6303 0178 ... [Handled by Desmond Lee - 6303 0167]									
Claimant's Insurer: Allied World Assurance Company, Ltd (HQ) - Tel: 62201188									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 20/07/2018]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJU1742G (DMPC1800280H)
[SKW3598X]

TP

WANG YIHONG

Jul 6 2018 5:00PM

[POH HOCK LEONG]

K Kim Hin Auto Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[View](#)
[View in Browser](#)

Assessment Reports

1 per page



No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	13/07/18 16:40	Adjuster Immediate Advice	 Load HTM	☐

Photos/Images

3 per page



No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	09/09/19 16:20	General View	 Load JPG	☒
2	09/09/19 16:20	General View	 Load JPG	☒
3	09/09/19 16:20	General View	 Load JPG	☒
4	09/09/19 16:20	General View	 Load JPG	☒
5	09/09/19 16:20	General View	 Load JPG	☒
6	09/09/19 16:20	General View	 Load JPG	☒
7	09/09/19 16:20	General View	 Load JPG	☒
8	09/09/19 16:20	General View	 Load JPG	☒
9	09/09/19 16:20	General View	 Load JPG	☒
10	09/09/19 16:20	General View	 Load JPG	☒
11	09/09/19 16:20	General View	 Load JPG	☒
12	09/09/19 16:20	General View	 Load JPG	☒
13	09/09/19 16:20	General View	 Load JPG	☒
14	09/09/19 16:20	General View	 Load JPG	☒
15	09/09/19 16:20	General View	 Load JPG	☒
16	09/09/19 16:20	General View	 Load JPG	☒
17	09/09/19 16:20	General View	 Load JPG	☒
18	09/09/19 16:20	General View	 Load JPG	☒
19	09/09/19 16:20	General View	 Load JPG	☒
20	09/09/19 16:20	General View	 Load JPG	☒
21	09/09/19 16:20	General View	 Load JPG	☒
22	09/09/19 16:20	General View	 Load JPG	☒
23	09/09/19 16:20	General View	 Load JPG	☒
24	09/09/19 16:20	General View	 Load JPG	☒
25	09/09/19 16:20	General View	 Load JPG	☒
26	09/09/19 16:20	General View	 Load JPG	☒
27	09/09/19 16:20	General View	 Load JPG	☒
28	09/09/19 16:20	General View	 Load JPG	☒
29	09/09/19 16:20	General View	 Load JPG	☒
30	09/09/19 16:20	General View	 Load JPG	☒
31	09/09/19 16:20	General View	 Load JPG	☒
32	09/09/19 16:20	General View	 Load JPG	☒
33	09/09/19 16:20	General View	 Load JPG	☒
34	09/09/19 16:20	General View	 Load JPG	☒
35	09/09/19 16:20	General View	 Load JPG	☒
36	09/09/19 16:20	General View	 Load JPG	☒
37	09/09/19 16:20	General View	 Load JPG	☒
38	09/09/19 16:20	General View	 Load JPG	☒
39	09/09/19 16:20	General View	 Load JPG	☒
40	09/09/19 16:20	General View	 Load JPG	☒

Assessment Reports				1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
					☒
41	09/09/19 16:20	General View		Load JPG	☒
42	09/09/19 16:20	General View		Load JPG	☒
43	09/09/19 16:20	General View		Load JPG	☒
44	09/09/19 16:20	General View		Load JPG	☒
45	09/09/19 16:20	General View		Load JPG	☒
46	09/09/19 16:20	General View		Load JPG	☒
47	09/09/19 16:20	General View		Load JPG	☒
48	09/09/19 16:20	General View		Load JPG	☒
Documentation				1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	11/07/18 16:12	ACKNOWLEDGEMENT EMAIL TO ICS DD 10.07.2018		Load PDF	
2	11/07/18 16:12	TP GIA REPORT		Load PDF	
3	16/07/18 11:05	TP ESTIMATE - MARKED		Load PDF	
4	18/07/18 15:34	OI GIA REPORT		Load PDF	
5	01/08/18 14:05	LETTER TO OI		Load PDF	
6	09/09/19 16:27	EMAIL TO ICS DD 090919		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/ICS18012635/KEA3Q2

Date: 08/10/2019

REFERENCE

Handling Insurer: ECICS Limited Policy No: MPC17A00498402

Claimant Vehicle No : SJU1742G Insured Vehicle No : SKW3598X

Date of Loss: 06/07/2018 Nature of Claim: TP Claim No: DMPC1800280H

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJU1742G**
 Make & Model: **HYUNDAI AVANTE, 1.6 ABS AIRBAG 2WD 4DR (A)** Engine No: **G4FC9U750364**
 Reg. Date: **21/11/2009 (Man. Year: 2009)** Chassis No: **KMH DU41BMAU897517**
 Colour: **Metallic Black** Odometer: **117265 km**
 Engine Capacity: **1591 cc**
 Market Value/New Car Price: **N/A**
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: **215/45 R17** Rear Tyre Size: **215/45 R17**
 Front Left Side: **Hankook 8 mm** Rear Left Side: **Falken 7 mm**
 Front Right Side: **Hankook 8 mm** Rear Right Side: **Falken 7 mm**

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	25,415.57	13,470.66	11,944.91	47.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,570.00	5,560.00	1,010.00	15.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	31,985.57	19,030.66	12,954.91	40.50
Approved Total (Overridden) (S\$)		7,200.00		
(S\$)	31,985.57	7,200.00	24,785.57	77.49
+ GST 7.00/7.00% (S\$)	2,238.99	504.00	1,734.99	77.49
Nett Amount (S\$)	34,224.56	7,704.00	26,520.56	77.49
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 10/07/2018

Date Inspected: 11/07/2018 Inspected At:

K Kim Hin Auto Pte Ltd (HQ)
160 Sin Ming Drive #02-20, Sin Ming
AutoCity
Singapore 575722

Estimated Period of Repair: 24.0 days

Adjuster: KENNETH KONG**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Oct 2019)
Parts:	143	HYUNDAI AVANTE 1.6 ABS AIRBAG 2WD 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJU1742G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Bent	461.46 FL	*461.46 FL
2	2		*FRONT BUMPER SIDE RETAINER (LH/RH)	Cracked	37.40 FL	*37.40 FL
3	10		*FRONT BUMPER CLIPS	Necessary	20.00 FL	*20.00 FL
4	1		*FRONT BUMPER FOGLAMP ASSY (LH/RH)	O/S Cracked	283.40 FL	*141.70 FL
5	1		*FRONT BUMPER LOWER CENTRE GRILLE	Distorted	47.00 FL	*47.00 FL
6	1		*FRONT BUMPER SPONGE	Cracked	113.40 FL	*113.40 FL
7	1		*FRONT BUMPER REINFORCEMENT	Bent	254.00 FL	*254.00 FL
8	2		*FRONT BUMPER REINFORCEMENT BRACKET (LH/RH)	Not Necessary	59.60 FL	*- FL
9	2		*HEADLAMP ASSY (LH/RH)	Mtg Broken	960.00 FL	*960.00 FL
10	2		*HEADLAMP LOWER BRACKET (LH/RH)	Bent	59.60 FL	*59.60 FL
11	8		*FRONT GRILLE CLIPS	Necessary	16.00 FL	*16.00 FL
12	2		*FRONT FENDER (LH/RH)	Buckled	868.60 FL	*868.60 FL
13	2		*FRONT FENDER VVT EMBLEM (LH/RH)	Necessary	36.40 FL	*36.40 FL
14	2		*FRONT FENDER INNER SHIELD (LH/RH)	Serviceable	96.00 FL	*- FL
15	18		*FRONT FENDER INNER SHIELD CLIP	Not Necessary	36.00 FL	*- FL
16	1		*BONNET	Bent	1,792.40 FL	*1,792.40 FL
17	2		*BONNET HINGES (LH/RH)	Repair	111.40 FL	*- FL
18	1		*BONNET INSULATOR	Deformed	230.10 FL	*230.10 FL
19	11		*BONNET INSULATOR CLIPS	Necessary	22.00 FL	*22.00 FL
20	2		*BONNET RUBBER STOPPER	Serviceable	13.40 FL	*- FL
21	1		*BONNET STAY	Serviceable	18.90 FL	*- FL
22	1		*BONNET STAY BUSH	Serviceable	7.00 FL	*- FL
23	1		*BONNET STAY CLIP HOLDER	Serviceable	7.00 FL	*- FL
24	1		*BONNET STAY TOP PROTECTOR	Not Necessary	15.00 FL	*- FL
25	1		*BONNET STAY TOP PROTECTOR RIVET	Necessary	3.00 FL	*3.00 FL
26	1		*BONNET LOCK	Distorted	44.80 FL	*44.80 FL
27	1		*BONNET LOCK COVER	Not Necessary	8.00 FL	*- FL
28	1		*BONNET PULL LOCK CABLER -OUTER	Not Necessary	24.20 FL	*- FL
29	1		*BONNET INNER SEAL	Cut	14.60 FL	*14.60 FL
30	1		*FRONT SUPPORT PANEL	Cracked	791.30 FL	*791.30 FL
31	2		*HORN (LH/RH)	Not Necessary	147.60 FL	*- FL
32	1		*AIRCON CONDENSER	Not Necessary	990.90 FL	*- FL
33	1		*AIRCON CONDENSER LIQUID PIPE	Not Necessary	360.50 FL	*- FL
34	1		*AIRCON CONDENSER DISCHARGE PIPE	Not Necessary	191.50 FL	*- FL
35	1		*AIRCON CONDENSER SUCTION PIPE	Not Necessary	200.20 FL	*- FL
36	1		*RADIATOR	Not Necessary	588.70 FL	*- FL
37	2		*RADIATOR AIR GUIDE (LH/RH)	Not Necessary	30.00 FL	*- FL
38	2		*RADIATOR TOP BRACKET (LH/RH)	Not Necessary	29.40 FL	*- FL
39	2		*RADIATOR TOP BUSH (LH/RH)	Not Necessary	29.40 FL	*- FL
40	2		*RADIATOR BOTTOM BUSH (LH/RH)	Not Necessary	29.40 FL	*- FL
41	1		*RADIATOR TOP HOSE	Not Necessary	41.50 FL	*- FL
42	1		*RADIATOR BOTTOM HOSE	Not Necessary	41.90 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*RADIATOR SPARE TANK	Dented	30.20 FL	*30.20 FL
44	1		*RADIATOR SPARE TANK BYPASS HOSE	Not Necessary	10.00 FL	*- FL
45	1		*RADIATOR SPARE TANK BYPASS HOSE PIPE	Not Necessary	17.50 FL	*- FL
46	1		*RADIATOR FAN ASSY	Not Necessary	567.50 FL	*- FL
47	1		*WIPER WASHER TANK	Dented	58.30 FL	*58.30 FL
48	1		*WIPER WASHER TANK MOTOR	Not Necessary	54.70 FL	*- FL
49	1		*AIR INTAKE DUCT	Cracked	96.80 FL	*96.80 FL
50	1		*AIR CLEANER BOX ASSY	Serviceable	179.90 FL	*- FL
51	1		*AIR INTAKE HOSE	Not Necessary	246.40 FL	*- FL
52	1		*THROTTLE BODY ASSY	Serviceable	732.50 FL	*- FL
53	1		*THROTTLE BODY GASKET	Not Necessary	10.00 FL	*- FL
54	1		*INTAKE MANIFOLD	Not Necessary	406.10 FL	*- FL
55	1		*ENGINE TOP COVER	Cracked	202.90 FL	*202.90 FL
56	1		*BATTERY TRAY	Not Necessary	33.80 FL	*- FL
57	1		*FRONT BUMPER UNDER COVER	Not Necessary	43.20 FL	*- FL
58	2		*ENGINE UNDER COVER (LH/RH)	Not Necessary	49.80 FL	*- FL
59	2		*ENGINE UNDER SIDE COVER (LH/RH)	Not Necessary	26.00 FL	*- FL
60	1		*ENGINE MOUNTING -LH	Not Necessary	285.70 FL	*- FL
61	1		*ENGINE MOUNTING -RH	Not Necessary	303.60 FL	*- FL
62	1		*ENGINE MOUNTING -FRONT	Not Necessary	217.00 FL	*- FL
63	1		*ENGINE MOUNTING -REAR	Not Necessary	261.10 FL	*- FL
64	1		*ALTERNATOR	Not Necessary	743.40 FL	*- FL
65	2		*REAR NUMBER PLATE LAMP ASSY (LH/RH)	Serviceable	124.20 FL	*- FL
66	1		*REAR BUMPER	Bent	489.10 FL	*489.10 FL
67	3		*REAR BUMPER LOWER BRACKET	Cracked	64.80 FL	*64.80 FL
68	2		*REAR BUMPER TOP BRACKET (LH/RH)	Not Necessary	48.00 FL	*- FL
69	1		*REAR BUMPER SPONGE	Cracked	109.90 FL	*109.90 FL
70	1		*REAR BUMPER REINFORCEMENT	Bent	270.00 FL	*270.00 FL
71	2		*REAR BUMPER REINFORCEMENT BRACKET (LH/RH)	Bent	134.60 FL	*134.60 FL
72	10		*REAR BUMPER CLIPS	Necessary	20.00 FL	*20.00 FL
73	2		*TAILLAMP ASSY (LH/RH)	Cracked	576.80 FL	*576.80 FL
74	2		*TAILLAMP CLIPS	Necessary	10.00 FL	*10.00 FL
75	2		*TAILLAMP PANEL (LH/RH)	Bent	351.40 FL	*351.40 FL
76	1		*REAR FENDER (LH/RH)	O/S Buckled	3,612.20 FL	*1,806.10 FL
77	2		*REAR FENDER INNER SHIELD (LH/RH)	Cracked	26.00 FL	*26.00 FL
78	16		*REAR FENDER INNER SHIELD CLIPS	Necessary	32.00 FL	*32.00 FL
79	2		*REAR FENDER INNER TRIM LINING (LH/RH)	Not Necessary	326.00 FL	*- FL
80	20		*REAR FENDER INNER TRIM LINING CLIPS	Not Necessary	40.00 FL	*- FL
81	1		*REAR WINDSCREEN GLASS MOULDING	Necessary	47.50 FL	*47.50 FL
82	1		*BOOTLID	Bent	985.90 FL	*985.90 FL
83	2		*BOOTLID HINGES (LH/RH)	Repair	264.00 FL	*- FL
84	1		*BOOTLID OUTER GARNISH	Warped	62.40 FL	*62.40 FL
85	1		*BOOTLID OUTER GARNISH CHROME	Necessary	70.70 FL	*70.70 FL
86	1		*BOOTLID OUTER GARNISH TOP SEAL	Necessary	15.40 FL	*15.40 FL
87	6		*BOOTLID OUTER GARNISH CLIPS	Necessary	12.00 FL	*12.00 FL
88	1		*BOOTLID AVANTE EMBLEM	Necessary	31.20 FL	*31.20 FL
89	1		*BOOTLID LOGO	Necessary	23.30 FL	*23.30 FL
90	1		*BOOTLID S EMBLEM	Necessary	20.30 FL	*20.30 FL
91	1		*BOOTLID WEATHERSTRIP (50%)	Distorted / Dented	63.44 FS	*39.65 FS
92	2		*BOOTLID LAMP ASSY (LH/RH)	Cracked	327.20 FL	*327.20 FL
93	1		*BOOTLID LOCK	Bent	118.30 FL	*118.30 FL
94	1		*BOOTLID LOCK CATCH	Distorted	15.00 FL	*15.00 FL
95	1		*BOOTLID INNER TRIM LINING	Buckled	151.10 FL	*151.10 FL
96	10		*BOOTLID INNER TRIM LINING CLIP	Necessary	20.00 FL	*20.00 FL
97	2		*BOOTLID RUBBER STOPPER	Serviceable	8.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
98	1		*SET KEY CYLINDER	Dented	238.80 FL	*238.80 FL
99	1		*REAR FENDER TOP 1/4 GLASS	O/S Necessary	726.00 FL	*363.00 FL
100	1		*REAR END PANEL	Bent	493.80 FL	*493.80 FL
101	1		*REAR END PANEL TOP GARNISH	Distorted	34.40 FL	*34.40 FL
102	1		*SPARE TYRE PANEL	Bent / Buckled	878.30 FL	*878.30 FL
103	1		*SPARE TYRE PANEL TOP BOARD	Not Necessary	220.00 FL	*- FL
104	2		*SPARE TYRE PANEL EXTENSION PANEL (LH/RH)	Not Necessary	193.40 FL	*- FL
105	1		*SPARE TYRE LOCK SCREW	Not Necessary	8.00 FL	*- FL
106	1		*O/S REAR CHASSIS MEMBER	Not Necessary	657.20 FL	*- FL
107	1		*REAR EXHAUST MUFFLER	Not Necessary	711.20 FL	*- FL
108	2		*REAR EXHAUST MUFFLER MOUNTING	Not Necessary	100.40 FL	*- FL
109	1		*REAR EXHAUST MUFFLER GASKET	Not Necessary	16.00 FL	*- FL
110	1		*CENTRE EXHAUST MUFFLER	Not Necessary	394.50 FL	*- FL
111	2		*CENTRE EXHAUST MUFFLER MOUNTING	Not Necessary	38.00 FL	*- FL
112	1		*CENTRE BRACKET MUFFLER GASKET	Not Necessary	16.00 FL	*- FL
113	1		*FRONT NUMBER PLATE	Bent	40.00 FS	*40.00 FS
114	1		*FRONT BUMPER SPOILER	Cracked	480.00 FS	*480.00 FS
115	1		*FRONT GRILLE (SPORT)	Cracked	350.00 FS	*350.00 FS
116	1		*RADIATOR COOLANT	Necessary	48.00 FS	*20.00 FS
117	1		*BATTERY	Not Necessary	380.00 FS	*- FS
118	1		*REAR NUMBER PLATE	Bent	40.00 FS	*40.00 FS
119	1		*REAR BUMPER SPOILER	Distorted / Dented	480.00 FS	*480.00 FS
120	1		*REVERSE SENSOR	Shorted	220.00 FS	*200.00 FS
121	1		*REVERSE CAMERA	Dented	380.00 FS	*380.00 FS
122	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	40.00 FS	*40.00 FS
123	1		*REAR WINDSCREEN GLASS DAMPING SEAL	Necessary	20.00 FS	*20.00 FS
124	1		*BOOTLID TOP SPOILER	Serviceable	450.00 FS	*- FS
125	2		*REAR FENDER TOP 1/4 GLASS SEALANT	Necessary	80.00 FS	*60.00 FS
126	2		*REAR FENDER TOP 1/4 GLASS DAMPING SEAL	Necessary	40.00 FS	*40.00 FS
127	1		*SPARE TYRE	Not Necessary	380.00 FS	*- FS
128	1		*REAR SUBWOOFER	Not Necessary	450.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	30,784.10	16,290.91
- List Item Discount on L Items 20.00/20.00% (\$\$)	5,368.53	2,820.25
Total Parts (\$\$)	25,415.57	13,470.66

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO TOW ACCIDENT VEHICLE TO WORKSHOP BY FLATBED OR KINGS DOLLY TOWING	New	200.00	0.00
2	TO REMOVE,CUT OUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN ,REFIX AND TO RENEW AFFECTED PARTS	New	2,400.00	2,200.00
3	TO FOCUS HEADLAMPS AND TAILLAMPS (NPA)	New	0.00	0.00
4	TO CHECK FRONT AND REAR LIGHTING OPERATION AND REWIRING	New	60.00	40.00
5	TO REMOVE AND REFIT REAR WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST	New	120.00	120.00
6	TO REMOVE AND REFIT LEFT REAR FENDER TOP GLASS AND CONDUCT WATER LEAK TEST	New	100.00	40.00
7	TO REMOVE AND REFIT RIGHT REAR FENDER TOP GLASS AND CONDUCT WATER LEAK TEST	New	100.00	40.00
8	TO REMOVE AND REFIT REAR UPHOLSTERY TRIMMING ,ROOF LINING ,SEATS,SPEAKET BOARD IN ORDER TO FACILITATE REPAIRING WORKS	New	120.00	120.00
9	TO REMOVE AIRCON CONDENSER ,PIPES AND DRIERS ,VACUUM AND RECHARGE GAS	New	100.00	100.00
10	TO APPLY UNDERSEALING	New	180.00	180.00
11	TO DISMANTLE AND CHECK REAR UNDERCARRIAGE .TO REPLACE AFFECTED PORTIONS	New	240.00	220.00
12	TO CONDUCT REAR WHEEL ALIGNMENT TEST	New	80.00	60.00
13	TO CHECK AND REALIGNMENT ON CHASSIS MEMBER	New	350.00	250.00
14	TO REMOVE AND REFIT PETROL /DIESEL TANK IN ODER TO FACILITATE REPAIRING WORKS	New	220.00	60.00
15	TO REMOVE AND RENEW EXHAUST SILENCER BOX	New	120.00	80.00
16	TO REMOVE AND REFIT REVERSE SENSOR ASSY	New	80.00	50.00
17	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS	New	2,100.00	2,000.00
Gross Labour Cost (S\$)			6,570.00	5,560.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >