

**金興(龔)汽車私人有限公司**

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

No. : 29883

Vehicle Insured : SKW 3598 X
Accident Date : 06-Jul-2018

Date : 09-Jul-2018

Our Ref : 180432 (ECICS) / SANDRA

PAGE : 1

WANG YIHONG (MR)
Singapore

Not Notified
1/10/18 @ 7
Return After Repair
24 days

ESTIMATED COST OF REPAIR FOR HYUNDAI AVANTE 1.6 AT (2009) SJU1742G

1 pc front bumper		<i>Bz</i>	461.46	—
2 pcs front bumper side retainer (LH/RH)	@ S\$ 18.70	<i>CM</i>	37.40	—
10 pcs front bumper clips	@ S\$ 2.00	<i>nu</i>	20.00	✓
2 pcs front bumper foglamp assy (LH/RH)	@ S\$141.70	<i>all parts</i>	283.40	✓
1 pc front bumper lower centre grille		<i>Div</i>	47.00	✓
1 pc front bumper sponge		<i>CM</i>	113.40	—
1 pc front bumper reinforcement		<i>Bz</i>	254.00	—
2 pcs front bumper reinforcement bracket (LH/RH)	@ S\$ 29.80		59.60	✓
2 pcs headlamp assy (LH/RH)	@ S\$480.00	<i>my Bz</i>	960.00	—
2 pcs headlamp lower bracket (LH/RH)	@ S\$ 29.80	<i>Bz</i>	59.60	—
8 pcs front grille clips	@ S\$ 2.00	<i>nu</i>	16.00	—
2 pcs front fender (LH/RH)	@ S\$434.30	<i>Bz</i>	868.60	—
2 pcs front fender "VVT" emblem (LH/RH)	@ S\$ 18.20	<i>nu</i>	36.40	—
2 pcs front fender inner shield (LH/RH)	@ S\$ 48.00	<i>nu</i>	96.00	X
18 pcs front fender inner shield clip	@ S\$ 2.00	<i>nu</i>	36.00	X
1 pc bonnet		<i>By</i>	1,792.40	—
2 pcs bonnet hinges (LH/RH)	@ S\$ 55.70	<i>nu</i>	111.40	X
1 pc bonnet insulator		<i>Return</i>	230.10	—
11 pcs bonnet insulator clips	@ S\$ 2.00	<i>nu</i>	22.00	—
2 pcs bonnet rubber stopper	@ S\$ 6.70	<i>nu</i>	13.40	X
1 pc bonnet stay		<i>nu</i>	18.90	X
1 pc bonnet stay bush		<i>nu</i>	7.00	X
1 pc bonnet stay clip holder		<i>nu</i>	7.00	X
1 pc bonnet stay top protector			15.00	?

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Con't Page 2 ...

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

Vehicle Insured : SKW 3598 X
Our Ref : 180432

Page : 2
No. : 29883

1 pc bonnet stay top protector rivet		MC 3.00	✓
1 pc bonnet lock		Dr 44.80	✓
1 pc bonnet lock cover		8.00	?
1 pc bonnet pull lock cabler-outer		24.20	?
1 pc bonnet inner seal		Gr 14.60	✓
1 pc front support panel		CM 791.30	✓
2 pcs horn (LH/RH)	@ S\$ 73.80	147.60	?
1 pc aircon condenser		990.90	?
1 pc aircon condenser liquid pipe		360.50	?
1 pc aircon condenser discharge pipe		191.50	?
1 pc aircon condenser suction pipe		200.20	?
1 pc radiator		588.70	?
2 pcs radiator air guide (LH/RH)	@ S\$ 15.00	30.00	?
2 pcs radiator top bracket (LH/RH)	@ S\$ 14.70	29.40	?
2 pcs radiator top bush (LH/RH)	@ S\$ 14.70	29.40	?
2 pcs radiator bottom bush (LH/RH)	@ S\$ 14.70	29.40	?
1 pc radiator top hose		41.50	?
1 pc radiator bottom hose		41.90	?
1 pc radiator spare tank		MC 30.20	✓
1 pc radiator spare tank bypass hose		10.00	?
1 pc radiator spare tank bypass pipe		17.50	?
1 pc radiator fan assy		567.50	?
1 pc wiper washer tank		Dr 58.30	✓
1 pc wiper washer tank		54.70	?
1 pc air intake duct		CM 96.80	✓
1 pc air cleaner box assy		Sm 179.90	×
1 pc air intake hose		Sm 246.40	?
1 pc throttle body assy		Sm 732.50	×
1 pc throttle body gasket		nn 10.00	×
1 pc intake manifold		406.10	?
1 pc engine top cover		CM 202.90	✓
1 pc battery tray		33.80	?
1 pc front bumper under cover		43.20	?

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

Vehicle Insured : SKW 3598 X
Our Ref : 180432

Page : 3
No. : 29883

2 pcs engine under cover (LH/RH)	@ S\$ 24.90	49.80	7
2 pcs engine under side cover(LH/RH)	@ S\$ 13.00	26.00	7
1 pc engine mounting-LH		285.70	7
1 pc engine mounting-RH		303.60	7
1 pc engine mounting-front		217.00	7
1 pc engine mounting-rear		261.10	7
1 pc alternator		743.40	7
2 pcs rear number plate lamp assy (LH/RH)	@ S\$ 62.10	124.20	X
1 pc rear bumper		489.10	✓
3 pcs rear bumper lower bracket	@ S\$ 21.60	64.80	✓
2 pcs rear bumper top bracket(LH/RH)	@ S\$ 24.00	48.00	7
1 pc rear bumper sponge		109.90	✓
1 pc rear bumper reinforcement		270.00	✓
2 pcs rear bumper reinforcement bracket (LH/RH)	@ S\$ 67.30	134.60	✓
10 pcs rear bumper clips	@ S\$ 2.00	20.00	✓
2 pcs taillamp assy (LH/RH)	@ S\$288.40	576.80	✓
2 pcs taillamp clips	@ S\$ 5.00	10.00	✓
2 pcs taillamp panel (LH/RH)	@ S\$175.70	351.40	✓
2 pcs rear fender (LH/RH)	@ \$1806.10	3,612.20	✓
2 pcs rear fender inner shield (LH/RH)	@ S\$ 13.00	26.00	✓
16 pcs rear fender inner shield clips	@ S\$ 2.00	32.00	✓
2 pcs rear fender inner trim lining (LH/RH)	@ S\$163.00	326.00	?
20 pcs rear fender inner trim lining clips	@ S\$ 2.00	40.00	7
1 pc rear windscreen glass moulding		47.50	✓
1 pc bootlid		985.90	✓
2 pcs bootlid hinges (LH/RH)	@ S\$132.00	264.00	X
1 pc bootlid outer garnish		62.40	✓
1 pc bootlid outer garnish chrome		70.70	✓
1 pc bootlid outer garnish top seal		15.40	✓
6 pcs bootlid outer garnish clips	@ S\$ 2.00	12.00	✓
1 pc bootlid "AVANTE" emblem		31.20	✓
1 pc bootlid logo		23.30	✓

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

Vehicle Insured : SKW 3598 X
Our Ref : 180432

Page : 4
No. : 29883

1 pc	bootlid "S" emblem		20.30	✓
1 pc	bootlid weatherstrip		79.30	506m
2 pcs	bootlid lamp assy (LH/RH)	@ S\$163.60	327.20	✓
1 pc	bootlid lock		118.30	✓
1 pc	bootlid lock catch		15.00	✓
1 pc	bootlid inner trim lining		151.10	✓
10 pcs	bootlid inner trim lining clip	@ S\$ 2.00	20.00	✓
2 pcs	bootlid rubber stopper	@ S\$ 4.00	8.00	x
1 pc	key cylinder set		238.80	✓
2 pcs	rear fender top 1/4 glass	dwma @ S\$363.00	726.00	✓
1 pc	rear end panel		493.80	✓
1 pc	rear end panel top garnish		34.40	✓
1 pc	spare tyre panel		878.30	✓
1 pc	spare tyre panel top board		220.00	7
2 pcs	spare tyre panel extension panel (LH/RH)	@ S\$ 96.70	193.40	7
1 pc	spare tyre lock screw		8.00	7
1 pc	o/s rear chassis member		657.20	7
1 pc	rear exhaust muffler		711.20	7
2 pcs	rear exhaust muffler mounting	@ S\$ 50.20	100.40	7
1 pc	rear exhaust muffler gasket		16.00	7
1 pc	centre exhaust muffler		394.50	7
2 pcs	centre exhaust muffler mounting	@ S\$ 19.00	38.00	7
1 pc	centre exhaust muffler gasket		16.00	7
			26,921.96	
Less 20% :			-5,384.39	
			21,537.57	
1 pc	front number plate		40.00	sn ✓
1 pc	front bumper spoiler		480.00	sn ✓
1 pc	front grille (sport)		350.00	sn ✓
1 pc	radiator coolant		48.00	sn 205m
1 pc	battery		380.00	sn 7
1 pc	rear number plate		40.00	sn ✓
1 pc	rear bumper spoiler		480.00	sn ✓

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkinhin.com.sg

Vehicle Insured : SKW 3598 X
Our Ref : 180432

Page : 5
No. : 29883

1 pc reverse sensor
1 pc reverse camera
1 pc rear windscreen glass sealant
1 pc rear windscreen glass damping seal
1 pc bootlid top spoiler
2 pcs rear fender top 1/4 glass @ S\$ 40.00
sealant
2 pcs rear fender top 1/4 glass @ S\$ 20.00
damping seal
1 pc spare tyre
1 pc rear subwoofer

Shan 220.00 sn
nu 380.00 sn ✓
nu 40.00 sn ✓
nu 20.00 sn ✓
sn 450.00 sn X
nu 80.00 sn *60sn*
nu 40.00 sn ✓
380.00 sn ?
450.00 sn ?

To tow accident vehicle to workshop
by flatbed or Kings Dolly towing

(Bill) 200.00 ?

To remove, cut out damaged parts,
panel beating, welding, align,
refix and to renew affected parts.

2200
2,400.00

To focus Headlamps and Taillamps.

To check front and rear lighting
operation and rewiring

60.00 *401*

To remove and refit rear windscreen
glass and conduct water leak test

120.00 ✓

To remove and refit left rear
fender top glass and conduct water
leak test.

100.00 *401*

To remove and refit right rear
fender top glass and conduct water
leak test.

100.00 *401*

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkinhin.com.sg

Vehicle Insured : SKW 3598 X
Our Ref : 180432

Page : 6
No. : 29883

To remove and refit rear upholstery trimming, roof lining, seats, speaker board in order to facilitate repairing works	120.00 ✓
To remove aircon condenser, pipes and driers. Vaccum and recharge gas	100.00 ✓
To apply undersealing	180.00 ✓
To dismantle and check rear under-carriage. To replace affected portions.	240.00 220.00
To conduct rear wheel alignment test.	80.00 60.00
To check and realignment on chassis member.	350.00 250.00
To remove and refit petrol/diesel tank in order to facilitate repairing works.	220.00 80.00
To remove and renew exhaust silencer box	120.00 80.00
To remove and refit reverse sensor assy.	80.00 50.00
To putty and respray on affected portions.	2,100.00 200.00

Total :	S\$31,985.57
	=====

Singapore Dollars Thirty One Thousand Nine Hundred and Eighty Five and Cents Fifty Seven Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.