

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7524D**AAD1807-065***Not Authored
L1Pny 8560d*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHB 7524D

KL1LA69RJBB071972

CHEVROLET

EPICA 2.0

6.7.2018

AIG**PART****LIST**

1	1	Front Door RH	\$	<i>Bz</i> 1,133.00 ✓
2	1	Front Door Glass Guide RH Chrome Moulding	\$	<i>Sn</i> 60.00 X
3	1	Front Door Outer Moulding	\$	<i>Sn</i> 220.00 X
4	1	Front Door Outer Handle	\$	<i>Dis</i> 125.00 ✓
5	1	Front Door Handle Support	\$	<i>Sn</i> 3.00 X
6	1	Front Door outer handle inner seal	\$	<i>Sn</i> 89.15 X
7	1	Front Door outer key lock	\$	<i>Sn</i> 25.00 X
8	1	Front Door Hinge Upper	\$	<i>n</i> 65.00 X
9	1	Front Door Hinge Lower	\$	<i>n</i> 65.00 X
10	1	Front Door inner lock	\$	<i>Tr</i> 586.00 ✓
11	1	Front Door Inner Lock Latch RH	\$	<i>n</i> 206.00 X
12	1	Front Door Check / Arrestor	\$	<i>Sn</i> 67.50 X
13	1	Front Door Weatherstrip RH	\$	<i>Gr</i> 138.79 <i>508 Jan</i>
14	1	Front Door glass channel weatherstrip	\$	<i>Dis/Red Cut</i> 160.00 <i>2</i>
15	1	Front Door inner trim board	\$	<i>Bz</i> 455.69 ✓
16	1	Front Door window glass	\$	<i>Sn</i> 456.12 X
17	1	Front Door Power Window Motor (Master) RH	\$	<i>Tr</i> 284.97 ✓
18	1	Front Door power window motor switch	\$	<i>Sn</i> 145.00 X
19	1	Front Door Window Regulator Gear RH	\$	<i>Bz</i> 84.58 ✓
20	1	Front Door Outer Pillar Panel RH	\$	<i>n</i> 715.00 X
21	1	Front Door Pillar Inner Panel RH	\$	<i>n</i> 850.00 X
22	1	Front Door Center Pillar Panel RH	\$	<i>Bz</i> 698.15 ✓
23	1	Front Side View Mirror Assy RH	\$	<i>Sn</i> 1,191.00 X
24	1	Rear Door RH (Panel A-RR DR LH)	\$	<i>Bz</i> 1,133.00 ✓
25	1	Rear door weatherstrip - Inner	\$	<i>Sn</i> 41.40 X
26	1	Rear door weatherstrip - 2nd Frame	\$	<i>Sn</i> 25.90 X
27	1	Rear door top hinge	\$	<i>Bz</i> 35.00 ✓

69.40 Jan

Trans-cab Auto Services Pte Ltd

AAD1807-065

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7524D

28	1	Rear door bottom hinge	\$	<i>Bn</i> 35.00 ✓
29	1	Rear door inner lock	\$	<i>h</i> 425.00 X
30	1	Rear door check / arrestor	\$	<i>Dis</i> 65.00 ✓
31	1	Rear door lock striker / latch	\$	<i>R</i> 120.00 X
32	1	Rear door outer weatherstrip moulding	\$	<i>Sm</i> 85.00 X
33	1	Side Rocker Panel Garnish RH	\$	<i>Br/Br</i> 236.40 ✓
34	1	Rear Fender RH	\$	<i>R</i> 1,145.00 X
35	1	Rear Fender Inner Trim RH	\$	<i>Sm</i> 418.44 X
36	1	Front Side Rocker Panel Garnish RH	\$	<i>Sm</i> 236.40 X
37	1	Front Side Rocker Panel Outer RH	\$	<i>Sm</i> 600.00 X
38	1	Front Side Rocker Panel Inner RH	\$	<i>Sm</i> 519.30 X

TOTAL	\$	12,944.79
10%	\$	1,294.48
	\$	11,650.31

Special Nett

1	Front right door 'Trans-cab'	\$	<i>nn</i> 80.00 <i>60sm</i>
1	Right rear door '6555-3333'	\$	<i>nn</i> 80.00 <i>60sm</i>
1Set	Rear Fender Inner Trim Clip RH	\$	<i>nn</i> 30.00 X

TOTAL	\$	190.00
--------------	-----------	---------------

TOTAL PARTS	\$	11,840.31
--------------------	-----------	------------------

LABOUR

To Check Electrical Lighting Concerned.	\$	170.00 <i>201</i>
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	4,500.00 <i>9001</i>
Putty and spray painting of the affected portion.	\$	4,000.00 <i>12001</i>
Towing Fees.	\$	120.00 <i>501</i>

Trans-cab Auto Services Pte Ltd

AAD1807-065

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7524D

To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	nn 380.00 X
To check steering geometry and computer wheel alignment	\$	nn 220.00 X
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00 X
To rust-proofing of the affected areas.	\$	170.00 Pol
To check steering geometry and computer wheel alignment	\$	nn 220.00 X
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00 X
To transfer of door fittings, attachment and perform water seepage test.	\$	170.00 12d
To transfer of fender fittings, attachment and perform water seepage test.	\$	nn 170.00 X
To dismantle and re-fix the fender advertisement	\$	nn 340.00 X
To dismantle and re-fix the door advertisement	\$	nn 240.00 X

TOTAL	\$	10,460.00
--------------	-----------	------------------

Over All Total	\$	22,300.31
-----------------------	-----------	------------------

LKK Auto Consultants hence notify the Repairer **Repair Days (Lump Sum)**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

15 days
7 days