



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

Date of Accident : 10.07.2018.

Mr Foo Lai Yong

Date : 11 July 2018

Estimate To Repair SCU792B - Volkswagen GOLF GTI 2.0L AT 5DR 5K19V3
Chassis No : WVVZZZ1KZ9W549421

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
01	1 pc	rear bumper upper	\$ 1,710.00
02	1 pc	rear bumper reinforcement	\$ 318.00
03	2 pc	rear bumper side retainer @ \$38.00	\$ 76.00
04	4 pc	rear bumper assist sensor @ \$205.00	\$ 820.00
05	4 pc	rear bumper assists sensor holder @ \$25.00	\$ 100.00
06	1 pc	rear bumper lower	\$ 600.00
07	1 pc	rear bumper lower tow hook cover	\$ 95.00
08	1 pc	rear bumper top bracket	\$ 160.00
09	1 pc	rear license plate	\$ 50.00
10	1 pc	rear exhaust box with chrome muffler	\$ 115.00
11	1 pc	rear panel	\$ 420.00
12	1 pc	bootlid "GIT" badge	\$ 65.00
Less 10 %			\$ 4,529.00 \$ 452.90 \$ 4,076.10
<u>LABOUR & MISC. CHARGES</u>			
01		To reinstall of rear bumper parking sensor.	\$ 120.00
02		To drop rear exhaust box and renew the same.	\$ 80.00
03		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 500.00
04		Putty and spray painting of the affected portion.	\$ 600.00
Total			\$ 1,300.00 \$ 5,376.10

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: