

ASS. REC. BY:

REF: CS3 / MSG18012646 / R124d30k

Special Instruction:

Surveyor

Meimen

Kalsu)

ASSIGNMENT (Office)

From (Person):

Monica Chung

of

MSG

Date/Time:

11/7/18 @ 4:4pm

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBD1487C

Insured:

SLW1208Z

at Workshop m/s

Hua chin (2000)

Tel:

68966619

of

50 Bkt Batok st. 23 #02-02

Policy No:

29070671AVW

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 08/07/2018

CA / REV / REP. / REV 24 HRS

(up)

12/07/2018

H.O.D. Endorsement:

Date/Time:

4:47pm @ 11/7/18

Person Contacted:

Mr. Lim

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (X) Estimate
	FBD1487C - X
	SLW1208Z - X
	Range 3,500 - 4,000/-
	Repair days 4
	TG Lim
	11/11/18


REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD TP/WS/TP RES/OD RES/EVA/INV/MV
 To Inspect Vehicle No: FBD 1487C
 at Workshop m/s Hua CHIN
 of 50, BUKIT PARUK ST 23 # 0202
 Insured: MSIC
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: FBD 1487 Yr Regn: NOV / 2008
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____

Make: _____ c.c. 135
 Colour: MULTI A/C: Insured / Std / NI / NA
 Sp. Reading: 658182 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: _____
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Order / Jammed / Leaked / Burnt or
 Brake: Order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 90/80-17
 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or MAXXI

Front _____ Rear _____
 R/Bal. 3 mm R/Bal. 3 mm
 L/Bal. _____ mm L/Bal. _____ mm
 D.O.A. _____ D.O.I. 12/07/18

Survey held at HUA CHIN
 Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>7/8</u>	<u>Submit PRE report.</u>

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1) _____
 Date/Time, File Return to?

2) _____

Report Format: PRE

Lump Sum / I.B.I.: (\$ _____)

Days Of Repair: 4.

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____
) \$ + RS. \$ _____

) Photos
) Others

TOTAL

120

10

130

7/8/2018

Condition (CON)

(01) Bent (2) Dented (3) Distorted (4) Cracked (5) Cut (6) Scratched
(07) Deformed (08) Shifted (09) Buckled (10) Broken (11) Necessary
(12) Missing (13) Torn (14) Unconfirmed (15) Not Working

FOR MOTORCYCLE

ACTION (AC)

1. Replace (✓) 2. Repair (X) 3. Check (?)
4. Not Consistent (NC)

May 2005

Motorcycle

NAC	INC	Item	CON	AC	Qty
1001	991886	Front Number Plate			
3001	995065	Front Tyre			
3002	995095	Front Rim			
3003	994872	Front Tyre Rim Spoke			
3004	991771	Front Fender Wheel Guard	SCR	R	X
3005	991283	Front Brake Disc			
3006	991281	Front Brake Caliper	SCR	R	X
3007	991785	Front Fork Assy			
3008	991787	Front Fork Inner Tube			
3009	991789	Front Fork Outer Tube	RH	CUT	R X
3010	991167	Front Fork Bracket			
3011	991182	Front Fork Oil Seal			
3012	991174	Front Fork Garnish			
3013	992376	Front Headlamp Rim			
3014	992328	Front Headlamp			
3015	992337	Front Headlamp Bracket			
3016	992345	Front Headlamp Fairing	CUT	✓	75.00
3017	992130	Front Windshield			
3018	992134	Front Wing Mirror	CUT/MR	✓	2 104.00
3019	995245	Front LH Signal Lamp			
3020	995246	Front RH Signal Lamp			
3021	992556	Meter Casing			
3022	992553	Meter Assy			
1118	991019	ERP Bracket			
1119	991020	ERP Unit	CUT	✓	156.00
3023	992446	Ignition Switch			
3024	992442	Ignition Key Assy			
3025	990706	Cowling Stay			
3026	994470	Steering Stem			
3027	994427	Steering Cone			
3028	992299	Handle Bar			
3029	992312	Handle Bar Switch			
3030	992310	Handle Bar Grip	CUT	✓	15.00
3031	995184	Handle Bar Balancer LH			
3032	992300	Handle Bar Balancer RH			
1252	992179	Fuel Tank			
3033	990438	Brake Reservoir			
3034	990621	Clutch Lever	CUT	✓	75.00
3035	992293	Hand Brake Lever	BR	✓	75.00
3036	991119	Side Fairing			
3037	994220	Side Fairing Top Garnish			
3038	994219	Side Fairing Inner Garnish	HR	BR	✓ 2 90.00
3039	991118	Fairing Shield			
3040	992047	Front Top Fairing Inner Garnish			
3041	991123	Fairing Top Garnish	CUT	✓	60.00
3042	990538	Center Fairing	BR	✓	22.00
3043	993378	Rear Fairing			
3044	991121	Fairing Stopper			
3045	991117	Fairing Lower	BR	✓	97.00

Vehicle No:

NAC	INC	Item	CON	AC	Qty
1052	995074	Radiator	SCR	✓	170
1053	992738	Radiator Cowling			
3046	994146	Seat Assy			
3047	990915	Engine Crash Bar			
3048	990928	Engine Guard			
1067	990219	Battery			
1068	990224	Battery Cover			
1069	990223	Battery Bracket			
3049	991144	Foot Brake			
3050	991154	Front Foot Rest	BT	✓	58
3051	991779	Front Foot Rest Bracket			
3052	994269	Side Stand			
3053	992549	Main Stand			
3054	990615	Clutch Engine Cover			
3055	992478	Kick Starter Rubber			
3056	992477	Kick Starter Lever			
3057	991145	Foot Gear Shifter			
3058	993500	Rear Foot Rest	HR	CUT/BR	✓ 2 76
3059	993501	Rear Foot Rest Bracket			
3060	992581	Exhaust Muffler Heat Shield			
3061	991058	Exhaust Muffler Assy	CUT	✓	28
1405	993719	Rear LH Shock Absorber			
1415	993720	Rear RH Shock Absorber			
3062	995065	Rear Tyre			
3063	991200	Rear Rim			
3064	994872	Rear Tyre Rim Spoke			
3065	993474	Rear Fender Wheel Guard			
3066	993443	Rear Fender Mudflap			
3067	992940	Rear Brake Disc			
3068	992936	Rear Brake Caliper			
3069	995236	Rear Spocket			
3070	990585	Chain			
3071	990580	Chain Guard			
3072	994530	Swing Arm	SCR	R	X
1420	993819	Rear Sub frame			
3073	995245	Rear LH Signal Lamp			
3074	995246	Rear RH Signal Lamp			
3075	995251	Rear Taillamp			
1137	993626	Rear Number Plate	BT	✓	12
3076	994192	Side Box			
3077	992927	Rear Box			
3078	992928	Rear Box Bracket	CUT	✓	150
3079	991328	Emblem			
1436	990247	Sticker			

No of Items: _____ Assessor: _____

Original Copy



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD			Ref : CS3/MSG18012646/R1z4d3	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581			Date : 11-07-2018	
			Code : MSG	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	SLW 1208Z	Veh. Inspected	FBD 1487C	
Policy No.	29070671AVW	Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From	MERIMEN (MONICA CHUNG)	Assign Date	11/07/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	08/07/2018	Inspection Date		
Survey held at	HUA CHIN (2000) TRADING MOTOR SVC CENTRE 50, BUKIT BATOK STREET 23, #02-02 MIDVIEW BUILDING SINGAPORE 659578			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Jul 2018		11 Jul 2018 16:14 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]	
Insured:	LUKE ALEXANDER ROBERTSON, ID: S7489894G, Tel: +6590914450, Email: LUKE.JYD@GMAIL.COM
Main Claimant:	SAIRAN BIN OTHMAN, ID: S1835682A
Vehicle Reg. No.:	FBD1487C
Claim Type:	TP
Vehicle Reg. No. (Insured):	SLW1208Z
Repairer:	Hua Chin (2000) Trading Motor Service Centre (HQ) 50 BUKIT BATOK STREET 23, #02-02 MIDVIEW BUILDING, 659578 Bukit Batok - Tel: 68966619
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 12/07/2018]
Driver/Custodian (Insured):	LUKE ALEXANDER ROBERTSON (43 / Male), NRIC: S7489894G, Tel: +6590914450
Adj Asg. Remarks:	on WP. LIABILTY NOT CLEAR TP DISAGREE SJE -APPOINT LKK CONSULTANCY PTE LTD ACCODING TO CHART PLS CONTACT MR LIM W.KOON FOR SURVEY @68966619

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)[Compose Case Mail](#)

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	FBD1487C		
Vehicle Type :	P00 - Passenger Motorcycle/Autocycle/Moped		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	YAMAHA		
Vehicle Model :	T135		
Chassis No. :	5YP300312		
Propellant :	Petrol		
Engine No. :	5YP300312		
Engine Capacity :	135 cc		
Maximum Power Output :	-		
Maximum Laden Weight :	-		
Unladen Weight :	101 kg		
Year Of Manufacture :	2008		
Original Registration Date :	06 Nov 2008		
Lifespan Expiry Date :	-		
COE Category :	D - Motorcycle		
Quota Premium :	\$1,509.00		
COE Expiry Date :	05 Nov 2018		
Road Tax Expiry Date :	05 Nov 2018		
Inspection Due Date :	05 Nov 2018		
Intended Transfer Date :	13 Jul 2018		
CO2 Emission :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00

You may print this page for reference.

OK Print

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5682A
Vehicle Details	
Vehicle No.:	FBD1487C
Vehicle to be Exported:	No
Intended De-registration Date:	16 Jul 2018
Vehicle Make:	YAMAHA
Vehicle Model:	T135
Primary Colour:	Blue
Manufacturing Year:	2008
Engine No.:	5YP300312
Chassis No.:	5YP300312
Maximum Power Output:	-
Open Market Value:	\$1,721.00
Original Registration Date:	06 Nov 2008
First Registration Date:	06 Nov 2008
Transfer Count:	1
Actual ARF Paid:	\$259.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	05 Nov 2018
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$1,509.00
COE Rebate Amount:	\$45.00
Total Rebate Amount:	\$45.00

The information contained herein is correct as at 16 Jul 2018

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)














































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Jul 2018		11 Jul 2018 16:14 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	LUKE ALEXANDER ROBERTSON, ID: S7489894G, Tel: +6590914450, Email: LUKE.JYD@GMAIL.COM								
Main Claimant:	SAIRAN BIN OTHMAN, ID: S1835682A								
Vehicle Reg. No.:	FBD1487C	Date of Loss:	08/07/2018 17:00 - :59 [116 Months and 2 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 564047	Policy/Cover Note No.:	A29070671AVW (Comprehensive) Coverage: 30/01/2018 - 29/01/2019						
Vehicle Reg. No. (Insured):	SLW1208Z	Policy No. (Claimant):							
		Excess:	S\$2,000.00						
Repairer:	Hua Chin (2000) Trading Motor Service Centre (HQ) 50 BUKIT BATOK STREET 23, #02-02 MIDVIEW BUILDING, 659578 Bukit Batok - Tel: 68966619								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Imm.Advice due 12/07/2018]								
Driver/Custodian (Insured):	LUKE ALEXANDER ROBERTSON (43 / Male), NRIC: S7489894G, Tel: +6590914450								
Adj Asg. Remarks:	on WP. LIABILTY NOT CLEAR TP DISAGREE SJE -APPOINT LKK CONSULTANCY PTE LTD ACCODING TO CHART PLS CONTACT MR LIM W.KOON FOR SURVEY @68966619								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***FBD1487C (564047)**
[SLW1208Z]
TP
SAIRAN BIN OTHMAN
Jul 8 2018 5:00PM
[LUKE ALEXANDER ROBERTSON]
Hua Chin (2000) Trading Motor Service Centre

Upload Documents			Upload Photos			Compose New Letter			View		View in Browser	
Video									1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)							Thumbnail		Print	
1	12/07/18 08:50	Video - AccidentOI									Load MOV	
Photos/Images									3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail		Print	
1	13/07/18 11:54	General View									Load JPG <input checked="" type="checkbox"/>	
2	13/07/18 11:54	General View									Load JPG <input checked="" type="checkbox"/>	
3	13/07/18 11:54	General View									Load JPG <input checked="" type="checkbox"/>	
4	13/07/18 11:54	General View									Load JPG <input checked="" type="checkbox"/>	
5	13/07/18 11:54	General View									Load JPG <input checked="" type="checkbox"/>	
6	13/07/18 11:54	General View									Load JPG <input checked="" type="checkbox"/>	
7	13/07/18 11:54	General View									Load JPG <input checked="" type="checkbox"/>	
8	13/07/18 11:54	General View									Load JPG <input checked="" type="checkbox"/>	
9	13/07/18 11:54	General View									Load JPG <input checked="" type="checkbox"/>	
10	13/07/18 11:54	General View									Load JPG <input checked="" type="checkbox"/>	
11	13/07/18 11:54	General View									Load JPG <input checked="" type="checkbox"/>	
12	13/07/18 11:54	General View									Load JPG <input checked="" type="checkbox"/>	
13	13/07/18 11:54	General View									Load JPG <input checked="" type="checkbox"/>	
14	13/07/18 11:54	General View									Load JPG <input checked="" type="checkbox"/>	
15	13/07/18 11:54	General View									Load JPG <input checked="" type="checkbox"/>	
16	13/07/18 11:54	General View									Load JPG <input checked="" type="checkbox"/>	
17	13/07/18 11:54	General View									Load JPG <input checked="" type="checkbox"/>	
18	13/07/18 11:54	General View									Load JPG <input checked="" type="checkbox"/>	
19	13/07/18 11:54	General View									Load JPG <input checked="" type="checkbox"/>	
20	13/07/18 11:54	General View									Load JPG <input checked="" type="checkbox"/>	
21	13/07/18 11:54	General View									Load JPG <input checked="" type="checkbox"/>	
22	13/07/18 11:54	General View									Load JPG <input checked="" type="checkbox"/>	
23	13/07/18 11:54	General View									Load JPG <input checked="" type="checkbox"/>	
24	13/07/18 11:54	General View									Load JPG <input checked="" type="checkbox"/>	
25	13/07/18 11:54	General View									Load JPG <input checked="" type="checkbox"/>	
26	13/07/18 11:54	General View									Load JPG <input checked="" type="checkbox"/>	
27	13/07/18 11:54	General View									Load JPG <input checked="" type="checkbox"/>	
28	13/07/18 11:54	General View									Load JPG <input checked="" type="checkbox"/>	
29	13/07/18 11:54	General View									Load JPG <input checked="" type="checkbox"/>	
30	13/07/18 11:54	General View									Load JPG <input checked="" type="checkbox"/>	
31	13/07/18 11:54	General View									Load JPG <input checked="" type="checkbox"/>	
32	13/07/18 11:54	General View									Load JPG <input checked="" type="checkbox"/>	
33	13/07/18 11:54	General View									Load JPG <input checked="" type="checkbox"/>	
34	13/07/18 11:54	General View									Load JPG <input checked="" type="checkbox"/>	

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	13/07/18 11:54	General View	 Load JPG	<input checked="" type="checkbox"/>
36	13/07/18 11:54	General View	 Load JPG	<input checked="" type="checkbox"/>
37	13/07/18 11:54	General View	 Load JPG	<input checked="" type="checkbox"/>
38	13/07/18 11:54	General View	 Load JPG	<input checked="" type="checkbox"/>
39	13/07/18 11:54	General View	 Load JPG	<input checked="" type="checkbox"/>
40	13/07/18 11:54	General View	 Load JPG	<input checked="" type="checkbox"/>
41	13/07/18 11:54	General View	 Load JPG	<input checked="" type="checkbox"/>
42	13/07/18 11:54	General View	 Load JPG	<input checked="" type="checkbox"/>
43	13/07/18 11:54	General View	 Load JPG	<input checked="" type="checkbox"/>
44	13/07/18 11:54	General View	 Load JPG	<input checked="" type="checkbox"/>
45	13/07/18 11:54	General View	 Load JPG	<input checked="" type="checkbox"/>
46	13/07/18 11:54	General View	 Load JPG	<input checked="" type="checkbox"/>
47	13/07/18 11:54	General View	 Load JPG	<input checked="" type="checkbox"/>
48	13/07/18 11:54	General View	 Load JPG	<input checked="" type="checkbox"/>
49	13/07/18 11:54	General View	 Load JPG	<input checked="" type="checkbox"/>
50	13/07/18 11:54	General View	 Load JPG	<input checked="" type="checkbox"/>
51	13/07/18 11:54	General View	 Load JPG	<input checked="" type="checkbox"/>
52	13/07/18 11:54	General View	 Load JPG	<input checked="" type="checkbox"/>
53	13/07/18 11:54	General View	 Load JPG	<input checked="" type="checkbox"/>
54	13/07/18 11:54	General View	 Load JPG	<input checked="" type="checkbox"/>
55	13/07/18 11:54	General View	 Load JPG	<input checked="" type="checkbox"/>
56	13/07/18 11:54	General View	 Load JPG	<input checked="" type="checkbox"/>
57	13/07/18 11:54	General View	 Load JPG	<input checked="" type="checkbox"/>
58	13/07/18 11:54	General View	 Load JPG	<input checked="" type="checkbox"/>
59	13/07/18 11:54	General View	 Load JPG	<input checked="" type="checkbox"/>
60	13/07/18 11:54	General View	 Load JPG	<input checked="" type="checkbox"/>
61	13/07/18 11:54	General View	 Load JPG	<input checked="" type="checkbox"/>
62	13/07/18 11:54	General View	 Load JPG	<input checked="" type="checkbox"/>
63	13/07/18 11:54	General View	 Load JPG	<input checked="" type="checkbox"/>
64	13/07/18 11:54	General View	 Load JPG	<input checked="" type="checkbox"/>
65	13/07/18 11:54	General View	 Load JPG	<input checked="" type="checkbox"/>
66	13/07/18 11:54	General View	 Load JPG	<input checked="" type="checkbox"/>
67	13/07/18 11:54	General View	 Load JPG	<input checked="" type="checkbox"/>
68	13/07/18 11:54	General View	 Load JPG	<input checked="" type="checkbox"/>
69	13/07/18 11:54	General View	 Load JPG	<input checked="" type="checkbox"/>
70	13/07/18 11:54	General View	 Load JPG	<input checked="" type="checkbox"/>
71	13/07/18 11:54	General View	 Load JPG	<input checked="" type="checkbox"/>
72	13/07/18 11:54	General View	 Load JPG	<input checked="" type="checkbox"/>
73	13/07/18 11:54	General View	 Load JPG	<input checked="" type="checkbox"/>
74	13/07/18 11:54	General View	 Load JPG	<input checked="" type="checkbox"/>
75	13/07/18 11:54	General View	 Load JPG	<input checked="" type="checkbox"/>
76	13/07/18 11:54	General View	 Load JPG	<input checked="" type="checkbox"/>
77	13/07/18 11:54	General View	 Load JPG	<input checked="" type="checkbox"/>
78	13/07/18 11:54	General View	 Load JPG	<input checked="" type="checkbox"/>
79	13/07/18 11:54	General View	 Load JPG	<input checked="" type="checkbox"/>
80	13/07/18 11:54	General View	Load JPG	<input checked="" type="checkbox"/>
81	13/07/18 11:54	General View	Load JPG	<input checked="" type="checkbox"/>
82	13/07/18 11:54	General View	Load JPG	<input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	10/07/18 13:50	OI SLW1208Z GIA REPORT	Load PDF	
2	10/07/18 13:50	TPD FBD1487C GIA REPORT	Load PDF	
3	10/07/18 14:07	FAX TO MAHADI ABU BAKAR & PARTNERS WITH 10 SURVEY NAME - FBD1487C	Load PDF	
4	10/07/18 15:50	TPD FBD1487C - SURVEY LISTING	Load PDF	
5	10/07/18 15:50	Reject email to TP Lawyer & appoint LKK AUTO - FBD1487C	Load PDF	
6	11/07/18 11:00	WORKSHOP DETAILS -FBD1487C.pdf	Load PDF	
7	06/08/18 17:17	LOD, POLICE RPEORT, REPAIR BILL, SURVERY REPORT, COI & GIA SEARCH	Load PDF	
8	06/08/18 17:17	COLOURED IMAGES	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18012646/R1Z4D3E2

Date: 08/08/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A29070671AVW

Claimant Vehicle No : FBD1487C

Insured Vehicle No : SLW1208Z

Date of Loss: 08/07/2018

Nature of Claim: TP

Claim No: 564047

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FBD1487C

Make & Model: YAMAHA T135, 135cc (A)

Engine No: 5YP300312

Reg. Date: 06/11/2008 (Man. Year: 2008)

Chassis No: 5YP300312

Colour: Multi-colour

Odometer: 658182 km

Engine Capacity: 135 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 90/80-17

Rear Tyre Size: 90/80-17

Front Left Side: Maxxis 3 mm

Rear Left Side: Maxxis 3 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 11/07/2018

Date Inspected: 12/07/2018 Inspected At:

Hua Chin (2000) Trading Motor Service
Centre (HQ)
50 BUKIT BATOK STREET 23, #02-02
MIDVIEW BUILDING
Singapore 659578

Estimated Period of Repair: 0.0 days

Adjuster: XING GUO QIANG

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,500.00 -\$4,000.00

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 08 Aug 2018)

Parts: N/A YAMAHA T135 135cc (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for FBD1487C)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >