



ComfortDefGro Engineering

205 Braddell Road S(579701)

ACCIDENT REPAIR ESTIMATES

Our Ref:

Type of Claim : TPVehicle No. : SLR9596BMake & Model : HONDA GRACE HB cvt 1.5Year of Manufacture : 2017Chassis No. : GM41105483Ins Company : AIG / AXA

Engine No. : _____

Excess : _____

Policy No. : _____

Date of Accident : 9/7/2018

Time of Accident : _____

Suggested Days of Repair : _____

In-house Vehicle Assessor**Repair Estimates**Case Owner : PATRICK

Signature : _____

Contact No

Parts (a) Cost / List Price Items \$-Plus/Less 20% \$-Total of Cost / List \$-(b) Nett Price Items \$-

Less _____

Total of Nett Item _____

(c) Special Nett Items \$70.00Total Parts Cost (Appendix A) \$70.00Labour (Appendix B) \$2,900.00Total Repair Cost \$2,970.0063837466 – Patrick
patricktia@sparkcarcare.com

63838115 – WILLIAM

63837656 - Ngo
ngotw@cdge.com.sg

63837730 – Brenda Ng

The above total will be subjected to 7% G.S.T.

Name of Surveyor : _____

Company : _____

Survey conducted on : _____ at _____

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair _____ day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : _____ Date: _____



Spark Car Care

ComfortDelGro Engineering Pte Ltd
205 Braddell Road S (579701)
Tel: 63837168 / 63837466 Fax:62815767

Spare Parts

Vehicle No : <u>SLR9596B</u>	Case Owner : <u>PATRICK</u>
Make & Model : <u>HONDA GRACE HB cvt 1.5</u>	Year Manufacture : <u>2017</u>
Chassis No : <u>GM41105483</u>	Engine No : <u>0</u>
Sales Order : _____	Supplier : _____
Order By : _____	Type of Claim : <u>TP</u>

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	REAR BUMPER	1					
2	REAR BUMPER SIDE RETAINER	1					
3	REAR BUMPER LH REFLECTOR	1					
4	REAR LH RIM COVER	1					
5	REAR LH FENDER	1					
6	REAR WINDSCREEN GLASS MOULDING	1					
7	SEALANT	2				\$40.00	
8	INNER SEAL	1				\$30.00	
9	0	0					
10	0	0					
11	0	0					
12	0	0					
13	0	0					
14	0	0					
15	0	0					
16	0	0					
17	0	0					
18	0	0					
19	0	0					
20	0	0					
21	0	0					
22	0	0					
23	0	0					
24	0	0					
25	0	0					
26	0	0					
27	0	0					
28	0	0					
29	0	0					
30		0					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spark Car Care

ComfortDelGro Engineering Pte Ltd
205 Braddell Road S (579701)
Tel: 63837168 / 63837466 Fax: 62815767

Labour

Vehicle No.	: <u>SLR9596B</u>	Case Owner	: <u>PATRICK</u>
Make & Model	: <u>HONDA GRACE HB cvt 1.5</u>	Year of Manufacture	: <u>2017</u>

[illegible]

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.