

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLN 3897 T.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	BUMPER COVER <i>Replaced</i>	\$ 1,697.00 ✓	1357.60
2	FIXING PARTS FOR BUMPER <i>new</i>	\$ 166.00 x	} x
3	GUIDE SECTION - LH/RH <i>new</i>	2 \$ 28.00 x	
4	LOCKING MECHANISM <i>Not new</i>	2 \$ 50.00 x	
5	SPOILER <i>Replaced</i>	\$ 206.00 ✓	164.40
6	REAR LIGHT REFLECTOR - LH/RH <i>new</i>	2 \$ 70.00 x	} x
7	SENSOR PRIME - INNER/OUTER <i>new</i>	2 \$ 421.00 x	
8	WIRING SET FOR BUMPER <i>Not new</i>	\$ 458.00 x	
9	REAR LID <i>Replaced</i>	\$ 2,310.00 ✓	1848.00
10	ATTACHMENT PARTS FOR REAR LID <i>Not new</i>	\$ 253.00 ?	} x
11	GASKET FOR FLAP <i>Not new</i>	\$ 176.00 x	
12	PACKING ADHESIVE <i>new</i>	\$ 15.00 ✓	11.60
13	AUDI EMBLEM	\$ 108.00 ✓	86.00
14	A3' EMBLEM	\$ 83.00 ✓	66.16
15	TFSI' EMBLEM	\$ 83.00 ✓	66.16
16	LED TAIL LIGHT - LH/RH <i>Not new</i>	2 \$ 1,460.00 x	} x
17	TRIM FOR TAIL LIGHT - LH/RH <i>Not new</i>	2 \$ 52.00 x	
18	REAR CROSS PANEL <i>Repair</i>	\$ 317.00 x	
19	REINFORCEMENT FOR CROSS PANEL <i>Repair</i>	\$ 645.00 x	
20	CONNECTING PLATE - LH <i>Not new</i>	\$ 126.00 x	
21	ARCYLIC SEALANT <i>Not new</i>	\$ 180.00 x	
SUB - TOTAL SPARE PARTS		\$ 8,904.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLN 3897 T

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	CAVITY WAX	\$ 140.00	+
22	STONE CHIP TREATMENT	\$ 180.00	+
23	SUNDRIES	\$ 500.00	?
TOTAL SPARE PARTS		:	\$ 9,724.00
TOTAL LABOUR CHARGES		:	\$ 8,024.00
GRAND TOTAL		:	\$ 17,748.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

18,249.00

18,148.40

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lim
Surveyed Date : 11/07/18
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 06 Pys

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PAJODI0768/2018/PH 31-Jul-18 CHANG 1 of 1 SLN 3897 T Audi A3 SEDAN 1.0 TFSI	
Quantity	Description	Unit Price	Amount	
<u>Parts</u> 1	REAR REINFORCEMENT BEAM <i>Best</i>	\$ 501.00	✓ 400.40	
GRAND TOTAL :		\$ 501.00		

AS
31/07/18

For Premium Automobiles Pte Ltd



Authorised Signature

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Celine Fong (LKKAUTO)

From: Janice Lee (LKKAUTO)
Sent: Thursday, 4 October 2018 5:20 PM
To: Boo seng yak; Adrian Ling (LKKAUTO); SUR; Carrine Leong; jiayee.yap@premiumauto.com.sg;
Chang Chee Sing
Subject: RE: FINAL REVISION - SLN3897Y - OD AIG - SURVEYED 11 JUL 18

Dear Mr. Boo,

Confirm \$7,658.40 @ 6 days

Kindly send us the invoice and dv for our closure.

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Boo seng yak [mailto:boojohnny@gmail.com]
Sent: Monday, September 10, 2018 7:07 PM
To: Adrian Ling (LKKAUTO) <adrianling@lkkauto.com>; Janice Lee (LKKAUTO) <JaniceLee@lkkauto.com>; SUR <sur@lkkauto.com>; Carrine Leong <carrine.leong@premiumauto.com.sg>; jiayee.yap@premiumauto.com.sg;
Chang Chee Sing <claims@premiumauto.com.sg>
Subject: FINAL REVISION - SLN3897Y - OD AIG - SURVEYED 11 JUL 18

Hi Adrian and all,

Revised estimate is attached.

Please confirm repair cost of \$7658.40 @ 6 days of repairs.

Your early closure is well appreciated.

Best regards - jb

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183
Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0768/2018/PH
Date : 05-Jul-18

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Adrian
6 days - ok - jb - 10 Sep 18

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Foo Cher Sing Jeffrey
Address : 493 Yio Chu Kang Road
#02-04
Singapore 787079
Telephone : HP +65 90182898
Type of Claim : Own Damage Claim
Policy No. : 1800043288
Vehicle No : **SLN 3897 Y**
Model Code : Audi A3 Sedan 1.0 TFSI
Model / Year : Apr-17
Engine No : CHZ 332364
Chassis No : WAUZZZ8VXH1063868
Mileage : -
Date In : -
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 04-Jul-18
Place of Accident : SLE towards Woodlands near Mandai Rd exit 7

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLN 3897 T .

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid. Check function and renew according to damage.	S/N \$	280.00	\$ 280.00
2	To remove and transfer rear lid's convenience lock system and wire harness for tail lights.	S/N \$	280.00	\$ 280.00
3	To dislodge and reinstall rear wire harness for tail lights, battery manager, fuse and relay trays, electrical and audio components.	S/N \$	480.00	
4	To dismantle rear bumper and rear lid. Cut out and weld rear outer, inner cross panel and connecting plates. Repair lhs rear fender. Re-organise rear crash management components. Reinstall all parts removed.	S/N \$	3,600.00	\$ 1,250.00
5	To respray rear bumper, rear lid, lhs rear fender and end panelling. To carry out joint sealer works and stone chip treatment	\$	3,000.00	\$ 1,650.00
6	To carry out diagnostic checks.	S/N \$	384.00	\$ 196.00
TOTAL LABOUR CHARGES		:	<u>\$ 8,024.00</u>	<u>\$ 3,656.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLN 3897 T .

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	BUMPER COVER	\$ 1,697.00	\$ 1,357.60
2	FIXING PARTS FOR BUMPER	\$ 166.00	
3	GUIDE SECTION - LH/RH	2 \$ 28.00	
4	LOCKING MECHANISM	2 \$ 50.00	
5	SPOILER	\$ 206.00	\$ 164.40
6	REAR LIGHT REFLECTOR - LH/RH	2 \$ 70.00	
7	SENSOR PRIME - INNER/OUTER	2 \$ 421.00	
8	WIRING SET FOR BUMPER	\$ 458.00	
9	REAR LID	\$ 2,310.00	\$ 1,848.00
10	ATTACHMENT PARTS FOR REAR LID	\$ 253.00	
11	GASKET FOR FLAP	\$ 176.00	
12	PACKING ADHESIVE	\$ 15.00	\$ 11.60
13	AUDI EMBLEM	\$ 108.00	\$ 86.00
14	A3' EMBLEM	\$ 83.00	\$ 66.16
15	TFSI' EMBLEM	\$ 83.00	\$ 66.16
16	LED TAIL LIGHT - LH/RH	2 \$ 1,460.00	
17	TRIM FOR TAIL LIGHT - LH/RH	2 \$ 52.00	
18	REAR CROSS PANEL	\$ 317.00	
19	REINFORCEMENT FOR CROSS PANEL	\$ 645.00	
20	CONNECTING PLATE - LH	\$ 126.00	
21	ARCYLIC SEALANT	\$ 180.00	
SUB - TOTAL SPARE PARTS		\$ 8,904.00	\$ 3,599.92

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLN 3897 T

S/N	Parts Description		Damage Parts & Prices	
			S/NETT	REMARKS
		c/f		\$ 3,599.92
21	CAVITY WAX		\$ 140.00	
22	STONE CHIP TREATMENT		\$ 180.00	
23	SUPPLEMENTARY		\$ 500.50	\$ 400.40
24	SUNDRIES		\$ 500.00	\$ 2.08
TOTAL SPARE PARTS		:	\$ 10,224.50	\$ 4,002.40
TOTAL LABOUR CHARGES		:	\$ 8,024.00	\$ 3,656.00
GRAND TOTAL		:	\$ 18,248.50	\$ 7,658.40

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLN 3897 T

S/N	Parts Description	c/f	Damage Parts & Prices	
			S/NETT	REMARKS
				\$ 3,599.92
21	CAVITY WAX		\$ 140.00	
22	STONE CHIP TREATMENT		\$ 180.00	
23	SUPPLEMENTARY		\$ 500.50	\$ 400.40
24	SUNDRIES		\$ 500.00	\$ 2.08
TOTAL SPARE PARTS			\$ 10,224.50	\$ 4,002.40
TOTAL LABOUR CHARGES			\$ 8,024.00	\$ 3,656.00
GRAND TOTAL			\$ 18,248.50	\$ 7,658.40

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No: 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0768/2018/PH 31-Jul-18 CHANG 1 of 1 SLN 3897 T Audi A3 SEDAN 1.0 TFSI	
Quantity	Description	Unit Price	Amount	
<u>Parts</u>				
1	REAR REINFORCEMENT BEAM	\$ 501.00	\$ 400.40	
GRAND TOTAL :		\$ 501.00	\$ 400.40	

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SLN 3897 T

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0768/2018/MAS

24 Oct 2018

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

RE: INSURANCE CLAIM FOR SLN 3897 T, Audi A3 Sedan 1.0 TFSI

With reference to the above-mentioned vehicle, no **SLN 3897 T**, claimant, **Mr. Foo Cher Sing Jeffrey**, please find the related document per attached.

1. A copy of the Original invoice no. 85013034 – S\$8,194.49
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SLN 3897 T

total pages

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone: 6836 2223
Main Telefax: 6471 3733
Page 1 14:08

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone: 6388 2223
Telefax: 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408091
Telephone: 6388 2223
Telefax: 6841 1182

Customer Service
Service Appointment: 6366 2323
24-hour Breakdown Service: 9828 1233
Email: customer.care@premiumauto.com.sg

INS TAX INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120 079120

Invoice: 85013034
Date : 22/10/2018
Order : SLN3897T
Term : 30

Account: A0005 (T 0)
AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120

Regn No.: SLN3897T (V 33404)

Regn Date: 29/04/2017

Mileage: 22565

WIP No.: 16329

Model: A3 SEDAN 1.0 TFSI 8VMANG

Chassis: WPAUZZ8VXH1063868

Engine: CHZ 332364

Dept: U

USB No.:

You have been assisted by :- UB-Jiayee

(33)

		Details	Qty	Unit Price	Amount
S	BODYWORK	M: TO REMOVE AND TRANSFER REAR PARKING AID. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGED	280.00	1.00	280.00
S	BODYWORK	M: TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS	280.00	1.00	280.00
S	BODYWORK	M: TO DISMANTLE REAR BUMPER AND REAR LID.CUT OUT AND WELD REAR OUTER, INNER CROSS PANEL AND CONNECTING PLATES.REPAIR LHS REAR FENDER. REORGANISE REAR CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	1250.00	1.00	1,250.00
S	BODYWORK	M: TO RESPRAY REAR BUMPER,REAR LID AND LHS REAR FENDER.TO CARRY OUT JOINT SEALER WORKS AND STONE CHIP TREATMENT	1650.00	1.00	1,650.00
Sub-Total					
7% GST					
Grand Total					

Customer



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone 6388 2223
Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408024
Telephone 6388 2123
Telefax 6641 5123

Customer Service:
Service Appointment
9-hour Breakdown Service
Email customer.care@premiumauto.com.sg
6366 2323
9828 1233

INS TAX INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

Page 2 14:08

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013034 Date : 22/10/2018 Order : SLN3897T Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SLN3897T (V 33404) Regn Date: 29/04/2017 Mileage: 22565 WIP No.: 16329
Model: A3 SEDAN 1.0 TFSI 8VMANG Chassis: WAUZZZ8VXH1063868 Engine: CHZ 332364 Dept: U
VSB No.:
You have been assisted by :- UB-Jiayee (33)

		Details	Qty	Unit Price	Amount
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	196.00	1.00	196.00
X	A8V5827025F	LID	1.00	2310.00	1,848.00
X	A8V5807521L 989	SPOILER	1.00	205.50	164.40
X	A8V5807309	BEAM	1.00	500.50	400.40
X	A8V5807067G GRU	COVER	1.00	1697.00	1,357.60
X	A8X0853737A 2ZZ	INSCRIPTION 'TFSI'	1.00	82.70	66.16
X	A8P0853741 2ZZ	INSCRIPTION 'A3'	1.00	82.70	66.16
X	A8V7853742 2ZZ	AUDI SIGN	1.00	107.50	86.00
X	A8D0853419F	PACKING	1.00	14.50	11.60
X	A8T0827310A	CLIP	2.00	1.30	2.00

Parts 4,002.40
Labour 0.00
Sublet 3,656.00
Menus 0.00
Lubricant 0.00

Sub-Total 7,658.40
7% GST 536.09
Grand Total 8,194.49



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Customer

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SGX 293 L

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/0768/2018/KS
6 August 2018

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

total pages

RE : CLAIM – OWNER’S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A3 SEDAN 1.0 TFSI
Vehicle Chassis No. : WAUZZZ8VXH1063868
Vehicle Regn No. : SLN 3897 Y
Vehicle Mileage : 22565 KM
Vehicle Owner : Mr Foo Cher Sing Jeffrey
Certificate No : 1800043288
Policy Excess : NIL
Accident Date : 4TH July 2018
Place : SLE towards Woodlands near Mandai RD exit 7
Repair Cost : \$ 8,194.49
WIP No. : 16329
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature : 
Time :
Date : 6/8/18

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Jul 2018		11 Jul 2018 20:00 Edit Adj Rpt	S\$7,658.40 Edit Estimates	S\$7,658.40 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured: **FOO CHER SING JEFFERY**, ID: S7026459E, Tel: +6590182898, Email: JEFFCHER@GMAIL.COM

Vehicle Reg. No.: **SLN3897T** Date of Loss: 04/07/2018 21:00 - :59
[14 Months and 5 Days From LTA Reg Date (Man Yr)]

Claim Type: **OD / 4528751794SG** Policy/Cover Note No.: 1800043288 (Comprehensive)

Excess: S\$0.00

Repairer: **Premium Automobiles Pte Ltd (UBI)** 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911

Handling Insurer: **AIG Asia Pacific Insurance Pte. Ltd. (SG)** - Tel: 65-6419-3000 ... [Handled by **Mohd Zawaye, Norsazani**]
Norsazani.Zawaye@aig.com

Adjuster: **LKK Auto Consultants Pte Ltd (HQ)** - Tel: 6256-3561 ... [Handled by **ADRIAN LING**] ... [Final Rpt due 20/07/2018]

Driver/Custodian: **FOO CHER SING JEFFERY** (47 / Male), NRIC: S7026459E, Tel: +6590182898

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

- AIG_SG (02/10/2018): Alert - Adj Mandate Approved (S\$8847.00) - SLN3897T - Claim Handler: Mohd Zawaye...
- AIG_SG (12/07/2018): Alert - Adj Mandate Approved (S\$8346.00) - SLN3897T - Claim Handler: Mohd Zawaye...
- AIG_SG (12/07/2018): SLN3897T / OD / 04/07/2018 / Coverage & Excess update

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLN3897T (4528751794SG)
OD

Jul 4 2018 9:40PM
[FOO CHER SING JEFFERY]
Premium Automobiles Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser ▼	
Video			1 per page ▼	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	05/07/18 12:10	Video - Accident [Linked Accident Report Documents]	Load MP4	☐
2	05/07/18 12:10	Video - Accident [Linked Accident Report Documents]	Load MP4	☐
Assessment Reports			1 per page ▼	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	12/07/18 10:30	Adjuster Immediate Advice	Load HTM	☐
2	11/09/18 09:22	Adjuster Immediate Advice	Load HTM	☐
Photos/Images			3 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	12/07/18 10:38	General View	Load JPG	☒
2	12/07/18 10:38	General View	Load JPG	☒
3	12/07/18 10:38	General View	Load JPG	☒
4	12/07/18 10:38	General View	Load JPG	☒
5	12/07/18 10:38	General View	Load JPG	☒
6	12/07/18 10:38	General View	Load JPG	☒
7	12/07/18 10:38	General View	Load JPG	☒
8	12/07/18 10:38	General View	Load JPG	☒
9	12/07/18 10:38	General View	Load JPG	☒
10	12/07/18 10:38	General View	Load JPG	☒
11	12/07/18 10:38	General View	Load JPG	☒
12	12/07/18 10:38	General View	Load JPG	☒
13	12/07/18 10:38	General View	Load JPG	☒
14	12/07/18 10:38	General View	Load JPG	☒
15	12/07/18 10:38	General View	Load JPG	☒
16	12/07/18 10:38	General View	Load JPG	☒
17	12/07/18 10:38	General View	Load JPG	☒
18	12/07/18 10:38	General View	Load JPG	☒
19	12/07/18 10:38	General View	Load JPG	☒
20	12/07/18 10:38	General View	Load JPG	☒
21	12/07/18 10:38	General View	Load JPG	☒
22	11/09/18 09:24	Reinspection Photo	Load JPG	☒
23	11/09/18 09:24	Reinspection Photo	Load JPG	☒
24	11/09/18 09:24	Reinspection Photo	Load JPG	☒
25	11/09/18 09:24	Reinspection Photo	Load JPG	☒
26	11/09/18 09:24	Reinspection Photo	Load JPG	☒
27	11/09/18 09:24	Reinspection Photo	Load JPG	☒

Video			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
28	11/09/18 09:24	Reinspection Photo	 Load JPG	☒
29	11/09/18 09:24	Reinspection Photo	 Load JPG	☒
30	11/09/18 09:24	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	12/07/18 10:36	SLN 3897T ESTIMATE	 Load PDF	
2	12/07/18 10:36	Certificate of Insurance	 Load PDF	
3	12/07/18 10:36	SLN 3897T NRIC & DL	 Load PDF	
4	12/07/18 10:36	Police Report	 Load PDF	
5	12/07/18 10:36	Singapore Accident Statement	 Load PDF	
6	11/09/18 09:25	SLN 3897T SUPPLEMENTARY EST	 Load PDF	
7	21/11/18 11:40	DISCHARGE VOUCHER	 Load PDF	
8	21/11/18 11:40	SUPPLEMENTARY	 Load PDF	
9	21/11/18 11:40	WORKSHOP INVOICE	 Load PDF	

Linked Accident Report Documents

Video			View	View in Browser
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	05/07/18 12:10	Video - Accident	 Load MP4	
2	05/07/18 12:10	Video - Accident	 Load MP4	
Assessment Reports			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	05/07/18 12:18	Accident Statement	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	05/07/18 12:11	Police Report	 Load JPG	☒
2	05/07/18 12:11	Police Report	 Load JPG	☒
3	05/07/18 12:11	Police Report	 Load JPG	☒
4	05/07/18 12:15	Accident Photo	 Load JPG	☒
5	05/07/18 12:15	Accident Photo	 Load JPG	☒
6	05/07/18 12:15	Accident Photo	 Load JPG	☒
7	05/07/18 12:15	Accident Photo	 Load JPG	☒
8	05/07/18 12:15	Accident Photo	 Load JPG	☒
9	05/07/18 12:15	Accident Photo	 Load JPG	☒
10	05/07/18 12:15	Accident Photo	 Load JPG	☒
11	05/07/18 12:15	Accident Photo	 Load JPG	☒
12	05/07/18 12:15	Accident Photo	 Load JPG	☒
13	05/07/18 12:15	Accident Photo	 Load JPG	☒
14	05/07/18 12:15	Accident Photo	 Load JPG	☒
15	05/07/18 12:15	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	05/07/18 12:11	Sketch Plan	 Load JPG	☒
2	05/07/18 12:11	Sketch Plan #2	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CC3/AIG18012669/ARBS2

Date: 21/11/2018

REFERENCE

Insured/Claimant:	FOO CHER SING JEFFERY	Policy No:	1800043288	Claim No:	4528751794SG
Date of Loss:	04/07/2018	Nature of Claim:	OD		

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLN3897T	Engine No:	CHZ332364
Make & Model:	AUDI A3, 999cc TFSI (A)	Chassis No:	WAUZZZ8VXH1063868
Reg. Date:	29/04/2017 (Man. Year: 2017)	Odometer:	21649 km
Colour:	Blue		
Engine Capacity:	999 cc		
Market Value/New Car Price:	S\$100,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,124.40	4,002.40	6,122.00	60.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,024.00	3,656.00	4,368.00	54.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	18,148.40	7,658.40	10,490.00	57.80
+ GST 7.00/7.00% (S\$)	1,270.39	536.09	734.30	57.80
Nett Amount (S\$)	19,418.79	8,194.49	11,224.30	57.80

INSPECTION

Date of Assignment:	11/07/2018		Premium Automobiles Pte Ltd (UBI)
Date Inspected:	11/07/2018	Inspected At:	55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	6.0 days		

Adjuster: ADRIAN LING

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER	Deformed	1,697.00 FS	*1,357.60 FS
2	1		*FIXING PARTS FOR BUMPER	Not Necessary	166.00 FS	*- FS
3	2		*GUIDE SECTION - LH/RH	Not Necessary	28.00 FS	*- FS
4	2		*LOCKING MECHANISM	Not Necessary	50.00 FS	*- FS
5	1		*SPOILER	Deformed	206.00 FS	*164.40 FS
6	2		*REAR LIGHT REFLECTOR - LH/RH	Not Necessary	70.00 FS	*- FS
7	2		*SENSOR PRIME - INNER / OUTER	Not Necessary	421.00 FS	*- FS
8	1		*WIRING SET FOR BUMPER	Not Necessary	458.00 FS	*- FS
9	1		*REAR LID	Dented	2,310.00 FS	*1,848.00 FS
10	1		*ATTACHMENT PARTS FOR REAR LID	Not Necessary	253.00 FS	*- FS
11	1		*GASKET FOR FLAP	Not Necessary	176.00 FS	*- FS
12	1		*PACKING ADHESIVE	Necessary	15.00 FS	*11.60 FS
13	1		*AUDI EMBLEM	Necessary	108.00 FS	*86.00 FS
14	1		*A3 EMBLEM	Necessary	83.00 FS	*66.16 FS
15	1		*TFSI EMBLEM	Necessary	83.00 FS	*66.16 FS
16	2		*LED TAIL LIGHT - LH/RH	Not Necessary	1,460.00 FS	*- FS
17	2		*TRIM FOR TAIL LIGHT - LH/RH	Not Necessary	52.00 FS	*- FS
18	1		*REAR CROSS PANEL	Repair	317.00 FS	*- FS
19	1		*REINFORCEMENT FOR CROSS PANEL	Repair	645.00 FS	*- FS
20	1		*CONNECTING PLATE - LH	Not Necessary	126.00 FS	*- FS
21	1		*ARCYLIC SEALANT	Not Necessary	180.00 FS	*- FS
22	1		*CAVITY WAX	Not Necessary	140.00 FS	*- FS
23	1		*STONE CHIP TREATMENT	Not Necessary	180.00 FS	*- FS
24	1		*SUNDRIES	Necessary	500.00 FS	*2.08 FS
25	1		*REAR REINFORCEMENT BEAM	Bent	400.40 FS	*400.40 FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					10,124.40	4,002.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE.	New	280.00	280.00
2	TO REMOVE AND TRANSFER REAR LIDS CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS.	New	280.00	280.00
3	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR TAIL LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO COMPONENTS.	New	480.00	0.00
4	TO DISMANTLE REAR BUMPER AND REAR LID, CUT OUT AND WELD REAR OUTER, INNER CROSS PANEL AND CONNECTING PLATES. REPAIR LHS REAR FENDER. RE-ORGANISE REAR CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS.	New	3,600.00	1,250.00
5	TO RESPRAY REAR BUMPER, REAR LID, LHS REAR FENDER AND END PANELLING. TO CARRY OUT JOINT SEALER WORKS AND.	New	3,000.00	1,650.00
6	TO CARRY OUT DIAGNOSTIC CHECKS.	New	384.00	196.00
Gross Labour Cost (S\$)			8,024.00	3,656.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >