

ASS. REC. BY:

REF: CS/TMI18012679/Kvd3n2 Special Instruction:

Survivor: **Meinren**

Kenneth

ASSIGNMENT (Office)

From (Person):

Telma Gomez

of

TMI

Date/Time:

12/7/18 @ 10:11am

Estimated Cost:

Bill to:

OD (D) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHB 7549H

Insured:

SLL 28345

at Workshop m/s

Trans-Cab

Tel:

93691265

of

No. 2 AMK St. 63

Policy No:

MJ000259

Claim No:

M1803453

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

10/07/2018

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

10:22am @ 12/7/18

Person Contacted:

Candy

Vehicle

IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SHB 7549H - CI / MSG 18 000094 / Nn-1

DOA: 27/10/2017

SLL 28345 - X

ASSIGNMENT

From: _____ Date: 12/07/2018

Veh No: SHB 7549H Yr Regn: 03, 12

Estimated Cost: _____

Type: M.Car / M.Cycle / Bus / Van / Lorry (Taxi) Prime Mover /

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No: SHB 7549H

Make: Chevrolet Epice c.c. 1991

at Workshop m/s Trans-Cab

Colour White / Red A/C: Insured / Std / NI / NA

of No. 2 AMK St - 63

Sp. Reading 438745 T/Radio: Insured / Std / NI / NA

Insured: _____

Eng/No: _____

Policy No. _____

C/No: KL11A69RJBB 091670

Claims No. _____

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured: _____ Excess: _____

Steering: In order / Jammed / Leaked / Burnt or

(Client's Record)

Brake: In order / Jammed / Leaked / Burnt or

Make of Veh: _____

Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)

Tyre Size: F: 195/65R15

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Giti

Bal. or Market Value: _____

Front Rear

IDAC Accident Rpt: _____ Consistent? : Yes or No

R/Bal. 9 mm R/Bal. 9 mm

GIA / PR Seen: _____ Consistent? : Yes or No

L/Bal. 9 mm L/Bal. 9 mm

Est. Repairs: 02 days Res.: Yes or No

D.O.A. 10/7/18 D.O.I. 12/7/18

Lum Sum: 20 % 3 Val.: Yes or No

Survey held at _____

CA / REV / REP. / 24 HRS (up)

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or O/S FR

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

13/7 File sent to Catherine

13/7/18 L1 Rpt @ 2800 (Reel 18,798.72, 87M)

RECEIVED 13 JUL 2018

Date/Time, File Pass to?

: Preli. Report

Days Of Repair: 2

1)

: Final Report

Resurvey No. of Trip: -

Date/Time, File Return to?

2) 13/7 - typist

Add Fee: : Site Insp (\$ _____)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

250
10
260

Report Format : merimen

Lump Sum / I.B.I: (\$ 2800/-)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

TOKIO MARINE INSURANCE SINGAPORE LTD Ref : CS/TMI18012679/Kvd3

20 MCCALLUM STREET #09-01
TOKIO MARINE CENTRESINGAPORE 069046

Date : 12-07-2018



Code : TMI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLL 2834S	Veh. Inspected	SHB 7549H
Policy No.	MJ000259	Coverage (\$)	0.00
Claim No.	M1803453	Excess (\$)	0.00
Assign From	MERIMEN (TELMA GOMEZ)	Assign Date	12/07/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	10/07/2018	Inspection Date	12/07/2018
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	11 Jul 2018		12 Jul 2018 10:11 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]	
Insured:	LEE SHAOWEN JOSHUA, ID: S9125474C		
Main Claimant:	TRANS-CAB SERVICES PTE LTD, Co. Reg. No.: 200303878K		
Vehicle Reg. No.:	SHB7549H	Date of Loss:	10/07/2018 21:00 - :59
Claim Type:	TP / M1803453	Policy/Cover Note No.:	MJ000259 (Comprehensive) Coverage: 27/02/2018 - 26/02/2019
Vehicle Reg. No. (Insured):	SLL2834S	Policy No. (Claimant):	
		Excess:	S\$800.00
Repairer:	Trans-Cab Services Pte Ltd (HQ) 58 Defu Lane 1, 539498 Defu Lane - Tel: 93691265		
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Telma Gomez - 65926402]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 23/07/2018]		
Adj Asg. Remarks:	PLEASE NOTE: ===== 1. SPOKEN TO CATHERINE, LKK AUTO FOR ASSIGNMENT - 12.07.18(BW)		

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company
Owner ID: 3878K

Vehicle Details

Vehicle No.: SHB7549H
Vehicle to be Exported: Yes
Intended De-registration Date: 11 Jul 2018
Vehicle Make: CHEVROLET
Vehicle Model: EPICA 2.0DSL AT ABS D/AB 2WD 4DR TURBO
Primary Colour: Red
Manufacturing Year: 2011
Engine No.: Z20S1454440K
Chassis No.: KL1LA69RJBB091670
Maximum Power Output: 110.0 kW (147 bhp)
Open Market Value: \$14,361.00
Original Registration Date: 30 Mar 2012
First Registration Date: 30 Mar 2012
Transfer Count: 0
Actual ARF Paid: \$14,361.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 29 Mar 2020
PARF Rebate Amount: \$9,334.00

Intended COE Rebate Details

COE Expiry Date: 29 Mar 2020
COE Category: A - Car (1600cc & below)
COE Period(Years): 8
PQP Paid: \$40,962.00
COE Rebate Amount: \$8,781.00
Total Rebate Amount: \$18,115.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 11 Jul 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	11/07/2018 11:42
Date Of Accident	10/07/2018 21:20
Exact Location Of Accident	SOMERSET ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB7549H
Insured/Policyholder	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62866666

Vehicle Particulars

Manufacturer	CHEVROLET
Model	EPICA-2.0 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	

Driver

Name of Driver	WANG HUI-LIH
NRIC No	S2220654J
Date Of Birth	08/01/1962
Occupation	OUTDOOR
Date Of Driving Pass	22/12/1999
Driving Experience	18 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90089658
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 809 WOODLANDS STREET 81 #04-165
Postcode	730809
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

On 10.07.2018 at about 2120hours, I was travelling straight on the Second lane along Somerset Road. Suddenly I felt an impact. Vehicle B (SLL2834S) which drive out from Hotel Jen exit without observing oncoming vehicle and hit onto my taxi's right side front portion.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE TOO BIG
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLL2834S
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	AMANDA CHONG
NRIC/Passport Number	S9101224C
Contact Number	91298141
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver.**
3. Information provided must be as **truthful and accurate as possible.** Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability.**
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

pls see attach OA Report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Wayne Hui

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Andy

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Transcab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7549H

AAD1807-101

*Not Authorized
U/Simp & 2800h*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHB 7549H

KL1LA69RJBB091670

CHEVROLET

EPICA 2.0

10.7.2018

Bilio

PART			LIST
1	1	Front Bumper	\$ Bu. 1,202.00 ✓
2	1	Front Bumper Lower Absorber	\$ Su 180.00 X
3	1	Front Bumper Reinforcement	\$ R 356.00 X
4	1	Front Bumper Retainer RH	\$ Dis 102.00 ✓
5	1	Front Bumper Retainer LH	\$ Su 102.00 X
6	1	Front Bumper Lower Grille	\$ Su 78.00 X
7	1	Front Bumper Lower Stiffener	\$ R 134.37 X
8	1	Front Bumper Bracket LH	\$ R 10.00 X
9	1	Front Bumper Bracket RH	\$ R 10.00 X
10	1	Bumper Fog Lamp Cover RH	\$ Su 32.40 X
11	1	Bumper Fog Lamp Cover LH	\$ Su 32.40 X
12	1	Headlamp RH	\$ Lu / mg Di 816.00 ✓
13	1	Headlamp RH inner panel	\$ R 611.16 X
14	1	Front Fender RH	\$ R 837.60 ✓
15	1	Front Fender Liner RH	\$ Su 47.00
16	1	Front Fender Inner Wheel House Panel RH	\$ R 1,437.00
17	1	Front Shock Absorber Assy RH	\$ Su 216.17
18	1	Front Shock Absorber Top Mounting RH	\$ Su 48.32
19	1	Front Lower Arm RH	\$ Su 283.00
20	1	Front Knuckle Arm RH	\$ Su 230.00
21	1	Front Hub Unit	\$ Su 376.00
22	1	Front Disc Brake RH	\$ Su 157.55
23	1	Front Strut Bar Bracket RH	\$ R 235.01
24	1	Front Stabilizer Bar	\$ Su 234.00
25	1	Front Stabilizer Bar Link RH	\$ Su 51.79
26	1	Front Stabilizer Bar Bracket RH	\$ R 105.75
27	1	Front Stabilizer Bar Bush RH	\$ Su 66.00
28	1	Front Beam A - Impact RH	\$ R 214.00
29	1	Bonnet Panel	\$ R 1,250.00

Trans-cab Auto Services Pte Ltd

AAD1807-101

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7549H

30	1	Horn Unit (Low Tone)	\$	Sm	53.46	}
31	1	Horn Unit (High Tone)	\$	Sm	53.46	
32	1	Front Support Panel Assy	\$	N	1,222.32	
33	1	Front brace panel	\$	N	134.37	
34	1	Windscreen Washer Tank (Reservoir A-W/Shield)	\$	Sm	62.00	
35	1	Windscreen Washer Tank Motor (Pump Wswa)	\$	Sm	51.00	
36	1	TANK, WIPER HOSE	\$	Sm	21.00	
37	1	Radiator Assembly (Radiator A	\$	Sm	618.00	
38	1	Front Door RH	\$	N	1,133.00	
TOTAL			\$		12,804.13	
10%			\$		1,280.41	
			\$		11,523.72	

Special Nett

1	1 Set	Front Fender Liner clip LH	\$	na	30.00	}
2	1 Set	Louver Cowl Top clip	\$	na	30.00	
3	1	Front right tyre rim	\$	Sm	380.00	
4	1	Front right tyre	\$	Sm	300.00	
5	2	Bonnet stopper	\$	Sm	15.00	
6	6	Bonnet under weatherstrip seal clips	\$	na	30.00	
7	10	Bonnet insulator clip	\$	na	30.00	
8	1	Front right door advertisement sticker	\$	na	300.00	
TOTAL			\$		1,115.00	

TOTAL PARTS \$ 12,638.72**LABOUR**

To Check Electrical Lighting Concerned.	\$	170.00	201
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	3,500.00	4001

Trans-cab Auto Services Pte Ltd

AAD1807-101

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7549H

Putty and spray painting of the affected portion.	\$	3,200.00	<i>4001</i>
To Remove And Refit Front And Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	<i>na</i> 440.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>na</i> 380.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>na</i> 380.00	X
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	<i>na</i> 380.00	X
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	<i>na</i> 170.00	X
To Transfer Of Bonnet Fittings, Attachments And Perform Water Seepage Test.	\$	<i>na</i> 170.00	X
To Transfer Of Door Fittings, Attachments And Perform Water Seepage Test.	\$	<i>na</i> 170.00	X

TOTAL \$ 8,960.00**Over All Total** \$ 21,598.72**Repair Days**~~10 DAYS~~
2 days

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI18012679/KVD3N2

Date: 17/07/2018

REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MJ000259
Claimant Vehicle No :	SHB7549H	Insured Vehicle No :	SLL2834S
Date of Loss:	10/07/2018	Nature of Claim:	TP
		Claim No:	M1803453

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB7549H	Engine No:	Z20S1454440K
Make & Model:	CHEVROLET EPICA, 2.0 (A)	Chassis No:	KL1LA69RJBB091670
Reg. Date:	30/03/2012 (Man. Year: 2011)	Odometer:	436745 km
Colour:	White/Red		
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Giti 9 mm	Rear Left Side:	Giti 9 mm
Front Right Side:	Giti 9 mm	Rear Right Side:	Giti 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	12,638.72	2,661.84	9,976.88	78.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,960.00	820.00	8,140.00	90.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,598.72	3,481.84	18,116.88	83.88
Approved Total (Overridden) (S\$)		2,800.00		
(S\$)	21,598.72	2,800.00	18,798.72	87.04
+ GST 7.00/7.00% (S\$)	1,511.91	196.00	1,315.91	87.04
Nett Amount (S\$)	23,110.63	2,996.00	20,114.63	87.04

INSPECTION

Date of Assignment:	12/07/2018		
Date Inspected:	12/07/2018	Inspected At:	Trans-Cab Services Pte Ltd (HQ) 58 Defu Lane 1 Singapore 539498
Estimated Period of Repair:	2.0 days		

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 17 Jul 2018)
Parts: 143	CHEVROLET EPICA 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SHB7549H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled	1,202.00 FL	*1,202.00 FL
2	1		*FRONT BUMPER LOWER ABSORBER	Serviceable	180.00 FL	*- FL
3	1		*FRONT BUMPER REINFORCEMENT	Repair	356.00 FL	*- FL
4	1		*FRONT BUMPER RETAINER RH	Distorted	102.00 FL	*102.00 FL
5	1		*FRONT BUMPER RETAINER LH	Serviceable	102.00 FL	*- FL
6	1		*FRONT BUMPER LOWER GRILLE	Serviceable	78.00 FL	*- FL
7	1		*FRONT BUMPER LOWER STIFFENER	Repair	134.37 FL	*- FL
8	1		*FRONT BUMPER BRACKET LH	Repair	10.00 FL	*- FL
9	1		*FRONT BUMPER BRACKET RH	Repair	10.00 FL	*- FL
10	1		*BUMPER FOG LAMP COVER RH	Serviceable	32.40 FL	*- FL
11	1		*BUMPER FOG LAMP COVER LH	Serviceable	32.40 FL	*- FL
12	1		*HEADLAMP RH	Cut/Mtg Distorted	816.00 FL	*816.00 FL
13	1		*HEADLAMP RH INNER PANEL	Repair	611.16 FL	*- FL
14	1		*FRONT FENDER RH	Bent	837.60 FL	*837.60 FL
15	1		*FRONT FENDER LINER RH	Serviceable	47.00 FL	*- FL
16	1		*FRONT FENDER INNER WHEEL HOUSE PANEL RH	Repair	1,437.00 FL	*- FL
17	1		*FRONT SHOCK ABSORBER ASSY RH	Serviceable	216.17 FL	*- FL
18	1		*FRONT SHOCK ABSORBER TOP MOUNTING RH	Serviceable	48.32 FL	*- FL
19	1		*FRONT LOWER ARM RH	Serviceable	283.00 FL	*- FL
20	1		*FRONT KNUCKLE ARM RH	Serviceable	230.00 FL	*- FL
21	1		*FRONT HUB UNIT	Serviceable	376.00 FL	*- FL
22	1		*FRONT DISC BRAKE RH	Serviceable	157.55 FL	*- FL
23	1		*FRONT STRUT BAR BRACKET RH	Repair	235.01 FL	*- FL
24	1		*FRONT STABILIZER BAR	Serviceable	234.00 FL	*- FL
25	1		*FRONT STABILIZER BAR LINK RH	Serviceable	51.79 FL	*- FL
26	1		*FRONT STABILIZER BAR BRACKET RH	Repair	105.75 FL	*- FL
27	1		*FRONT STABILIZER BAR BUSH RH	Serviceable	66.00 FL	*- FL
28	1		*FRONT BEAM A-IMPACT RH	Repair	214.00 FL	*- FL
29	1		*BONNET PANEL	Repair	1,250.00 FL	*- FL
30	1		*HORN UNIT (LOW TONE)	Serviceable	53.46 FL	*- FL
31	1		*HORN UNIT (HIGH TONE)	Serviceable	53.46 FL	*- FL
32	1		*FRONT SUPPORT PANEL ASSY	Repair	1,222.32 FL	*- FL
33	1		*FRONT BRACE PANEL	Repair	134.37 FL	*- FL
34	1		*WINDSCREEN WASHER TANK (RESERVOIR A-W/SHIELD)	Serviceable	62.00 FL	*- FL
35	1		*WINDSCREEN WASHER TANK MOTOR (PUMP WSWA)	Serviceable	51.00 FL	*- FL
36	1		*TANK,WIPER HOSE	Serviceable	21.00 FL	*- FL
37	1		*RADIATOR ASSEMBLY (RADIATOR A)	Serviceable	618.00 FL	*- FL
38	1		*FRONT DOOR RH	Repair	1,133.00 FL	*- FL
39	1		*SET FRONT FENDER LINER CLIP LH	Not Necessary	30.00 FS	*- FS
40	1		*SET LOUVER COWL TOP CLIP	Not Necessary	30.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
41	1		*FRONT RIGHT TYRE RIM	Serviceable	380.00 FS	*- FS
42	1		*FRONT RIGHT TYRE	Serviceable	300.00 FS	*- FS
43	2		*BONNET STOPPER	Serviceable	15.00 FS	*- FS
44	6		*BONNET UNDER WEATHERSTRIP SEAL CLIPS	Not Necessary	30.00 FS	*- FS
45	10		*BONNER INSULATOR CLIP	Not Necessary	30.00 FS	*- FS
46	1		*FRONT RIGHT DOOR ADVERTISEMENT STICKER	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	13,919.13	2,957.60
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,280.41	295.76
Total Parts (\$\$)	12,638.72	2,661.84

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
2	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	3,500.00	400.00
3.	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	3,200.00	400.00
4	TO REMOVE AND REFIT FRONT AND REAR W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	440.00	-
5	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH,TO FACILITATE REPAIR	New	380.00	-
6	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER,TO ENABLE REPAIR	New	380.00	-
7	TO DISMANTLE AND REFIT FRONT END SUSPENSION,UNDERCARRIAGE PARTS,FINAL CHECKING AND TESTING	New	380.00	-
8	TO TRANSFER OF FENDER FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	-
9	TO TRANSFER OF BONNET FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	-
10	TO TRANSFER OF DOOR FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	-
Gross Labour Cost (S\$)			8,960.00	820.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >