

1582(11)

INS. CASE OWNER:

Jus. 1cc f km 2684, Gubbsen

LKK:
IDAC:

Surveyor:

x692

DOI:

ASSIGNMENT

2/7/18

Date / Time:

24/7/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

YN 9022H

Name of Insured:

PAK Logistics Services Pte Ltd

Insured Tel No.:

66650190

HP:

2/6/18

Excess Sec II :SS

D.O.A.:

Is driver the owner?

(YES NO)

Nature of Accident:

If NO, Driver Name / Age:

Vinodh Kumar S/O Mahalingam

Driver Tel No.:

84544560

(VL: YES / NO)

Claim No.:

S8M00NS6/56864

Policy No.:

VCX/P1973121

Make / Model:

Mitsubishi Canter 3.0D

Place of Accident:

CTE Towards City (before upper Serangoon Exit)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

GUBH 2022

INSRS:
WSP:
Tel:
Liability:
RMKS:

Torque 5

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

2/7/18
TTHGUBH 2022
YN 9022H
amundam - virtual

PRS only

RECEIVED 13 AUG 2018

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28. Ass. Lia:

Repair Cost:

S\$

Loss of Rental (LOR):

S\$

(

days)

Loss of Use (LOU):

S\$

(\$

x

days)

Loss of Income (LOI):

S\$

(\$

x

days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

1) Claim status: Normal/Reject/Private Settle

2) Report Format: w/d

3) Survey fee: \$ 250.00

Total:

S\$

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

Name 1:

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

22/03/2012

ASS. REC. BY:

REF:

CS3/ASM18012684/ 44b

Special Instruction:

Surveyor

ASSIGNMENT (Office)

Smart claim

Vale Oh

of

ASM

Date/Time: 11/07/2018 1:17pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBH 303K

Insured:

YN 9022H

at Workshop m/s

Torque 5

Tel:

9147 8841

of

Blk 8 Kaki Bukit Ave 4 #01-49

Policy No:

Claim No:

S8MOONS6

Sum Insured:

Excess:

Make of Vch:

D.O.A.

22062018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

13/07/2018 @ 10am

H.O.D. Endorsement:

Date/Time:

12/07/2018 1052am

Person Contacted:

Stephanie

Vehicle IN/OUT

Date/Time

Action/Instruction

(X)

Estimate

'Virtual Case'

GBH 303K - NA 17/4/2018 / r3

D.A. 22062018

YN 9022H - X

(08/11/13) wef

ASS. REC. BY: XLRREF: ISM(AXA)C7078KVirtual Case**ASSIGNMENT**From: _____ Date: 13/07/2018

Estimated Cost: _____

OD TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: GBH 303Kat Workshop m/s Torque 5of Blk 8, kaki Bukit Ave 4 #01-49

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: 10 am
stephanie

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$68k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or NoLum Sum: PIP % 3 Val.: Yes or NoCA / REV / REP. / 24 HRS up

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: GBH 303K Yr Regn: 27 Dec 2017

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Nissan Cabstar c.c. 2953Colour: yellow A/C: Insured / Std / NI / NASp. Reading: 5258 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: INISC2480860742Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 175/80R15R: 155R13BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mm

D.O.A. _____

D.O.I. 13-07-18Survey held at w/sDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

- \$3507.22 / - Cred: \$15239.59 / 81%)

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

Photos

Others

TOTAL

Report Format: _____

Lump Sum / I.B.I: (\$ _____)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM18012684/Gub3		
8 SHENTON WAY #24-01 AXA TOWERS SINGAPORE 068811		Date : 12-07-2018		
		Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YN 9022H	Veh. Inspected	GBH 303K	
Policy No.		Coverage (\$)	0.00	
Claim No.	S8M00NS6	Excess (\$)	0.00	
Assign From	SMART CLAIM (VALE OH)	Assign Date	11/07/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	22/06/2018	Inspection Date	13/07/2018	
Survey held at	TORQUE 5 PTE LTD 8 KAKI BUKIT AVENUE 4 #01-50 PREMIER @ KAKI BUKIT SINGAPORE 415875			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

13/7/18 Limson repair 4 Days.
QuoQup After repair photos.



Torque 5 Pte Ltd
No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : GBH303K
Make & Model : NISSAN ,CABSTAR 3.0 5M/T ABS 2DR 2WD
EURO 5,JN15C2F24Z0860742
Year of Manufacture : 2017

Estimation No. : E18070012
DOA : 11/07/2018

No	Description	Qty	U/P	Amt	
Section: List Items					
1	Tailgate / BT	1.00	1,788.40	1,788.40	?
2	Tailgate lock (RH) X BT NN	1.00	0.00	0.00	
3	Tailgate side lever (RH) X BT	1.00	210.00	210.00	?
4	Corner panel (RH) / BT	1.00	512.00	512.00	?
5	Rear floor panel assy X	1.00	7,524.00	7,524.00	
6	Rear chassis member (RH) X	1.00	0.00	0.00	
7	Rear number plate bracket X	1.00	143.80	143.80	
8	Side gate (RH) X	1.00	3,498.10	3,498.10	
9	Side gate lever (RH) X	1.00	0.00	0.00	
				Amt	S\$
					13,676.30
				Discount (30.00%)	S\$ 999.99
				Subtotal	S\$ 9,573.41

Section: Nett Items NN					
10	Tailgate hinge X	3.00	24.50	73.50	
11	Tail lamp (RH) / CRA	1.00	277.20	277.20	
12	Tail lamp bucket (RH) X NN	1.00	160.00	160.00	
13	Corner panel rubber (RH) / M's	1.00	89.40	89.40	
14	Rear exhaust pipe X	1.00	720.00	720.00	
15	Rear exhaust pipe mounting X	1.00	35.40	35.40	
16	Rear exhaust pipe gasket X	1.00	32.30	32.30	
17	Side gate hinge X	2.00	69.10	138.20	
				Amt	S\$ 1,526.00
				Discount (10.00%)	S\$ 152.60
				Subtotal	S\$ 1,373.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Continue on next page...



Torque 5 Pte Ltd
 No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
 Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
 Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : GBH303K
 Make & Model : NISSAN ,CABSTAR 3.0 5M/T ABS 2DR 2WD
 Year of Manufacture : 2017
 EURO 5,JN1SC2F24Z0860742

Estimation No. : E18070012
 DOA : 11/07/2018

No	Description	Qty	U/P	Amt
Section: Special Nett Items				
18	Tailgate sticker - NISSAN	1.00	80.00	80.00
19	Tailgate sticker - 13 pax	1.00	35.00	35.00
20	Tailgate sticker - 70km/h	1.00	35.00	35.00
21	Tailgate P - plate	1.00	40.00	40.00
22	Tailgate aluminium board	1.00	600.00	600.00
23	Rear floor panel aluminium board	1.00	1,600.00	1,600.00
24	Rear floor panel reverse sensor	1.00	150.00	150.00
25	Rear step panel	1.00	300.00	300.00
26	Rear number plate	1.00	50.00	50.00
27	Side gate sticker - company detail	1.00	300.00	300.00
28	Side gate aluminium board	1.00	800.00	800.00

Amt S\$ 3,990.00
 Discount (0.00%) S\$ 0.00
 Subtotal S\$ 3,990.00

Section: Labour Items

29	To R&R accident affected areas	1.00	1,500.00	1,500.00
30	To putty & respray accident affected areas	1.00	1,300.00	1,300.00
31	To rust proof accident affected areas	1.00	90.00	90.00
32	To check wiring layout of tail lamp	1.00	80.00	80.00
33	To R&R rear floor reverse sensor & check function	1.00	80.00	80.00
34	To R&R exhaust pipe assy	1.00	180.00	180.00
35	To check chassis alignment	1.00	380.00	380.00
36	To R&R rear canopy	1.00	200.00	200.00

Continue on next page...



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : GBH303K
Make & Model : NISSAN ,CABSTAR 3.0 5M/T ABS 2DR 2WD
EURO 5,JN1SC2F24Z0860742
Year of Manufacture : 2017

Estimation No. : E18070012
DOA : 11/07/2018

No	Description	Qty	U/P	Amt
				Amt S\$ 3,810.00
				Discount (0.00%) S\$ 0.00
				Subtotal S\$ 3,810.00

List Items Subtotal S\$ 9,573.41
Nett Items Subtotal S\$ 1,373.40
Special Nett Items S\$ 3,990.00
Subtotal
Labour Items Subtotal S\$ 3,810.00
Total S\$ 18,746.81



Service Request Details

Claim

S8M00NS6

Reference

None 

Loss Date

June 22, 2018

Request Date

July 11, 2018

Due Date

July 18, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pre-Repair Survey

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

GBH303K

Make

TPVD NISSAN

Model

CABSTAR

Service Address

...

Primary Contact/Insured

AAK LOGISTICS SERVICES PTE LTD

BLK 153 BUKIT BATOK STREET 11, #03-292, 650153, Singapore

63380083

iana@aakls.com; vehicle@aakls.com

Claim Handler

OH Vale

6568804897

vale.oh@axa.com.sg

Additional Instructions

virtual Acc Torque 5 Please conduct PRI only.

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

SERVICE REQUESTS

MESSAGES

CLAIMS

<<

Service Request Details

Claim	S8M00NS6	Vehicle Information	
Reference	CC4/ASM18012684/Gubss Date	Incident Vehicle	GBH303K
		Registration #	TPVD NISSAN
		Make	CABSTAR
		Service Address	
June 22, 2018	Request Date	Primary Contact/Insured	
July 11, 2018	Due Date	AAK LOGISTICS SERVICES PTE LTD	
July 12, 2019	Vendor Name	BLK 153 BUKIT BATOK STREET 11, #03-292, 650153, Singapore	
LKK AUTO CONSULTANTS PTE LTD (TP)	Type of Loss	63380083	
Third Party Vehicle Damage	Services	iana@aakls.com; vehicle@aakls.com	

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
TP SAS GBH303K.pdf	Reports & Statement	GIA Report	TAY Jon	July 11, 2018
YN9022H INSD GIA REPORT.PDF	Reports & Statement	GIA Report	DHAKAL Raghav	July 11, 2018
TP TORQUE 5-PRI RECEIVED FROM WORKSHOP.msg	Letters and Correspondence	Workshop	DHAKAL Raghav	July 11, 2018

<<Service Request Details

Claim	S8M00NS6	Vehicle Information				
Reference	CC4/ASM18012684/Gub3s2Date	Actions			Incident Vehicle	GBH303K
		Next Step	Finish the work	Complete Work	Registration #	TPVD NISSAN
					Make	CABSTAR
					Address	



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#
GBH303K

Purchase Date
mm/dd/yyyy



Registration State

SINGAPORE

Registration Date *

12/27/2017



Mileage

5258

Age of Vehicle
0

CATEGORY

Manufacturing Year

Driver Details

POLICY INFORMAT...

CATEGORY Driver Name

ASSESSMENT INFO...

2017

FNOL INFORMATI... KHAN MD NA YEM

CATEGORY Make

POST SURVEY INF...

CATEGORY	Engine No
POLICY INFORMAT ...	
ASSESSMENT INFO ...	ZD30026945N
CATEGORY	Engine Capacity
POLICY INFORMAT ...	
ASSESSMENT INFO ...	2953 cc
CATEGORY	Sum Insured
POLICY INFORMAT ...	
ASSESSMENT INFO ...	0
CATEGORY	Market Value
POLICY INFORMAT ...	
ASSESSMENT INFO ...	0

FNOL INFORMATI...	0
POST SURVEY INF...	
CATEGORY	Driver License #
FNOL INFORMATI...	
POST SURVEY INF...	
CATEGORY	License Type
FNOL INFORMATI...	
POST SURVEY INF...	▼
CATEGORY	License Issue Date
FNOL INFORMATI...	
POST SURVEY INF...	mm/dd/yyyy
CATEGORY	License Expiration Date
FNOL INFORMATI...	
POST SURVEY INF...	mm/dd/yyyy
CATEGORY	Address

POST SURVEY INF...



SERVICE REQUESTS

MESSAGES

CLAIMS

English (default) LKK AUTO CONSULTANTS PTE LTD (TP)



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous

Summary

Front left side

DUNLOP 6mm

Rear left side

DUNLOP 6mm

Front right side

DUNLOP 6mm

Rear right side

DUNLOP 6mm

SERVICE REQUESTSMESSAGESCLAIMS

Assessment Details

General & Workshop DetailsVehicle & Driver DetailsVehicle ConditionTaxes & RatioParts & LabourMiscellaneousSummaryParts

Edit		SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)
		1	1			TAILGATE			Bent	1788.4		30		1251.88	Review
		2	1			TAILGATE LOCK (RH)			Serviceable	0		30		0	Review
		3	1			TAILGATE SIDE LEVER (RH)			Bent	210		30		147	Review
		4	1			CORNER PANEL			Bent	512		30		358.4	Review
		5	1			REAR FLOOR PANEL ASSY			Serviceable	0		30		0	Review
		6	1			REAR CHASSIS MEMBER (RH)			Serviceable	0		30		0	Review
		7	1			REAR NUMBER PLATE BRACKET			Serviceable	0		30		0	Review
		8	1			SIDE GATE (RH)			Serviceable	0		30		0	Review

SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
	1	DAYS OF REPAIR	Reviewing	0	4	
	2	TAILGATE HINGE	Reviewing	0	NOT NECESSARY	
	3	TAIL LAMP (RH) (DISC 10%)	Reviewing	249.48	CRACKED	
	4	TAIL LAMP BRACKET (RH)	Reviewing	0	NOT NECESSARY	

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
☐	 12	TAILGATE STICKER - 70KM/H	Reviewing	10	NECESSARY	
☐	 13	TAILGATE P - PLATE	Reviewing	10	NECESSARY	
☐	 14	TAILGATE ALUMINIUM BOARD	Reviewing	150	BENT	
☐	 15	REAR FLOOR PANEL ALUMINIUM BOARD	Reviewing	0	NOT NECESSARY	
☐	 16	REAR FLOOR PANEL REVERSE SENSOR	Reviewing	0	NOT NECESSARY	
☐	 17	REAR STEP PANEL	Reviewing	0	NOT NECESSARY	
☐	 18	REAR NUMBER PLATE	Reviewing	0	NOT NECESSARY	

SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details	Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous
Summary	Claim Amount	\$3,507.22	Claim Amount	\$3,507.22	

CATEGORY	ESTIMATE	REVISED AMOUNT
----------	----------	----------------

Labour	\$1,070.00	\$1,070.00
--------	------------	------------

Miscellaneous	\$679.94	\$679.94
---------------	----------	----------

Spare Parts	\$1,757.28	\$1,757.28
-------------	------------	------------

Submit for Review