

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
☐	 19	SIDE GATE STICKER - COMPANY DETAIL	Reviewing	150	NECESSARY	
☐	 20	SIDE GATE ALUMINIUM BOARD	Reviewing	0	NOT NECESSARY	

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
☐	 5	CORNER PANEL RUBBER (RH) (DISC 10%)	Reviewing	80.46	MISSING	
☐	 6	REAR EXHAUST PIPE	Reviewing	0	NOT NECESSARY	
☐	 7	REAR EXHAUST PIPE MOUNTING	Reviewing	0	NOT NECESSARY	
☐	 8	REAR EXHAUST PIPE GASKET	Reviewing	0	NOT NECESSARY	
☐	 9	SIDE GATE HINGE	Reviewing	0	NOT NECESSARY	
☐	 10	TAILGATE STICKER - NISSAN	Reviewing	20	NECESSARY	
☐	 11	TAILGATE STICKER - 13 PAX	Reviewing	10	NECESSARY	

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BITTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PART)
	9	1			SIDE GATE LEVER (RH)			Serviceable	0		30		0	Review

Labour

A-11 Approve Deny Submit All											
EDIT	SR NO	REPAIR/REPLACE (LABOUR)		PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	R	
	1			TO R&R ACCIDENT AFFECTED AREAS.	400	0	0	Reviewing		1	
	2			TO PUTTY & RESPRAY ACCIDENT AFFECTED AREAS.	600	0	0	Reviewing		1	
	3			TO RUST PROOF ACCIDENT AFFECTED AREAS.	40	0	0	Reviewing		1	
	4			TO CHECK WIRING LAYOUT OF TAIL LAMP.	30	0	0	Reviewing		1	
	5			TO R&R REAR FLOOR REVERSE SENSOR & CHECK FUCNTION.	0	0	0	Reviewing		1	
	6			TO R&R EXHAUST PIPE ASSY.	0	0	0	Reviewing		1	
	7			TO CHECK CHASSIS ALIGNMENT.	0	0	0	Reviewing		1	
	8			TO R&R REAR CANOPY.	0	0	0	Reviewing		1	

Detailed Assessment

Inspection Date *

07/13/2018



Condition of Vehicle at time of survey

General condition

Good



Total Loss

Yes

No

Steering (Serviceable)

Yes

No

Towing Charges

0

Footbrake (Serviceable)

Yes

No

Voluntary Excess

0

Handbrake (Serviceable)

Yes

No

Compulsory Excess

0

Engine Modification

Yes

No

Young/Inexperienced/Unnamed Driver Excess

0

Pre-accident condition

Good



Other Excess

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

175/80R15

Rear Tyre Size

155 R13

FNOL INFORMATI...
63 KALLANG BAHRU, #05-441,
KALLANG BAHRU VILLE, 330063,
Singapore

POST SURVEY INF...

CATEGORY Address type

FNOL INFORMATI... Personal Correspondence

POST SURVEY INF...

CATEGORY Gender

FNOL INFORMATI... Male

POST SURVEY INF...

CATEGORY Marital status

FNOL INFORMATI... Unknown

POST SURVEY INF...

CATEGORY Identification #

FNOL INFORMATI... G8102982U

POLICY INFORMAT... TPVD NISSAN

ASSESSMENT INFO...

NISSAN

CATEGORY

Model

POLICY INFORMAT... CABSTAR

ASSESSMENT INFO...

CABSTAR 3.0 5M/T ABS 2DR 2WD EUF

CATEGORY

Type

POLICY INFORMAT... Other non-owned

ASSESSMENT INFO...



CATEGORY

Type of Paint

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY

Chassis No

POLICY INFORMAT...

ASSESSMENT INFO...

JN1SC2F24Z0860742

CATEGORY

Date of Birth

FNOL INFORMATI...

December 13, 1989

POST SURVEY INF...

mm/dd/yyyy



CATEGORY

Age

FNOL INFORMATI...

28

POST SURVEY INF...

CATEGORY

Occupation

FNOL INFORMATI...

Unknown

POST SURVEY INF...

CATEGORY

Education Qualification

FNOL INFORMATI...

Other

POST SURVEY INF...

CATEGORY

Driving Experience

Pre-Repair Survey

Claim Handler

TAN Jas
6568804844
jas.tan@axa.com.sg

- Messages
- Assessment
- Invoices
- Metrics
- History
- Notes
- Documents
- Add

Additional Instructions

virtual Acc Torque 5 Please conduct PRI only.

CREATED USER	VERSION DATE	ESTIMATED AMOUNT	APPROVED AMOUNT	STATUS	SHARE	CLONE
TAN Jas	7/11/18 1:17 PM	3507.22	3507.22	Open	Share	Clone

Pre-Repair Survey

Claim Handler

TAN Jas
6568804844
jas.tan@axa.com.sg

Additional Instructions

virtual Acc Torque 5 Please conduct PRI only.

Document SubType

Upload Documents

Messages Invoices History Documents

Assessment Metrics Notes
Document Type

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
Driving Licence.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	August 2, 2018
LKK INSPECTION PHOTO.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	August 2, 2018
TP ESTIMATE-MARKED.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	July 24, 2018