

**LIUS BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793J . Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: liusbros@gmail.com

Invoice/Ref No: GBF847T180709

Estimate**Customer**

Name: AXA Insurance Singapore Pte Ltd

Date: 11-07-18

Address: Motor Claims Department

Vehicle No: GBF847T

8 Shenton Way #27-01

Model/Make: Fiat Doblo Cargo

AXA Tower

Singapore 068811

Maxi 1.6 MTJ AMT D/AB Panel

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Rh Tailgate <i>22/32</i>	\$ 1,895.90	
2	Tailgate Lock Top <i>11</i>	\$ 189.30	X
3	Tailgate Lock Lower <i>211</i>	\$ 192.90	X
4	Tailgate Weatherstrip <i>10-11</i>	\$ 297.00	X
5	Tailgate Outer Garnish <i>310-1</i>	\$ 321.80	X
6	Tailgate "FIAT Logo" Emblem <i>111</i>	\$ 87.80	X
7	Tailgate "Professional" Emblem <i>111</i>	\$ 163.50	X
8	Tailgate "90" Emblem <i>111</i>	\$ 97.50	SN 605.2
9	Tailgate "MultiJet" Emblem <i>111</i>	\$ 119.60	SN 605.2
10	Tailgate "6 PAX" Sticker <i>111</i>	\$ 12.00	SN 105.2
11	Tailgate Glass <i>shop</i>	\$ 540.00	X
12	Tailgate Glass Sealant <i>111</i>	\$ 80.00	SN 405.2
13	Rear Lh Tailgate <i>22/32</i>	\$ 2,395.00	
14	Tailgate Weatherstrip <i>111</i>	\$ 344.50	X
15	Tailgate Lock <i>111</i>	\$ 331.00	X
16	Tailgate Inner Trim Board <i>111</i>	\$ 384.90	SN X
17	Tailgate Handle Outer Garnish <i>111</i>	\$ 369.80	X
18	Tailgate Outer Handle <i>111</i>	\$ 556.40	X
19	Tailgate "Maxi" Emblem <i>111</i>	\$ 86.00	X
20	Tailgate "Doblo" Emblem <i>111</i>	\$ 118.00	X
21	Tailgate "70 KM/H" Sticker <i>111</i>	\$ 12.00	SN 105.2
22	Tailgate Wiper Motor <i>111</i>	\$ 428.00	X
23	Tailgate Wiper Link <i>111</i>	\$ 165.30	X
24	Tailgate Wiper Rubber <i>111</i>	\$ 98.00	X
25	Tailgate Glass <i>shop</i>	\$ 841.50	X
26	Tailgate Glass Sealant <i>111</i>	\$ 80.00	SN 405.2
27	Number Plate Outer Garnish <i>111</i>	\$ 387.00	X
28	Rear Bumper <i>22/32</i>	\$ 745.00	X
29	Bumper Clips 1 set <i>111</i>	\$ 65.00	SN X
30	Bumper Reinforcement	\$ 475.30	X
31	Bumper Reflector Lh <i>111</i>	\$ 117.60	X
32	Bumper Reverse Sensor <i>111</i>	\$ 220.00	SN 2005.2
33	End Panel	\$ 430.00	X
34	End Panel Top Garnish <i>111</i>	\$ 347.70	X
35	End Panel Top Garnish Clips 1set <i>111</i>	\$ 58.00	SN X
36	End Panel Sealant <i>111</i>	\$ 50.00	SN X
37	Tail Lamp Lh	\$ 462.70	X
38	Number Plate & Base <i>111</i>	\$ 48.00	SN 40
39	"Corporate" Advertisement & Art Work <i>111</i>	\$ 400.00	SN 300
C/F Balance ---->		\$ 14,014.00	



**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793J . Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: liusbros@gmail.com

Invoice/Ref No: GBF847T180709

Estimate

Customer		Date:	11-07-18
Name:	AXA Insurance Singapore Pte Ltd	Vehicle No:	GBF847T
Address:	Motor Claims Department	Model/Make:	Fiat Doblo Cargo
	8 Shenton Way #27-01		Maxi 1.6 MTJ AMT D/AB Panel
	AXA Tower		
	Singapore 068811		

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
	B/F Balance ---->	\$ 14,014.00	
	Remove & reinstall Rear Rh & Lh Windscreen Glass to facilitate repairs	\$ 240.00	200
	Remove and refix rear Rh & Lh tailgate components & wiper mechanism	\$ 180.00	120
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 1,200.00	
	To putty & spray painting & including touch up paint on accident affected area	\$ 1,200.00	800
	To check all wiring & electrical component for proper function	\$ 80.00	20
	Remove and refix rear reverse sensor	\$ 100.00	50
	To apply Rust Proofing , reseal tuff-coating treatment on accident area	\$ 120.00	60

Total Parts & Labour of estimate for damaged vehicle

\$ 17,134.00

Total amount in Lump Sum Basis for repaired vehicle

SDLS: _____



M/s Liu's Brother Auto Engrg Wks

not allowed
LKK
11/7/18

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____