



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE KIA PTE LTD**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684567 Fax: 65651240

**ESTIMATE**

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
CHOW CHEE ON  BLK 53 KENT RD #02-12 210053  Contact No Mobile: 93808288	Cust No/Name	/MR CHOW CHEE ON
	Reg No/Reg Date	SKQ6291S / 16/12/201
	Date In/Mileage	/ 0
	Chassis No	KNAFX411MF5347135
	Engine No	G4FGEH747820
	Make/Model	KIA/FORTE K3 1.6 A EX GB43 BLACK
	Colour/Trim	K3N / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00081	Cash	12/07/2018/ 09:49	QUD	247 / DonBong	31778			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								550 2200.00
RENEW & RE-ALIGN RR DAMAGED PORTION:								
RENEW RR BUMPER								
REPAIR BOOTLID , RR END PNL , LHR FENDER								420
E PNT98000								2100.00
RESPRAY RR BUMPER , RR END PNL , BOOTLID AND LHR FENDER								
E PNT88000								60 150.00
REMOVE & REFIT RR FLR BOARD,TRIM & CARPET TO FACILITATE REPAIR								
A 54900099								30 50.00
CHECK WIRING & ELECTRICAL SYSTEM								
A 10028901								✓ 200.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST								
USING HI-SCAN PRO TEST								
M SUNDRY								x 80.00
APPLY ANTI CORROSION ON AFFECTED AREAS								
E PNT88000								60 100.00
REMOVE & REFIT REVERSE SENSOR								
M SUNDRY								aw ✓ 220.00
TO SUPPLY REVERSE SENSOR								
M SUNDRY								x 50.00
TO SUPPLY C&C BADGE								
M SUNDRY								20 30.00
Sundries								
M COVER-RR BUMPER					1.00	768.00	00.00	de ✓ 768.00
M COVER-RR BUMPER,UPR					1.00	234.00	00.00	de ✓ 234.00
M BEAM-RR BUMPER					1.00	365.00	00.00	? 365.00
M STAY-RR BUMPER LH					1.00	75.00	00.00	? 75.00
M STAY-RR BUMPER RH					1.00	75.00	00.00	? 75.00
M BRACKET-RR BUMPER SIDE MTG,LH					1.00	33.00	00.00	new ✓ 33.00
M BRACKET-RR BUMPER SIDE MTG,RH					1.00	33.00	00.00	new ✓ 33.00
M LAMP ASSY-REAR COMBINATION,LH					1.00	302.00	00.00	x 302.00
M LOGO ASSY-KIA SUB					1.00	37.00	00.00	x 37.00
M EMBLEM-CERATO					1.00	35.00	00.00	x 35.00

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684567 Fax: 65651240



ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Table with 2 main columns: Invoice Name & Address, Owner Name & Vehicle Info. Includes details for CHOW CHEE ON and vehicle specifications like Reg No, Date, Chassis No, Engine No, Make/Model, and Colour/Trim.

Table with 6 columns: Account No, Terms, Date/Time Printed, CSE, Operator, WIP No. Row 1: CSM00081, Cash, 12/07/2018/ 09:49, QUD, 247 / DonBong, 31778

Table with 4 columns: Description of Goods / Services, Qty, Unit Price, Disc%, Amount. Row 1: M EMBLEM K3, 1.00, 15.00, 00.00, 15.00

Estimate

SURVEYOR NAME: Tanjun 97495749

SURVEYOR SIGNATURE: [Signature]

DATE: 12/7/18 @ 1640

REMARKS: Resurvey before paint 03 days surc@klands.com

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company
Acknowledged by Repairer
Signature:
Date:

Summary table: 7% GST on 7152.00, Total Payable 7,652.64

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.