

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHB 4162J

MAKE :

MODEL : HYUNDAI i40

AIG/LKK

DATE 11/7/2018 11:29

REAR

Tz

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper <i>Detached</i>			\$ 603.60	
	Rear Bumper Reinforcement <i>25m</i>			\$ 504.35	
	Rear Bumper Reinforcement Bracket (LH/RH) <i>25m</i>		\$ 180.00	\$ 360.00	
	Rear Bumper Side Bracket <i>25m</i>			\$ 49.00	
	Rear Bumper Clips <i>x 22</i>			\$ 22.00	
	Rear Bumper Sponge <i>25m</i>			\$ 143.40	
	Rear Bumper Under Cover <i>cut</i>			\$ 225.00	
	SUB TOTAL			\$ 1,907.35	
	LESS 20%			\$ 381.47	
	DISCOUNTED TOTAL			\$ 1,525.88	
	Rear Bumper Reverse Sensor <i>x 22</i>			\$ 135.70	Nett
	Rear Bumper Advertisement Logo <i>1 m</i>			\$ 50.00	Nett
	Rear Fender Advertisement Logo (LH/RH) <i>1 m</i>		\$ 100.00	\$ 200.00	Nett
				\$ 385.70	
	Labour Charge				
	Panel Beating			\$ 350.00 <i>200</i>	
	Spray Painting Charge			\$ 250.00 <i>200</i>	
	Wiring Charge			\$ 50.00 <i>x 22</i>	
	R/Refix Reverse Sensor			\$ 120.00 <i>x 22</i>	
	TOTAL LABOUR			\$ 770.00	
	ESTIMATE TOTAL			\$ 2,681.58	
<i>Kahar Ulla</i> <i>11/7/18 1530 hrs.</i> <i>2 Days</i> <i>4s</i> <i>After Repair p LK</i>					
LKK Auto Consultants hence notify the Repairer of the following: - To resurvey before/after spray painting - To display damaged part(s) during resurvey - Parts prices are subject to confirmation - Third party survey is on a "Without Prejudice" basis - No illegal modification(s) is allowed - Supplementary repair must be resurveyed and is subject to final approval from insurance Company Acknowledged by Repairer Signature: _____ Date: _____					
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					