



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R


Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS/AIG18012718/R1vbe2

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 15-08-2018



ATTN :SHAWN WUI

Code : AIG

1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)

Insured Veh.	SBB 1998E	Veh. Inspected	XE 2148J
Policy No.	2100420518-02000	Coverage (\$)	0.00
Claim No.	9766028768SG-003	Excess (\$)	0.00
Assign From	SHAWN WUI	Assign Date	11/07/2018

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ ACTROS	c.c	11946
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	WDB9321612L910329	Colour	MULTI COLOUR
Odometer	72471	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	315/80 R22.5	BRIDGESTONE	8 mm
L/H Front Tyre	315/80 R22.5	BRIDGESTONE	8 mm
R/H Rear Tyre	315/80 R22.5 (D)	BRIDGESTONE	8/8 mm
L/H Rear Tyre	315/80 R22.5 (D)	BRIDGESTONE	8/8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	31/07/2017	Inspection Date	18/07/2018
Survey held at	16 TUAS SOUTH ST 7		
Repairer	N-51 AUTOMOTIVE PL		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **6 Working Days**