

CHUNNI MOTOR WORK PTE LTD**REPAIR ESTIMATE***

So Survey by Bryan [KKK]

VEHICLE NO : SH 7728X

DATE : 10.07.2018

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039

AIG

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Headlamp (LH) <i>mounting crack</i>			\$ 1,388.00	✓
	Front Fender (LH) <i>Bnc</i>			\$ 619.00	✓
	Front Fender Shield (LH) <i>deformed</i>			\$ 169.80	✓
	Front Door (LH) <i>denture</i>			\$ 1,403.00	✓
	Front Door Rubber <i>hbc</i>			\$ 290.50	✓
	Front Door Gear / Regulator (LH) <i>hbc crack</i>			\$ 785.50	✓
	Front Door Hinge Upper (LH) <i>2 HNL</i>			\$ 53.40	2 X
	Front Door Hinge Lower (LH) <i>2 HNL</i>			\$ 53.40	2 X
	Front Door Check (LH) <i>2 HNL</i>			\$ 110.15	2 X
	Front Door Mirror (LH) <i>hbc</i>			\$ 980.50	X
	Front Door Power Motor <i>hbc</i>			\$ 950.90	X
	Door Centre Pillar Outer (LH) <i>denture</i>			\$ 1,786.20	photo
	Front Windscreen Moulding <i>hbc</i>			\$ 60.00	✓
	Front Windscreen Pillar Outer (LH) <i>denture</i>			\$ 1,843.10	photo
	Front Wheel Rim (LH) <i>2 denture</i>			\$ 351.90	2 ✓
	Front Wheel Hub Cap (LH) <i>2</i>			\$ 150.70	✓
	Front Wheel Bearing <i>2 down</i>			\$ 258.50	2 ✓
	Front Shock Absorber (Assy) (LH) <i>2 distorted</i>			\$ 342.20	2 ✓
	Front Shock Absorber Mounting (LH) <i>hbc</i>			\$ 75.10	X
	Front Drive Shaft (LH) <i>hbc distorted</i>			\$ 1,069.55	2 ✓
	Rack & Pinion Assy <i>hbc distorted</i>			\$ 2,184.00	X ✓
	STG Tie End <i>2 distorted</i>			\$ 69.50	2 ✓
	Front Suspension Lower Arm (LH) <i>2 distorted</i>			\$ 715.10	2 ✓
	Knuckle Arm (LH) <i>2 distorted</i>			\$ 582.95	2 ✓
	Engine Under Cover <i>hbc</i>			\$ 343.10	X
	Engine Crossmember <i>hbc distorted</i>			\$ 2,236.90	2 ✓
	Electric Power Steering <i>hbc</i>			\$ 4,880.50	X
	SUB TOTAL			\$ 23,753.45	
	LESS 20%			\$ 4,750.69	
	DISCOUNTED TOTAL			\$ 19,002.76	
	Front Fender Advertisement Logo (LH) <i>crd</i>			\$ 100.00	Nett ✓
	Front Door Comfort Logo (LH) <i>hbc</i>			\$ 75.00	Nett ✓
	Front Door Advertisement Logo (LH) <i>crd</i>			\$ 100.00	Nett ✓
	Front Windscreen Sealant <i>hbc</i>			\$ 46.00	Nett ✓
	Front Tyre (LH) <i>3vc</i>			\$ 216.00	Nett X
				\$ 537.00	

SH 7728X

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper <i>Replaced</i>			\$ 603.60	✓
	Rear Bumper Clip 10 pcs <i>h/c</i>			\$ 22.00	✓
	Rear Bumper Bracket, LH <i>h/c</i>			\$ 49.00	X
	Rear Door (LH) <i>Replaced</i>			\$ 1,351.10	✓
	Rear Tyre Rim (LH) <i>h/c</i>			\$ 351.90	X
	Rear Wheel Hub-Cap (LH) <i>h/c</i>			\$ 150.70	✓
	Rear Wheelbearing ING & Hub <i>2 Down</i>			\$ 401.40	✓
	Rear Trailing Arm (LH) <i>2 distal</i>			\$ 120.00	✓
	Rear Assist (LH) <i>2 distal</i>			\$ 120.00	✓
	Rear Shock Absorber (LH) <i>2 distal</i>			\$ 342.20	✓
	Rear Shock Absorber Mounting (LH) <i>h/c</i>			\$ 57.70	X
	Rear Upper Arm (LH) <i>2 distal</i>			\$ 335.75	✓
	Rear Lower Arm (LH) <i>2 distal</i>			\$ 204.35	✓
	Rear Knuckle Arm (LH) <i>2 distal</i>			\$ 574.80	✓
	SUB TOTAL			\$ 4,684.50	
	LESS 20%			\$ 936.90	
	DISCOUNTED TOTAL			\$ 3,747.60	
	Rear Bumper Advertisement Logo <i>h/c</i>			\$ 50.00	Nett ✓
	Rear Bumper Rubber Mat <i>h/c</i>			\$ 50.00	Nett ✓
	Rear Fender Advertisement Logo (LH/RH) <i>h/c</i>		\$ 100.00	\$ 200.00	Nett ✓
	Rear Door Advertisement Logo (LH) <i>cst</i>			\$ 100.00	Nett ✓
	Rear Door Comfortdelgro & Apps Sticker (LH) <i>h/c</i>			\$ 80.00	Nett ✓
	Rear Tyre (LH) <i>SVL</i>			\$ 216.00	Nett X
				\$ 696.00	
	Labour Charge				
	Panel Beating			\$ 2,200.00	800/-
	Spray Painting Charge			\$ 1,750.00	800/-
	Wiring Charge			\$ 100.00	30/-
	Tuff Kote			\$ 150.00	40/-
	Towing Charge			\$ 50.00	4H
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00	4H
	Transfer of Door		\$ 120.00	\$ 240.00	120/-
	Remove/Refix Undercarriage (FRT)			\$ 200.00	150/-
	Remove/Refix Undercarriage (RR)			\$ 200.00	150/-
	Four Wheel Alignment			\$ 120.00	60/-
	Remove/Refix Dashboard			\$ 350.00	4H
	Remove/Refix Front Windscreen Glass			\$ 120.00	80/-
	Remove/Refix Cushion & Upholstery Front			\$ 90.00	4H
	TOTAL LABOUR			\$ 5,720.00	
	ESTIMATE TOTAL			\$ 29,703.36	

LKK Auto Confirm
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) for resurvey
 • Parts prices are subject to resurvey
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.