

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHC4684P
Ref. No : TAX/07/18/2040
Reg. Date : 10/09/2014
Vehicle Type : TAXI
Make : TOYOTA PRIUS
Model : PRIUS
Name of Driver : TAN AI BEE
Type of Accident : SIDE SWIPE
Date / Time of Accident : 10/07/2018 11:30:00 AM
Accident Reported Date / Time : 10/07/2018 12:00:00 AM
Surveyor is Required? : Yes
Survey by :
Vehicle is Towed Back? : No
Towed Back Date/Time :
Replacement Vehicle issued? : No
Accident Repair Job Card No : 000024096936
Special Instruction to ARC, if any :
SJV7455R
Prepared Date : 10/07/2018 05:05:01 PM



Sathya Sai

11/7/2018

- Lump Sum Repair
- Photo after paint

3 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U405748758

Mileage

: 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates**Quotation from ARC****Adjusted by Surveyor, if applicable**

Total Labour Charges	:	845.00	0.00
Total Spray Painting Charges	:	1,674.00	0.00
Total Material Charges	:	3,684.50	3,684.50
Other Charges	:	820.00	0.00
TOTAL	:	7,023.50	0.00
Lum Sum Total	:	7,000.00	0.00
No. of Repair Days	:	6.00	0.00 3 days
Prepared / Adjusted By	:		
Arc / Surveyor Sing Off Date	:	10/07/2018 06:23:18 PM	01/01/1900 12:00:00 AM

Prepared / Adjusted Date :

Remarks :

Prepared Date : 10/07/2018 06:23:18 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount : 0.00

Prepared Date : 7/10/2018 6:23:41 PM

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR LH PORTION	845.00	0.00 600
Total Labour	845.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	378.00	0.00 200
TO RESPRAY FRONT FENDER LH	378.00	0.00 200
TO RESPRAY RIM	180.00	0.00 100
TO RESPRAY ROCKER PANEL MOULDING	180.00	0.00 100
TO RESPRAY FRONT DOOR LH	378.00	0.00 200
TO RESPRAY VIEW MIRROR	180.00	0.00 80
Total Spray Painting & Panel Beating	1,674.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 40
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 50
TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0.00 60
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	0.00 60
TO REMOVE AND REFIT TYRE	120.00	0.00 50
TO REPLACE SUNDRY PARTS	100.00	0.00 20
TO WASH AND VACUUM	60.00	0.00 X
TO REMOVE AND REFIX WING MIRROR	120.00	0.00 50
Total Other Costs	820.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
52119-47930		6505517	BUMPER FRT <i>R</i>	1	482.00	25.00	361.50	Replace	Replace	No
53802-47050		6505558	FENDER FRT/LH <i>✓DT</i>	1	723.40	25.00	542.55	Replace	Replace	No
75374-47051			NAME PLATE (HYBRID) <i>✓NEC</i>	1	51.90	25.00	38.92	Replace	Replace	No
53876-47030		6505554	FENDER LINER FRT/LH <i>✓Deform</i>	1	171.70	25.00	128.77	Replace	Replace	No
42611--47140 (Frt)		6505658	WHEEL DISC. FRONT <i>R</i>	1	1,484.20	25.00	1,113.15	Replace	Replace	No
		6503707	TYRE <i>X</i>	1	126.74	0.00	126.74	Replace	Replace	No
75852-47900			MOULDING BODY, LH <i>R</i>	1	673.60	25.00	505.20	Replace	Replace	No
67002-47070		6505529	DOOR FRT/LH <i>R</i>	1	894.40	25.00	670.80	Replace	Replace	No
			STICKER DECAL SMRT (DOOR) <i>✓NEC</i>	1	60.00	0.00	60.00	Replace	Replace	No
87940-47310		6505599	MIRROR ASSY, LH <i>X</i>	1	1,224.90	25.00	918.67	Replace	Replace	No
81740-52040		6505465	MIRROR LAMP LH <i>✓SCR</i>	1	65.30	10.00	58.77	Replace	Replace	No
87945-74010		6505597	COVER, OUTER MIRROR, LH <i>✓SCR</i>	1	107.40	25.00	80.55	Replace	Replace	No
TOTAL MATERIALS								4,605.64	4,605.62	
TOTAL MATERIALS(Discounted)								3,684.50	3,684.50	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									