

ASS. REC. BY:

REF CS/FCI18012740/Kxd3 n2

Surveyor

ASSIGNMENT (Office)

From (Person):

Kenneth
May Chua

of

FCI

Date/Time:

12/7/18 @ 5:27pm

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SDF 8 A

Insured:

SH 9240Y

at Workshop m/s:

City Auto

Tel:

64 531235

of

Blk 160, Sin Ming Drive #05-01

Policy No:

Claim No:

D8085322MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

09/07/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS (DS)

H.O.D. Endorsement:

Date/Time:

5:37pm @ 12/7/18

Person Contacted:

Viviana

Vehicle IN (OUT)

Date/Time

Action/Instruction (✓) Estimate

SDF 8 A - CS/FCI13016741 / Tlv m3k3

DOA: 05/09/2013

SH 9240Y - CC3/AIG16016405 / Hly m3q2

DOA: 29/08/2016

18/1/18

Email preli revised to FCI

26/7

01775.90

Car Insured

(Red

15,255.99,

8960

(No LS)

REF: FCI

ASSIGNMENT

From Date: 17072018
 Estimated Cost:
 OD: TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: SDF 8A
 at Workshop m/s: City Auto
 of: Blk 8 Sim ming # 01-60
 Insured:
 Policy No:
 Claims No:
 Sum Insured: Excess:
 (Client's Record)
 Make of Veh:

11am

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

Bal. or Market Value: \$700k
 IDAC Accident Report: Consistent? : Yes or No
 GIA / PR Seen: Consistent? : Yes or No
 Est. Repairs: 04 days Res.: Yes or No
 Lum Sum: 1.31 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SDI-8A Yr Regn: 04 13
 Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Rolls Royce
 Colour: M.P. White A/C: Insured / Std / NI / NA
 Sp. Reading: 56680 T/Radio: Insured / Std / NI / NA
 Eng/No:
 C/No: SC A664 L0 PCULT22635
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 255/45R20
 R: 285/40R20
 FS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front: R/Bal: 5 mm
 L/Bal: 5 mm
 D.O.I: 9/7/18
 Rear: R/Bal: 7 mm
 L/Bal: 7 mm
 D.O.I: 17/7/18
 Survey held at:
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 O/S Area
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

18/7 File passed to Coroner

26/7/2018

RECEIVED 26 JUL 2018

Date/Time: File Pass to?

☐ : Prelim. Report
☐ : Final Report

1)

Date/Time: File Return to?

3) 06/7- typist

Report Format:

CWS

Lump Sum / L.B. (\$) :

1775.90

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee:

☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech Invs (\$)
☐ Weekend (\$)

Survey Fee:

Transportation:

) \$ - R\$ - SI

) Photos

) Others:

TOTAL

7x15 = 105

170 + 105

50

50

14

389



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18012740/Kvd3	
36 ROBINSON ROAD #16-01 CITY HOUSES SINGAPORE 068877			Date : 13-07-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 9240Y	Veh. Inspected	SDF 8A	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18005322MFSH	Excess (\$)	0.00	
Assign From	CWS (MAY CHUA)	Assign Date	13/07/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	09/07/2018	Inspection Date		
Survey held at	CITY AUTO PTE LTD BLK 8, SIN MING IND. ESTATE #01-60/62 SIN MING ROAD SINGAPORE 575643.			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAVA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18005322MFSH

Our ref: CS/FCI18012740/Kvd3

Date : 18/7/2018

The Motor Claims Department
M/s FIRST CAPITAL INSURANCE LTD

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SDF 8A


We thank for your instruction on 12/7/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 17/7/2018 at the premises of M/s CITY AUTO PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$17,031.89
Revised Estimate Amount	: S\$1,775.90
"Check" Items Amount	: S\$1,199.21
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the
o/s rear portion



Comments/Present Status:

Damages Consistent

Yours faithfully,

Kenneth Kong
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	10-07-2018	Our Ref No. D18005322MFSH
Accident Date	09-07-2018	Claim Type. Third Party
Insured Vehicle	SH9240Y	Third Party Vehicle. SDF8A
Survey Location	BLK 160, SIN MING DRIVE, SIN MING AUTO CITY #05-01	
Contact Person.	VRONICA LAW	
Contact No.	64531235/ 0	Fax No. 64537944
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CITY AUTO PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/242238)



PRI Documents



Close



PRI Header Details

Claim No	D18005322MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & CITY AUTO
Workshop Name	CITY AUTO PTE LTD (Contact Person : VRONICA LAW)	Survey Location & Contact Details	BLK 160, SIN MING DRIVE, SIN MING AUTO CITY #05-C Mobile: 0 , Phone: 64531235 , Fax: 64537944 EmailId: CITYAUTO@SINGNET.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SH9240Y	TP Vehicle No	SDF8A
PRI Recieved Date	12-07-2018 04:53:54 PM	Surveyor Appointed Date	12-07-2018 05:26:16 PM	Surveyor Accept Date	12-07-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	12-07-2018	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 18 July 2018 4:34 PM
To: 'Claim Workflow System'
Cc: MAYCHUA@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18005322MFSH/1, SDF 8 A
Attachments: SDF 8A PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SDF 8 A
Date of survey: 17/7/2018
Number of days :4 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Thursday, 12 July 2018 5:35 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: MAYCHUA@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18005322MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 12 July 2018 5:27 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; MAYCHUA@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18005322MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



AVG

This email has been checked for viruses by AVG antivirus software.
www.avg.com



CITY AUTO PTE LTD

One Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643

TEL: 6453 1235, 6452 0850 FAX: 6453 7944

24hrs Towing Services Tel: 9823 9898

Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

Estimate : QUOT201807-000206(00)

MS FIRST CAPITAL INSURANCE LTD

NO. 36

ROBINSON RD

CITY HOUSE

SINGAPORE 068877

Contact : 68685186/98522809

Fax No. : 6507 3849

Date : 11/07/2018

Vehicle No. : SDF8A

Make/Model : ROLLS ROYCE GHOST EWB

Mileage (km) : 0

Chassis No. : SCA664L09CUH22635

Accident Date : 09/07/2018 00:00:00

Claim No. : SH8240Y

Reference : SDF8A

Policy No. : SI18V03666

*Not Authorized
Resurvey After Paint
4 days*

S/No	Particular	Quantity	Unit Price	Amount S\$
------	------------	----------	------------	------------

LIST ITEMS :

1	Rear RH fender	1.0	5,455.56	R 5,455.56 X
2	Rear RH fender lower garnish	1.0	1,262.33	Sn 1,262.33 X
3	Rear RH fender sticker	1.0	522.00	Sn 522.00 ✓
4	Rear bumper	1.0	2,072.83	R 2,072.83 X
5	Rear bumper retainer	1.0	223.80	Sn 223.80 X
6	Rear windscreen glass moulding	1.0	352.00	na 352.00 X
7	Rear exhaust chrome	1.0	652.00	Sn 652.00 X
8	RH rear rim	1.0	3,500.00	Sn 3,500.00 X
9	Quarter glass moulding	1.0	298.32	na 298.32 X
List Total :				14,338.84
5. % Discount S\$				716.95
				13,621.89

SPECIAL NET :

1	Rear windscreen glass sealant	1.0	80.00	na 80.00 X
2	Rear bumper stone guard	1.0	180.00	na 180.00 ✓
SPECIAL NET Total S\$:				260.00

LABOUR :

*Labour charge to remove and install rear windscreen	1.0	300.00	na	300.00	X
*Computerized wheel alignment	1.0	150.00	na	150.00	X
-To knock jackout damaged parts, panel beating, welding, align, refix and to renew accident parts	1.0	1,500.00		1,500.00	5001
- Spray painting on affected & replace parts	1.0	900.00		900.00	6001
*To remove and refill of fuel tank	1.0	300.00	na	300.00	X
				<u>3,150.00</u>	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

CONTINUE NEXT PAGE



CITY AUTO PTE LTD

One Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643
TEL: 6453 1235, 6452 0850 FAX: 6453 7944
24hrs Towing Services Tel: 9823 9898
Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

MS FIRST CAPITAL INSURANCE LTD

NO. 36
ROBINSON RD
CITY HOUSE
SINGAPORE 068877

Contact : 68685186/98522809

Fax No. : 6507 3849

Estimate : QUOT201807-000206(00)

Date : 11/07/2018

Vehicle No. : SDF8A

Make/Model : ROLLS ROYCE GHOST EWB

Mileage (km) : 0

Chassis No. : SCA664L09CUH22635

Accident Date : 09/07/2018 00:00:00

Claim No. : SH8240Y

Reference : SDF8A

Policy No. : SI18V03666

S/No	Particular	Quantity	Unit Price	Amount S\$
------	------------	----------	------------	------------

E. & O.E.

Total S\$ 17,031.89

GST 7% S\$ 1,192.23

Amount Due S\$ 18,224.12


for CITY AUTO PTE LTD



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18012740/Kvd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 01-08-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 9240Y	Veh. Inspected	SDF 8A	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18005322MFSH	Excess (\$)	0.00	
Assign From	MAY CHUA	Assign Date	12/07/2018	
2. Vehicle Particulars & Condition				
Make & Model	ROLLS ROYCE (A)	c.c	6592	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	SCA664L09CUH22635	Colour	METALLIC PEARL WHITE	
Odometer	96680	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	255/45 R20	GOODYEAR	5 mm	
L/H Front Tyre	255/45 R20	GOODYEAR	5 mm	
R/H Rear Tyre	285/40 R20	GOODYEAR	7 mm	
L/H Rear Tyre	285/40 R20	GOODYEAR	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	09/07/2018	Inspection Date	17/07/2018	
Survey held at	CITY AUTO PTE LTD BLK 8, SIN MING IND. ESTATE #01-60/62 SIN MING ROAD SINGAPORE 575643.			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDF 8A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR RH FENDER	TO REPAIR SEE LABOUR	5,455.56	-
1	REAR RH FENDER LOWER GARNISH	SERVICEABLE	1,262.33	-
1	REAR RH FENDER STICKER	NECESSARY	522.00	522.00
1	REAR BUMPER	TO REPAIR SEE LABOUR	2,072.83	-
1	REAR BUMPER RETAINER	SERVICEABLE	223.80	-
1	REAR WINDSCREEN GLASS MOULDING	NOT NECESSARY	352.00	-
1	REAR EXHAUST CHROME	SERVICEABLE	652.00	-
1	RH REAR RIM	SERVICEABLE	3,500.00	-
1	QUATER GLASS MOULDING	NOT NECESSARY	298.32	-
	LESS 5% DISCOUNT		-716.95	-26.10
			13,621.89	495.90
SPECIAL NETT ITEMS				
1	REAR WINDSCREEN GLASS SEALANT (SN)	NOT NECESSARY	80.00	-
1	REAR BUMPER STONE GUARD (SN)	NECESSARY	180.00	180.00
			260.00	180.00
LABOUR				
	LABOUR CHARGE TO REMOVE AND INSTALL REAR WINDSCREEN.	NOT NECESSARY	300.00	-
	COMPUTERIZED WHEEL ALIGNMENT .	NOT NECESSARY	150.00	-
	TO KNOCK JACKOUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN, REFIX AND TO RENEW ACCIDENT PARTS.INCLUSIVE OF THE REPAIR OF REAR RH FENDER AND REAR BUMPER .		1,500.00	500.00
	SPRAY PAINTING ON AFFECTED & REPLACE PARTS.		900.00	600.00
	TO REMOVE AND REFILL OF FUEL TANK .	NOT NECESSARY	300.00	-
	-		-	-
	-		-	-
	-		-	-
			3,150.00	1,100.00
GRAND TOTAL			17,031.89	1,775.90

Report Ref No. CS/FCI18012740/Kvd3n2



RECOMMENDED COST OF REPAIRS			1,775.90
-----------------------------	--	--	----------

Report Ref No. CS/FCI18012740/Kvd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.