

21052901

ASS. REP. BY:

REP: CS/FCI 18012741 / Avd3 n2

Special Instruction:

Surveyor:  
CWS

Adrian

ASSIGNMENT (Office)

From (Person)

Sithara

of

FCI

Date/Time:

12/7/18 @ 5:35pm

Estimated Cost:

Bill to:

OD  WS / TP RES / OD RES / PVA / INV / MV / CS

To Inspect Vehicle No:

SLW 2008C

Insured:

SHA 0811B

at Workshop no/:

Tick Hai Motor

Tel:

68429089/

of

Ikaki Bukit Ave 6 # 01-54 Autobay

Policy No:

Claim No:

D18005358 MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

09/07/2018

CA / REV / REP. / REV 24 HRS

(up)

16/07/2018 @

H.O.D. Endorsement:

Date/Time:

13/7/18 @ 9:20am

Person Contacted:

Connie

Vehicle IN /

OUT

Date/Time

Action/Instruction (✓) Estimate

SLW 2008C - X

SHA 0811 B - NS/INC18010093/K/tbn2

D.O.A: 30/05/2018

17/7/18

Informed FCI pending workshop est by email

16/11/18

Adrian confirmed LS \$2300 (Red 4313.30, 65%)

16/11/18

Email preli revised to FCI

ASSIGNMENT

From: Date: 16/7/2018

Estimated Cost:

On (TP) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLW 2008 C  
at Workshop m/s Tick Hai Motor  
of 1 Kaki Bkt Ave 6 #01-54 Autobay

Insured:

Policy No.:

Claims No.:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS <sup>lup</sup>

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SLW2008C Yr Regn: 2018 / Jan

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Civic c.c 1597

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 15820 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: MRHFC5650HT000858

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/55R16

R: 215/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Hancock.

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. D.O.I. 16/07/18

Survey held at Tick Hai

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Front N/S.

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP / 1st Cap.

RECEIVED 19 NOV 2018

Date/Time, File Pass to?

: Preli. Report

Days Of Repair: 4

1)

: Final Report

Resurvey No. of Trip: 2

Date/Time, File Return to?

2) 16/11 - typist

Add Fee:

: Site Insp (\$

: Interview (\$

: Tech. Invs (\$

: Weekend (\$

Survey Fee:

Transportation:

\_\_\_\_ S + RS, \_\_\_\_ SI

Photos

Others

TOTAL

145
50
50+50
52
347

Report Format: CWS

Lump Sum / I.B.I: (\$ 2300 1/2 )



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18012741/Avd3

36 ROBINSON ROAD  
#16-01 CITY HOUSESINGAPORE 068877

Date : 13-07-2018



Code : FCI2

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 811B	Veh. Inspected	SLW 2008C
Policy No.		Coverage (\$)	0.00
Claim No.	D18005358MFSH	Excess (\$)	0.00
Assign From	CWS (SITHARA)	Assign Date	13/07/2018

## 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	09/07/2018	Inspection Date	
Survey held at	TICK HAI MOTOR & WELDING SERVICES BLK 1 KAKI BUKIT AVE 6 #01-54 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18005358MFSH

Our ref: CS/FCI18012741/Avd3

Date : 16/11/2018

The Motor Claims Department  
MS FIRST CAPITAL INSURANCE LTD

Dear Sir/Madam,

**INITIAL INSPECTION REPORT OF VEHICLE NO. SLW 2008C**


We thank you for your instruction on 12/7/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 16/7/2018 at the premises of M/s TICK HAI MOTOR & WELDING SERVICES and have the following to report:-

Workshop Estimate Amount	: S\$6,613.30
Revised Estimate Amount	: S\$2,300.00 (Lump Sum)
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

**Description of Damage:**

The vehicle sustained damages at the front n/s portion



**Comments/Present Status:**

Damages Consistent

Yours faithfully,

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**MOTOR SURVEY ASSIGNMENT**

<b>Date</b>	11-07-2018	<b>Our Ref No.</b> D18005358MFSH
<b>Accident Date</b>	09-07-2018	<b>Claim Type.</b> Third Party
<b>Insured Vehicle</b>	SHA0811B	<b>Third Party Vehicle.</b> SLW2008C
<b>Survey Location</b>	1 Kaki Bukit Avenue 6 #01-54Autobay @ Kaki Bukit	
<b>Contact Person.</b>	MS CONNIE SEE	
<b>Contact No.</b>	68429089/ 0	<b>Fax No.</b> 0
<b>Survey Type</b>	WITHOUT PREJUDICE:	
<b>Appointed Surveyor</b>	LKK AUTO CONSULTANTS PTE LTD	
<b>Contact Person</b>	NA	<b>Fax No.</b> 68416315
<b>Contact Number.</b>	NA	

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**THIRD PARTY SURVEY REQUEST**

<b>Cc : Workshop</b>	TICK HAI MOTOR & WELDING SERVICES	<b>Attention.</b> NIL
<b>Cc : TP Solicitor</b>	ARIDAS & ASSOCIATES	<b>TP Solicitor Fax No.</b> NA
<b>Officer Incharge</b>	SITHARA	

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/242287)



PRI Documents



Close



## PRI Header Details

<b>Claim No</b>	D18005358MFSH	<b>Policy No</b>	D-18088937MFSH	<b>Claimant S.No &amp; Name</b>	1 & ARIDAS &
<b>Workshop Name</b>	TICK HAI MOTOR & WELDING SERVICES (Contact Person : MS CONNIE SEE)	<b>Survey Location &amp; Contact Details</b>	1 Kaki Bukit Avenue 6 #01-54Autobay @ Kaki Bukit <b>Mobile:</b> 0 , <b>Phone:</b> 68429089 , <b>Fax:</b> 0 <b>EmailId:</b> ARIDASV@SINGNET.COM.SG		
<b>Our Surveyor</b>	LKK AUTO CONSULTANTS PTE LTD	<b>Instructions To Surveyor</b>	WITHOUT PREJUDICE:		
<b>Insured Name</b>	CITYCAB PTE LTD	<b>Insured Vehicle No</b>	SHA0811B	<b>TP Vehicle No</b>	SLW2008C
<b>PRI Recieved Date</b>	11-07-2018 08:45:46 PM	<b>Surveyor Appointed Date</b>	12-07-2018 05:33:38 PM	<b>Surveyor Accept Date</b>	13-07-2018 0

## Survey Report Upload

<b>Surveyor Inspection Date *:</b>	<input type="text"/>	<b>Surveyor Report Date</b>	13-07-2018	<b>Upload Survey Report *:</b>	<input type="button" value="Choose File"/>
------------------------------------	----------------------	-----------------------------	------------	--------------------------------	--

## Vehicle Particulars

<b>Make</b>	<input type="text" value="Please Select Make"/>	<b>Model</b>	<input type="text" value="Please Select Model"/>	<b>Year</b>	<input type="text" value="Select Year"/>
<b>Chasis No</b>	<input type="text"/>	<b>Engine No</b>	<input type="text"/>	<b>Mileage</b>	<input type="text"/>
<b>Color</b>	<input type="text"/>	<b>Cubic Capacity</b>	<input type="text"/>		

## Multiple Documents Upload

<input type="button" value="Upload Multiple Documents"/>	
<b>File Name</b>	<b>Action</b>

## Surveyor Job Remarks

<b>Remarks</b>	<input type="text"/>	<input type="button" value="Save"/>
----------------	----------------------	-------------------------------------

## Veron Chen (LKKAuto)

---

**From:** Veron Chen (LKKAuto)  
**Sent:** Friday, 16 November 2018 4:39 PM  
**To:** 'Claim Workflow System'  
**Cc:** 'SITHARA@MSFIRSTCAPITAL.COM.SG'; SUR  
**Subject:** RE: SURVEY ASSESSMENT - D18005358MFSH/1, SLW 2008C  
**Attachments:** SLW 2008C PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SLW 2008C  
Date of survey: 16/7/2018  
Number of days : 4 days

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Veron Chen (LKKAuto)  
**Sent:** Tuesday, 17 July 2018 9:05 AM  
**To:** 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>  
**Cc:** SITHARA@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>  
**Subject:** RE: SURVEY ASSESSMENT - D18005358MFSH/1, SLW 2008C

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SLW 2008C on 16/7/2018 .

We are pending estimate from repairer.

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAuto)  
**Sent:** Friday, 13 July 2018 9:40 AM  
**To:** 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>  
**Cc:** SITHARA@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>  
**Subject:** RE: SURVEY ASSESSMENT - D18005358MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]

**Sent:** Thursday, 12 July 2018 5:35 PM

**To:** [ASSIGNMENTS@LKKAUTO.COM](mailto:ASSIGNMENTS@LKKAUTO.COM)

**Cc:** [CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG](mailto:CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG); [SITHARA@MSFIRSTCAPITAL.COM.SG](mailto:SITHARA@MSFIRSTCAPITAL.COM.SG)

**Subject:** PRI: SURVEY ASSESSMENT - D18005358MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

**PS: This is a system generated mail. Please do not reply to this mail.**



This email has been checked for viruses by AVG antivirus software.  
[www.avg.com](http://www.avg.com)

## Veron Chen (LKKAuto)

---

**From:** Veron Chen (LKKAuto)  
**Sent:** Tuesday, 17 July 2018 9:05 AM  
**To:** 'Claim Workflow System'  
**Cc:** SITHARA@MSFIRSTCAPITAL.COM.SG; SUR  
**Subject:** RE: SURVEY ASSESSMENT - D18005358MFSH/1, SLW 2008C

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SLW 2008C on 16/7/2018 .

We are pending estimate from repairer.

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAuto)  
**Sent:** Friday, 13 July 2018 9:40 AM  
**To:** 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>  
**Cc:** SITHARA@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>  
**Subject:** RE: SURVEY ASSESSMENT - D18005358MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

**G.Nivitha** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]  
**Sent:** Thursday, 12 July 2018 5:35 PM  
**To:** [ASSIGNMENTS@LKKAUTO.COM](mailto:ASSIGNMENTS@LKKAUTO.COM)  
**Cc:** [CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG](mailto:CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG); [SITHARA@MSFIRSTCAPITAL.COM.SG](mailto:SITHARA@MSFIRSTCAPITAL.COM.SG)  
**Subject:** PRI: SURVEY ASSESSMENT - D18005358MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,  
Admin Team  
Claim Workflow System  
Motor Claims Department  
MS First Capital Insurance Limited  
Tel : 6507 3848  
Fax : 6507 3849

**PS: This is a system generated mail. Please do not reply to this mail.**



**AVG**

This email has been checked for viruses by AVG antivirus software.  
[www.avg.com](http://www.avg.com)

**TICK HAI MOTOR & WELDING SERVICES**  
**1 KAKI BUKIT AVE 6 #01-54 SINGAPORE 417883**  
**TEL: 6842 9089 FAX: 6841 2869**  
**REG NO : 48992400W**

*TP 1st Cap*  
*Verona*

Vehicle Number: SLW2008C

S/N.	Item Description	Amount (\$)
1	Headlamp (LH) <i>cracked</i>	\$ 808.92
2	Front Bumper <i>delinted</i>	\$ 616.32
3	Front Bumper Side Bracket (LH) <i>new</i>	\$ 15.41
4	Front Fender (LH) <i>repair</i>	\$ 308.16
5	Front Fender Inner Garnish (LH) <i>take</i>	\$ 86.67
6	Front Fender Signal Light (LH) <i>bt</i>	\$ 53.93
7	Air Resonator <i>cracked</i>	\$ 96.30
8	Front Shock Absorber	\$ 256.80
9	Front Knuckle	\$ 264.83
10	Front Knuckle Bearing	\$ 144.45
11	Front Lower Arm	\$ 240.75
12	Front Steering Rack Ball Joint	\$ 72.23
13	Front Stabilizer Link	\$ 72.23
<b>Total :</b>		<b>\$ 3,037.00</b>
<i>20%</i> <b>Less 10% :</b>		<b>\$ 303.70</b>
<b>Amount :</b>		<b>\$ 2,733.30</b>

*1677.55*  
*1342.04*

S/N	Special Nett Item	Amount (\$)
1	Front Tyre Rim (LH) <i>bt</i>	\$ 1,500.00
<b>Total :</b>		<b>\$ 1,500.00</b>

*550. 550*

Labour	Amount (\$)	
To conduct 4-wheel alignment	\$ 80.00	
To remove & refit headlamp, to check wiring & focus headlamp	\$ 150.00	
To remove & reinstall front undercarriage	\$ 350.00	
To remove, replace above listed parts and panel beat accident affected parts	\$ 950.00	
To spray painting on affected area	\$ 850.00	
<b>Labour Total :</b>		<b>\$ 2,380.00</b>
<b>Total (Parts &amp; Labour) :</b>		<b>\$ 6,613.30</b>

*30*  
*220 1030*  
*300*  
*400*

\* To resurvey before/after spray painting  
 \* To display damaged part(s) during resurvey  
 \* Parts prices are subject to confirmation  
 \* Third party survey is on "without prejudice" basis  
 \* No illegal modifications allowed  
 \* Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

*total: 2922.04*  
*4/5: 2.31k*  
*242.00*



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18012741/Avd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 21-11-2018		
		Code : FCI2		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHA 811B	Veh. Inspected	SLW 2008C	
Policy No.	D-18088937MFSH	Coverage (\$)	0.00	
Claim No.	D18005358MFSH	Excess (\$)	0.00	
Assign From	SITHARA	Assign Date	12/07/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	HONDA CIVIC	c.c	1597	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	MRHFC5650HT000858	Colour	BLACK	
Odometer	15820	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	215/55 R16	HANKOOK	6 mm	
L/H Front Tyre	215/55 R16	HANKOOK	6 mm	
R/H Rear Tyre	215/55 R16	HANKOOK	6 mm	
L/H Rear Tyre	215/55 R16	HANKOOK	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	09/07/2018	Inspection Date	16/07/2018	
Survey held at	TICK HAI MOTOR & WELDING SERVICES BLK 1 KAKI BUKIT AVE 6 #01-54 AUTOBAY @ KAKI BUKIT SINGAPORE 417883			
<b>5a. Remarks</b>				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>4 Working Days</b>		



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLW 2008C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	HEADLAMP (LH)	CRACKED	808.92	808.92
1	FRONT BUMPER	DEFORMED	616.32	616.32
1	FRONT BUMPER SIDE BRACKET (LH)	NECESSARY	15.41	15.41
1	FRONT FENDER (LH)	TO REPAIR SEE LABOUR	308.16	-
1	FRONT FENDER INNER GARNISH (LH)	TORN	86.67	86.67
1	FRONT FENDER SIGNAL LIGHT (LH)	CUT	53.93	53.93
1	AIR RESONATOR	CRACKED	96.30	96.30
1	FRONT SHOCK ABSORBER	NOT NECESSARY	256.80	-
1	FRONT KNUCKLE	NOT NECESSARY	264.83	-
1	FRONT KNUCKLE BEARING	NOT NECESSARY	144.45	-
1	FRONT LOWER ARM	NOT NECESSARY	240.75	-
1	FRONT STEERING RACK BALL JOINT	NOT NECESSARY	72.23	-
1	FRONT STABILIZER LINK	NOT NECESSARY	72.23	-
	LESS 10% DISCOUNT		-303.70	-
	LESS 20% DISCOUNT		-	-335.51
			2,733.30	1,342.04
<b>SPECIAL NETT ITEMS</b>				
1	FRONT TYRE RIM (LH)(SN)	CUT	1,500.00	550.00
			1,500.00	550.00
<b>LABOUR</b>				
	TO CONDUCT 4 WHEEL ALIGNMENT.		80.00	80.00
	TO REMOVE & REFIT HEADLAMP, TO CHECK WIRING & FOCUS HEADLAMP.		150.00	30.00
	TO REMOVE & REINSTALL FRONT UNDERCARRIAGE.		350.00	220.00
	TO REMOVE, REPLACE ABOVE LISTED PARTS AND PANEL BEAT ACCIDENT AFFECTED PARTS. INCLUSIVE OF THE REPAIR OF FRONT FENDER (LH).		950.00	300.00
	TO SPRAY PAINTING ON AFFECTED AREA.		850.00	400.00
			2,380.00	1,030.00
<b>GRAND TOTAL</b>			<b>6,613.30</b>	<b>2,922.04</b>



<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>2,300.00</b>
---	--	--	-----------------

Report Ref No. CS/FCI18012741/Avd3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.  
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.