

REF:

CC3/ALH18012743/RNBnz

7834w

ASSIGNMENT

From: _____ Date: _____

Estimated Cost:

☒ OD / ☐ T / ☐ WS / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MV

To Inspect Vehicle No: SMC 3159L

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMC 3159L

Yr Regn: 2018 / Jun

Type: ☒ M. Car / ☐ M. Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make:

AUDI A3 SEDAN 1.0

c.c. 999

Colour:

Black

A/C: Insured / Std / NI / NA

Sp. Reading

346

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WQU 2228 V1J1069645

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

205/55R16

BS / DUN / EXNOVA / GY / S / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

10/07/18

D.O.I.

12/07/18

Survey held at

PREMIUM

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S FR

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

13/7/18

Revert via merimen

13/7/18

Rece approved \$12,386 from Victor by email

13/7/18

Informed Mr Chang c/A ex \$1600

30/10/18

Final fig \$11,014.12 (Real 4116.88, 2779) confirmed by email

RECEIVED 27 NOV 2018

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2) 27/11 - typist

Days Of Repair:

6

Resurvey No. of Trip:

1

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

200

10

210

Report Format:

merimen

Lump Sum / I.B.I. (\$

11,014.12

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Dally Amri, Mimi Zarina

Date: 13 Jul 2018

Preliminary Advice

Vehicle No	: SMC3159L	Accident Date	: 10/07/2018
Make	: AUDI A3	Policy No.	: 1800073461
Assignment Date	: 13/07/2018	Excess	: S\$0.00
Date of Inspection	: 12/07/2018	Est. Duration of Repair	: 6.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (BENOI) 24 BENOI SECTOR SINGAPORE 629857		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	14,651.00
Revised Amount	:S\$	12,386.00
Check Items (Estimated)	:S\$	893.00
Total	:S\$	13,279.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	139,000.00
COE / PARF Rebate	:S\$	51,167.00
Salvage Value	:S\$	
Margin for Repair	:S\$	87,833.00

Remarks

(X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

() The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

() Other comments :

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Monday, 16 July 2018 2:45 PM
To: Koh, Victor-CK; SUR
Cc: Fong, Andy-SY; Rasul (LKKAUTO)
Subject: RE: SMC3159L/ OD / 6313117641SG

Dear Victor,

Noted and thanks.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Koh, Victor-CK [mailto:Victor-CK.Koh@aig.com]
Sent: Monday, 16 July 2018 2:36 PM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: Fong, Andy-SY <Andy-SY.Fong@aig.com>
Subject: RE: SMC3159L/ OD / 6313117641SG

Hi Veron,

Photo required of the removal of the wing mirror.

Thanks & Regards

Victor Koh

AIG

Claims Technical Controller

Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore 079120

Tel +65 6419 1785 | Fax +65 68357416

Victor-ck.koh@aig.com | www.aig.com

From: Veron Chen (LKKAUTO) [mailto:veronchen@lkkauto.com]
Sent: Monday, July 16, 2018 9:18 AM
To: Koh, Victor-CK; SUR
Cc: Fong, Andy-SY
Subject: RE: SMC3159L/ OD / 6313117641SG

Dear Victor,

We refer to below email.

Accordingly to surveyor, to remove RH front wing mirror is necessary in order to spray paint the door.

Please refer to photos no 7.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Koh, Victor-CK [<mailto:Victor-CK.Koh@aig.com>]

Sent: Friday, 13 July 2018 5:25 PM

To: SUR <sur@lkkauto.com>

Cc: Fong, Andy-SY <Andy-SY.Fong@aig.com>

Subject: SMC3159L/ OD / 6313117641SG

Hi,

Kindly advise below:

Kindly advise why labour 3 is necessary? Is this a new labour have not seen this labour from your past survey.

Thanks & Regards

Victor Koh

AIG

Claims Technical Controller

Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore 079120

Tel +65 6419 1785 | Fax +65 68357416

Victor-ck.koh@aig.com | www.aig.com

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Monday, 16 July 2018 9:18 AM
To: Koh, Victor-CK; SUR
Cc: Fong, Andy-SY
Subject: RE: SMC3159L/ OD / 6313117641SG

Dear Victor,

We refer to below email.

Accordingly to surveyor, to remove RH front wing mirror is necessary in order to spray paint the door.

Please refer to photos no 7.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Koh, Victor-CK [mailto:Victor-CK.Koh@aig.com]
Sent: Friday, 13 July 2018 5:25 PM
To: SUR <sur@lkkauto.com>
Cc: Fong, Andy-SY <Andy-SY.Fong@aig.com>
Subject: SMC3159L/ OD / 6313117641SG

Hi,

Kindly advise below:

Kindly advise why labour 3 is necessary? Is this a new labour have not seen this labour from your past survey.

Thanks & Regards

Victor Koh
AIG
Claims Technical Controller
Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore 079120
Tel +65 6419 1785 | Fax +65 68357416
Victor-ck.koh@aig.com | www.aig.com

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into

Veron Chen (LKKAuto)

From: Koh, Victor-CK <Victor-CK.Koh@aig.com>
Sent: Friday, 13 July 2018 5:25 PM
To: SUR
Cc: Fong, Andy-SY
Subject: SMC3159L/ OD / 6313117641SG

Hi,

Kindly advise below:

Kindly advise why labour 3 is necessary? Is this a new labour have not seen this labour from your past survey.

Thanks & Regards

Victor Koh
AIG
Claims Technical Controller
Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore 079120
Tel +65 6419 1785 | Fax +65 68357416
Victor-ck.koh@aig.com | www.aig.com

*(To remove rh fct wing mirror is necessary
in order to spray paint the door) alignment of
side pillar is necessary as well. wiring
need to be disconnect*

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Veron Chen (LKKAuto)

From: PAL Claim <claims@premiumauto.com.sg>
Sent: Friday, 13 July 2018 6:06 PM
To: Veron Chen (LKKAuto)
Cc: SUR; 'PAL Claim'
Subject: RE: OD claim for SMC 3159 L - (VEHICLE IN)

Dear Veron,

Noted with thanks.

Kindly take note that we will only start the repair on coming Monday.

Thank you.

Best regards,
Chang Chee Sing
Estimator

Premium Automobiles Pte Ltd (Reg No 199902271W)
55 Ubi Road 1 Road Singapore 408699
p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183
e. claims@premiumauto.com.sg w. www.audi.com.sg
Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

From: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Sent: Friday, 13 July 2018 5:52 PM
To: claims@premiumauto.com.sg
Cc: SUR <sur@lkkauto.com>
Subject: RE: OD claim for SMC 3159 L - (VEHICLE IN)

Dear Mr Chang,

As instructed by our client , please proceed to repair the insured vehicle **SMC 3159L (Excess \$1600/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)

Sent: Thursday, 12 July 2018 5:40 PM

To: claims@premiumauto.com.sg

Cc: SUR <sur@lkkauto.com>

Subject: FW: OD claim for SMC 3159 L - (VEHICLE IN)

Dear Mr Chang,

Please forward us LTA rebate.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PAL Claim [<mailto:claims@premiumauto.com.sg>]

Sent: Thursday, 12 July 2018 5:34 PM

To: SUR <sur@lkkauto.com>

Cc: 'PAL Claim' <claims@premiumauto.com.sg>

Subject: RE: OD claim for SMC 3159 L - (VEHICLE IN)

Dear all,

Kindly assist on the OD claim approval.

Vehicle has been surveyed by Mr. Rasul just now, attached is the marked estimate for reference.

Thank you.

Best regards,

Chang Chee Sing

Estimator

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

From: Claims Dept <claims@premiumauto.com.sg>
Sent: Wednesday, 11 July 2018 4:48 PM
To: 'Claims Dept' <claims@premiumauto.com.sg>; 'assignments' <assignments@lkkauto.com>
Cc: 'Claims' <claims@premiumauto.com.sg>
Subject: RE: OD claim for SMC 3159 L - (VEHICLE IN)

Dear all,

Sorry for the wrong email send. Kindly ignore the email.

Thank you .

Best Regards,
Phua
Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)
55 Ubi Road 1 Road Singapore 408699
p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183
e. claims@premiumauto.com.sg w. www.audi.com.sg
Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

From: Claims Dept [<mailto:claims@premiumauto.com.sg>]
Sent: Wednesday, 11 July 2018 4:44 PM
To: 'PAL Claim'; 'assignments'
Cc: 'Claims'
Subject: RE: OD claim for SMC 3159 L - (VEHICLE IN)

Good afternoon all ,

Here is the attach estimate for your kind reference.

Thank you.

Best Regards,

Phua

Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

From: PAL Claim [<mailto:claims@premiumauto.com.sg>]

Sent: Wednesday, 11 July 2018 3:09 PM

To: 'assignments'

Cc: 'PAL Claim'

Subject: RE: OD claim for SMC 3159 L - (VEHICLE IN)

Dear all,

Attached is the GIA report for OD claim registration.

Kindly assist to arrange survey for above mentioned vehicle.

Address : **24 Benoi Sector, Singapore 629857.**

Thank you.

Best regards,

Chang Chee Sing

Estimator

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Friday, 13 July 2018 5:52 PM
To: claims@premiumauto.com.sg
Cc: SUR
Subject: RE: OD claim for SMC 3159 L - (VEHICLE IN)

Dear Mr Chang,

As instructed by our client , please proceed to repair the insured vehicle **SMC 3159L (Excess \$1600/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 12 July 2018 5:40 PM
To: claims@premiumauto.com.sg
Cc: SUR <sur@lkkauto.com>
Subject: FW: OD claim for SMC 3159 L - (VEHICLE IN)

Dear Mr Chang,

Please forward us LTA rebate.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PAL Claim [mailto:claims@premiumauto.com.sg]
Sent: Thursday, 12 July 2018 5:34 PM
To: SUR <sur@lkkauto.com>

Cc: 'PAL Claim' <claims@premiumauto.com.sg>
Subject: RE: OD claim for SMC 3159 L - (VEHICLE IN)

Dear all,

Kindly assist on the OD claim approval.

Vehicle has been surveyed by Mr. Rasul just now, attached is the marked estimate for reference.

Thank you.

Best regards,
Chang Chee Sing
Estimator

Premium Automobiles Pte Ltd (Reg No 199902271W)
55 Ubi Road 1 Road Singapore 408699
p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183
e. claims@premiumauto.com.sg w. www.audi.com.sg
Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

From: Claims Dept <claims@premiumauto.com.sg>
Sent: Wednesday, 11 July 2018 4:48 PM
To: 'Claims Dept' <claims@premiumauto.com.sg>; 'assignments' <assignments@lkkauto.com>
Cc: 'Claims' <claims@premiumauto.com.sg>
Subject: RE: OD claim for SMC 3159 L - (VEHICLE IN)

Dear all,

Sorry for the wrong email send. Kindly ignore the email.

Thank you .

Best Regards,
Phua
Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)
55 Ubi Road 1 Road Singapore 408699
p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183
e. claims@premiumauto.com.sg w. www.audi.com.sg
Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

From: Claims Dept [<mailto:claims@premiumauto.com.sg>]
Sent: Wednesday, 11 July 2018 4:44 PM
To: 'PAL Claim'; 'assignments'
Cc: 'Claims'
Subject: RE: OD claim for SMC 3159 L - (VEHICLE IN)

Good afternoon all ,

Here is the attach estimate for your kind reference.

Thank you.

Best Regards,
Phua
Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

From: PAL Claim [<mailto:claims@premiumauto.com.sg>]
Sent: Wednesday, 11 July 2018 3:09 PM
To: 'assignments'

Cc: 'PAL Claim'

Subject: RE: OD claim for SMC 3159 L - (VEHICLE IN)

Dear all,

Attached is the GIA report for OD claim registration.

Kindly assist to arrange survey for above mentioned vehicle.

Address : **24 Benoi Sector, Singapore 629857.**

Thank you.

Best regards,
Chang Chee Sing
Estimator

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

View Received Message

This mail is associated with :

***SMC3159L (6313117641SG)**

OD

Jul 10 2018 2:10PM

[VASILJKOVIC SASA]

Premium Automobiles Pte Ltd

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 13/07/2018 17:23 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$12386.00) - SMC3159L - Claim Handler: Mohd Zawaye, Norsazani

Approved:12386.00:Kindly advise why labour 3 is necessary? Is this a new labour have not seen this labour from your past survey. Re-inspection to be done for damage check and supplementary items / labour.

DOCUMENTS SUMMARY

There are no documents.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Foreign Identification Number
Owner ID:	7634W
Vehicle Details	
Vehicle No.:	SMC3159L
Vehicle to be Exported:	No
Intended De-registration Date:	13 Jul 2018
Vehicle Make:	AUDI
Vehicle Model:	A3 SEDAN 1.0 TFSI S TRONIC (LED)
Primary Colour:	Black
Manufacturing Year:	2018
Engine No.:	CHZ466329
Chassis No.:	WAUZZZ8V1J1069645
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$22,104.00
Original Registration Date:	28 Jun 2018
First Registration Date:	28 Jun 2018
Transfer Count:	0
Actual ARF Paid:	\$22,946.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Jun 2028
PARF Rebate Amount:	\$17,209.00
Intended COE Rebate Details	
COE Expiry Date:	27 Jun 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$34,110.00
COE Rebate Amount:	\$33,958.00
Total Rebate Amount:	\$51,167.00

The information contained herein is correct as at 13 Jul 2018

OK

REPUBLIC OF SINGAPORE DRIVING LICENCE

002194539G

VASILJKOVIC SASA

Birth Date: 22 Jul 1971
Issue Date: 21 Jun 2013
Valid Till: 20 Jun 2018

002194539G

EMPLOYMENT PASS
Employment of Foreign Manpower Act (Chapter 91A)
Republic of Singapore

Employer:
TOLL LOGISTICS (ASIA) LIMITED

Name:
VASILJKOVIC SASA
Occupation:
GENERAL MANAGER

FIN:
G5237634W

Date of Application:
27-01-2016
Date of Issue:
22-02-2016
Date of Expiry:
11-04-2019

L6510969

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 3 Motor Cars=<3000kg with =<7 passengers, exclusive of the driver; and other motor vehicles =< 2500kg **21 Jun 2013**

Licence No: G5237634W

NP 428A

VISIT PASS
Immigration Regulations

Name:
VASILJKOVIC SASA

Date of Birth: **22-07-1971** Sex: **M** Nationality: **AUSTRALIAN**
FIN: **G5237634W** Date of Issue: **22-02-2016** Date of Expiry: **11-04-2019**

YOU ARE TO SURRENDER THIS CARD WHEN IT IS CANCELLED OR HAS EXPIRED, OR WHEN A NEW CARD IS ISSUED TO YOU.



CERTIFICATE OF INSURANCE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : VASILJKOVIC SASA
Period of Insurance : 28 Jun 2018 To 27 Jun 2019
Engine No. : CHZ 466329
Chassis No. : WAUZZZ8V1J1069645

Vehicle No. : SMC3159L
Policy No. : 1800073461
Endorsement No. :
Issued Date : 10 Jul 2018

ABOUT THE COVER

Make/Model : AUDI A3 Sedan 1.0 TFSI S tronic
Engine Capacity/Tonnage : 999.00 CC
Driver Restriction : NA
Person or Classes of Persons Entitled to Drive* :
a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission.
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

Sum Insured : Market Value
Off Peak Car : No
First Year of Registration : 2018
Insuring with COE/PAF : Yes

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$1600 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

VASILJKOVIC SASA - \$1600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: DBS BANK LTD

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125261

PREMIUM LEASING -CYS

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE
SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE

Staffany Loh

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0792/2018/CCS
Date : 11-Jul-18

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Vasiljkovic Sasa
Address : 62 Namly Drive
Singapore 267470
Telephone : (HP) +65 97102502
Type of Claim : Own Damage Claim
Policy No. : 1800073461
Vehicle No : **SMC 3159 L**
Model Code : Audi A3 SEDAN 1.0 TFSI
Model / Year : Jun-18
Engine No : CHZ 466329
Chassis No : WAUZZZ8V1J1069645
Mileage :
Date In : 10-Jul-18
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 10-Jul-18
Place of Accident : Kung Chong Rd @ exit of Borneo Motors

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMC 3159 L.

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00 ✓	✓
2	To dismantle and renew front bumper, rhs front fender and rhs headlight. Re-organise front crash management components. Reinstall all parts removed.	\$ 2,100.00 1250 ✓	✓
3	To dismantle rhs front panel trims, remove and reinstall rhs wing mirror assy.	S/N \$ 300.00 ✓	✓
4	To respray front bumper, rhs front fender and rhs front door.	\$ 2,200.00 1650 ✓	✓
5	To renew rhs front rim and carry out wheel alignment.	S/N \$ 280.00 ✓	✓
6	To carry out diagnostic checks.	S/N \$ 192.00 ✓	✓
TOTAL LABOUR CHARGES		: <u>\$ 5,240.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMC 3159 L.

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00 ✓	✓
2	To dismantle and renew front bumper, rhs front fender and rhs headlight. Re-organise front crash management components. Reinstall all parts removed.	\$ 2,100.00 1250 ✓	✓
3	To dismantle rhs front panel trims, remove and reinstall rhs wing mirror assy.	S/N \$ 300.00 ✓	✓
4	To respray front bumper, rhs front fender and rhs front door.	\$ 2,200.00 1650 ✓	✓
5	To renew rhs front rim and carry out wheel alignment.	S/N \$ 280.00 ✓	✓
6	To carry out diagnostic checks.	S/N \$ 192.00 ✓	✓
TOTAL LABOUR CHARGES		: <u>\$ 5,240.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMC 3159 L.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER	\$ 1,739.00	DE - 1391
2	FRONT BUMPER FIXING PARTS	\$ 161.00	? X su
3	FRONT BUMPER GUIDE - RH	\$ 33.00	? M 25.84
4	FRONT BUMPER CLOSING ELEMENT - RH	\$ 254.00	? X
5	FRONT BUMPER ADAPTER - RH	\$ 32.00	? X } su
6	FRONT BUMPER GRILLE - RH	\$ 164.00	X
7	FRONT FENDER - RH	\$ 746.00	Beu - 596.80
8	FRONT FENDER BRACE - RH	\$ 84.00	? Pt 67.04
9	FRONT FENDER BRACKET - RH FRONT	\$ 34.00	ne - 26.64
10	FRONT FENDER BRACKET - RH REAR	\$ 24.00	ne - 18.88
11	FRONT FENDER RIVET SET	\$ 24.00	ne - 23.20
12	FRONT FENDER CLOSING ELEMENT - RH	\$ 29.00	? X su
13	FRONT WHEEL HOUSING LINER - RH	\$ 151.00	DE - 120.80
14	WHEEL HOUSING LINER ATTACHMENT PARTS	\$ 77.00	ne - 60.88
15	LED HEADLIGHT - RH	\$ 4,888.00	su - 3910.40
16	ALUMINIUM RIM - RH FRONT	\$ 659.00	su - 527.20
17	*TYRE VALVE	\$ 12.00	ne - 8.96
18	SUNDRIES	\$ 300.00	? 14.48 ne
TOTAL SPARE PARTS CHARGES		\$ 9,411.00	
TOTAL LABOUR CHARGES		\$ 5,240.00	
GRAND TOTAL		\$ 14,651.00	(5,13)

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

Surveyed Date

Authorised Date

Excess Cost

Liability

Remarks

: Rasul - 4p 90010068
: 12/07/18 @ 1620
: 6 days
: Resurvey by paint
: excess: ?
: Repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:


16/7/18

Please Note

- : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0792/2018/CCS
Date : 11-Jul-18

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian, Rasul

6 days - ok - jb - 27 Oct 18

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Vasiljkovic Sasa
Address : 62 Namly Drive
Singapore 267470
Telephone : (HP) +65 97102502
Type of Claim : Own Damage Claim
Policy No. : 1800073461
Vehicle No : **SMC 3159 L**
Model Code : Audi A3 SEDAN 1.0 TFSI
Model / Year : Jun-18
Engine No : CHZ 466329
Chassis No : WAUZZZ8V1J1069645
Mileage :
Date In : 10-Jul-18
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 10-Jul-18
Place of Accident : Kung Chong Rd @ exit of Borneo Motors

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMC 3159 L.

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$	360.00	\$ 360.00
2	To dismantle and renew front bumper, rhs front fender and rhs headlight. Re-organise front crash management components. Reinstall all parts removed.	\$	2,100.00	\$ 1,250.00
3	To dismantle rhs front panel trims, remove and reinstall rhs wing mirror assy.	S/N \$	300.00	\$ 300.00
4	To respray front bumper, rhs front fender and rhs front door.	\$	2,200.00	\$ 1,650.00
5	To renew rhs front rim and carry out wheel alignment.	S/N \$	280.00	\$ 280.00
5a	Added labour charge	\$	480.00	\$ 200.00
6	To carry out diagnostic checks.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	<u>\$ 5,240.00</u>	<u>\$ 4,232.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMC 3159 L.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER	\$ 1,739.00	\$ 1,391.00
2	FRONT BUMPER FIXING PARTS	\$ 161.00	
3	FRONT BUMPER GUIDE - RH	\$ 33.00	\$ 25.84
4	FRONT BUMPER CLOSING ELEMENT - RH	\$ 254.00	
5	FRONT BUMPER ADAPTER - RH	\$ 32.00	
6	FRONT BUMPER GRILLE - RH	\$ 164.00	
7	FRONT FENDER - RH	\$ 746.00	\$ 596.80
8	FRONT FENDER BRACE - RH	\$ 84.00	\$ 67.04
9	FRONT FENDER BRACKET - RH FRONT	\$ 34.00	\$ 26.64
10	FRONT FENDER BRACKET - RH REAR	\$ 24.00	\$ 18.88
11	FRONT FENDER RIVET SET	\$ 24.00	\$ 23.20
12	FRONT FENDER CLOSING ELEMENT - RH	\$ 29.00	
13	FRONT WHEEL HOUSING LINER - RH	\$ 151.00	\$ 120.80
14	WHEEL HOUSING LINER ATTACHMENT PARTS	\$ 77.00	\$ 60.88
15	LED HEADLIGHT - RH	\$ 4,888.00	\$ 3,910.40
16	ALUMINIUM RIM - RH FRONT	\$ 659.00	\$ 527.20
17	TYRE VALVE	\$ 12.00	\$ 8.96
18	SUNDRIES	\$ 300.00	\$ 4.48
TOTAL SPARE PARTS CHARGES		\$ 9,411.00	\$ 6,782.12
TOTAL LABOUR CHARGES		\$ 5,240.00	\$ 4,232.00
GRAND TOTAL		\$ 14,651.00	\$ 11,014.12

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/OD/0792/2018/CCS

17-Jul-18

JB

ONE

SMC3159L

A3 1.0 TFSI

Quantity	Description	Unit Price	Amount
<u>labour</u>			
1	To repair and spray RHS A pillar	\$ 480.00	\$ 200.00
		<u>\$ 480.00</u>	<u>\$ 200.00</u>
	TOTAL	\$ 480.00	\$ 200.00

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Tuesday, 30 October 2018 9:31 AM
To: Boo seng yak; Carrine Leong; jiayee.yap@premiumauto.com.sg; Chang Chee Sing; SUR
Subject: RE: FINAL REVISION - SMC3159L - OD AIG - SURVEYED 12 JUL 18 - RASUL

Dear Mr Boo,

Cconfirm repair cost of \$11,014.12 before excess \$1600 and GST @ 6 days of repairs.

Kindly send us invoice and discharge voucher for us to close file.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Boo seng yak <boojohnny@gmail.com>

Sent: Saturday, 27 October 2018 6:27 PM

To: Adrian Ling (LKKAUTO) <adrianling@lkkauto.com>; Veron Chen (LKKAUTO) <veronchen@lkkauto.com>; SUR <sur@lkkauto.com>; Carrine Leong <carrine.leong@premiumauto.com.sg>; jiayee.yap@premiumauto.com.sg; Chang Chee Sing <claims@premiumauto.com.sg>

Subject: FINAL REVISION - SMC3159L - OD AIG - SURVEYED 12 JUL 18 - RASUL

Hi Adrian, Rasul and all,

Revised estimate and photographs attached.

Please confirm repair cost of \$10104.32 @ 6 days of repairs.

Your early closure is well appreciated.

best regards - jb

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SMC 3159 L

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0792/2018/MAS

23 Nov 2018

Dear Sir,

RE: INSURANCE CLAIM FOR SMC 3159 L, Audi A3 Sedan 1.0 TFSI

With reference to the above-mentioned vehicle, no. **SMC 3159 L**, claimant, **Mr. Vasiljkovic Sasa**, please find the related document per attached.

1. A copy of the Original invoice no. 85013137 – S\$10,073.11
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SMC 3159 L

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

total pages

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Jul 2018 11:32		13 Jul 2018 10:16 Edit Adj Rpt	S\$11,014.12 Edit Estimates	S\$11,014.12 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured: **VASILJKOVIC SASA**, ID: G5237634W, Tel: +6597102502, Email: sasha.vasiljkovic@tollgroup.com

Vehicle Reg. No.: **SMC3159L** Date of Loss: 10/07/2018 14:00 - :59
[12 Days From LTA Reg Date (Man Yr)]

Claim Type: **OD / 6313117641SG** Policy/Cover Note No.: 1800073461 (Comprehensive)
Excess: S\$1,600.00

Repairer: **Premium Automobiles Pte Ltd (Benoi)** 24 Benoi Sector, 629857 Pioneer - Tel: 67689911 / 63882323

Handling Insurer: **AIG Asia Pacific Insurance Pte. Ltd. (SG)** - Tel: 65-6419-3000 ... [Handled by **Mohd Zawaye, Norsazani**] Norsazani.Zawaye@aig.com

Adjuster: **LKK Auto Consultants Pte Ltd (HQ)** - Tel: 6256-3561 ... [Handled by **MOHD RASUL**] ... **[Final Rpt due 24/07/2018]**

Driver/Custodian: **VASILJKOVIC SASA (46 / Male)**, NRIC: G5237634W, Tel: +6597102502

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

- AIG_SG (13/07/2018): Alert - Adj Mandate Approved (S\$12386.00) - SMC3159L - Claim Handler: Mohd Zawaye...
- AIG_SG (13/07/2018): SMC3159L / OD / 10/07/2018 / Coverage & Excess update

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SMC3159L (63131176415G)
OD
Jul 10 2018 2:10PM
[VASILJKOVIC SASA]
Premium Automobiles Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View		Use Viewer		▼		
Assessment Reports											1 per page		▼		☑	
No	Finalized On		LKK Auto Consultants Pte Ltd (HQ)							Thumbnail		Print				
1	13/07/18 12:00		Adjuster Immediate Advice							1 Load HTM						
Photos/Images											3 per page		▼		☑	
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)							Thumbnail		Print				
1	13/07/18 11:33		General View							1 Load JPG		☑				
2	13/07/18 11:33		General View							1 Load JPG		☑				
3	13/07/18 11:33		General View							1 Load JPG		☑				
4	13/07/18 11:33		General View							1 Load JPG		☑				
5	13/07/18 11:33		General View							1 Load JPG		☑				
6	13/07/18 11:33		General View							1 Load JPG		☑				
7	13/07/18 11:33		General View							1 Load JPG		☑				
8	13/07/18 11:33		General View							1 Load JPG		☑				
9	13/07/18 11:33		General View							1 Load JPG		☑				
10	13/07/18 11:33		General View							1 Load JPG		☑				
11	13/07/18 11:33		General View							1 Load JPG		☑				
12	13/07/18 11:33		General View							1 Load JPG		☑				
13	13/07/18 11:33		General View							1 Load JPG		☑				
14	13/07/18 11:33		General View							1 Load JPG		☑				
15	13/07/18 11:33		General View							1 Load JPG		☑				
16	13/07/18 11:33		General View							1 Load JPG		☑				
17	13/07/18 11:33		General View							1 Load JPG		☑				
18	13/07/18 11:33		General View							1 Load JPG		☑				
19	13/07/18 11:33		General View							1 Load JPG		☑				
20	13/07/18 11:33		General View							1 Load JPG		☑				
21	13/07/18 11:33		General View							1 Load JPG		☑				
22	13/07/18 11:33		General View							1 Load JPG		☑				
23	13/07/18 11:33		General View							1 Load JPG		☑				
24	13/07/18 11:33		General View							1 Load JPG		☑				
25	13/07/18 11:33		General View							1 Load JPG		☑				
26	13/07/18 11:33		General View							1 Load JPG		☑				
27	13/07/18 11:33		General View							1 Load JPG		☑				
28	13/07/18 11:33		General View							1 Load JPG		☑				
29	13/07/18 11:33		General View							1 Load JPG		☑				
30	13/07/18 11:33		General View							1 Load JPG		☑				
31	13/07/18 11:33		General View							1 Load JPG		☑				
32	30/10/18 09:34		Reinspection Photo							1 Load JPG		☑				
33	30/10/18 09:34		Reinspection Photo							1 Load JPG		☑				
34	30/10/18 09:35		Reinspection Photo							1 Load JPG		☑				
35	30/10/18 09:35		Reinspection Photo							1 Load JPG		☑				
36	30/10/18 09:35		Reinspection Photo							1 Load JPG		☑				
Documentation											1 per page		▼		☑	
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)							Thumbnail		Print				
1	13/07/18 12:01		Singapore Accident Statement							1 Load PDF						
2	13/07/18 12:01		Certificate of Insurance							1 Load PDF						

3	13/07/18 12:02	Insured's Driving License	1	Load PDF	
4	13/07/18 12:02	MARK ESTIMATE	1	Load PDF	
5	29/11/18 09:44	Supplementary	1	Load PDF	
6	29/11/18 09:44	WORKSHOP INVOICE	1	Load PDF	
7	29/11/18 09:44	DISCHARGE VOUCHER	1	Load PDF	

Linked Accident Report Documents

			View	Use Viewer	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print	
1	10/07/18 18:01	Accident Statement	1 Load HTM		
Photos/Images			3 per page	<input checked="" type="checkbox"/>	
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print	
1	10/07/18 17:06	Accident Photo	1 Load JPG	<input checked="" type="checkbox"/>	
2	10/07/18 17:06	Accident Photo	1 Load JPG	<input checked="" type="checkbox"/>	
3	10/07/18 17:06	Accident Photo	1 Load JPG	<input checked="" type="checkbox"/>	
4	10/07/18 17:06	Accident Photo	1 Load JPG	<input checked="" type="checkbox"/>	
5	10/07/18 17:06	Accident Photo	1 Load JPG	<input checked="" type="checkbox"/>	
6	10/07/18 17:06	Accident Photo	1 Load JPG	<input checked="" type="checkbox"/>	
7	10/07/18 17:06	Accident Photo	1 Load JPG	<input checked="" type="checkbox"/>	
8	10/07/18 17:06	Accident Photo	1 Load JPG	<input checked="" type="checkbox"/>	
9	10/07/18 17:06	Accident Photo	1 Load JPG	<input checked="" type="checkbox"/>	
10	10/07/18 17:06	Accident Photo	1 Load JPG	<input checked="" type="checkbox"/>	
11	10/07/18 17:06	Accident Photo	1 Load JPG	<input checked="" type="checkbox"/>	
12	10/07/18 17:06	Accident Photo	1 Load JPG	<input checked="" type="checkbox"/>	
13	10/07/18 17:06	Accident Photo	1 Load JPG	<input checked="" type="checkbox"/>	
14	10/07/18 17:06	Accident Photo	1 Load JPG	<input checked="" type="checkbox"/>	
15	10/07/18 17:06	Accident Photo	1 Load JPG	<input checked="" type="checkbox"/>	
16	10/07/18 17:06	Accident Photo	1 Load JPG	<input checked="" type="checkbox"/>	
17	10/07/18 17:06	Accident Photo	1 Load JPG	<input checked="" type="checkbox"/>	
18	10/07/18 17:06	Accident Photo	1 Load JPG	<input checked="" type="checkbox"/>	
19	10/07/18 17:06	Accident Photo	1 Load JPG	<input checked="" type="checkbox"/>	
Documentation			1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print	
1	10/07/18 16:29	Sketch Plan	1 Load JPG	<input checked="" type="checkbox"/>	
2	10/07/18 16:29	Sketch Plan #2	1 Load JPG	<input checked="" type="checkbox"/>	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 100px; width: 100%;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CC3/AIG18012743/R1VBN2

Date: 29/11/2018

REFERENCE

Insured/Claimant: VASILJKOVIC SASA Policy No: 1800073461
Date of Loss: 10/07/2018 Nature of Claim: OD Claim No: 6313117641SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMC3159L
Make & Model: AUDI A3, 999cc TFSI (A) Engine No: CHZ466329
Reg. Date: 28/06/2018 (Man. Year: 2018) Chassis No: WAUZZZ8V1J1069645
Colour: Black Odometer: 346 km
Engine Capacity: 999 cc
Market Value/New Car Price: S\$139,000.00
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm
Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	9,411.00	6,782.12	2,628.88	27.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,912.00	4,232.00	1,680.00	28.42
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,323.00	11,014.12	4,308.88	28.12
- Excess (S\$)	1,600.00	1,600.00	0.00	0.00
(S\$)	13,723.00	9,414.12	4,308.88	31.40
+ GST 7.00/7.00% (S\$)	960.61	658.99	301.62	31.40
Nett Amount (S\$)	14,683.61	10,073.11	4,610.50	31.40

INSPECTION

Date of Assignment: 13/07/2018

Date Inspected: 12/07/2018 Inspected At:

24 BENOI SECTOR
REPAIRER: PREMIUM AUTOMOBILES
PTE LTD
55 UBI ROAD 1
SINGAPORE 408699

Estimated Period of Repair: 6.0 days

Adjuster: MOHD RASUL

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,739.00 FS	*1,391.00 FS
2	1		*FRONT BUMPER FIXING PARTS	Serviceable	161.00 FS	*- FS
3	1		*FRONT BUMPER GUIDE-RH	Bent	33.00 FS	*25.84 FS
4	1		*FRONT BUMPER CLOSING ELEMENT-RH	Serviceable	254.00 FS	*- FS
5	1		*FRONT BUMPER ADAPTER-RH	Serviceable	32.00 FS	*- FS
6	1		*FRONT BUMPER GRILLE-RH	Serviceable	164.00 FS	*- FS
7	1		*FRONT FENDER-RH	Buckled	746.00 FS	*596.80 FS
8	1		*FRONT FENDER BRACE-RH	Bent	84.00 FS	*67.04 FS
9	1		*FRONT FENDER BRACKET-RH FRONT	Necessary	34.00 FS	*26.64 FS
10	1		*FRONT FENDER BRACKET-RH REAR	Necessary	24.00 FS	*18.88 FS
11	1		*FRONT FENDER RIVET SET	Necessary	24.00 FS	*23.20 FS
12	1		*FRONT FENDER CLOSING ELEMENT-RH	Serviceable	29.00 FS	*- FS
13	1		*FRONT WHEEL HOUSING LINER-RH	Deformed	151.00 FS	*120.80 FS
14	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Necessary	77.00 FS	*60.88 FS
15	1		*LED HEADLIGHT-RH	Scratched	4,888.00 FS	*3,910.40 FS
16	1		*ALUMINIUM RIM-RH FRONT	Scratched	659.00 FS	*527.20 FS
17	1		*TYRE VALVE	Necessary	12.00 FS	*8.96 FS
18	1		*SUNDRIES	Necessary	300.00 FS	*4.48 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	9,411.00	6,782.12
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO DISMANTLE AND RENEW FRONT BUMPER,RHS FRONT FENDER AND RHS HEADLIGHT.RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	2,100.00	1,250.00
3	TO DISMANTLE RHS FRONT PANEL TRIMS,REMOVE AND REINSTALL RHS WING MIRROR ASSY	New	300.00	300.00
4	TO RESPRAY FRONT BUMPER,RHS FRONT FENDER AND RHS FRONT DOOR	New	2,200.00	1,650.00
5	TO RENEW RHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
6	TO CARRY OUT DIAGNOSTIC CHECKS	New	192.00	192.00
7	TO REPAIR AND SPRAY RHS A PILLAR	New	480.00	200.00
Gross Labour Cost (S\$)			5,912.00	4,232.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >