

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

12-Jul-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8676 S

S/NETT

1 set	n/s door sticker	\$	100.00
1 pc	Front n/s fender sticker	\$	30.00
	Sundry	\$	50.00 20
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the front n/s fender, front n/s door & n/s rocker panel garnish, etc	\$	400 850.00
	To putty and spray painting on front bumper ^{n/s Front Fender} , front n/s door, n/s rocker panel garnish	\$	500 750.00
	To apply rustproofing on the repaired and replaced panels.	\$	120.00 120.00
		\$	1,900.00

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)
THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE
ANY UNFORESEEN DAMAGES.

Kaki 10/11/18
12/7/18 1605hr
3 Pys.
4/s
After Repair

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: