

INS. CASE OWNER:

CC 4 ^{UP} / AG 1801 2755, FjrbLKK:
IDAC:

Surveyor:

Kenneth

DOI:

ASSIGNMENT

17/3/18

Date / Time:

17/3/18

Registered in Merimen:

17/3/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLF 8626T

Name of Insured:

UP

Insured Tel No.:

HP:

Excess Sec II :S\$

D.O.A:

10/3/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO. Driver Name / Age:

MAY HOONH PATT

Driver Tel No.:

(V/L) YES / NO

Claim No.:

660205W4234

Policy No.:

AAAAA4143

Make / Model:

TOYOTA

Place of Accident:

APT WATIK WEST AVE 5

OI GIA REPORT: YES / NO

YES / NO

TP GIA REPORT: YES / NO

Insured Liability: YES / NO

Final ? Yes / No

SLF 1001T



INSRS:

WSP:

Tel:

Liability:

RMKS:

Cheng HEE



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

17/3/18
704SLF 1001T - LCU / 25 M / 8000000 / 10/1/18
SLF 8626T - LCU / 25 M / 8000000 / 10/1/18OID - U TURN
TP - STRAIGHT

28-1-19 PENDING FINALISATION

STAGE

DATE / PIC

Non-Reporting Itr (1st):

Non-Reporting Itr (2nd):

Non-Reporting Itr (Final):

Notification Itr (if non-pickup):

Call OI:

JOY 23-7-18

After call Itr to OI:

Documentation Check List: Handler Typist

Notification Itr (if non-pickup)

After call Itr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

LTA

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(Agreed / Assessed)

BOLA S/N No.:

NIL

Repair Cost:

S\$

6,259.50

Loss of Rental (LOR):

S\$

X

(days)

Loss of Use (LOU):

S\$

X

(days)

Loss of Income (LOI):

S\$

700

(days)

LOR only

LOU only

LOR + LOU

LOR + LO

[Tick only one]

GIA/LTA Search

S\$

8. x f

Medical:

S\$

X

Disbursement:

S\$

X

(e.g. Tow/ Independent)

Legal Cost:

S\$

X

Total:

S\$

6,967.50

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

6,967.50

Name 1:

CHENG HEE MOTOR PTE LTD

Payee 2: (Strike if N.A.)

S\$

X

Name 2:

X

Payee 3: (Strike if N.A.)

S\$

X

Name 3:

X

COPY SENT
21/4/18

ASSIGNMENT

From: _____ Date: 13/07/18

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SCZ 1001T

at Workshop m/s

of Cheng Hoe Motor
Blk 1019, Yishun Ind Park A #01-374

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: 06 days

Res.: Yes or No

Lum Sum: 20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{1up}
9/20

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SCZ 1001T Yr Regn: 09, 10Type: M Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Vios ^(A)c.c. 1497Colour: M. Maroon

A/C: Insured / Std / NI / NA

Sp. Reading: 294572

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: NR053144930 5191930Gen. Cond: Good Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S Rim / STD A/Rim or

Tyre Size: F: _____

R: 1P5/55R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal. 0 mmR/Bal. 0 mmL/Bal. 0 mmL/Bal. 0 mmD.O.A. 10/7/18D.O.I. 13/7/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

18/7 File notes to Catherine11/8 8550h CatherineTuition Co
(641 x 100)R (\$2,842.46/337.)

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐

: Site Insp (\$ _____)

☐

: Interview (\$ _____)

☐

: Tech. Invs (\$ _____)

☐

: Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

____ \$ + RS, ____ \$

Photos _____

Others _____

TOTAL

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

OK
SCZ1001T
TP/AIG

M/S: AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department \ THE MOTOR

WS Ref: TP/AIG/YS

Claim Type: Third Party

Accident Date: 10/07/2018

TP Veh Reg No: SLF8626T

Estimate No: ES1890782/YISHUN

Date: 13 Jul 2018

Policy No: 5045874150-07

Veh Reg No: SCZ1001T

Make/Model: TOYOTA VIOS 1.5 G A

Chassis No: MR053HY9305191930

Engine No: 1NZY181791

Reg. Date: 20/09/2010

Estimate Repair Cost to Vehicle No :SCZ1001T

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
List Price				
1 FRONT BUMPER	407.25	1 PC	407.25	✓
2 FRONT BUMPER REINFORCEMENT	372.00	1 PC	372.00	✓
3 FRONT BUMPER REINFORCEMENT BRACKETS	251.00	2 PCS	502.00	✓ 251.00 ✓
4 FRONT BUMPER SIDE RETAINERS	58.24	2 PCS	116.48	✓
5 FRONT BUMPER CENTRE LOWER GRILLE	74.74	1 PC	74.74	✓
6 FRT BUMPER LOGO	47.67	1 PC	47.67	✓
7 FRONT BUMPER CLIPS	3.50	10 PCS	35.00	✓
8 FRONT GRILLE	350.24	1 PC	350.24	✓
9 HEADLAMPS	395.34	2 PCS	790.68	✓
10 AIR-CON CONDENSER	1,293.37	1 PC	1,293.37	✓
11 RADIATOR	1,607.00	1 PC	1,607.00	✓
12 RADIATOR SIDE GARNISH RH	32.20	1 PC	32.20	X
13 RADIATOR SIDE GARNISH CLIPS	3.50	4 PCS	14.00	✓
14 RADIATOR FAN COWLING	246.90	1 PC	246.90	X
15 RADIATOR FAN BLADE	201.60	1 PC	201.60	✓
16 RADIATOR FAN MOTOR	263.70	1 PC	263.70	✓
17 FRONT FENDER EMBLEMS	38.43	2 PCS	76.86	✓
18 FRONT LH FENDER INNER SHIELD	161.19	1 PC	161.19	X
19 HORN	101.19	1 PC	101.19	✓
20 FRT SUPPORT PANEL	788.60	1 PC	788.60	✓
21 FRONT SUPPORT PANEL INNER GARNISH	92.40	1 PC	92.40	✓
22 HEADLAMP TOP PANELS	77.20	2 PCS	154.40	✓ R X
23 BONNET LOCK	82.25	1 PC	82.25	✓
			7,811.72	
		Less 25%	1,952.93	5,858.79

Special Net

- 24 FRONT NUMBER PLATE 80.00
25 COOLANT (3 LTRS) 75.00

UKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

80.00	1 PC	80.00	✓
75.00	1 UNIT	75.00	✓ 75.00
		155.00	155.00

Cheng Hoe Motor Pte Ltd

Bk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120
 TEL: 64193000 FAX: 64153727
 ATTN: Motor Claim Department \ THE MOTOR
 WS Ref: TP/AIG/YS
 Claim Type: Third Party
 Accident Date: 10/07/2018
 TP Veh Reg No: SLF8626T

Estimate No: ES1890782/YISHUN
 Date: 13 Jul 2018
 Policy No: 5045874150-07
 Veh Reg No: SCZ1001T
 Make/Model: TOYOTA VIOS 1.5 G A
 Chassis No: MR053HY9305191930
 Engine No: 1NZY181791
 Reg. Date: 20/09/2010

Estimate Repair Cost to Vehicle No :SCZ1001T

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
Labour				
26 REMOVE & REFIX FRT BUMPER ASSY,HEADLAMPS,GRILLE,BONNET & ATTACHMENT,RADIATOR & MOTOR,FRT FENDERS,TO CUT,WELD & RENEW FRT SUPPORT PANEL,KNOCK & REPAIR FRT HEADLAMP PANELS,FRT LH CHASSIS,FRT BOTH FENDERS & REALIGN THE SAME	1,000.00	1 LA	1,000.00	700.00
27 REMOVE AND REFIX AIRCON,CHECK,VACUUM & REFILL GAS	100.00	1 LA	100.00	200.00
28 PUTTY & RESPRAY ON FRT BUMPER,REINFORCEMENT,FRT GRILLE,FRT FENDERS,SUPPORT PANEL,BONNET,FRT LH DOOR	950.00	1 LA	950.00	750.00
29 RUSTPROOFING	30.00	1 LA	30.00	200.00
30 TO REPAIR WIRE HARNESS & CHECK WIRING	30.00	1 LA	30.00	200.00
			2,110.00	2,110.00
Total				S\$ 8,123.79
Add GST @ 7%				568.67
Total Amount Payable				S\$ 8,692.46

Sup =

2 pr head lamp side panel \$89.10 x 2
 = \$178.20
 Lens rslp 44.55
 \$133.65

CoR - 856506
 7m2 for car - 6+1=7 x \$100
 1.7A - 8

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

\$7127.22
 178.20
 \$7305.42
 1826.35
 \$5479.07
 155.90
 1700
 \$7334.07
 1/5 \$5850

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
TEL: 64193000 FAX: 64153727
ATTN: Motor Claim Department \ THE MOTOR
WS Ref: TP/AIG/YS
Claim Type: Third Party
Accident Date: 10/07/2018
TP Veh Reg No: SLF8626T

Estimate No: ES1890782/YISHUN
Date: 17 Jul 2018
Policy No: 5045874150-07
Veh Reg No: SCZ1001T
Make/Model: TOYOTA VIOS 1.5 G A
Chassis No: MR053HY9305191930
Engine No: 1NZY181791
Reg. Date: 20/09/2010

Estimate Repair Cost to Vehicle No :SCZ1001T

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
Supplementary 1				
List Price				
1 HEADLAMP SIDE PANEL	89.10	2 PCS	178.20	
			178.20	
		Less 25%	44.55	133.65
Total				S\$ 133.65
GST Amount				S\$ 9.36
Total Amount Payable				S\$ 143.01

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382 Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SCZ1001T
TP/AIG

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

TEL: 64193000 FAX: 64153727

ATTN: Motor Claim Department \ THE MOTOR

WS Ref: TP/AIG/YS

Claim Type: Third Party

Accident Date: 10/07/2018

TP Veh Reg No: SLF8626T

Estimate No: ES1890782/YISHUN

Date: 13 Jul 2018

Policy No: 5045874150-07

Veh Reg No: SCZ1001T

Make/Model: TOYOTA VIOS 1.5 G A

Chassis No: MR053HY9305191930

Engine No: 1NZY181791

Reg. Date: 20/09/2010

Estimate Repair Cost to Vehicle No :SCZ1001T

6 days

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
List Price				
1 FRONT BUMPER	407.25	1 PC	407.25	✓
2 FRONT BUMPER REINFORCEMENT	372.00	1 PC	372.00	✓
3 FRONT BUMPER REINFORCEMENT BRACKETS	251.00	2 PCS	502.00	✓
4 FRONT BUMPER SIDE RETAINERS	58.24	2 PCS	116.48	✓
5 FRONT BUMPER CENTRE LOWER GRILLE	74.74	1 PC	74.74	✓
6 FRT BUMPER LOGO	47.67	1 PC	47.67	✓
7 FRONT BUMPER CLIPS	3.50	10 PCS	35.00	✓
8 FRONT GRILLE	350.24	1 PC	350.24	✓
9 HEADLAMPS	395.34	2 PCS	790.68	✓
10 AIR-CON CONDENSER	1,293.37	1 PC	1,293.37	✓
11 RADIATOR	1,607.00	1 PC	1,607.00	✓
12 RADIATOR SIDE GARNISH RH	32.20	1 PC	32.20	✓
13 RADIATOR SIDE GARNISH CLIPS	3.50	4 PCS	14.00	✓
14 RADIATOR FAN COWLING	246.90	1 PC	246.90	✓
15 RADIATOR FAN BLADE	201.60	1 PC	201.60	✓
16 RADIATOR FAN MOTOR	263.70	1 PC	263.70	✓
17 FRONT FENDER EMBLEMS	38.43	2 PCS	76.86	X
18 FRONT LH FENDER INNER SHIELD	161.19	1 PC	161.19	X
19 HORN	101.19	1 PC	101.19	✓
20 FRT SUPPORT PANEL	788.60	1 PC	788.60	✓
21 FRONT SUPPORT PANEL INNER GARNISH	92.40	1 PC	92.40	✓
22 HEADLAMP TOP PANELS	77.20	2 PCS	154.40	✓
23 BONNET LOCK	82.25	1 PC	82.25	✓
			7,811.72	
		Less 25%	1,952.93	5,858.79

Special Net

- 24 FRONT NUMBER PLATE 80.00
25 COOLANT (3 LTRS) 75.00

1 PC	80.00	✓
1 UNIT	75.00	✓
	155.00	155.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
TEL: 64193000 FAX: 64153727
ATTN: Motor Claim Department \ THE MOTOR
WS Ref: TP/AIG/YS
Claim Type: Third Party
Accident Date: 10/07/2018
TP Veh Reg No: SLF8626T

Estimate No: ES1890782/YISHUN
Date: 13 Jul 2018
Policy No: 5045874150-07
Veh Reg No: SCZ1001T
Make/Model: TOYOTA VIOS 1.5 G A
Chassis No: MR053HY9305191930
Engine No: 1NZY181791
Reg. Date: 20/09/2010

Estimate Repair Cost to Vehicle No :SCZ1001T

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
Labour				
26 REMOVE & REFIX FRT BUMPER ASSY,HEADLAMPS,GRILLE,BONNET & ATTACHMENT,RADIATOR & MOTOR,FRT FENDERS,TO CUT,WELD & RENEW FRT SUPPORT PANEL,KNOCK & REPAIR FRT HEADLAMP PANELS,FRT LH CHASSIS,FRT BOTH FENDERS & REALIGN THE SAME	1,000.00	1 LA	1,000.00	800
27 REMOVE AND REFIX AIRCON,CHECK,VACUUM & REFILL GAS	100.00	1 LA	100.00	?
28 PUTTY & RESPRAY ON FRT BUMPER,REINFORCEMENT,FRT GRILLE,FRT FENDERS,SUPPORT PANEL,BONNET,FRT LH DOOR	950.00	1 LA	950.00	750
29 RUSTPROOFING	30.00	1 LA	30.00	?
30 TO REPAIR WIRE HARNESS & CHECK WIRING	30.00	1 LA	30.00	20
			2,110.00	2,110.00
Total				S\$ 8,123.79
Add GST @ 7%				568.67
Total Amount Payable				S\$ 8,692.46

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7029E
Vehicle Details	
Vehicle No.:	SCZ1001T
Vehicle to be Exported:	No
Intended De-registration Date:	11 Jul 2018
Vehicle Make:	TOYOTA
Vehicle Model:	VIOS G AUTO
Primary Colour:	Red
Manufacturing Year:	2010
Engine No.:	1NZY181791
Chassis No.:	MR053HY9305191930
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$13,617.00
Original Registration Date:	20 Sep 2010
First Registration Date:	20 Sep 2010
Transfer Count:	0
Actual ARF Paid:	\$13,617.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	19 Sep 2020
PARF Rebate Amount:	\$8,170.00
Intended COE Rebate Details	
COE Expiry Date:	19 Sep 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$29,000.00
COE Rebate Amount:	\$6,347.00
Total Rebate Amount:	\$14,517.00

The information contained herein is correct as at 11 Jul 2018

OK

Enquire Vehicle & Owner Information (Vehicle No. SLF8626T As At 10 Jul 2018 / 16:45:00)**Law Firm Search Details**

Search Reason: Insurance claim in relation to traffic accident

Law Firm Case No.: CHM-SCZ1001

Current Owner Details

Owner ID Type: Company

Owner ID: 201624597K

Owner Name: LCRF PTE LTD

Registered Address Type: Private Residential (non-Condo Apt / non-House)

Registered Block/House No.:60

Registered Street Name: ANSON ROAD

Registered Unit No.: # 11 - 01

Registered Building Name: MAPLETREE ANSON

Registered Postal Code: 079914

Current Vehicle Details

Vehicle No.: SLF8626T

Make Description/Model: TOYOTA / COROLLA AXIO 1.5X A

Insurance Company Name: AIG ASIA PACIFIC INSURANCE PTE. LTD.

[> Back to OneMotoring](#)**Enquire Transfer Fee**

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	SCZ1001T		
Vehicle Type :	L10 - For Instruction Motor Car		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	TOYOTA		
Vehicle Model :	VIOS G AUTO		
Chassis No. :	MR053HY9305191930		
Propellant :	Petrol		
Engine No. :	1NZY181791		
Engine Capacity :	1497 cc		
Maximum Power Output :	80.0 kW (107 bhp)		
Maximum Laden Weight :	1520 kg		
Unladen Weight :	1110 kg		
Year Of Manufacture :	2010		
Original Registration Date :	20 Sep 2010		
Lifespan Expiry Date :	-		
COE Category :	A - Car (1600cc & below)		
Quota Premium :	\$29,000.00		
COE Expiry Date :	19 Sep 2020		
Road Tax Expiry Date :	19 Sep 2018		
PARF Eligibility Expiry Date :	19 Sep 2020		
Inspection Due Date :	19 Sep 2018		
Intended Transfer Date :	11 Jul 2018		
CO2 Emission :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
The current road tax expiry is 19 Sep 2018. You may renew the road tax from 20 Jun 2018 with all pre-requisite(s) fulfilled. If the road tax is renewed after 19 Sep 2018, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable (From 20 Sep 2018 to 19 Mar 2019)			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Sub Total :			25.00
Nett Road Tax Amount (After Offsetting Over Payment) :	342.00	-	342.00
Total Amount Payable :			367.00
Amount Payable (From 20 Sep 2018 to 19 Sep 2019)			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Sub Total :			25.00
Nett Road Tax Amount (After Offsetting Over Payment) :	684.00	-	684.00
Total Amount Payable :			709.00

You may print this page for reference.

OK

Print

Joy

PAYMENT ADVICE

Your Ref : AIG Vehicle no.	: SLF8626T
Claimant Vehicle No.	: SCZ1001T
Date of Accident	: 10/07/2018
Traffic Accident involving vehicle/s No.	: ALONG BUKIT BATOK WEST AVE 5

BREAKDOWN OF PAYMENT/S

<u>S/No.</u>	<u>Items</u>	<u>Amount</u>	<u>Remark</u>
1	Repair cost	\$ 6,259.50	
2	Loss of Income	\$ 700.00	\$100 X 7 days (Tuition car)
3	LTA Search	\$ 8.00	
TOTAL		\$ 6,967.50	

All payment should be made payable to Cheng Hoe Motor Pte Ltd.

Service Adviser : LKK
Contact No. : 6256 3561

Joy Irene (LKKAUTO)

From: Joy Irene (LKKAUTO)
Sent: Monday, 23 July 2018 5:37 PM
To: Eileen Yap
Cc: Admin A; Vivian Lau (LKKAUTO); Hsiao Tong (LKKAUTO)
Subject: ACCIDENT INVOLVING SLF 8626T & SCZ 1001T ON 10/07/2018 (16:30) ALONG BUKIT BATOK WEST AVE 5

23 July 2018

LCRF PTE LTD

Policy Holder

Your Ref: SLF 8626T
Our Ref: CC4/LCR18012755/Kjb3

Dear Sir/Madam,

ACCIDENT INVOLVING SLF 8626T & SCZ 1001T ON 10/07/2018 (16:30) ALONG BUKIT BATOK WEST AVE 5

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

We have received a claim from **SCZ 1001T** against your insurance policy.

Based on the information on hand, we are of the opinion that we cannot be absolved from liability. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please call us if you have further queries.

Best Regards,
Joy Irene | Case Handler
LKK Auto Consultants Pte Ltd
DID: 6841-2409 | email: joyirene@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

AUTHORISATION TO ACT
(AIG Asia Pacific - Express Third Party Claim)

I, Ong Chin Hong (the third party claimant) of 221 Pavilion
Circle Singapore 658236 (address), owner of SCZ1001T (vehicle no.) hereby
authorize CHENG HOE MOTOR PTE LTD ("the workshop") to act for me with respect to
my claim for repair costs and/or rental and/or loss of use ("claim") for my vehicle no. SCZ1001T that
was damaged pursuant to the accident which occurred on 10/7/2018 (date) along BT Batok
West Ave 5 (location) involving vehicle no/s SLF8626T ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit and the
workshop is further authorized to receive payment further to settlement of my claim with payment cheque/s
being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice
and without admission of liability basis insofar as the driver/owner/insurers of the other vehicle/s is
concerned.

Dated this 11 (day) of Feb (month) 20 19 (year)



Signed by "the third party claimant"
(with chop if applicable)



Signed by "the workshop"
(with chop)

Claimant's claim for property damages only does not constitute a full discharge for any other claims or further claims whatsoever present or future that may in whole or in part arise directly or indirectly from this accident. This settlement terms herein is without an admission of liability on the part of the claimant and the settlement terms should not be used as evidence in any related suits or claims arising from this accident.

RELEASE VOUCHER

(AIG Asia Pacific - EXPRESS THIRD PARTY CLAIM)

"We/I, **CHENG HOE MOTOR PTE LTD** ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd **LKK** **AUTO CONSULTANTS PTE LTD** (name of surveyor) with respect to the amount claimed for **S\$6259.50** (Repair Cost), **S\$700.00** (Loss of Income), **S\$8.00** (Disbursement), for vehicle no **SCZ1001T** that was damaged pursuant to the accident which occurred **10/7/2018** (date) along **Bukit Batok West Ave 5** (location) involving vehicle no/s **SLF8626T**. This is pursuant to the inspection conducted on **13/7/2018** (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner **Ong Chin Hong** ("the third party claimant") of vehicle no **SCZ1001T** make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage **SCZ1001T** (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 12 (day) of May (month) 2019 (year)



Signed by appointed surveyor



Signed by "the workshop" (with chop)

Cheng Hoe Motor Pte Ltd

Bkk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

TAX INVOICE

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
TEL: 64193000 FAX: 64153727
ATTN: Motor Claim Department
WS Ref: TP/AIG/YS
Claim Type: Third Party
Accident Date: 10/07/2018
TP Veh Reg No: SLF8626T

NO: CL8190331
Date: 12 Apr 2019
Policy No: 5045874150-07
Veh Reg No: SCZ1001T
Make/Model: TOYOTA VIOS 1.5 G A
Job No: JC1599543

Description	Quantity	List Price	PAGE:1
			Amount
To Supply all replaced parts, all necessary and agreed labour & miscellaneous charges. (As recommended by your appointed surveyor)	1 PC	<u>S\$</u> S\$ 5,850.00	<u>S\$</u> S\$ 5,850.00

Total	S\$ 5,850.00
Add GST @ 7%	409.50
Total Amount payable	S\$ 6,259.50

For Cheng Hoe Motor Pte Ltd

E. & O. E.

AUTHORISED SIGNATURE

A.C. SYED & PARTNERS

ADVOCATES & SOLICITORS

COMMISSIONER FOR OATHS

101A UPPER CROSS STREET, #13-23 PEOPLE'S PARK CENTRE, SINGAPORE 058358

TEL : 6538 7411 & FAX : 6534 1011

TO : CHENG HOE MOTOR PTE LTD	BILL NO: B053/ 2018
YOUR REF:	
OUR REF : ACS.CH.LTA.2018 (JULY 2018)	DATE : 3/8/18

TO OUR PROFESSIONAL CHARGES for acting for you in the above matter including where necessary perusals, attendance preparation examination of documents relating thereto; correspondence, attendance, perusals, telephone calls, searches and all other incidental works not specifically mentioned herein to enable us to carry out the work entrusted to us inclusive of all advice.

LTANET SEARCHES FOR THE MONTH JULY 2018

S/NO	TP NO.	CHM	DOA	
1	2/7/2018	SLV2480B	GBC801R	30/6/2018
2	2/7/2018	WC6758U	SKB9008D	2/7/2018
3	3/7/2018	SJP5443U	SGT8169G	1/7/2018
4	5/7/2018	SKZ6272A	SGT2238E	5/7/2018
5	6/7/2018	SJJ4674H	SLG3720G	5/7/2018
6	6/7/2018	FBG8275K	GBB2867T	4/7/2018
7	7/7/2018	SJM7602E	SLT3675K	7/7/2018
8	9/7/2018	SLQ3458L	SJY4796K	8/7/2018
9	8/7/2018	SLN6813R	SLV2410D	7/7/2018
10	10/7/2018	SKV8647K	SGT2713A	6/7/2018
11	10/7/2018	PA8339B	SLL4307J	5/7/2018
12	10/7/2018	SJJ3340C	SLB8162K	23/6/2018
13	11/7/2018	SLF8626T	SCZ1001T	10/7/2018
14	11/7/2018	SKA5113P	PC4270E	8/7/2018
15	11/7/2028	XD6205G	GZ9305S	6/7/2018
16	11/7/2018	SKT9130M	SLX295Y	11/7/2018
17	11/7/2018	SBR1111M	SLP5483E	10/7/2018
18	11/7/2018	SLL7910Y	SGN6284B	8/7/2018
19	14/7/2018	SLP7837E	GBE4435	13/7/2018
20	18/7/2018	XD4751J	GBF5975Z	17/7/2018
21	19/7/2018	FU5986R	SLG784S	18/8/2017
22	19/7/2018	GBF5606P	GBD5240X	8/11/2017
23	19/7/2018	GBC1638P	SKQ9644M	18/7/2018
24	23/7/2018	EL1998T	EL351P	22/7/2018
25	23/7/2018	SLH8653D	SLS5743P	17/7/2018
26	26/7/2018	SLZ4725L	SJX9961Y	25/7/2018
27	27/7/2018	XB3212R	SKF5193G	26/7/2018
28	31/7/2018	SJK4937U	SGE2583L	9/1/2018
29	31/7/2018	PA9787J	SLU9737X	17/5/2018

29 searches @\$8.00 per search

Total:

\$ 232.00

[SINGAPORE DOLLARS; TWO HUNDRED & THIRTY-TWO ONLY.]

M/s. A.C. SYED & PARTNERS
ADVOCATES & SOLICITORS
SINGAPORE

We reserved the right to forward a subsequent bill for any
disbursements omitted herein.

E. & O.E.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Jul 2018 Edit Reg		12 Jul 2018 00:00 Edit Adj Rpt	S\$5,850.00 Edit Estimates	S\$5,850.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	LCRF Pte Ltd, Co. Reg. No.: NA								
Main Claimant:	ONG CHIN HONG, ID: S1257029E								
Vehicle Reg. No.:	SCZ1001T	Date of Loss:	10/07/2018 16:00 - :59 [93 Months and 20 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 6642052442SG	Policy/Cover Note No.:	0999994763 (Comprehensive)						
Vehicle Reg. No. (Insured):	SLF8626T	Policy No. (Claimant):	5045874150-07						
		Excess:							
Repairer:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Olea, Maricel] Maricel.Olea@aig.com								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 24/07/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SCZ1001T (6642052442SG)
[SLF8626T]
TP
ONG CHIN HONG
Jul 10 2018 4:00PM
[LCRF Pte Ltd]
Cheng Hoe Motor Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Letters/Correspondences				
			1 per page	☒
No	Finalized On		Thumbnail	Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown		Edit
Assessment Reports				
			1 per page	☒
No	Finalized On		Thumbnail	Print
1	16/07/18 12:27	Accident Statement From: SC - Reg. No: SLF8626T; Claimant: LION CITY RENTALS PTE LTD		Load HTM
Photos/Images				
			3 per page	☒
No	Relabel/Reorder		Thumbnail	Print
1	07/05/19 14:55	LKK INSPECTION PHOTOS		Load PDF
2	07/05/19 14:55	LKK RE-INSPECTION PHOTOS		Load PDF
3	07/05/19 14:55	LKK RE-INSPECTION PHOTOS2		Load PDF
4	07/05/19 14:55	LKK RE-INSPECTION PHOTOS3		Load PDF
Documentation				
			1 per page	☒
No	Relabel/Reorder		Thumbnail	Print
1	13/07/18 11:56	EMAIL FROM AIG DD 12072018		Load PDF
2	13/07/18 11:56	TP GIA REPORT		Load PDF
3	16/07/18 17:45	TP ESTIMATE- MARKED		Load PDF
4	15/05/19 11:04	WORKSHOP INVOICE		Load PDF
5	15/05/19 11:04	AUTHORISATION TO ACT FORM		Load PDF
6	15/05/19 11:04	Release Voucher		Load PDF
7	15/05/19 11:04	LTA SEARCH		Load PDF
8	15/05/19 11:04	LETTER TO OI		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST		Reset Save Print
There are no document checklists configured.		
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)		
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.		

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SLF8626T (Insd veh)	Model:	TOYOTA VIOS 1.5 G (A)
	SCZ1001T (TP veh)		
Date of Accident:	10/07/2018		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	8,835.46
Final Repair Cost	:	\$	6,259.50
Loss of Use	:	\$	700.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	8.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	6,967.50

7.00 days at \$100.00 per day

days

Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: ~~Yes~~/ No BOLA Scenario No: _____

BOLA Liability: _____ 100 (%) Assessed Liability (*): _____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Cheng Hoe Motor Pte Ltd	:	\$ 6,967.50
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

15 May
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd

(Co Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/LCR18012755/KJB3Q2

Date: 15/05/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

0999994763

Claimant Vehicle No : SCZ1001T

Insured Vehicle No : SLF8626T

Date of Loss: 10/07/2018

Nature of Claim:

TP

Claim No: 6642052442SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SCZ1001T

Make & Model: TOYOTA VIOS, 1.5 G (A)

Engine No: 1NZY181791

Reg. Date: 20/09/2010 (Man. Year: 2010)

Chassis No: MR053HY9305191930

Colour: Metallic Maroon

Odometer: 294572 km

Engine Capacity: 1497 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/55 R15

Rear Tyre Size:

195/55 R15

Front Left Side: Bridgestone 8 mm

Rear Left Side:

Bridgestone 8 mm

Front Right Side: Bridgestone 8 mm

Rear Right Side:

Bridgestone 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	6,147.44	5,780.65	366.79	5.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,110.00	1,700.00	410.00	19.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,257.44	7,480.65	776.79	9.41
Approved Total (Overridden) (S\$)		5,850.00		
(S\$)	8,257.44	5,850.00	2,407.44	29.15
+ GST 7.00/7.00% (S\$)	578.02	409.50	168.52	29.15
Nett Amount (S\$)	8,835.46	6,259.50	2,575.96	29.15
+ Loss of Use (7.0 x S\$100.00/day) (S\$)		700.00		
+ Doc/Search Fee (S\$)		8.00		
Nett Liability (S\$)		6,967.50		

INSPECTION

Date of Assignment: 12/07/2018

Date Inspected: 13/07/2018 Inspected At:

Cheng Hoe Motor Pte Ltd (Yishun)

Blk 1019 #01-374/382, Yishun Industrial

Park A
Singapore 768761

Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG

Manager: Joy Irene Bascao

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled / Cracked	407.25 FL	*407.25 FL
2	1		*FRONT BUMPER REINFORCEMENT	Bent	372.00 FL	*372.00 FL
3	1		*FRONT BUMPER REINFORCEMENT BRACKETS	N/S Bent	502.00 FL	*251.00 FL
4	2		*FRONT BUMPER SIDE RETAINERS	Distorted	116.48 FL	*116.48 FL
5	1		*FRONT BUMPER CENTRE LOWER GRILLE	Distorted	74.74 FL	*74.74 FL
6	1		*FRT BUMPER LOGO	Necessary	47.67 FL	*47.67 FL
7	10		*FRONT BUMPER CLIPS	Necessary	35.00 FL	*35.00 FL
8	1		*FRONT GRILLE	Cracked	350.24 FL	*350.24 FL
9	2		*HEADLAMPS	Mtg Cracked	790.68 FL	*790.68 FL
10	1		*AIR-CON CONDENSER	Twisted / Punctured	1,293.37 FL	*1,293.37 FL
11	1		*RADIATOR	Bent	1,607.00 FL	*1,607.00 FL
12	1		*RADIATOR SIDE GARNISH RH	Cracked	32.20 FL	*32.20 FL
13	4		*RADIATOR SIDE GARNISH CLIPS	Necessary	14.00 FL	*14.00 FL
14	1		*RADIATOR FAN COWLING	Cracked	246.90 FL	*246.90 FL
15	1		*RADIATOR FAN BLADE	Distorted	201.60 FL	*201.60 FL
16	1		*RADIATOR FAN MOTOR	Jammed	263.70 FL	*263.70 FL
17	2		*FRONT FENDER EMBLEMS	Not Necessary	76.86 FL	*- FL
18	1		*FRONT LH FENDER INNER SHIELD	Serviceable	161.19 FL	*- FL
19	1		*HORN	Dented	101.19 FL	*101.19 FL
20	1		*FRT SUPPORT PANEL	Bent	788.60 FL	*788.60 FL
21	1		*FRONT SUPPORT PANEL INNER GARNISH	Cracked	92.40 FL	*92.40 FL
22	2		*HEADLAMP TOP PANELS	Bent	154.40 FL	*154.40 FL
23	1		*BONNET LOCK	Distorted	82.25 FL	*82.25 FL
24	1		*FRONT NUMBER PLATE	Dented / Cracked	80.00 FS	*80.00 FS
25	1		*UNIT COOLANT (3 LTRS)	Necessary	75.00 FS	*75.00 FS
26	2		*HEADLAMP SIDE PANEL	Bent	178.20 FL	*178.20 FL

F=Franchise part. S=SpcNett. L=ListItemDisc

Sub Total (S\$) **8,144.92** **7,655.87**
 - List Item Discount on L Items 25.00/25.00% (S\$) 1,997.48 1,875.22

Total Parts (S\$) **6,147.44** **5,780.65**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REFIX FRT BUMPER ASSY ,HEADLAMPS ,GRILLE ,BONNET & ATTACHMENT ,RADIATOR & MOTOR ,FRT FENDERS ,TO CUT ,WELD & RENEW FRT SUPPORT PANEL ,KNOCK & REPAIR FRT HEADLAMP PANELS ,FRT LH CHASSIS ,FRT BOTH FENDERS & REALIGN THE SAME	New	1,000.00	800.00
2	REMOVE AND REFIX AIRCON ,CHECK ,VACUUM & REFILL GAS	New	100.00	100.00
3	PUTTY & RESPRAY ON FRT BUMPER ,REINFORCEMENT ,FRT GRILLE ,FRT FENDERS ,SUPPORT PANEL ,BONNET ,FRT LH DOOR	New	950.00	750.00
4	RUSTPROOFING	New	30.00	30.00
5	TO REPAIR WIRE HARNESS & CHECK WIRING	New	30.00	20.00
Gross Labour Cost (S\$)			2,110.00	1,700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >