

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SCZ1001T
TP/AIG

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department \ THE MOTOR

WS Ref: TP/AIG/YS

Claim Type: Third Party

Accident Date: 10/07/2018

TP Veh Reg No: SLF8626T

Estimate No: ES1890782/YISHUN

Date: 13 Jul 2018

Policy No: 5045874150-07

Veh Reg No: SCZ1001T

Make/Model: TOYOTA VIOS 1.5 G A

Chassis No: MR053HY9305191930

Engine No: 1NZY181791

Reg. Date: 20/09/2010

Estimate Repair Cost to Vehicle No :SCZ1001T

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
List Price				
1 FRONT BUMPER	407.25	1 PC	407.25	✓
2 FRONT BUMPER REINFORCEMENT	372.00	1 PC	372.00	?
3 FRONT BUMPER REINFORCEMENT BRACKETS	251.00	2 PCS	502.00	?
4 FRONT BUMPER SIDE RETAINERS	58.24	2 PCS	116.48	✓
5 FRONT BUMPER CENTRE LOWER GRILLE	74.74	1 PC	74.74	✓
6 FRT BUMPER LOGO	47.67	1 PC	47.67	✓
7 FRONT BUMPER CLIPS	3.50	10 PCS	35.00	✓
8 FRONT GRILLE	350.24	1 PC	350.24	✓
9 HEADLAMPS	395.34	2 PCS	790.68	?
10 AIR-CON CONDENSER	1,293.37	1 PC	1,293.37	?
11 RADIATOR	1,607.00	1 PC	1,607.00	?
12 RADIATOR SIDE GARNISH RH	32.20	1 PC	32.20	?
13 RADIATOR SIDE GARNISH CLIPS	3.50	4 PCS	14.00	?
14 RADIATOR FAN COWLING	246.90	1 PC	246.90	?
15 RADIATOR FAN BLADE	201.60	1 PC	201.60	?
16 RADIATOR FAN MOTOR	263.70	1 PC	263.70	?
17 FRONT FENDER EMBLEMS	38.43	2 PCS	76.86	?
18 FRONT LH FENDER INNER SHIELD	161.19	1 PC	161.19	?
19 HORN	101.19	1 PC	101.19	?
20 FRT SUPPORT PANEL	788.60	1 PC	788.60	?
21 FRONT SUPPORT PANEL INNER GARNISH	92.40	1 PC	92.40	?
22 HEADLAMP TOP PANELS	77.20	2 PCS	154.40	?
23 BONNET LOCK	82.25	1 PC	82.25	✓
			7,811.72	
		Less 25%	1,952.93	5,858.79

Special Net

- 24 FRONT NUMBER PLATE 80.00
25 COOLANT (3 LTRS) 75.00

1 PC	80.00	✓
1 UNIT	75.00	?
	155.00	155.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
TEL: 64193000 FAX: 64153727
ATTN: Motor Claim Department \ THE MOTOR
WS Ref: TP/AIG/YS
Claim Type: Third Party
Accident Date: 10/07/2018
TP Veh Reg No: SLF8626T

Estimate No: ES1890782/YISHUN
Date: 13 Jul 2018
Policy No: 5045874150-07
Veh Reg No: SCZ1001T
Make/Model: TOYOTA VIOS 1.5 G A
Chassis No: MR053HY9305191930
Engine No: 1NZY181791
Reg. Date: 20/09/2010

Estimate Repair Cost to Vehicle No :SCZ1001T

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
Labour				
26 REMOVE & REFIX FRT BUMPER ASSY,HEADLAMPS,GRILLE,BONNET & ATTACHMENT,RADIATOR & MOTOR,FRT FENDERS,TO CUT,WELD & RENEW FRT SUPPORT PANEL,KNOCK & REPAIR FRT HEADLAMP PANELS,FRT LH CHASSIS,FRT BOTH FENDERS & REALIGN THE SAME	1,000.00	1 LA	1,000.00	?
27 REMOVE AND REFIX AIRCON,CHECK,VACUUM & REFILL GAS	100.00	1 LA	100.00	?
28 PUTTY & RESPRAY ON FRT BUMPER,REINFORCEMENT,FRT GRILLE,FRT FENDERS,SUPPORT PANEL,BONNET,FRT LH DOOR	950.00	1 LA	950.00	750
29 RUSTPROOFING	30.00	1 LA	30.00	?
30 TO REPAIR WIRE HARNESS & CHECK WIRING	30.00	1 LA	30.00	20
			2,110.00	2,110.00
			Total	S\$ 8,123.79
			Add GST @ 7%	568.67
			Total Amount Payable	S\$ 8,692.46

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE