



Adnan Lkk - C/P2  
 新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K

12/07/2018

Blk 1 Kaki Bukit Ave 6

# 01-43

Singapore 417883

TP China.

Asher.

MRHDD4870FP000020

Accident date: 07/07/2018

Estimated repair cost for vehicle no: SKS2879M HONDA MOBILIO 1.5 A '15

CHASSIS: MRHDD4870FP000020

S/n	Qty	Items / List	U/price	Amount
1	1	Front Bonnet <i>Dented</i>		\$698.90 ✓
2	2	Front Bonnet Hinge <i>None</i>	\$59.10	\$118.20 ✗
3	1	Front Bonnet Lock <i>Damaged</i>		\$106.20 ✓
4	1	Front Bonnet Insulator <i>2 new</i>		\$82.60 ✗
5	10	Front Bonnet Insulator Clip <i>5 new</i>	\$6.50	\$65.00 ✗
6	2	Front Bonnet Inner Side Rubber <i>new</i>	\$69.80	\$139.60 ✗
7	1	Front Bonnet Inner Air Duct Cover <i>Not new</i>		\$150.10 ✗
8	2	Front Head Lamp <i>RH cracked</i>	\$1,088.70	\$2,177.40 ✓ <i>1088.70</i>
9	2	Front Head Lamp Lower Bracket <i>Not new</i>	\$61.10	\$122.20 ✗
10	1	Front Grille <i>cracked</i>		\$282.00 ✓
11	1	Front Grille Emblem Logo <i>new</i>		\$57.10 ✓
12	1	Front Grille Chrome Moulding Assy <i>cracked</i>		\$263.50 ✓
13	1	Front Bumper <i>Dented</i>		\$559.80 ✓
14	10	Front Bumper Clip <i>new</i>	\$6.50	\$65.00 <i>30</i>
15	2	Front Bumper Side Retainer <i>new</i>	\$31.00	\$62.00 ✓
16	1	Front Bumper Number Plate <i>Bent</i>		\$50.00 ✓
17	1	Front Bumper Centre Garnish Cover <i>cracked</i>		\$165.10 ✓
18	1	Front Bumper Reinforcement <i>Bent</i>		\$210.50 ✓
19	2	Front Bumper Fog Lamp <i>Not new</i>	\$327.20	\$654.40 ✗
20	2	Front Bumper Fog Lamp Cover & Chrome Assy <i>Not new</i>	\$185.40	\$370.80 ✗
21	1	Front Support Panel <i>Repair</i>		\$663.10 ✗
22	1	Front Support Panel Top Cover <i>Dented</i>		\$98.90 ✓
23	8	Front Support Panel Top Cover Clip <i>new</i>	\$6.50	\$52.00 <i>20</i>
24	1	Front Air-Con Condenser <i>Not new</i>		\$668.10 ✗
25	1	Front Radiator <i>Not new</i>		\$1,200.50 ✗

3692.70  
 2954.16

Subtotal :- \$9,083.00

**Labour charges**

To remove & refit air-con condenser, radiator, fan motor & top up gas	<del>\$380.00</del> 120
To check wiring	<del>\$60.00</del> 30
Towing fee	1200 <del>\$100.00</del> X
Tuff kote	<del>\$150.00</del> X
Panel beating	<del>\$1,400.00</del> 450
Spray painting	<del>\$1,400.00</del> 600

Subtotal :- \$3,490.00

Total:- \$12,573.00

total: 4154.16

2/s: 3.3K

3.3K  
04 Days

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: