

Surveyor:

LWP

DOI:

12/1/18

Date / Time:

12/1/18

Registered in Merimen:

13/1/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

EP 707 B

Name of Insured:

SEE STEW LUAN @ TAN STEW LUAN

Insured Tel No.:

HP:

48 200001

Excess Sec II :S5

D.O.A:

11/1/2018

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

1700092226

M- BENZ E250

Amk Ave 5

If NO, Driver Name / Age:

Driver Tel No.:

(V/L YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

STV 4196H



INSRS:

WSP:

Tel:

Liability:

RMKS:

M17



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

12/1/18

STV 4196H. X; EP 707 B. X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI: EMAIL 1-8-18

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by: LWP

Repair Cost:

43 S\$9,800

(

14 days)

Reduction:

68 %

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with: S\$404

Email

Call

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.:

3

If NO or B 28, Ass. Lia:

Repair Cost:

S\$9,800-00

OI MAKE A RM TURN E

CONTROL JUNCTION.

Loss of Rental (LOR):

S\$ -

(

days)

Loss of Use (LOU):

S\$ 1,280-00

(S\$ 80

x

14 days)

Loss of Income (LOI):

S\$ -

(S\$

x days)

LOR only

LOU only

LOR + LOU

LOR + LOI

(Tick only one)

GIA/LTA Search

S\$ 1.45

Medical:

S\$ -

Disbursement:

S\$ -

(e.g. Tow/ Independent)

Legal Cost

S\$ -

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

S\$30 + S\$20

Total:

S\$ 11,081.45

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with: S\$404

Email

Call

Payee 1:

S\$ 11,081.45

Name 1:

New Hook Tech Motor Pte Ltd.

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

28/01/19





Adnan LF-116  
新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K

12/07/2018

Blk 1 Kaki Bukit Ave 6

# 01-43

Singapore 417883

TPA16

Poker

KMH0U41BMAU932924

Accident date: 11/07/2018

Estimated repair cost for vehicle no: SJV4196H HYUNDAI AVANTE 1.6 A '10

CHASSIS: KMH0U41BMAU932924

S/n	Qty	Items / List	U/price	Amount
1	1	Front Bonnet Distorted		\$1,001.90 ✓
2	2	Front Bonnet Hinge Bent	\$43.80	\$87.60 ✓
3	1	Front Bonnet Insulator crumpled		\$180.70 ✓
4	8	Front Bonnet Insulator Clip ne	\$6.50	\$52.00 ✓
5	1	Front Bonnet Lock Dand		\$122.30 ✓
6	1	Front Bonnet Rubber ct		\$65.50 ✓
7	2	Front Head Lamp cracked	\$463.80	\$927.60 ✓
8	2	Front Head Lamp Lower Bracket Dand	\$32.00	\$64.00 ✓
9	1	Front Bumper Distorted		\$428.00 ✓
10	10	Front Bumper Clip new	\$6.50	\$65.00 ✓
11	2	Front Bumper Side Retainer NA	\$33.00	\$66.00 ✓
12	1	Front Bumper Number Plate Bent		\$50.00 ✓
13	1	Front Bumper Centre Garnish Bent		\$86.40 ✓
14	1	Front Bumper Inner Sponge crumpled		\$106.90 ✓
15	2	Front Bumper Reinforcement Bent	\$239.60	\$479.20 ✓
16	2	Front Bumper Fog Lamp Cover new	\$74.40	\$148.80 x
17	1	Front Grille cracked		\$288.00 ✓
18	1	Front Grille Emblem Logo new		\$61.10 ✓
19	2	Front Fender Distorted	\$396.70	\$793.40 ✓
20	2	Front Fender Vvti Logo new	\$31.00	\$62.00 ✓
21	2	Front Fender Cowling 3 new	\$53.60	\$107.20 x
22	16	Front Fender Cowling Clip ne	\$6.50	\$104.00 x
23	2	Front Fender Inner Panel Repair	\$468.70	\$937.40 x
24	2	Front Fender Housing Repair	\$651.80	\$1,303.60 x
25	1	Front Wiper Tank Distorted		\$75.80 ✓
26	2	Front Wiper Tank Motor x new	\$55.80	\$111.60 x
27	1	Front Support Panel Distorted		\$753.00 ✓
28	1	Front Support Panel Top Air Cleaner Air Duct cracked		\$186.60 ✓

29	1	Front Support Panel Top Air Cleaner Air Duct Hose	Asy	\$169.40	✓
30	1	Front Air Cleaner Box	Not New	\$102.00	+
31	1	Front Air-Con Condenser	Distorted	\$876.00	✓
32	1	Front Air-Con Section Pipe	Bent	\$231.80	✓
33	1	Front Air-Con Discharge Pipe		\$345.10	✓
34	1	Front Air-Con Fan Motor Assy	Not New	\$1,040.40	+
35	1	Front Radiator	Distorted	\$589.00	✓
36	1	Front Radiator Top Hose	Torn	\$38.60	✓
37	1	Front Radiator Lower Hose	Not New	\$42.80	+
38	1	Front Radiator Spare Tank	Distorted	\$69.20	✓
39	1	Front Radiator Fan Motor Assy	Asy	\$488.00	✓
40	1	Front Air-Con Compressor	Not New	\$1,467.00	+
41	1	Front Dohc 16v Cover	2	\$106.00	+
42	1	Front Battery	Not New	\$180.00	+
43	1	Front Battery Lower Cover		\$38.60	+
44	1	Front Chassis	Bent	\$489.00	+
45	1	Front Crossmember	Bent	\$2,598.40	✓
46	4	Front Engine Mounting	2	\$286.00	+
47	1	Front Antenna		\$166.00	✓
48	2	Front Horn	Asy	\$61.80	+
49	2	Front Lower Arm	Not New	\$305.00	+
50	2	Front Knuckle Arm		\$281.00	+
51	2	Front Knuckle Arm Bearing		\$108.00	+
52	2	Front Shock Absorber		\$298.00	+
53	2	Front Drive Shaft		\$727.10	+
54	1	Front Steering Rack	✓	\$1,328.00	+

Subtotal :- \$22,928.70

11408.5  
9126.80

### Labour charges

To remove & refit front engine	<del>\$550.00</del> 380
To remove & refit crossmember, undercarriage, drive shaft & steering rack	<del>\$750.00</del> 500
To remove & refit air-con condenser, radiator, fan motor & top up gas	<del>\$380.00</del> 120
To check wheel alignment	<del>\$150.00</del> 80
To check wiring	<del>\$100.00</del> 30
Towing fee	<del>\$100.00</del> 60
Tuff kote	<del>\$150.00</del> 50
Panel beating	<del>\$3,000.00</del> 1600
Spray painting	<del>\$2,200.00</del> 1400
	4220
Subtotal :-	<u>\$7,380.00</u>
Total:-	<u>\$30,308.70</u>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be seen in work and is subject to final approval from insurance company

Acknowledged by Repairer

Signature:

Date:

Total: 13346.8

l/s : 9.8K

14 Days

9.8K



[SEARCH](#)







[Advanced Search](#)

## Used Car Comparison

— Comparing 3 Vehicles —

Hyundai Avante 1.6A



Clear All

[Add all to Shortlist](#)

[Back to search result](#)

[Add to Shortlist](#)

Hyundai Avante 1.6A S



[Add to Shortlist](#)

Hyundai Avante 1.6A S



[Add to Shortlist](#)



Use search bar above to set to compare.

### CAR DETAILS

Price	\$18,500	\$17,500	\$16,800	-
Instalment	\$794	\$751	\$721	-
Registration Date	02-Jan-2010	06-Jan-2010	18-Dec-2009	-
Manufactured	2009	2009	2009	-
Mileage	-	108,916 km	-	-
Transmission	Auto	Auto	Auto	-
Engine Cap	1,591 cc	1,591 cc	1,591 cc	-
Road Tax	\$738 /yr	\$738 /yr	\$738 /yr	-
Power	89.7 kW (120 bhp)	89.7 kW (120 bhp)	89.7 kW (120 bhp)	-
Curb Weight	1,264 kg	1,264 kg	1,264 kg	-
Features	-	Original Condition.	1.6L DOHC 16V VVT Engine, Smooth 5 Speed Auto Transmission, Dual SRS Airbags, ABS, EPS, Digital Climatic Control Aircon, Etc.	-
Accessories	-	Factory Fitted Interior.	Sports Rims, Leather Seats, Audio Player, Remote Alarm, Solar Film, Knockdown Rear Seats, Reverse Sensors, Etc.	-
Description	Down Payment \$2.3k Monthly \$796, Showroom Condition, Serviced Regularly, Accident Free, Well Maintained By Retiree Owner, Call Now. Quality Used Cars You Can Trust Only At Choon Bee.	(High Specification S Model!) 1st Owner Unit. We Have 11 Unit Of Quality Pre (Hyundai Avante) Fully Done Up In Showroom Condition For Your Selection. Purchase And Enjoy 6 Months Engine And Gearbox Protection Plan With 24/7 Roadside Assistant And Replacement Vehicle Coverage Worth \$688! STA/VICOM/AA/IDAC Evaluation Friendly. (Viewing Available Daily By Appointment.)	Guarantee Buy Back At \$7k. Cheapest In The Market! Quiet Engine And Undercarriage With Smooth Running Condition. Very Good Condition! Fuel Efficiency At 12Km/L! Easy To Drive And Maintain! Welcome Trade In Or High Loan! Not To Be Missed! Call Us Now!	-
COE	\$18,502	\$18,150	\$18,502	-
OMV	\$11,398	\$11,545	\$11,334	-
ARF	\$11,398	\$11,545	\$11,334	-
Depreciation	\$8,680 /yr	\$7,900 /yr	\$7,770 /yr	-
No. of Owners	3	1	2	-
Type of Vehicle	Sedan	Sedan	Sedan	-
Category	PARF Car	PARF Car, Premium Ad Car	PARF Car	-
Availability	Available	Available	Available	-

### SELLER INFORMATION

[-> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Limited Liability Partnership  
Owner ID: 1847F

**Vehicle Details**

Vehicle No.: SJV4196H  
Vehicle to be Exported: No  
Intended De-registration Date: 12 Jul 2018  
Vehicle Make: HYUNDAI  
Vehicle Model: AVANTE 1.6 AT ABS D/AB 2WD 4DR  
Primary Colour: White  
Manufacturing Year: 2009  
Engine No.: G4FC9U775446  
Chassis No.: KMH DU41BMAU932924  
Maximum Power Output: 89.7 kW (120 bhp)  
Open Market Value: \$11,325.00  
Original Registration Date: 26 Jan 2010  
First Registration Date: 26 Jan 2010  
Transfer Count: 2  
Actual ARF Paid: \$11,325.00

**Intended PARF Rebate Details**

PARF Eligibility: Yes  
PARF Eligibility Expiry Date: 25 Jan 2020  
PARF Rebate Amount: \$6,228.00

**Intended COE Rebate Details**

COE Expiry Date: 25 Jan 2020  
COE Category: E - Open Category  
COE Period(Years): 10  
QP Paid: \$19,000.00  
COE Rebate Amount: \$2,570.00  
**Total Rebate Amount: \$8,798.00**

The information contained herein is correct as at 12 Jul 2018

OK

## Asher Sng (LKKAuto)

---

**From:** Asher Sng (LKKAuto)  
**Sent:** Tuesday, 18 December 2018 11:02 AM  
**To:** Lee, Ming-Yao  
**Subject:** [MANDATE REQUEST] Your ref : 8326986534SG, ACCIDENT ON 11/07/2018 INVOLVING EP 707B (OI) & SJV 4196H (TP)

Your ref : **8326986534SG**  
Our ref : CC6/AIG18012763/Aea3

Dear Sirs,

### ACCIDENT ON 11/07/2018 INVOLVING EP 707B (OI) & SJV 4196H (TP)

We refer to the above matter.

The accident occurred when our insured make a right turn @ control junction hit third party vehicle.

Basing on the reports of the circumstance of the accident, we propose to settle third-party claim at 100% liability.

We did clarify with insured the nature of the accident and he's aware that NCD (if any) would be affected.

We seek your approval to offer repairer " **NEW HOCK TECK MOTOR PTE LTD**" at **\$ 10,767.45 (all-in).**

The summary is as follows: -

	Amount Claimed	Amount Revised
1. Cost of Repairs	\$ 30,308.70	\$ 9,800.00
2. Loss of Use (16days x \$120)	\$ 1,920.00	\$ 960.00 (16days x \$60)
3. LTA Search Fee	\$ 7.45	\$ 7.45
Total	\$ 32,236.15	<b><u>\$10,767.45</u></b>

**For your approval in merimen please.**

Thank You.

Best Regards,

**Asher Sng** | Case Handler

**LKK Auto Consultants Pte Ltd**

phone: 6841-6051 | email: [ashersng@lkkauto.com](mailto:ashersng@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



## Print Received Message

This mail is associated with :

**\*SJV4196H (8326986534SG)  
[EP707B]**

TP

SGCARZ LLP

Jul 11 2018 11:00AM

[SEE SIEW LUAN @TAN SIEW LUAN]

New Hock Teck Motor Pte Ltd

**From** AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG\_SG\_EXPRESS), sent on 03/01/2019 17:53 PM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (S\$10767.45) - SJV4196H - Claim Handler: Lee, Ming-Yao

Approved:10767.45:Hi, Please do your utmost to settle claim at best

## Asher Sng (LKKAuto)

---

**From:** Asher Sng (LKKAuto)  
**Sent:** Wednesday, 23 January 2019 11:34 AM  
**To:** 'Lee, Ming-Yao'  
**Subject:** RE: [MANDATE REQUEST] Your ref : 8326986534SG, ACCIDENT ON 11/07/2018 INVOLVING EP 707B (OI) & SJV 4196H (TP)  
**Attachments:** Re: SJV4196H CLAIMING EP707B DOA 11.07.18 \*\*\* LKK REF: CC6/AIG18012763/Aea3

Hi George,

We refer to the above matter.

Third party would like to claim for the loss of use under rental rate.

Enclosed document for your easy reference.

**For your approval in merimen please.**

Thank You.

Best Regards,

**Asher Sng** | Case Handler

**LKK Auto Consultants Pte Ltd**

phone: 6841-6051 | email: [ashersng@lkkauto.com](mailto:ashersng@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



---

**From:** Lee, Ming-Yao <MingYao.Lee@aig.com>  
**Sent:** Thursday, 3 January 2019 5:55 PM  
**To:** Asher Sng (LKKAuto) <AsherSng@lkkauto.com>  
**Subject:** RE: [MANDATE REQUEST] Your ref : 8326986534SG, ACCIDENT ON 11/07/2018 INVOLVING EP 707B (OI) & SJV 4196H (TP)

Hi Asher,

## Print Received Message

This mail is associated with :

**\*SJV4196H (8326986534SG)**  
**[EP707B]**

TP

SGCARZ LLP

Jul 11 2018 11:00AM

[SEE SIEW LUAN @TAN SIEW LUAN]

New Hock Teck Motor Pte Ltd

**From** AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG\_SG\_EXPRESS), sent on 23/01/2019 11:38 AM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (S\$11087.45) - SJV4196H - Claim Handler: Lee, Ming-Yao

Approved:11087.45:Hi Asher, Refer to telephone conversation, as TP is rental company and wishes to claim for loss of usage of rented vehicle. May offer LOU up to S\$80.00/day in view of long term hire.

## NEW HOCK TECK MOTOR PTE LTD

Our Ref : NPI1810-0196 / SJV4196H  
Your Ref : EP707B  
Date : 17<sup>th</sup> October 2018

1 Kaki Bukit Avenue 6  
Blk C #01-43 Autobay@KB  
Singapore 417883

AIG ASIA Pacific Insurance Pte Ltd  
78 Shenton Way,  
AIG Building, #09-16  
Singapore 079120

WITHOUT PREJUDICE

Dear Sirs,

**RE: ACCIDENT INVOLVING SJV4196H & EP707B AT ANG MO KIO AVE 5 X ANG MO KIO ST 53  
ON 11.07.2018, 11:15HRS**

We are instructed by **SGCARZ LLP** to claim damages and losses against you in connection with the above captioned road traffic accident which our client's vehicle **SJV4196H** was damaged by vehicle **EP707B** driven by your insured at the material time.

We are instructed that the said accident was caused by your insured's negligent driving and/or management of the vehicle. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expenses, particulars of which are as follows:

1) Repair Costs	\$	9,800.00
2) Loss of Use for 16 days (14 + 2 Weekends) (Rental)	\$	1,920.00
3) LTA Search Fees	\$	7.45
	\$	<u>11,727.45</u>

A copy each of the following supporting document is enclosed:

- 1) Final Repair Bill
- 2) LTA Receipt

Please let us have your cheque for the sum **\$11,727.45** made payable to us, **NEW HOCK TECK MOTOR PTE LTD** in the next 14 days.

Yours faithfully,

  
NEW HOCK TECK MOTOR PTE LTD



Assignment

To: New Hock Teck Motor Pte Ltd (Workshop)

In consideration for your agreement to repair my motor vehicle registration no. SJV 4196H and to defer demanding for payment of the cost of repair, I/we the undersigned do hereby irrevocably assign absolutely to you all the proceeds of my/our claim(s) including damages, interest, costs and expenses (including legal costs / disbursements payable on a party and party basis which are to be paid to the parties so entitled including solicitors, vehicle appraisers and other experts / consultants).

I/We further confirm that payment to you only or to any person authorised by you to receive payment shall constitute a good and effectual discharge of the obligations by any party of the aforesaid proceeds of my/our claim(s).

I/We authorise you expressly to give notice of this assignment to the party concerned.

I/We confirm that by this assignment, I/we shall not be entitled in law to receive any payment. If a cheque is sent to me/us, I/we shall return same to the sender as I/we am/are precluded from accepting any payment.

Dated this 11 day of 07 20 15.

Signature	:	
Name	:	
ID No.	:	<u>T1661847F</u>
Address	:	
Witness Signature	:	
Witness Name	:	<u>Chew Yee Yim</u>
Witness ID	:	<u>S882061824</u>
Witness Address	:	<u>1 Kaki Bukit Avenue 6 #01-43</u> <u>Singapore 417883</u>

**Asher Sng (LKKAUTO)**

---

**From:** Asher Sng (LKKAUTO)  
**Sent:** Wednesday, 1 August 2018 12:52 PM  
**To:** 'SEEJENNIFER5@GMAIL.COM'  
**Subject:** ACCIDENT INVOLVING EP 707B AND SJV 4196H ON 11/07/2018

**Our Ref: CC6/AIG18012763/Aea3**

01 AUG 2018

**SEE SIEW LUAN @ TAN SIEW LUAN**

Dear Sir/Madam,

**ACCIDENT INVOLVING EP 707B AND SJV 4196H ON 11/07/2018**

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Asher  
Case Handler  
DID: 6841 6051  
FAX: 6741 4108  
Email: [Ashersng@lkkauto.com](mailto:Ashersng@lkkauto.com)

c.c. AIG Asia Pacific Insurance Pte Ltd  
(Motor Claims Dept)

# LETTER OF AUTHORISATION

**New Hock Teck Motor Pte Ltd**  
Kaki Bukit Avenue 6  
Blk 1 #01-43  
Singapore 417883

Dear Sir,

Accident on

Involving Vehicles

Along

11/7/2018 @ 1115 hrs.  
SJV 4196 H & EP 707 B  
Ang Mo Kio Ave 5 X Ang Mo Kio St 53

I/We, the registered owner/driver of vehicle registration no: SJV 4196 H  
have involved in the above accident.

I/We hereby authorize **New Hock Teck Motor Pte Ltd** to commence repairs of the said vehicle forthwith.

I/We agree to assign the whole proceeds of my/our comprehensive/third party claim to you and our solicitor, \_\_\_\_\_, to act on my/our behalf in respect of the above matter. And if applicable, my/our solicitors shall accept this as my/our irrevocable authority to pay the amount as deemed compensated direct to you after deduction of their costs on a Solicitor and client basis.

I/We undertake to co-operate fully with you and our solicitors to ensure that claim is successful.

I/We also authorize you to sign all discharge vouchers/indemnity forms and all necessary papers in relation with the above claim in my/our absence.

Your kind co-operation in this matter will be much appreciated.

Yours truly,



Owner's Signature  
(Company's stamp if applicable)

Name: SGCAE LLP  
NRIC No.: T16111847F  
Date: 12/07/18

WITHOUT PREJUDICE to:  
(a) Insurance Subrogated Claim and/or  
(b) Any Personal Injury Claims  
(Note: This Release covers all circumstances  
found in this Discharge Voucher)

**RELEASE VOUCHER**  
**(AIG Asia Pacific - Express Third Party Claim)**

"We/I, **NEW HOCK TECK MOTOR PTE LTD** ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd **LKK AUTO CONSULTANTS PTE LTD** (name of surveyor) with respect to the amount claimed for **S\$9,800.00** (Repair Cost), **S\$1,280.00** (Loss of Use/Rental), **S\$7.45** (Disbursement) for vehicle no. **SJV 4196H** that was damaged pursuant to the accident which occurred on **11/07/2018** (date) along **ANG MO KIO AVE 5 & ANG MO KIO ST 3** (location) involving vehicle no/s **EP 707B**.

This is pursuant to the inspection conducted on **12/07/2018** (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner **SGCARZ LLP** ("the third party claimant") of vehicle no. **SJV 4196H** make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to **SJV 4196H** (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 28 (day) of 01 (month) 2019 (year)



LWP

Signed by appointed surveyor



Sukji Chong

Signed by "the workshop" (with chop)





新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7270

UEN: 201718370K

## TAX INVOICE

AIG ASIA Pacific Insurance Pte Ltd

78 Shenton Way,

AIG Building, #09-16

Singapore 079120

Client: SGCARZ LLP

Invoice No : NPL1810-0196

Date : 17-Oct-18

Date of Accident : 11-Jul-18

Vehicle No. : SJV4196H

Model Type : Hyundai Avante

Descriptions		Amount
Lump Sum Repair Cost		9,800.00
Total		9,800.00

SIN DOLLARS: NINE THOUSAND AND EIGHT HUNDRED ONLY



# SGCARZ LLP

31 Kaki Bukit Road 3, Techlink, #01-01  
Singapore 417818  
Tel: 6844 7567 Fax: 6747 2738

## VEHICLE RENTAL AGREEMENT

THIS RENTAL CONTRACT IS MADE EFFECTIVE ON THE 22 OF March 2018 @ HR, BETWEEN SGCARZ LLP LOCATED AT 31 KAKI BUKIT RD 3, TECHLINK #01-01 SINGAPORE 417818 AND RENTER Ban Hui Heng Motor Trading  
NRIC/PIN/PASSPORT NUMBER: 53296124 LOCATED AT: 2A Simei Street 1 #10-14 Meville  
Park 3 (S29946) CONTACT NO: 8488 2588

### VEHICLE DETAILS

VEHICLE NO.	<u>S0V4196H</u>	REPLACEMENT VEHICLE NO.	
MAKE & MODEL	<u>Hyundai Accent 1.6AT</u>	DATE/TIME OUT	
CHASSIS NO.	<u>KAH004888932924</u>	DATE/TIME IN	
ENGINE NO.	<u>G4K9UT3544</u>	PAYMENT	
MILEAGE	<u>86686km</u>	DEPOSIT	<u>\$1000 (unpaid on 22/03/18)</u>
MILEAGE CAP	<u>-</u>	ADVANCED PAYMENT	<u>22/03/18 - 21/04/18 (208930km on 21/04/18)</u>
FUEL LEVEL	<u>20%</u>		<u>22/03/18 - 21/04/18</u>
VEHICLE CHECKLIST			<u>22/03/18 - 21/04/18</u>
			<u>22/03/18 - 21/04/18</u>
			<u>22/03/18 - 21/04/18</u>
			<u>22/03/18 - 21/04/18</u>
			<u>22/03/18 - 21/04/18</u>
			<u>22/03/18 - 21/04/18</u>
			<u>22/03/18 - 21/04/18</u>
			<u>22/03/18 - 21/04/18</u>
			<u>22/03/18 - 21/04/18</u>
			<u>22/03/18 - 21/04/18</u>
			<u>22/03/18 - 21/04/18</u>
			<u>22/03/18 - 21/04/18</u>
			<u>22/03/18 - 21/04/18</u>
			<u>22/03/18 - 21/04/18</u>
			<u>22/03/18 - 21/04/18</u>
		* Inclusive of 10km standing and 9km travel. * Renter agrees to be fully responsible for any damage, repairs, and any other maintenance. * Due to no issue.	

RATES: \$1000

MINIMUM PERIOD: 2 months till 21/05/2020

ADDITIONAL DRIVER 1: \_\_\_\_\_

ADDITIONAL DRIVER 2: \_\_\_\_\_

THE TERMS AND CONDITIONS MENTIONED FORM AN INTEGRAL PART OF THIS CONTRACT. BY SIGNING THIS CONTRACT, THE RENTER CONFIRMS HAVING CLEARLY READ AND UNDERSTOOD THE TERMS AND CONDITIONS FOR RENTAL AND IS GIVING HIS UNCONDITIONAL APPROVAL TO THE STIPULATIONS OF THESE TERMS AND CONDITIONS.

RENTER'S SIGNATURE 	REPRESENTATIVE (SGCARZ LLP)'S SIGNATURE 
START DATE: <u>22/03/18</u>	RETURN DATE: _____

[> Back to OneMotoring](#)

Land Transport Authority  
 10 Sin Ming Drive  
 Singapore 575701  
 GST Registration No. : M4-0006529-2

Print Date/Time : 12 Jul 2018 / 10:08:41

Receipt Date/Time : 12 Jul 2018 / 10:08:41

**Tax Invoice/Receipt**

Receipt No. : ITNET-00000-180712-000452

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - EP707B				
As at 11 Jul 2018/11:15:00				
Insurance Co: AIG ASIA PACIFIC INSURANCE PTE. LTD.				
1	Insurance Enquiry - EP707B			
	Enquiry Fee	7.00	0.49	7.49
	20180712100806425958			
	<b>Sub-Total</b>	7.00	0.49	7.49
	<b>Total Before Rounding</b>	7.00	0.49	7.49
	<b>Rounding Difference</b>			0.04
	<b>Total Amount Payable</b>			7.45
Paid By				
	xxxxxxxxxxxx4469	Credit Card: Visa/MasterCard		7.45
	<b>Total</b>			7.45
	<b>Cash Change</b>			0.00
	<b>Tendered Amount</b>			7.45
	<b>Excess Refundable Amount</b>			0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane









































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	16 Jul 2018 <a href="#">Edit Reg</a>		12 Jul 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$9,800.00</b> <a href="#">Edit Estimates</a>	<b>S\$9,800.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured: <b>SEE SIEW LUAN @TAN SIEW LUAN</b> , ID: S1367679H									
Main Claimant: <b>SGCARZ LLP</b> , Co. Reg. No.: T16111847F									
Vehicle Reg. No.:	<b>SJV4196H</b>	Date of Loss:	11/07/2018 11:00 - :59 <b>101 Months and 15 Days From LTA Reg Date (Man Yr)</b>						
Claim Type:	<b>TP / 8326986534SG</b>	Policy/Cover Note No.:	(Comprehensive) Coverage: 02/01/2018 - 01/01/2019						
Vehicle Reg. No. (Insured):	<b>EP707B</b>	Policy No. (Claimant):	5093832042-01						
		Excess:							
Repairer:	<b>New Hock Teck Motor Pte Ltd (HQ)</b> 1 Kaki Bukit Ave 6, Bldg C #01-43 Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel: 6747 9241								
Handling Insurer:	<b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>Lee, Ming-Yao</b> ] MingYao.Lee@aig.com								
Claimant's Insurer:	<b>NTUC Income Insurance Co-operative Ltd (HQ)</b> - Tel:								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>ADRIAN LING</b> ] ... <b>[Final Rpt due 24/07/2018]</b>								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>AIG_SG_EXPRESS (23/01/2019): Alert - Adj Mandate Approved (S\$11087.45) - SJV4196H - Claim Handler: Lee, Ming-...</li> <li>AIG_SG_EXPRESS (03/01/2019): Alert - Adj Mandate Approved (S\$10767.45) - SJV4196H - Claim Handler: Lee, Ming-...</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SJV4196H (8326986534SG)  
 [EP707B]  
 TP  
 SGCARZ LLP  
 Jul 11 2018 11:00AM  
 [SEE SIEW LUAN @TAN SIEW LUAN]  
 New Hock Teck Motor Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View		View in Browser		View	
Letters/Correspondences										1 per page					
No	Finalized On		LKK Auto Consultants Pte Ltd (HQ)							Thumbnail		Print			
1	(Draft)		Third Party Express Settlement – Payment Breakdown							1		Edit			
Photos/Images										3 per page					
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)							Thumbnail		Print			
1	15/08/18 14:46		General View							1		Load JPG		<input checked="" type="checkbox"/>	
2	15/08/18 14:46		General View							1		Load JPG		<input checked="" type="checkbox"/>	
3	15/08/18 14:46		General View							1		Load JPG		<input checked="" type="checkbox"/>	
4	15/08/18 14:46		General View							1		Load JPG		<input checked="" type="checkbox"/>	
5	15/08/18 14:46		General View							1		Load JPG		<input checked="" type="checkbox"/>	
6	15/08/18 14:46		General View							1		Load JPG		<input checked="" type="checkbox"/>	
7	15/08/18 14:46		General View							1		Load JPG		<input checked="" type="checkbox"/>	
8	15/08/18 14:46		General View							1		Load JPG		<input checked="" type="checkbox"/>	
9	15/08/18 14:46		General View							1		Load JPG		<input checked="" type="checkbox"/>	
10	15/08/18 14:46		General View							1		Load JPG		<input checked="" type="checkbox"/>	
11	15/08/18 14:46		General View							1		Load JPG		<input checked="" type="checkbox"/>	
12	15/08/18 14:46		General View							1		Load JPG		<input checked="" type="checkbox"/>	
13	15/08/18 14:46		General View							1		Load JPG		<input checked="" type="checkbox"/>	
14	15/08/18 14:46		General View							1		Load JPG		<input checked="" type="checkbox"/>	
15	15/08/18 14:46		General View							1		Load JPG		<input checked="" type="checkbox"/>	
16	15/08/18 14:46		General View							1		Load JPG		<input checked="" type="checkbox"/>	
17	15/08/18 14:46		General View							1		Load JPG		<input checked="" type="checkbox"/>	
18	15/08/18 14:46		General View							1		Load JPG		<input checked="" type="checkbox"/>	
19	15/08/18 14:46		General View							1		Load JPG		<input checked="" type="checkbox"/>	
20	15/08/18 14:46		General View							1		Load JPG		<input checked="" type="checkbox"/>	
21	15/08/18 14:46		General View							1		Load JPG		<input checked="" type="checkbox"/>	
22	15/08/18 14:46		General View							1		Load JPG		<input checked="" type="checkbox"/>	
23	15/08/18 14:46		General View							1		Load JPG		<input checked="" type="checkbox"/>	
24	15/08/18 14:46		General View							1		Load JPG		<input checked="" type="checkbox"/>	
25	15/08/18 14:46		General View							1		Load JPG		<input checked="" type="checkbox"/>	
26	15/08/18 14:46		General View							1		Load JPG		<input checked="" type="checkbox"/>	
27	15/08/18 14:46		General View							1		Load JPG		<input checked="" type="checkbox"/>	
28	15/08/18 14:46		General View							1		Load JPG		<input checked="" type="checkbox"/>	
29	15/08/18 14:46		General View							1		Load JPG		<input checked="" type="checkbox"/>	
30	15/08/18 14:46		Reinspection Photo							1		Load JPG		<input checked="" type="checkbox"/>	
31	15/08/18 14:46		Reinspection Photo							1		Load JPG		<input checked="" type="checkbox"/>	
32	15/08/18 14:46		Reinspection Photo							1		Load JPG		<input checked="" type="checkbox"/>	
33	15/08/18 14:46		Reinspection Photo							1		Load JPG		<input checked="" type="checkbox"/>	
34	15/08/18 14:46		Reinspection Photo							1		Load JPG			

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	15/08/18 14:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
36	15/08/18 14:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
37	15/08/18 14:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
38	15/08/18 14:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	15/08/18 14:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	15/08/18 14:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	15/08/18 14:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	15/08/18 14:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	15/08/18 14:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	15/08/18 14:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	15/08/18 14:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	15/08/18 14:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	15/08/18 14:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	15/08/18 14:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	15/08/18 14:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	15/08/18 14:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	15/08/18 14:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	15/08/18 14:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	15/08/18 14:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	15/08/18 14:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	15/08/18 14:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	15/08/18 14:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	15/08/18 14:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	15/08/18 14:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	15/08/18 14:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	15/08/18 14:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	15/08/18 14:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	15/08/18 14:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	15/08/18 14:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	15/08/18 14:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	15/08/18 14:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	13/07/18 13:51	TP GIA REPORT	 Load PDF	
2	05/12/18 14:10	TP LOD	 Load PDF	
3	10/12/18 16:45	LTA SEARCH	 Load PDF	
4	23/01/19 11:34	RENTAL AGREEDMENT	 Load PDF	
5	29/01/19 10:57	WORKSHOP INVOICE	 Load PDF	
6	29/01/19 10:57	AUTHORISATION TO ACT FORM	 Load PDF	
7	29/01/19 10:57	Release Voucher	 Load PDF	
8	29/01/19 10:57	LETTER TO OI	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	16/07/18 12:18	OI GIA REPORT	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**

	⌵
--	---

**Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

### THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	EP707B (Insd veh)	Model:	HYUNDAI AVANTE 1.6 ABS
	SJV4196H (TP veh)		AIRBAG 2WD 4DR (A)
Date of Accident:	11/07/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	30,308.70
Final Repair Cost	:	\$	9,800.00
Loss of Use	:	\$	1,280.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	7.45
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	11,087.45

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability \_\_\_\_ 100 \_\_\_\_ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: \_\_\_\_

BOLA Liability: \_\_\_\_ (%) Assessed Liability (\*): \_\_\_\_ (%)

\* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks \_\_\_\_\_

Payment Instruction: Payee's Breakdown			
1)	New Hock Teck Motor Pte Ltd	:	\$ 11,087.45
2)		:	\$
3)		:	\$
4)		:	\$

JOANNE LEE KHANG MIN

29 Jan  
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.  
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))



# LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18012763/AEA3Q2

Date: 29/01/2019

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No: SJV4196H

Insured Vehicle No: EP707B

Date of Loss: 11/07/2018

Nature of Claim: TP

Claim No: 8326986534SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJV4196H**

Make &amp; Model: HYUNDAI AVANTE, 1.6 ABS AIRBAG 2WD 4DR (A)

Engine No: G4FC9U775446

Reg. Date: 26/01/2010 (Man. Year: 2009)

Chassis No: KMHDU41BMAU932924

Colour: White

Odometer: 164820 km

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size: 205/55 R16

Front Left Side: Dunlop 6 mm

Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	22,928.70	9,126.80	13,801.90	60.19
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,380.00	4,220.00	3,160.00	42.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>30,308.70</b>	<b>13,346.80</b>	<b>16,961.90</b>	<b>55.96</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>9,800.00</b>		
<b>Nett Amount (S\$)</b>	<b>30,308.70</b>	<b>9,800.00</b>	<b>20,508.70</b>	<b>67.67</b>
<b>+ Loss of Use (16.0 x S\$80.00/day) (S\$)</b>		1,280.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>11,087.45</b>		

### INSPECTION

Date of Assignment: 12/07/2018

Date Inspected: 12/07/2018 Inspected At:

New Hock Teck Motor Pte Ltd (HQ)

1 Kaki Bukit Ave 6, Blk C #01-43

Autobay@Kaki Bukit

Singapore 417883

Estimated Period of Repair: 14.0 days

---

**Adjuster:** ADRIAN LING**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Distorted	1,001.90 F	*1,001.90 FL
2	2		*FRONT BONNET HINGE	Bent	87.60 F	*87.60 FL
3	1		*FRONT BONNET INSULATOR	Crumpled	180.70 F	*180.70 FL
4	8		*FRONT BONNET INSULATOR CLIP	Necessary	52.00 F	*52.00 FL
5	1		*FRONT BONNET LOCK	Damaged	122.30 F	*122.30 FL
6	1		*FRONT BONNET RUBBER	Cut	65.50 F	*65.50 FL
7	2		*FRONT HEAD LAMP	Cracked	927.60 F	*927.60 FL
8	2		*FRONT HEAD LAMP LOWER BRACKET	Damaged	64.00 F	*64.00 FL
9	1		*FRONT BUMPER	Distorted	428.00 F	*428.00 FL
10	10		*FRONT BUMPER CLIP	Necessary	65.00 F	*65.00 FL
11	2		*FRONT BUMPER SIDE RETAINER	Necessary	66.00 F	*66.00 FL
12	1		*FRONT BUMPER NUMBER PLATE	Bent	50.00 F	*50.00 FL
13	1		*FRONT BUMPER CENTRE GARNISH	Deformed	86.40 F	*86.40 FL
14	1		*FRONT BUMPER INNER SPONGE	Cracked	106.90 F	*106.90 FL
15	2		*FRONT BUMPER REINFORCEMENT	Bent	479.20 F	*479.20 FL
16	2		*FRONT BUMPER FOG LAMP COVER	Not Necessary	148.80 F	*- FL
17	1		*FRONT GRILLE	Cracked	288.00 F	*288.00 FL
18	1		*FRONT GRILLE EMBLEM LOGO	Necessary	61.10 F	*61.10 FL
19	2		*FRONT FENDER	Distorted	793.40 F	*793.40 FL
20	2		*FRONT FENDER VVTI LOGO	Necessary	62.00 F	*62.00 FL
21	2		*FRONT FENDER COWLING	Not Necessary	107.20 F	*- FL
22	16		*FRONT FENDER COWLING CLIP	Not Necessary	104.00 F	*- FL
23	2		*FRONT FENDER INNER PANEL	Repair	937.40 F	*- FL
24	2		*FRONT FENDER HOUSING	Repair	1,303.60 F	*- FL
25	1		*FRONT WIPER TANK	Distorted	75.80 F	*75.80 FL
26	2		*FRONT WIPER TANK MOTOR	Not Necessary	111.60 F	*- FL
27	1		*FRONT SUPPORT PANEL	Distorted	753.00 F	*753.00 FL
28	1		*FRONT SUPPORT PANEL TOP AIR CLEANER AIR DUCT	Cracked	186.60 F	*186.60 FL
29	1		*FRONT SUPPORT PANEL TOP AIR CLEANER AIR DUCT HOSE	Damaged	169.40 F	*169.40 FL
30	1		*FRONT AIR CLEANER BOX	Not Necessary	102.00 F	*- FL
31	1		*FRONT AIR-CON CONDENSER	Distorted	876.00 F	*876.00 FL
32	1		*FRONT AIR-CON SECTION PIPE	Bent	231.80 F	*231.80 FL
33	1		*FRONT AIR-CON DISCHARGE PIPE	Bent	345.10 F	*345.10 FL
34	1		*FRONT AIR-CON FAN MOTOR ASSY	Not Necessary	1,040.40 F	*- FL
35	1		*FRONT RADIATOR	Distorted	589.00 F	*589.00 FL
36	1		*FRONT RADIATOR TOP HOSE	Twisted	38.60 F	*38.60 FL
37	1		*FRONT RADIATOR LOWER HOSE	Not Necessary	42.80 F	*- FL
38	1		*FRONT RADIATOR SPARE TANK	Deformed	69.20 F	*69.20 FL
39	1		*FRONT RADIATOR FAN MOTOR ASSY	Damaged	488.00 F	*488.00 FL
40	1		*FRONT AIR-CON COMPRESSOR	Not Necessary	1,467.00 F	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
41	1		*FRONT DOHC 16V COVER	Not Necessary	106.00 F	*- FL
42	1		*FRONT BATTERY	Not Necessary	180.00 F	*- FL
43	1		*FRONT BATTERY LOWER COVER	Not Necessary	38.60 F	*- FL
44	1		*FRONT CHASSIS	Repair	489.00 F	*- FL
45	1		*FRONT CROSSMEMBER	Bent	2,598.40 F	*2,598.40 FL
46	4		*FRONT ENGINE MOUNTING	Not Necessary	286.00 F	*- FL
47	1		*FRONT ANTENNA	Not Necessary	166.00 F	*- FL
48	2		*FRONT HORN	Not Necessary	123.60 F	*- FL
49	2		*FRONT LOWER ARM	Not Necessary	610.00 F	*- FL
50	2		*FRONT KNUCKLE ARM	Not Necessary	562.00 F	*- FL
51	2		*FRONT KNUCKLE ARM BEARING	Not Necessary	216.00 F	*- FL
52	2		*FRONT SHOCK ABSORBER	Not Necessary	596.00 F	*- FL
53	2		*FRONT DRIVE SHAFT	Not Necessary	1,454.20 F	*- FL
54	1		*FRONT STEERING RACK	Not Necessary	1,328.00 F	*- FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>22,928.70</b>	<b>11,408.50</b>
<b>- List Item Discount on L Items 0.00/20.00% (\$\$)</b>	<b>0.00</b>	<b>2,281.70</b>
<b>Total Parts (\$\$)</b>	<b>22,928.70</b>	<b>9,126.80</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & REFIT FRONT ENGINE	New	550.00	380.00
2	TO REMOVE & REFIT CROSSMEMBER ,UNDERCARRIAGE ,DRIVE SHAFT & STEERING RACK	New	750.00	500.00
3	TO REMOVE & REFIT AIR-CON CONDENSER ,RADIATOR ,FAN MOTOR & TOP UP GAS	New	380.00	120.00
4	TO CHECK WHEEL ALIGNMENT	New	150.00	80.00
5	TO CHECK WIRING	New	100.00	30.00
6	TOWING FEE	New	100.00	60.00
7	TUFF KOTE	New	150.00	50.00
8	PANEL BEATING	New	3,000.00	1,600.00
9	SPRAY PAINTING	New	2,200.00	1,400.00
Gross Labour Cost (S\$)			<b>7,380.00</b>	<b>4,220.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >