

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9515G**AAD1807-091***Not Authorized
L1 Sup @ 5700*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 9515G

KL1LA69RJB089111

CHEVROLET

EPICA 2.0

10.7.2018

*AIG***PART****LIST**

1	1	Front Fender LH	\$	<i>B1</i> 837.60 ✓
2	1	Front Fender Liner LH	\$	<i>SL</i> 47.00 X
3	1	Front Fender Inner Wheel House Panel LH	\$	<i>R</i> 1,437.00 X
4	1	Front Shock Absorber Assy LH	\$	<i>SL</i> 216.17 X
5	1	Front Shock Absorber Top Mounting LH	\$	<i>SL</i> 48.32 X
6	1	Front Lower Arm LH	\$	<i>SL</i> 283.00 X
7	1	Front Knuckle Arm LH	\$	<i>SL</i> 230.00 X
8	1	Front Door LH	\$	<i>B1</i> 1,133.00 ✓
9	1	Front Door Glass Guide RH Chrome Moulding	\$	<i>SL</i> 60.00 X
10	1	Front Door Outer Moulding	\$	<i>SL</i> 220.00 X
11	1	Front Door Outer Handle	\$	<i>SL</i> 125.00 X
12	1	Front Door Handle Support	\$	<i>SL</i> 3.00 X
13	1	Front Door outer handle inner seal	\$	<i>SL</i> 89.15 X
14	1	Front Door outer key lock	\$	<i>SL</i> 25.00 X
15	1	Front Door Hinge Upper	\$	<i>R</i> 65.00 X
16	1	Front Door Hinge Lower	\$	<i>B1</i> 65.00 ✓
17	1	Front Door inner lock	\$	<i>Not</i> 586.00 ✓
18	1	Front Door Inner Lock Latch LH	\$	<i>R</i> 206.00 X
19	1	Front Door Check / Arrestor	\$	<i>SL</i> 67.50 X
20	1	Front Door Weatherstrip LH	<i>69.4054</i> \$	<i>Not</i> 138.79 <i>509.12</i>
21	1	Front Door glass channel weatherstrip	\$	<i>SL</i> 160.00 X
22	1	Front Door inner trim board	\$	<i>SL</i> 455.69 X
23	1	Front Door window glass	\$	<i>SL</i> 456.12 X
24	1	Front Door Power Window Motor (Master) LH	\$	<i>T1</i> 284.97 ✓
25	1	Front Door power window motor switch	\$	<i>SL</i> 145.00 X
26	1	Front Door Window Regulator Gear LH	\$	<i>Not</i> 84.58 ✓
27	1	Front Door Outer Pillar Panel LH	\$	<i>B1</i> 715.00 ✓

Trans-cab Auto Services Pte Ltd**AAD1807-091**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9515G

28	1	Front Door Pillar Inner Panel LH	\$	<i>N</i>	850.00	X
29	1	Front Door Center Pillar Panel LH	\$	<i>N</i>	698.15	X
30	1	Front Side View Mirror Assy LH	\$	<i>SL</i>	1,191.00	X
31	1	Rear Door LH (Panel A-RR DR LH)	\$	<i>B</i>	1,133.00	✓
32	1	Rear door weatherstrip - Inner	\$	<i>SL</i>	41.40	X
33	1	Rear door weatherstrip - 2nd Frame	\$	<i>SL</i>	25.90	X
34	1	Rear door top hinge	\$	<i>N</i>	35.00	X
35	1	Rear door bottom hinge	\$	<i>B</i>	35.00	✓
36	1	Rear door inner lock	\$	<i>N</i>	425.00	X
37	1	Rear door check / arrestor	\$	<i>SL</i>	65.00	X
38	1	Rear door lock striker / latch	\$	<i>SL</i>	120.00	X
39	1	Rear door outer weatherstrip moulding	\$	<i>SL</i>	85.00	X
40	1	Side Rocker Panel Garnish LH	\$	<i>N</i>	236.40	✓
41	1	Rear Fender LH	\$	<i>N</i>	1,145.00	X
42	1	Rear Fender Inner Trim LH	\$	<i>SL</i>	418.44	X
43	1	Front Side Rocker Panel Garnish LH	\$	<i>SL</i>	236.40	X
44	1	Front Side Rocker Panel Outer LH	\$	<i>N</i>	600.00	✓
45	1	Front Side Rocker Panel Inner LH	\$	<i>N</i>	519.30	X

TOTAL	\$	16,043.88
10%	\$	1,604.39
	\$	14,439.49

Special Nett

1 Set	Front Bumper Fastener Clip	\$	<i>na</i>	24.00	X
1 Set	Front licence plate with holder	\$	<i>SL</i>	192.00	X
1 Set	Radiator Grille clip	\$	<i>na</i>	35.00	X
1 Set	Front Fender Liner clip	\$	<i>na</i>	30.00	X
1	Front Fender RR Bracket LH	\$	<i>N</i>	7.10	X
1	Front Wheel Rim Hub Cap LH	\$	<i>SL</i>	166.30	X
1	Front Tyre LH	\$	<i>SL</i>	180.00	X
1	Front Tyre Rim LH	\$	<i>SL</i>	126.00	X
1	Front left door sticker 'Trans-cab'	\$	<i>na</i>	80.00	<i>60.00</i>
1	Rear rear door sticker '6555-3333'	\$	<i>na</i>	80.00	<i>60.00</i>

Trans-cab Auto Services Pte Ltd**AAD1807-091**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9515G

TOTAL	\$	920.40
--------------	-----------	---------------

TOTAL PARTS	\$	15,359.89
--------------------	-----------	------------------

LABOUR

To Check Electrical Lighting Concerned.	\$	170.00	201
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	4,500.00	9001
Putty and spray painting of the affected portion.	\$	4,000.00	12001
Towing Fees.	\$	nn 120.00	X
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	nn 380.00	X
To check steering geometry and computer wheel alignment	\$	nn 220.00	X
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00	X
To rust-proofing of the affected areas.	\$	170.00	1201
To check steering geometry and computer wheel alignment	\$	nn 220.00	X
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00	X
To transfer of door fittings, attachment and perform water seepage test.	\$	170.00	1201

Trans-cab Auto Services Pte Ltd**AAD1807-091**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9515G

To transfer of fender fittings, attachment and
perform water seepage test.

\$ *22* 170.00 X

TOTAL	\$	10,460.00
--------------	-----------	------------------

Over All Total	\$	25,819.89
-----------------------	-----------	------------------

Repair Days (Lump Sum)~~15 days~~*8 days*