

AUTOEXCEL ENGINEERING PTE LTD
160, Sin Ming Drive
Sin Ming Auto City #06-15
Singapore 575722
Tel: 64535654, 64591630
Fax: 64591698

Not Notarized

Date : 12/07/2018

QUOTATION -THIRD PARTY CLAIM

AIG ASIA PACIFIC INSURANCE PTE LTD

Attn: Motor Claim Department . Officer In Charge

Accident on : 11/07/2018

Claim : Third Party Claim
Veh. No : SBW 6068 X
Model : NISSAN LATIO
Insured Ins: TOKIO MARINE

QTY	PARTICULARS	AMOUNT	SURVEYOR
	Your Insurer Vehicle No : SCV 31 J		
1	BOOTLID		
1	BOOTLID LOCK	\$ 788.45	
1	BOOTLID WEATHERSTRIP	\$ 124.00	
1	BOOTLID CENTER LOGO	\$ 98.00	
1	BOOTLID LATIO EMBLEM	\$ 61.00	
1	BOOTLID LOWER LOCK SENSOR	\$ 58.00	
2	TAILLAMPS	\$ 280.00	
2	TAILLAMP PANELS	\$ 646.00	
2	TAILLAMP SIDE CLIPS	\$ 448.00	
2	REAR FENDERS	\$ 40.00	
2	REAR FENDER INNER SIDE GARNISHS	\$ 1,638.80	
1	REAR BUMPER	\$ 560.00	
1	REAR BUMPER SPONGE	\$ 548.60	
10	REAR BUMPER CLIPS	\$ 48.50	
2	REAR BUMPER BRACKETS	\$ 35.00	
2	REAR BUMPER SIDE RETAINERS	\$ 220.00	
1	END PANEL	\$ 96.00	
1	END PANEL TOP GARNISH	\$ 485.60	
1	END PANEL TOP LATCH	\$ 128.00	
1	SPARE TYRE PANEL	\$ 65.00	
1	SPARE TYRE PANEL TOP BOARD	\$ 720.80	
1	REAR EXHAUST	\$ 462.00	
		\$ 580.60	
		\$ 8,132.35	
	Less 10%	\$ 813.24	
		\$ 7,319.12	
	<u>S/NETT</u>		
1	REVERSE SENSOR	\$ 280.00	
1	REAR No.PLATE WITH FRAME	\$ 60.00	
	TOTAL S/N :	\$ 340.00	
	TOTAL PARTS :	\$ 7,659.12	

AUTOEXCEL ENGINEERING PTE LTD
 160, Sin Ming Drive
 Sin Ming Auto City #06-15
 Singapore 575722
 Tel: 64535654, 64591630
 Fax: 64591698

Balance b/f	\$ 7,659.12	
LABOUR CHARGES		
Labour to do cutting, welding remove refix, replace, repair damage area	\$ 1,400.00	9001
To check rear wiring system, remove refix sensor etc	\$ 150.00	501
To do sealant seal gap, waterproofing on welding cutting area	\$ 250.00	301
To do spray painting on accident affected area (Inner outer)	\$ 1,200.00	10001
Transfer bootlid to another bootlid	\$ 80.00	501
To remove refix rear w/screen	\$ nn 140.00	X
Remove refix, garnish, side trim, car seat , upholstery etc	\$ 350.00	1001
Replace rear exhaust	\$ 120.00	?
To do anti rust	\$ 120.00	601
TOTAL LABOUR :	\$ 3,810.00	
GRAND TOTAL :	\$ 11,469.12	

AUTOEXCEL ENGINEERING PTE LTD
160, Sin Ming Drive
Sin Ming Auto City #06-15
Singapore 575722
Tel: 64535654, 64591630
Fax: 64591698

Not Withain
C/Ly 87
Presing After Paint
6days

Date : 12/07/2018

QUOTATION -THIRD PARTY CLAIM

AIG ASIA PACIFIC INSURANCE PTE LTD

Claim : Third Party Claim
Veh. No : SBW 6068 X
Model : NISSAN LATIO
Insured Ins: TOKIO MARINE

Attn: Motor Claim Department . Officer In Charge

Accident on : 11/07/2018

QTY	PARTICULARS	NETT LESS 10 %	LISTS LESS 30 %	S/NETT
	YOUR INSURED VEHICLE : SCV 31 J			
	PARTS LIST			
1	BOOTLID	\$ -	\$ <i>R</i> 788.45	\$ - ✓
1	BOOTLID LOCK	\$ 124.00	\$ -	\$ -
1	BOOTLID WEATHSTRIP	\$ 98.00	\$ <i>50</i> -	\$ -
1	BOOTLID CENTER LOGO	\$ <i>RM</i> 61.00	\$ -	\$ -
1	BOOTLID LATIO EMBLEM	\$ <i>RM</i> 58.00	\$ -	\$ -
1	BOOTLID LOWER LOCK SENSOR	\$ 280.00	\$ -	\$ -
1	REAR No.PLATE WITH FRAME	\$ -	\$ -	\$ <i>RM</i> 60.00
2	TAILLAMPS	\$ -	\$ 646.00	\$ -
2	TAILLAMP PANELS	\$ 448.00	\$ -	\$ -
2	TAILLAMP SIDE CLIPS	\$ 40.00	\$ -	\$ -
2	REAR FENDERS	\$ -	\$ <i>R</i> 1,638.80	\$ -
2	REAR FENDER INNER SIDE GARNISHS	\$ 560.00	\$ -	\$ -
1	REAR BUMPER	\$ -	\$ <i>R</i> 548.60	\$ - ✓
1	REAR BUMPER SPONGE	\$ 48.50	\$ -	\$ -
10	REAR BUMPER CLIPS	\$ 35.00	\$ -	\$ -
2	REAR BUMPER SIDE RETAINERS	\$ 96.00	\$ -	\$ -
2	REAR BUMPER BRACKETS	\$ 220.00	\$ -	\$ -
1SET	REVERSE SENSORS	\$ -	\$ -	\$ <i>Short</i> 280.00
1	END PANEL	\$ -	\$ 485.60	\$ -
1	END PANEL TOP GARNISH	\$ 128.00	\$ -	\$ -
1	END PANEL TOP LATCH	\$ 65.00	\$ -	\$ -
1	SPARE TYRE PANEL	\$ -	\$ 720.80	\$ -
1	SPARE TYRE PANEL BOARD	\$ 462.00	\$ -	\$ -
1	REAR EXHAUST	\$ -	\$ 580.60	\$ -
	TOTAL :	\$ 2,723.50	\$ 5,408.85	\$ 340.00
	TOTAL AFTER LESS :	\$ 2,451.15	\$ 3,785.95	\$ 340.00
	GRAND TOTAL PARTS :	\$ 6,577.10		

X
✓
?
?
X
✓
?
2000m
?
✓
X
?
?

AUTOEXCEL ENGINEERING PTE LTD
160, Sin Ming Drive
Sin Ming Auto City #06-15
Singapore 575722
Tel: 64535654, 64591630
Fax: 64591698

Balance b/f	\$	6,577.10
LABOUR CHARGES		
Labour to do cutting, welding remove refix, replace, repair damage area	\$	1,400.00
To check rear wiring system, remove refix sensor etc	\$	150.00
To do sealant seal gap, waterproofing on welding cutting area	\$	250.00
To do spray painting on accident affected area (Inner outer)	\$	1,200.00
Transfer bootlid to another bootlid	\$	80.00
To remove refix rear w/screen	\$	na 140.00
Remove refix, garnish, side trim, car seat , upholstery etc	\$	350.00
Replace rear exhaust	\$	120.00
To do anti rust	\$	120.00
TOTAL LABOUR :	\$	3,810.00
GRAND TOTAL :	\$	10,387.10

9001

501

301

10001

501

X

1001

?

601

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: