



陳林源有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : SMA9322C
Date of Accident : 08 July 2018

Messrs Global Advance Leasing

Date : 10 July 2018

Estimate To Repair SJJ4033H - Honda Odyssey 2.4A
Chassis No : JHMRB18508C204611

S/No	Quantity	Description	Amount
		<u>LIST ITEMS</u>	
01	1 pc	rear bumper <i>Deep cut</i>	\$ 734.30
02	1 pc	n/s rear bumper side retainer <i>neu</i>	\$ 18.70
03	8 pc	rear bumper clips @ \$3.90 <i>neu</i>	\$ 31.20
04	1 pc	n/s lamp <i>17</i>	\$ 654.40
		Less 20 %	\$ 1,438.60 \$ 287.72 \$ 1,150.88
		<u>SPECIAL NETT ITEMS</u>	
05	1 pc	n/s rear rim <i>R</i>	\$ 450.00
			\$ 450.00
		<u>LABOUR & MISC. CHARGES</u>	
01		To reinstall of rear bumper parking sensor.	\$ 120.00
02		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 480.00
03		Putty and spray painting of the affected portion.	\$ 750.00
			\$ 1,350.00
		Total	\$ 2,950.88

Link Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Not Acknowledged
neu
1/5 @ 1200/2
2017.
13/7/18
take photo of damage.
Confirmed
on 13/07/18

1-784.2
627.36
1507.36

///
///
X
X
50
300
530