

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5470H**AAD1807-107***Not Wharfed*
L1Pny @ 23506

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHC 5470H

VF1ABL15AUC280955

RENAULT

LATITUDE

11.7.2018

LONPAC

PART		LIST	
1	BUMPER COVER FRT	\$	Bu 1,259.42 ✓
1	BUMPER SPOILER FRT	\$	Sn 181.75 X
1	BUMPER ABSORBER FRT	\$	Sn 394.68 X
1	BUMPER RETAINER FRT RH	\$	Di 150.77 ✓
1	BUMPER SUPPORT FRT	\$	Sn 123.88 X
1	BUMPER UNDERTRAY FRT	\$	Sn 472.83 X
1	BUMPER GRILLE LOWER FRT	\$	Sn 266.80 X
1	BUMPER FOG LAMP GRILLE RH	\$	Sn 207.21 X
1	BUMPER BEAM FRT	\$	N 914.08 X
1	HEADLAMP RH	\$	Sn 1,184.43 X
1	HEADLAMP PANEL FRT RH	\$	R 152.15 X
1	FENDER PANEL FRT RH	\$	R 783.83 ✓
1	WHEELARCH FRT RH	\$	Sn 278.84
1	FENDER BRACKET LOWER RH	\$	Sn 15.79
1	FENDER INSULATOR RH	\$	Sn 130.84
1	DOOR PANEL FRT RH	\$	R 2,844.66
1	RADIATOR GRILLE	\$	Sn 1,707.78
1	RADIATOR GRILLE BADGE 'RENAULT'	\$	Sn 225.36
1	RADIATOR GRILLE FRAME	\$	Sn 1,353.75
1	RADIATOR FAN COWLING	\$	Sn 820.54
1	RADIATOR FAN MOTOR LH	\$	Sn 967.36
1	RADIATOR FAN MOTOR RH	\$	Sn 1,479.46
1	FRAME FULL SUPPORT PANEL	\$	N 615.90
1	FRAME FULL SUPPORT BRACKET	\$	N 89.79
1	DOOR MIRROR ASSY RH	\$	Sn 1,483.40
1	DOOR PANEL FRT RH	\$	N 2,844.66
1	BONNET	\$	N 1,941.63
1	BONNET INSULATOR	\$	Sn 405.73
1	BONNET STRUT LH	\$	Sn 88.61
1	BONNET STRUT RH	\$	Sn 88.61

Trans-cab Auto Services Pte Ltd**AAD1807-107**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5470H

1	BONNET HINGE LH	\$	<i>na</i>	348.31	}
1	BONNET HINGE RH	\$	<i>na</i>	348.31	
1	BONNET LOCK	\$	<i>na</i>	305.48	
1	BONNET CABLE	\$	<i>sh</i>	119.19	
1	BONNET CABLE COVER	\$	<i>sh</i>	161.03	
1	BONNET SEAL OUTER	\$	<i>sh</i>	92.36	
1	BONNET SEAL INNER	\$	<i>sh</i>	157.28	
1	SUBFRAME OUTER FRT	\$	<i>na</i>	2,652.45	
1	SUBFRAME BRACKET OUTER LH	\$	<i>na</i>	92.36	
1	SUBFRAME BRACKET OUTER RH	\$	<i>na</i>	92.36	
1	ENGINE UNDERTRAY	\$	<i>sh</i>	564.98	
1	A/C CONDENSER	\$	<i>sh</i>	2,020.37	
1	A/C CONDENSER GARNISH LH UPPER	\$	<i>sh</i>	39.67	
1	A/C CONDENSER GARNISH RH UPPER	\$	<i>sh</i>	39.67	
1	A/C CONDENSER GARNISH LH	\$	<i>sh</i>	58.81	
1	A/C CONDENSER GARNISH RH	\$	<i>sh</i>	59.60	
1	LOWER ARM RH	\$	<i>sh</i>	685.76	
1	KUNCKLE ARM RH	\$	<i>sh</i>	846.98	
1	ABSORBER FRT RH	\$	<i>sh</i>	360.54	
1	STABILIZER BAR FRT	\$	<i>sh</i>	604.65	
1	DRIVESHAFT RH	\$	<i>na</i>	1,747.45	
1	WIPER RESERVOIR	\$	<i>sh</i>	348.25	
1	WIPER RESERVOIR NECK	\$	<i>sh</i>	136.11	
1	WIPER RESERVOIR MOTOR	\$	<i>sh</i>	270.06	

TOTAL	\$	35,626.53
10%	\$	3,562.65
	\$	32,063.87

Specical Nett

1SET	BUMPER CLIP FRT	\$	<i>na</i>	66.00	✓
1	BUMPER BRACKET CLIP FRT RH	\$	<i>na</i>	12.00	X
1	BUMPER SUPPORT CLIP FRT RH	\$	<i>na</i>	10.50	X
1SET	BUMPER GRILLE LOWER CLIP	\$	<i>na</i>	69.00	X
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	<i>na</i>	70.00	X
2	FRAME FULL SUPPORT PANEL NUT	\$	<i>na</i>	20.00	X
2	FRAME FULL SUPPORT PANEL STUD	\$	<i>na</i>	30.00	X

Trans-cab Auto Services Pte Ltd**AAD1807-107**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5470H

1SET	WHEELARCH CLIP FRT RH	\$	na	30.50	}	X
6	BONNET INSULATOR CLIP L70Y	\$	na	7.30		
2	BONNET STRUT L70Y	\$	sm	88.61		
2	BONNET CABLE CLIP L70Y	\$	na	6.31		
2	BONNET CABLE COVER SCREW L70Y	\$	na	10.85		
1	WINDSCREEN SEALANT	\$	na	253.80		
1	FRONT WINDSCREEN MOULDING	\$	na	120.00		
1	FRONT WINDSCREEN INNER SPONGE SEAL	\$	na	100.00		

TOTAL	\$	894.88	87
--------------	-----------	---------------	-----------

TOTAL PARTS	\$	32,958.78
--------------------	-----------	------------------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	4,500.00	400
Putty and spray painting of the affected portion.	\$	4,000.00	400
To rust-proofing of the affected areas.	\$	170.00	30
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	na	380.00 X
To check steering geometry and computer wheel alignment	\$	5	220.00 X
To transfer of tire, rim and on wheel balancing.	\$	5	170.00 X
To Check Electrical Lighting Concerned.	\$	170.00	100
To transfer of front fender fittings, attachment and perform water seepage test.	\$	na	380.00 X
To transfer of bonnet fittings, attachment and perform water seepage test.	\$	na	380.00 X

Trans-cab Auto Services Pte Ltd

AAD1807-107

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5470H

To vacuum, replace, refix and recharge air condenser	\$	na 380.00 X
To replace, refix and top up coolant for radiator	\$	7 170.00 X
To vacuum, replace, refix and recharge Air Intercooler	\$	7 170.00 X
To transfer of front windscreen fittings and conduct water seepage test	\$	4 170.00 X
TOTAL	\$	11,090.00 11260
Over All Total	\$	44,048.75 44218.78 X
LUMP SUM (REPAIR DAY)		15-DAYS 2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

0. 0

1,259.42 +

150.77 +

783.83 =

2,194.02 *

2,194.02 x

90. %

1,974.618 *

66. +

=

66. *

400. +

440. +

30. +

10. =

880. *

1,974.62 +

66. +

880. =

2,920.62 *

2,920.62 x

80. %

2,336.496 *

0. 0

4/5 - \$2350