

**Transcab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHB 9935M****AAD1807-051***Not Authorized  
C/Sys @ ?*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

**SHB 9935M**

VF1ABL15AUC273127

RENAULT

LATITUDE

6.7.2018

**CHINA TAIPING**

|    |   | PART                            |    | LIST               |          |
|----|---|---------------------------------|----|--------------------|----------|
| 1  | 1 | BUMPER COVER FRT                | \$ | <i>RM</i> 1,259.42 | <i>C</i> |
| 2  | 1 | BUMPER SPOILER FRT              | \$ | <i>CM</i> 181.75   | <i>—</i> |
| 3  | 1 | BUMPER ABSORBER FRT             | \$ | <i>SH</i> 394.68   | <i>}</i> |
| 4  | 1 | BUMPER RETAINER FRT LH          | \$ | <i>SH</i> 151.41   |          |
| 5  | 1 | BUMPER SUPPORT FRT              | \$ | <i>SH</i> 123.88   |          |
| 6  | 1 | BUMPER RETAINER FRT RH          | \$ | <i>SH</i> 150.77   |          |
| 7  | 1 | BUMPER SUPPORT FRT              | \$ | <i>SH</i> 123.88   |          |
| 8  | 1 | BUMPER UNDERTRAY FRT            | \$ | <i>SH</i> 472.83   |          |
| 9  | 1 | BUMPER GRILLE LOWER FRT         | \$ | <i>SH</i> 266.80   |          |
| 10 | 1 | BUMPER FOG LAMP GRILLE LH       | \$ | <i>SH</i> 207.21   |          |
| 11 | 1 | BUMPER FOG LAMP GRILLE RH       | \$ | <i>SH</i> 207.21   |          |
| 12 | 1 | BUMPER BEAM FRT                 | \$ | <i>SH</i> 914.08   |          |
| 13 | 1 | TOW COVER FRT                   | \$ | <i>SH</i> 28.61    |          |
| 14 | 1 | RADIATOR GRILLE                 | \$ | <i>SH</i> 1,707.78 |          |
| 15 | 1 | RADIATOR GRILLE BADGE 'RENAULT' | \$ | <i>SH</i> 225.36   |          |
| 16 | 1 | RADIATOR GRILLE FRAME           | \$ | <i>SH</i> 1,353.75 |          |
| 17 | 1 | FRAME FULL SUPPORT PANEL        | \$ | <i>SH</i> 615.90   |          |
| 18 | 1 | FRAME FULL SUPPORT BRACKET      | \$ | <i>SH</i> 89.79    |          |
| 19 | 1 | FRONT BRACE PANEL               | \$ | <i>SH</i> 177.22   |          |
| 20 | 1 | HORN                            | \$ | <i>SH</i> 314.17   |          |
| 21 | 1 | HORN BRACKET                    | \$ | <i>SH</i> 40.45    |          |
| 22 | 1 | HEADLAMP LH                     | \$ | <i>SH</i> 1,184.43 | <i>}</i> |
| 23 | 1 | HEADLAMP RH                     | \$ | <i>SH</i> 1,184.43 |          |
| 24 | 1 | HEADLAMP PANEL FRT LH           | \$ | <i>SH</i> 152.15   |          |
| 25 | 1 | HEADLAMP PANEL FRT RH           | \$ | <i>SH</i> 152.15   | <i>}</i> |
| 26 | 1 | AUTO GEARBOX                    | \$ | 41,101.58          |          |
| 27 | 1 | AUTO COMPUTER                   | \$ | <i>SH</i> 5,032.17 |          |
| 28 | 1 | AIR INTERCOOLER HOSE (LONG)     | \$ | 1,014.13           | <i>?</i> |

**Trans-cab Auto Services Pte Ltd**

AAD1807-051

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHB 9935M**

|    |   |                              |    |        |   |
|----|---|------------------------------|----|--------|---|
| 29 | 1 | AIR INTERCOOLER HOSE (Short) | \$ | 375.14 | 7 |
| 30 | 1 | HEATSHIELD                   | \$ | 150.00 | ✓ |

|              |           |                  |
|--------------|-----------|------------------|
| <b>TOTAL</b> | <b>\$</b> | <b>59,353.16</b> |
| <b>10%</b>   | <b>\$</b> | <b>5,935.32</b>  |
|              | <b>\$</b> | <b>53,417.84</b> |

**Special Nett**

|    |      |                                 |    |    |        |     |
|----|------|---------------------------------|----|----|--------|-----|
| 1  | 1SET | RADIATOR GRILLE FRAME CLIP      | \$ | na | 52.00  | ✓   |
| 2  | 1SET | BUMPER CLIP FRT                 | \$ | na | 66.00  | ✓   |
| 3  | 1    | BUMPER BRACKET CLIP FRT LH      | \$ | na | 12.00  | } X |
| 4  | 1    | BUMPER SUPPORT CLIP FRT LH      | \$ | na | 10.50  |     |
| 5  | 1    | BUMPER BRACKET CLIP FRT RH      | \$ | na | 12.00  |     |
| 6  | 1    | BUMPER SUPPORT CLIP FRT RH      | \$ | na | 10.50  |     |
| 7  | 1    | TOW COVER FRT                   | \$ | na | 14.50  |     |
| 8  | 1SET | RADAIOR GRILLE SCREW            | \$ | na | 16.00  |     |
| 9  | 1SET | BUMPER GRILLE LOWER CLIP        | \$ | na | 69.00  |     |
| 10 | 1SET | FRAME FULL SUPPORT PANEL CLIP   | \$ | na | 70.00  | }   |
| 11 | 2    | FRAME FULL SUPPORT PANEL NUT    | \$ | na | 20.00  |     |
| 12 | 2    | FRAME FULL SUPPORT PANEL STUD   | \$ | na | 30.00  |     |
| 13 | 1    | Windscreen moulding             | \$ | na | 100.00 |     |
| 14 | 1SET | Front licence plate with holder | \$ | na | 80.00  |     |

|              |           |               |
|--------------|-----------|---------------|
| <b>TOTAL</b> | <b>\$</b> | <b>562.50</b> |
|--------------|-----------|---------------|

|                    |           |                  |
|--------------------|-----------|------------------|
| <b>TOTAL PARTS</b> | <b>\$</b> | <b>53,980.34</b> |
|--------------------|-----------|------------------|

**LABOUR**

Panel beating, knocking and straightening the  
necessary portion, remove and renewal of parts,  
adjust and realign the same

\$ 5,400.00 2001

Towing Fees.

\$ 120.00 501

**Trans-cab Auto Services Pte Ltd****AAD1807-051**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHB 9935M**

|                                                                                                                     |    |              |
|---------------------------------------------------------------------------------------------------------------------|----|--------------|
| To apply paint protection system (PPS) maintain and enhancement                                                     | \$ | nn 380.00 X  |
| Putty and spray painting of the affected portion.                                                                   | \$ | 6,000.00 20q |
| To rust-proofing of the affected areas.                                                                             | \$ | nn 170.00 X  |
| To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.                     | \$ | nn 380.00 X  |
| To check steering geometry and computer wheel alignment                                                             | \$ | nn 220.00 X  |
| To transfer of tire, rim and on wheel balancing.                                                                    | \$ | nn 170.00 X  |
| To Check Electrical Lighting Concerned.                                                                             | \$ | 170.00 20q   |
| To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack. | \$ | nn 380.00 X  |
| Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.                                     | \$ | nn 380.00 X  |
| To lift-up engine with gear box and refit.                                                                          | \$ | 440.00 7     |
| To remove and renew power steering pump, oil cooler pipe and final checking and testing.                            | \$ | nn 440.00 X  |
| To remove and refit air bag system and reset.                                                                       | \$ | nn 480.00 X  |
| To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.                        | \$ | nn 380.00 X  |

**Trans-cab Auto Services Pte Ltd**

AAD1807-051

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHB 9935M**

|                                                                             |    |                           |
|-----------------------------------------------------------------------------|----|---------------------------|
| To vacuum, replace, refix and recharge air condenser                        | \$ | <i>nn</i> 380.00 <i>X</i> |
| To replace, refix and top up coolant for radiator                           | \$ | <i>nn</i> 170.00 <i>X</i> |
| To vacuum, replace, refix and recharge Air Intercooler                      | \$ | <i>nn</i> 170.00 <i>X</i> |
| To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test. | \$ | <i>nn</i> 170.00 <i>X</i> |

|              |           |                  |
|--------------|-----------|------------------|
| <b>TOTAL</b> | <b>\$</b> | <b>16,400.00</b> |
|--------------|-----------|------------------|

|                       |           |                  |
|-----------------------|-----------|------------------|
| <b>Over All Total</b> | <b>\$</b> | <b>70,380.34</b> |
|-----------------------|-----------|------------------|

(LUMP SUM)

~~20 DAYS~~  
*4 days*