

10/2010

INS. CASE OWNER:

Jacklyn

CC 6 /AIG1801

2782, U+639

LKK:

IDAC:

Surveyor:

marups

DOI:

ASSIGNMENT

17/7/18

Date / Time:

17/7/18

Registered in Merimen:

17/7/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

STB 7771L

Name of Insured:

TEO FOR BOON

Insured Tel No.:

HP: 81616271

Excess Sec II :SS

D.O.A: 12/7/18

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

501697457754

Policy No.:

200411096-03

Make / Model:

WISSAN

Place of Accident:

HOLLAND RD.

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

% Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:

WSP: NPEL
Liability: SENG



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

18/7/18

praktin

STW 18017-7

STB 7771L-7

STAGE

DATE / PIC

Non-Reporting 1st:

Non-Reporting 1st (2nd):

Non-Reporting 1st (Final):

Notification 1st (if non-pickup):

Call OI: 17/7/18

After call 1st to OI:

Documentation Check List: Handler Typist

Notification 1st (if non-pickup):

After call 1st to OI:

Authorisation to Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

17/7/18
HIS
potatur

spoke to OI, got an excellent statement, Internal TP claim
and HLD issue. OI agree to settle and course of HLD
issue sent letter to OI
update OI, OI want to know claim amount. Done

RECEIVED 3 SEP 2018

After repair photo

(4)

PRELIMINARY ADVICE

Date/Time:

15/8/2018

Sent By:

CPK

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$ 5,900.00

(7 days) Reduction:

62

%

Email

Call

FINAL SETTLEMENT

Date/Time:

5/9/2018

Confirm with

Mr Ng

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No. 27

Repair Cost:

S\$ 5,900.00

Loss of Rental (LOR):

S\$

-

(days)

Loss of Use (LOU):

S\$

800.00

(S 104.00 x 8 days)

Loss of Income (LOI):

S\$

-

(5 x days)

LOR only

LOU only

LOR + LOU

LOR + LOU

[Tick only one]

GIA/LTA Search

S\$

8.00

Medical:

S\$

-

Disbursement:

S\$

-

(e.g. Tow/ Independent)

Legal Cost:

S\$

-

Total:

S\$

6,708.00

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

6,708.00

Name 1:

Ngee Seng Auto Works

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

ah
6/9/18

(08/11/13) wef

REF:

SS. REC. BY: Marcus

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SW19917at Workshop m/s neelyof SKB 7731C

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 62k

IBAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: 2 Consistent? : Yes or NoEst. Repairs: 7 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

10580

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SW19917 Yr Regn: 1 / 12

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA /Make: Toyota Provia C.C. 2362Colour: White A/C: Insured / Std / NI / NASp. Reading: 53643 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTEGD52M90A028580

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/55R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC OHTSU / PIR / SUMI /

TOYO / YOKO or

Front 6 mm Rear 6 mmR/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 12/7/18 D.O.I. 13/7/18

Survey held at _____

Des. of Damages: Fd / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

LIA 44829L1514 5,900.00 / Red 14 9,557.50 / (62%)

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$ _____)

Survey Fee: _____

Transportation: _____

☐ : Interview (\$ _____)

Photos _____

☐ : Tech. Invs (\$ _____)

Others _____

☐ : Weekend (\$ _____)

TOTAL

Report Format: _____

Lump Sum / I.B.I.: (\$ _____)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC6/AIG18012782/Ufb3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 13-07-2018



Code : AIG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKB 7731L	Veh. Inspected	SJW 1991T
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	13/07/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	12/07/2018	Inspection Date	13/07/2018
Survey held at	NGEE SENG AUTO WORKS BLK. 3022A, UBI ROAD 1, #01-50 SINGAPORE 408716.		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



NGEE SENG AUTO WORKS 誼盛摩哆

REGISTRATION NO: 52791500M

Bld. 3022A, Ubi Road 1, #01-50, Singapore 408716. Tel: 6841 2276 Fax: 6743 9006

ALL TYPES OF MOTOR REPAIRS SERVICES, SPRAY PAINTING & INSURANCE CLAIMS.

AIG ASIA PACIFIC INSURANCE PTE LTD

78, Senton Way
#07-16 Chartis Building
Singapore 079120

Estimate Repair Bill :TP18014
Date :16/07/2018
Ref No :SJW1991T
Policy No :
Page :01

not Allowed
nkl
4/5 \$5900
7 dy.

RE : VEHICLE NO.SJW1991T JTEGDK2M90A

Qty	Description	Unit Price	AMOUNT
1	REAR BOOTLID GLASS MOULDING	187.95	\$261.40
1	REAR BOOTLID	1492.50	\$1,598.30
1	TOYOTA LOGO	68.10	\$86.50
1	PREVIA EMBLEM	91.70	\$97.20
1	TOYOYA EMBLEM	62.20	\$97.20
1	REAR BOOTLID INNER LOCK	409.10	\$621.40
1	REAR BOOTLID INNER TRIM BOARD CLIPS (SET)		\$90.00
1	REAR BOOTLID WEATHERSTRIP		\$362.30
1	REAR BUMPER	681.10	\$980.50
2	REAR BUMPER SIDE RETAINER	\$98.30	\$196.60
2	REAR BUMPER CENTRE RETAINER	\$78.30	\$156.60
2	REAR BUMPER TOWING COVER RH/LH	\$73.20	\$146.40
2	REAR BUMPER SPONGE RH/LH	\$183.50	\$367.00
1	REAR BUMPER CENTRE LOCK SENSOR		\$320.70
1	REAR END PANEL	609.66	\$987.40
1	REAR END PANEL TOP GARNISH	301.60	\$397.30
1	REAR END PANEL LOWER GARNISH		\$410.40
2	REAR FENDER INNER GARNISH RH/LH	725.10	\$1,974.40
1	REAR FLOORBOARD PANEL	1025.10	\$1,315.50
2	REAR BUMPER REFLECTOR	\$85.20	\$170.40
1	REAR REVERSE CAMERA		\$350.00
TOTAL (1)			\$10,987.50
SPECIAL NETT ITEM			
1	REAR BUMPER CLIPS (SET)		\$75.00
1	REAR END PANEL GARNISH CLIPS (SET)		\$60.00
1	REAR FENDER INNER GARNISH CLIPS (SET)		\$90.00
1	REAR WINDSCREEN SEALANT		\$80.00
1	REAR BUMPER REVERSE SENSOR (SET)		\$320.00
1	REAR NUMBER PLATE		\$80.00
TOTAL (2)			\$705.00
LABOUR			
	TO REMOVE & REFIX REVERSE SENSOR / CAMERA		\$180.00
	TO REMOVE & REFIX REAR WINDSCREEN		\$200.00
	TO REMOVE & REFIX REAR AIR CON BLOWER		\$180.00
	TO RUST PROOF AFFECTED AREAS		\$150.00
	TO REMOVE & REFIX CUSHION & CARPET		\$150.00
	TO PANEL BEATING		\$1,400.00
	TO SPARY PAINTING		\$1,500.00
TOTAL SPARE PARTS & LABOUR CHARGES			\$3,760.00
			\$15,452.50

TOTAL (1)

TOTAL (2)

LABOUR CHARGES

TOTAL SPARE PARTS & LABOUR CHARGES

Link Auto - Singapore's first
The Repairer - Free full wing
• To remove & re-attach spray painting
• To display damaged parts during survey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplemental item(s) must be surveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

6367.61
25%
4775.70

7375.70

Poh Kin (LKKAUTO)

From: Poh Kin (LKKAUTO)
Sent: Tuesday, 17 July 2018 2:49 PM
To: 'ngeesengautoworks@hotmail.com'
Cc: Hsiao Tong (LKKAUTO); Admin A
Subject: Our Ref: CC6/AXA18012782/Ufb3; Your Ref: SJW 1991T

Importance: High

WITHOUT PREJUDICE

Our Ref: CC6/~~AXA~~^{ALL}18012782/Ufb3
Your Ref: SJW 1991T

Dear Sirs,

ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE SKB 7731L AND SJW 1991T ON 12/07/2018

We refer to above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident.

And the days of LOU/ LOR will be based on the number of days of repair as recommended by our surveyor.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Poh Kin, Chong (Mr) | Case Handler


LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.





NGEE SENG AUTO WORKS 誼盛摩哆

REGISTRATION NO: 52791500M

Blk. 3022A, Ubi Road 1, #01-50, Singapore 408716. Tel: 6841 2276 Fax: 6743 9006

ALL TYPES OF MOTOR REPAIRS SERVICES, SPRAY PAINTING & INSURANCE CLAIMS.

AIG ASIA PACIFIC INSURANCE PTE LTD

78, Shenton Way
#07-16, Chartis Building
Singapore 079120

ATTN : Motor Claims Depts

FINAL Repair Bill

:TP18014

Date :13/08/2018
Ref No :SJW 1991 T
Your Ref :SKB 7731 L
Page : 01

RE : VEHICLE NO. SJW1991T TOYOYA PREVIA

LUMP SUM REPAIRS	\$5,900.00
RENTAL (5 DAYS X \$230.00)	\$1,150.00
LTA SEARCH FEES	\$8.00
TOTAL	<u>\$7,058.00</u>

DOLLARS : SEVEN THOUSAND AND FIFTY EIGHT ONLY .



NGEE SENG AUTO WORKS



Invoice

GOH KEN YI
27 GREENLEAF DRIVE
S(279574)

Invoice No : GPLIN0000883
Invoice Date : 31/7/2018
Due Date : 31/7/2018
VHA No : 1160
Referral ID : N005

Description :	Amount
Rental for 5 Day/s @ \$230 per Day	\$1,150

Vehicle No : SLP5941A

Vehicle Description : Toyota Previa 2.4A

Rental Period : 23/07/2018 to 27/07/2018

Total Amount Payable : \$1,150

GOOD WAY RENT-A-CAR PTE LTD

8 Kaki Bukit Ave 4 #06-04 Premier@Kaki Bukit Singapore 415875
Tel: 6315 8479 H/P: 9833 0807

VHA No: 1160

Invoice No: GPLIN883

Hirer's Vehicle No:

UEN: 201505120D

VEHICLE RENTAL AGREEMENT

HIRER'S PARTICULARS


Name: (as in I/C) Goh Ken-Yi
NRIC / FIN No: S7231658D
Address (Res): 27 Greenleaf Drive
Singapore 279574
Name & Address of Employer:

Occupation: Driving Exp:
Singapore Driving Licence No:
Issue Date: Date of Birth:
Tel: (O) (R) HP: 81815529

ADDITIONAL DRIVER'S PARTICULARS

Name: (as in I/C) Abdul Rahim
NRIC / FIN No: 1533269 G
Address (Res): Blk 420 Clementi Ave - 1
#14-213 Singapore 120420
Occupation: Driver Driving Exp:
Singapore Driving Licence No:
Issue Date: Date of Birth:
Tel: (O) (R) 93821405 H/P:

VEHICLE CHECK LIST



MISSING / FAULTY ACCESSORIES / PARTS

REMARKS:

Vehicle No: SLP5941A Replace Veh No:
Mileage Out: 113605 Mileage Out:
Make & Model: PREVIA Auto / Manual
Out : Date 23/7/18 Time: 11:15
HIRE / PERIOD EXPIRY Time:
NON-WAIVER EXCESS-\$ 3000/-

CHARGES

Daily	<u>5</u> @ \$ <u>230</u> per day	<u>#1150</u>
Weekly	@ \$ per week	
Monthly	@ \$ per month	
Hours	@ \$ per hour	
Extension	@ \$	
Delivery/Collection Service		

SUB-TOTAL \$

PETROL LEVEL

Out	E	1/8	1/4	3/8	1/2	5/8	3/4	7/8	F
In	E	1/8	1/4	3/8	1/2	5/8	3/4	7/8	F

Fuel
Traffic / Parking Fines

TOTAL CHARGES \$

Hirer's Signature [Signature]

Additional Driver's Signature [Signature]

I have read and agree to the terms and condition on both sides of the agreement. If I have presented a charge/credit card for payment, I agree that all amounts payable under this agreement and for parking and traffic infringements may be billed to that account and my signature above will be considered to have been made on the charge/credit card voucher. All information I have given GOOD WAY RENT-A-CAR PTE LTD in connection with this agreement is true.

*IMPORTANT

- VEHICLE IS STRICTLY PROHIBITED FOR "HIRE FOR REWARDS" USAGE SUCH AS UBER / GRABCAR / GRABSHARE ETC.
- ONLY PERSON ABOVE 23 YEARS OF AGE WITH MORE THAN 2 YEARS DRIVING EXPERIENCE, AUTHORIZED, LICENSED AND SIGNING THIS AGREEMENT MAY DRIVE THE VEHICLE.
- ALL PARKING AND TRAFFIC VIOLATIONS ARE THE RESPONSIBILITY OF THE HIRER. AN ADMINISTRATIVE CHARGE WILL BE LEVIED ON ANY TRAFFIC VIOLATIONS REDIRECTED.
- THE HIRER SHALL BE LIABLE FOR EXCESS CHARGES FOR ANY LATE RETURN AT THE RATE SHOWN PER HOUR OR PER DAY, INCLUSIVE OF CDW AND/OR PAI WHERE APPLICABLE.
- IN CASE OF ACCIDENT, THE HIRER SHALL REPORT TO RENTAL OFFICE IMMEDIATELY. IF THERE IS BODILY INJURIES, A POLICE REPORT MUST BE MADE WITHIN 24 HOURS.
- VEHICLE IS STRICTLY FOR SINGAPORE USE ONLY, AND MAY NOT BE DRIVEN OUT OF SINGAPORE WITHOUT PRIOR CONSENT OF THE COMPANY GOOD WAY RENT-A-CAR PTE LTD.

RETURN OF VEHICLE. THE HIRER / DRIVER IS REQUIRED TO SIGN IN THE COLUMN "SIGNATURE OF HIRER / DRIVER" FAILING WHICH THE DAY AND TIME INSERTED BELOW SHALL BE DEEMED TO BE THE DAY AND TIME THE VEHICLE IS RETURNED TO GOOD WAY RENT-A-CAR PTE LTD AND THE SAME SHALL BE ACCEPTED AS CONCLUSIVE EVIDENCE OF THE SAME AND SHALL NOT BE CHALLENGED OR QUESTIONED ON ANY ACCOUNT WHATSOEVER.

DATE IN	TIME IN	MILEAGE	CHECKED BY	REMARKS	SIGNATURE OF HIRER/DRIVER
<u>23/7/18</u>	<u>17:00</u>	<u>114070</u>			<u>[Signature]</u>



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

Our Ref: CC6/AIG18012782/Ufb3

18th July 2018

TEO KOK BOON

22 Wilby Road,
#08-14,
Singapore 276306.

Dear Sir/Madam,

**ROAD TRAFFIC ACCIDENT INVOLVING SKB 7731L AND SJW 1991T ALONG
HOLLAND ROAD ON 12.07.2018**

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 7 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Poh Kin, Chong

Case Handler

DID: 6841 2132

FAX: 6741 4108

Email: pohkin@lkkauto.com

c.c. *AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)*

AUTHORIZATION TO ACT
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

I, Goh Ken-Yi ("the third party claimant")
of 27 Greenleaf Drive, S(279574) (address),
owner of SSW 1991T (vehicle no.) hereby authorize
M/S NGEE SENG AUTO WORKS
("the workshop") to act for me with respect to my claim for repair costs and/or
rental and/or loss of use ("claim") for my vehicle no. SSW 1991T that was
damaged pursuant to the accident which occurred on 12/07/2018 (date) along
Holland Road (location)
involving vehicle no/s SKB 7731L ("the accident").

I further authorize the workshop to settle the above mentioned claim in a
manner that they deem fit and the workshop is further authorized to receive
payment fortherto settlement of my claim with payment cheque/s being made in
favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my
behalf is on a without prejudice and without admission of liability basis insofar
as the driver/owner/insurers of the other vehicle/s is concerned.

Date this 13th day of July (month) 20 18 (year)



Signed by "the third party claimant"

新 盛 摩 哆
NGEE SENG AUTO WORKS

Co. Reg. No. 5279150CM
Blk 3022A, Ubi Road 1, #01-50
Singapore 408716
Tel: 6841 2276 Fax: 6743 9006



Signed by "the workshop"

RELEASE VOUCHER
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

"We/I, NGEE SENG AUTO WORKS ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte. Ltd. M/S LKK Auto Consultants Pte Ltd ("name of surveyor") with respect to the amount claimed for S\$ 5,900.00 (repair costs), S\$ 800.00 (loss of use/rental) S\$ 8.00 (search fees) for vehicle no. SJW 1991T that was damaged pursuant to the accident which occurred on 12/7/2018 (date) along Holland Road (location) involving vehicle no/s SKB 7731 L.

This is pursuant to the inspection conducted on 13/07/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner Goh Ken-Yi ("third party claimant") of vehicle no. SJW 1991T to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte. Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SJW 1991T (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 5th day of September (month) 20 18 (year)



Signed by AIG appointed surveyor

NGEE SENG AUTO WORKS
Co. Reg. No. 52791500M
Blk 3022A, Ubi Road 1, #01-50
Singapore 408716
Tel: 6843 2276 Fax: 6743 9006

Chopped & Signed by "the workshop"



NGEE SENG AUTO WORKS 誼盛摩哆

REGISTRATION NO: 52791500M

Blk. 3022A, Ubi Road 1, #01-50, Singapore 408716. Tel: 6841 2276 Fax: 6743 9006

ALL TYPES OF MOTOR REPAIRS SERVICES, SPRAY PAINTING & INSURANCE CLAIMS

AIG ASIA PACIFIC INSURANCE PTE LTD

78, Shenton Way
#07-16, Chartis Building
Singapore 079120

ATTN : Motor Claims Depts

FINAL Repair Bill :TP18014

Date :13/08/2018
Ref No :SJW 1991 T
Your Ref :SKB 7731 L
Page : 01

RE : VEHICLE NO. SJW1991T TOYOYA PREVIA

LUMP SUM REPAIRS

\$5,900.00

TOTAL

\$5,900.00



NGEE SENG AUTO WORKS

Enquire Vehicle & Owner Information (Vehicle No. SKB7731L As At 12 Jul 2018 / 07:40:00)

Law Firm Search Details

Search Reason: Insurance claim in relation to traffic accident
Law Firm Case No.: N1-MISC-18

Current Owner Details

Owner ID Type: Singapore NRIC
Owner ID: S6942534H
Owner Name: TEO KOK BODN
Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes
Registered Block/House No.: 22
Registered Street Name: WILBY ROAD
Registered Unit No.: # 08 - 14
Registered Building Name: -
Registered Postal Code: 276306

Current Vehicle Details

Vehicle No.: SKB7731L
Make Description/Model: NISSAN / QASHQAI 2.0 CVT ABS D/AIRBAG 2WD SDR S/R
Insurance Company Name: AIG ASIA PACIFIC INSURANCE PTE. LTD.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane



















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Jul 2018 Edit Reg		13 Jul 2018 00:00 Edit Adj Rpt	S\$5,900.00 Edit Estimates	S\$5,900.00 View Rpt		Pending for Survey Report Cancel Case
























Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: Teo Kok Boon , ID: S6942534H									
Main Claimant: GOH KEN-YI , ID: S7231658D									
Vehicle Reg. No.: SJW1991T		Date of Loss: 12/07/2018 00:00 - :59 [78 Months and 7 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 5096974577SG		Policy/Cover Note No.: 2100411096							
Vehicle Reg. No. (Insured): SKB7731L		Policy No. (Claimant): DMPCSN3024331800							
		Excess:							
Repairer: Ngee Seng Auto Works (HQ) Block 3022A, Ubi Road 1, #01-50, 408716 Ubi - Tel: 6841 2276									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Kesaval, Jaclyn-M] Jaclyn-M.Kesaval@aig.com									
Claimant's Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 24/07/2018]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (16/07/2018): Request To Upload TP GIA Report 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJW1991T (5096974577SG)**
[SKB7731L]
TP
GOH KEN-YI
Jul 12 2018 12:00AM
[Teo Kok Boon]
Ngee Seng Auto Works

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Letters/Correspondences															1 per page		<input type="button" value="v"/>	<input checked="" type="checkbox"/>		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail		Print			
1	(Draft)	Third Party Express Settlement – Payment Breakdown													1		Edit			
Assessment Reports															1 per page		<input type="button" value="v"/>	<input checked="" type="checkbox"/>		
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)													Thumbnail		Print			
1	16/07/18 11:05	Accident Statement <small>From: SC - Reg. No: SKB7731L, Claimant: TEO KOK BOON</small>													1		Load HTM			
Photos/Images															3 per page		<input type="button" value="v"/>	<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail		Print			
1	14/07/18 11:41	Odometer Reading													1		Load JPG	<input checked="" type="checkbox"/>		
2	14/07/18 11:41	Chassis Number													1		Load JPG	<input checked="" type="checkbox"/>		
3	14/07/18 11:41	General View													1		Load JPG	<input checked="" type="checkbox"/>		
4	14/07/18 11:41	General View													1		Load JPG	<input checked="" type="checkbox"/>		
5	14/07/18 11:41	General View													1		Load JPG	<input checked="" type="checkbox"/>		
6	14/07/18 11:41	General View													1		Load JPG	<input checked="" type="checkbox"/>		
7	14/07/18 11:41	General View													1		Load JPG	<input checked="" type="checkbox"/>		
8	14/07/18 11:41	General View													1		Load JPG	<input checked="" type="checkbox"/>		
9	14/07/18 11:41	General View													1		Load JPG	<input checked="" type="checkbox"/>		
10	14/07/18 11:41	General View													1		Load JPG	<input checked="" type="checkbox"/>		
11	14/07/18 11:41	General View													1		Load JPG	<input checked="" type="checkbox"/>		
12	14/07/18 11:41	General View													1		Load JPG	<input checked="" type="checkbox"/>		
13	14/07/18 11:41	General View													1		Load JPG	<input checked="" type="checkbox"/>		
14	14/07/18 11:41	General View													1		Load JPG	<input checked="" type="checkbox"/>		
15	14/07/18 11:41	General View													1		Load JPG	<input checked="" type="checkbox"/>		
16	14/07/18 11:41	General View													1		Load JPG	<input checked="" type="checkbox"/>		
17	14/07/18 11:41	General View													1		Load JPG	<input checked="" type="checkbox"/>		
18	14/07/18 11:41	General View													1		Load JPG	<input checked="" type="checkbox"/>		
19	14/07/18 11:41	General View													1		Load JPG	<input checked="" type="checkbox"/>		
20	14/07/18 11:41	General View													1		Load JPG	<input checked="" type="checkbox"/>		
21	14/07/18 11:41	General View													1		Load JPG	<input checked="" type="checkbox"/>		
22	14/07/18 11:41	General View													1		Load JPG	<input checked="" type="checkbox"/>		
23	14/07/18 11:41	General View													1		Load JPG	<input checked="" type="checkbox"/>		
24	14/07/18 11:41	General View													1		Load JPG	<input checked="" type="checkbox"/>		
25	14/07/18 11:41	General View													1		Load JPG	<input checked="" type="checkbox"/>		
26	14/07/18 11:41	General View													1		Load JPG	<input checked="" type="checkbox"/>		
27	14/07/18 11:41	General View													1		Load JPG	<input checked="" type="checkbox"/>		
28	14/07/18 11:41	General View													1		Load JPG	<input checked="" type="checkbox"/>		
29	14/07/18 11:41	General View													1		Load JPG	<input checked="" type="checkbox"/>		
30	14/07/18 11:41	General View													1		Load JPG	<input checked="" type="checkbox"/>		

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No.	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
31	14/07/18 11:41	General View	 Load JPG	<input checked="" type="checkbox"/>
32	14/07/18 11:41	General View	 Load JPG	<input checked="" type="checkbox"/>
33	14/07/18 11:41	General View	 Load JPG	<input checked="" type="checkbox"/>
34	14/07/18 11:41	General View	 Load JPG	<input checked="" type="checkbox"/>
35	14/07/18 11:41	General View	 Load JPG	<input checked="" type="checkbox"/>
36	14/07/18 11:41	General View	 Load JPG	<input checked="" type="checkbox"/>
37	14/07/18 11:41	General View	 Load JPG	<input checked="" type="checkbox"/>
38	14/07/18 11:41	General View	 Load JPG	<input checked="" type="checkbox"/>
39	23/07/18 20:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	23/07/18 20:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	23/07/18 20:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	23/07/18 20:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	23/07/18 20:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	23/07/18 20:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	23/07/18 20:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	23/07/18 20:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	23/07/18 20:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	23/07/18 20:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	23/07/18 20:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	23/07/18 20:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	23/07/18 20:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	23/07/18 20:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	23/07/18 20:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	23/07/18 20:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	23/07/18 20:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	23/07/18 20:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	23/07/18 20:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	23/07/18 20:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	23/07/18 20:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	23/07/18 20:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	23/07/18 20:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	23/07/18 20:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	23/07/18 20:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	23/07/18 20:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	23/07/18 20:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	23/07/18 20:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	23/07/18 20:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	23/07/18 20:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	23/07/18 20:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	23/07/18 20:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	23/07/18 20:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	23/07/18 20:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	23/07/18 20:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	23/07/18 20:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	23/07/18 20:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	23/07/18 20:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	23/07/18 20:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	23/07/18 20:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	23/07/18 20:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	23/07/18 20:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
81	23/07/18 20:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	23/07/18 20:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	23/07/18 20:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
84	23/07/18 20:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	23/07/18 20:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	23/07/18 20:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	23/07/18 20:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
88	23/07/18 20:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	23/07/18 20:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	23/07/18 20:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	23/07/18 20:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	23/07/18 20:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
93	08/08/18 20:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
94	08/08/18 20:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
95	08/08/18 20:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
96	08/08/18 20:01	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	16/07/18 17:31	TP GIA REPORT	 Load PDF	
2	15/08/18 09:25	TP Estimate-Marked	 Load PDF	
3	06/09/18 10:10	LETTER TO OI	 Load PDF	
4	13/09/18 10:40	WORKSHOP INVOICE	 Load PDF	
5	13/09/18 10:40	AUTHORISATION TO ACT FORM	 Load PDF	
6	13/09/18 10:40	Release Voucher	 Load PDF	
7	13/09/18 10:40	LTA SEARCH	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 100px; width: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKB7731L (Insd veh)	Model:	TOYOTA PREVIA 2.4
	SJW1991T (TP veh)		8-SEATER (A)
Date of Accident:	12/07/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
Repair Estimate	: \$	15,452.50		
Final Repair Cost	: \$	5,900.00		
Loss of Use	: \$	800.00		8.00 days at \$100.00 per day
Rental (if any)	: \$	0.00		days
LTA / GIA Search Fee	: \$	8.00		
Others:	: \$	0.00		
	: \$			
Final Settlement Sum	: \$	6,708.00		

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ____ 100 ____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ (%) Assessed Liability (*): ____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Ngee Seng Auto Works	: \$	6,708.00
2)		: \$	
3)		: \$	

JOANNE LEE KHANG MIN

13 Sep
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co. Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18012782/UFB3Q2

Date: 13/09/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100411096
Claimant Vehicle No : SJW1991T **Insured Vehicle No :** SKB7731L
 Date of Loss: 12/07/2018 Nature of Claim: TP Claim No: 5096974577SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJW1991T**
 Make & Model: TOYOTA PREVIA, 2.4 8-SEATER (A) Engine No: 2AZH774269
 Reg. Date: 05/01/2012 (Man. Year: 2011) Chassis No: JTEGD52M90A028580
 Colour: Beige Odometer: 53643 km
 Engine Capacity: 2362 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55 R16 Rear Tyre Size: 225/55 R16
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,692.50	5,065.71	6,626.79	56.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,760.00	2,310.00	1,450.00	38.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,452.50	7,375.71	8,076.79	52.27
Approved Total (Overridden) (S\$)		5,900.00		
Nett Amount (S\$)	15,452.50	5,900.00	9,552.50	61.82
+ Loss of Use (8.0 x S\$100.00/day) (S\$)		800.00		
+ Doc/Search Fee (S\$)		8.00		
Nett Liability (S\$)		6,708.00		

INSPECTION

Date of Assignment: 13/07/2018
 Date Inspected: 13/07/2018 Inspected At: Ngee Seng Auto Works (HQ)
 Block 3022A, Ubi Road 1, #01-50
 Singapore 408716
 Estimated Period of Repair: 7.0 days

Adjuster: MARCUS CHUA**Manager:** Chong Poh Kin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID GLASS MOULDING	Necessary	261.40 F	*181.95 FL
2	1		*REAR BOOTLID	Badly Dented	1,598.30 F	*1,492.50 FL
3	1		*TOYOTA LOGO	Necessary	86.50 F	*68.10 FL
4	1		*PREVIA EMBLEM	Necessary	97.20 F	*91.70 FL
5	1		*TOYOTA EMBLEM	Necessary	97.20 F	*62.20 FL
6	1		*REAR BOOTLID INNER LOCK	Dented / Twisted	621.40 F	*409.10 FL
7	1		*SET REAR BOOTLID INNER TRIM BOARD CLIPS	Not Necessary	90.00 F	*- FL
8	1		*REAR BOOTLID WEATHERSTRIP	Twisted	362.30 F	*362.30 FL
9	1		*REAR BUMPER	Dented / Deformed	980.50 F	*685.10 FL
10	2		*REAR BUMPER SIDE RETAINER	Bent	196.60 F	*196.60 FL
11	2		*REAR BUMPER CENTRE RETAINER	Bent	156.60 F	*156.60 FL
12	2		*REAR BUMPER TOWING COVER RH/LH	Not Necessary	146.40 F	*- FL
13	2		*REAR BUMPER SPONGE RH/LH	Not Necessary	367.00 F	*- FL
14	1		*REAR BUMPER CENTRE LOCK SENSOR	Not Necessary	320.70 F	*- FL
15	1		*REAR END PANEL	Badly Dented	987.40 F	*609.66 FL
16	1		*REAR END PANEL TOP GARNISH	Twisted	397.30 F	*301.60 FL
17	1		*REAR END PANEL LOWER GARNISH	Not Necessary	410.40 F	*- FL
18	1		*REAR FENDER INNER GARNISH RH/LH	N/S Deformed	1,974.40 F	*725.10 FL
19	1		*REAR FLOORBOARD PANEL	Badly Dented	1,315.50 F	*1,025.10 FL
20	2		*REAR BUMPER REFLECTOR	Not Necessary	170.40 F	*- FL
21	1		*REAR REVERSE CAMERA	Not Necessary	350.00 F	*- FL
22	1		*SET REAR BUMPER CLIPS	Necessary	75.00 FS	*50.00 FS
23	1		*SET REAR END PANEL GARNISH CLIPS	Not Necessary	60.00 FS	*- FS
24	1		*SET REAR FENDER INNER GARNISH CLIPS	Not Necessary	90.00 FS	*- FS
25	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
26	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	320.00 FS	*200.00 FS
27	1		*REAR NUMBER PLATE	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,692.50	6,657.61
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	1,591.90
Total Parts (\$\$)	11,692.50	5,065.71

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & REFIX REVERSE SENSOR /CAMERA	New	180.00	50.00
2	TO REMOVE & REFIX REAR WINDSCREEN	New	200.00	120.00
3	TO REMOVE & REFIX REAR AIR CON BLOWER	New	180.00	0.00
4	TO RUST PROOF AFFECTED AREAS	New	150.00	60.00
5	TO REMOVE & REFIX CUSHION & CARPET	New	150.00	80.00
6	TO PANEL BEATING	New	1,400.00	1,000.00
7	TO SPRAY PAINTING	New	1,500.00	1,000.00
Gross Labour Cost (S\$)			3,760.00	2,310.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >