

ASSIGNMENT

From: Date: 18072018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SL3 669C
at Workshop m/s Performance
of 313 Alexandra Rd

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh: Inthiran

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 7 days Res: Yes or No

Lum Sum: 2.8.7 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No:

SL3 669C

Yr Regn: 2017 July

Type: M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BMW 2160

CC

1426

Colour:

Grey

A/C: Insured / Std / NI / NA

Sp. Reading:

2793

T/Radio: Insured / Std / NI / NA

Eng/No:

W5H 2K52000V925902

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/60R16

R:

2 2

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front:

6

Rear:

6

R/Bal:

6

mm

R/Bal:

6

mm

L/Bal:

6

mm

L/Bal:

6

mm

D.O.A:

D.O.I:

18/7/180/190

Survey held at

pmlc

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

15/1/18 Confirm 2-B-2 @ 9783.90 with 7 working days

(Ref: H 6674-47
41%)

Date/Time, File Pass to?

☐

: Prel. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S + RS \$

) Photo

) Other

)

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC3/AIG18012783/wb3		
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 13-07-2018		
		Code : AIG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJH 3274X	Veh. Inspected	SLS 6699C	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	13/07/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	30/06/2018	Inspection Date		
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 19740155W GST Reg. No M2-0020081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

180, Kampong Arang Road
East Coast Centre
Singapore 498180
Tel. 63190888 (AfterSales)
Fax. 63449773

115, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/330 (Motorrad)
Fax. 64756601 (AfterSales)
64756624 (Motorrad)



06 JUL 2018

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 47531 Page No. : 1 of 5
Date Estimated : 03/07/2018
Prepared By : Inthiran A/L Thurasamy

- ESTIMATE REPAIR FOR -

Melvin Lee Yen Hau
472 Pasir Ris Drive 6
#06-462

Singapore 510472

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLS6699C	V925962	31/07/2017	216d CAT	0

DESCRIPTION

To replace rear bumpee, taigate, tail panel and
attachements including knock out dent area cause by
accident.

Painting rear bumper, tailgate, tail panel and trunk floor.

To check electrical wiring systems and lightings at the
rear section for proper function.

To remove and install boot compartment carpet and garnish
to facilitate repairs.

To transfer lock mechanism from old to new bootlid
including conduct checks on new bootlid central locking
system for proper function.

To carry out body cavity preservation.
(Per panel).

To carry out body cavity preservation.
(For cut panel).

Sundries.

Repair - 2550 /
Repaint - 4250 /
Repair - 2397 /
Repaint - 2877 /
150 177.00 /
230 271.00 /
451 531.00 /
100 118.00 /
451? 531.00 X AN
80.00 /
? 150.00 /

Total Labour 1: 10,925.00

DESCRIPTION

TRUNK LID
TAIL PANEL
REAR BUMPER PANEL PRIMED (PDC)
RR BUMPER LH SIDE GUIDE
RR BUMPER RH SIDE GUIDE
REAR BUMPER CARRIER
SUPPORT
RR BUMPER LH INNER SIDE GUIDE

QTY	PRIC	VALUE
1	1,174.95	b1 1,174.95
1	355.20	? 355.20
1	966.25	di 966.25
1	47.85	? 47.85
1	47.85	? 47.85
1	423.80	bt 423.80
1	37.35	mic 37.35
1	58.55	rec 58.55

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, QST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 47531
Date Estimated : 03/07/2018
Prepared By : Inthiran A/L Thurasamy

Page No. :

REPAIR FOR -
Melvin Lee Yen Hau
472 Pasir Ris Drive 6
#06-462

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

Singapore 510472

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SLS6699C	V925962	31/07/2017	216d CAT	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
# To remove and install rear windscreen glass to facilitate repairs	574.00	disc ✓	574.00	
# To conduct water leak tests	75.00	✓	75.00	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# BUMP STOP *	3.25	10.00	disc ✓	32.50
# PLUG BLACK D=5MM *	0.90	10.00	disc ✓	9.00
# (DG/SL) W/SCREEN SEALANT (COLD 1 HOUR) *	131.55	2.00	disc ✓	263.10
# (DG/SL) GLASS PRIMER 30ML (VP206) *	27.85	1.00	disc ✓	27.85

Total Labour : 649.00
Total Parts : 332.45
Total Labour & Parts : 981.45

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559N, GST Reg. No. M2-0020081-8



FINAL REPORT

Estimate No. : b1 47531
Date Estimated : 03/07/2018
Prepared By : Inthiran A/L Thurasamy

Page No. :

REPAIR FOR -
Melvin Lee Yen Hau
472 Pasir Ris Drive 6
#06-462

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

Singapore 510472

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEASE	
SLS6699C	V925962	31/07/2017	216d CAT	0	
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT		
To replace rear bumper and attachments, trunk lid include making good the tail end panel and knocking out dents caused by the accident	2550.00		2,550.00		
To spray paint rear bumper, trunk lid and tail end panel	2399.00		2,399.00		
To check electrical wiring systems and lightings at the rear section for proper function.	150.00		150.00		
To remove and install boot compartment carpet and garnish to facilitate repairs	230.00		230.00		
To transfer lock mechanism from old to new trunk lid include conducting checks on new trunk lid central locking system for proper function	451.00		451.00		
To carry out body cavity preservation. (Per panel).	100.00		100.00		
# To remove and install rear windscreen glass to facilitate repairs	574.00		574.00		
# To conduct water leak tests	75.00		75.00		
Sundries	80.00		80.00		

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
TRUNK LID	1,174.95	1.00		1,174.95
REAR BUMPER PANEL PRIMED (PDC)	966.25	1.00		966.25
REAR BUMPER CARRIER	423.80	1.00		423.80
SUPPORT	45.30	1.00		45.30
RR BUMPER LH INNER SIDE GUIDE	58.55	1.00		58.55
RR BUMPER RH INNER SIDE GUIDE	58.55	1.00		58.55
GROMMET	0.75	2.00		1.50
PLAQUE 74MM	69.50	1.00		69.50
# BUMP STOP *	3.25	10.00		32.50
# PLUG BLACK D=5MM *	0.90	10.00		9.00

Performance Motors Limited

A member of the Sirex Carby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0000081-X



FINAL REPORT

DECOUPING RING PDC TORQUE CONVERTER	5.05	4.00	20.20
(DG) CLEANER R1 (100ML)	23.85	1.00	23.85
# (DG/SL) W/SCREEN SEALANT (COLD 1 HOUR) *	131.55	2.00	263.10 <i>AM</i>
# (DG/SL) GLASS PRIMER 30ML (VP206) *	27.85	1.00	27.85 <i>AM</i>

SUPPLEMENTARY ITEMS

Total Labour :	6,609.00
Total Parts :	3,174.90
Total Labour & Parts :	9,783.90
Deduction for Excess :	0.00
Total Repair Costs less Excess:	9,783.90
GST @7%:	684.87
Grand Total :	10,468.77

Asher Sng (LKKAUTO)

From: Asher Sng (LKKAUTO)
Sent: Friday, 22 February 2019 12:35 PM
To: 'Syed-Yusoff, Saliha'
Subject: [MANDATE REQUEST] Your ref : 4384218973SG, ACCIDENT ON 30/06/2018 INVOLVING SJH 3274X (OI) & SLS 6699C (TP)

Your ref : **4384218973SG**
Our ref : CC3/AIG18012783/T1eb3

Dear Sirs,

ACCIDENT ON 30/06/2018 INVOLVING SJH 3274X (OI) & SLS 6699C (TP)

We refer to the above matter.

The accident occurred when our insured rear ended third party vehicle.

Basing on the reports of the circumstance of the accident, we propose to settle third-party claim at 100% liability.

We did clarify with insured the nature of the accident and he's aware that NCD (if any) would be affected.

We seek your approval to offer repairer " **PERFORMANCE MOTORS LTD**" at **\$ 11,070.67 (all-in).**

The summary is as follows: -

	Amount Claimed	Amount Revised
1. Cost of Repairs (with GST)	\$ 17,524.03	\$ 10,468.77
2. Loss of Rental w/GST (7days x \$70)	\$ 524.30	\$ 524.30 (7days x \$70)
3. Medical Fee	\$ 77.60	\$ 77.60
Total	\$ 18,125.93	<u>\$ 11,070.67</u>

For your approval in merimen please.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Print Received Message

This mail is associated with :

***SLS6699C (4384218973SG)
[SJH3274X]**

TP

MELVIN LEE YEN HAU

Jun 30 2018 7:00PM

[Kinetic Holdings Pte Ltd]

Performance Motors Limited

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 05/04/2019 15:08 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$11070.67) - SLS6699C - Claim Handler: Syed-Yusoff, Saliha

Approved:11070.67.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**AIG THIRD PARTY EXPRESS SETTLEMENT
FOR ACCIDENTS ON OR AFTER 1ST JUNE 2008
(PAYMENT BREAKDOWN)**

Vehicle No:	SL56699C	Model:	BMW
Date of Accident:	30-6-2018		

Global Sum Settlement:	<input type="checkbox"/> Yes	<input type="checkbox"/> No
Repair Estimate	: \$	16458.37
Final Repair Cost	: \$	10468.77
Loss of Use	: \$	days at \$ per day
Rental (if any)	: \$	524.30 days
LTA / GIA Search Fee	: \$	
Others Medical fee	: \$	77.60
	: \$	
Final Settlement Sum	: \$	11070.67

Is Third Party Workshop GIA Registered? ☐ YES ☐ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ (%)

B) For GIA Registered Workshop: BOLA Application: Yes / No
BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown

1)	Performance Motor Limited	: \$	10468.77
2)	Melvin Lee Yen Hau	: \$	524.30
3)	Tan Pui Kean	: \$	77.60

Signed by appointed surveyor _____

Date _____

Please attach all the supporting documents to the form.
Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act;
Survey Report; Medical Report / Bill (if any)

Report No = T/20180707/2123

AXA INSURANCE PTE LTD

8 Shenton Way, #24-01
AXA Tower, Singapore 068811
Customer Service Centre #B1-01
Tel: 6336 7288 Fax: 6336 2522
Website: www.axa.com.sg
GST Registration Number: 199903512M



Original

Agent Code: **14235**

Policy No. (if any):

New Business

SmartDrive Quote Ref:

MOTOR COVER NOTE

No. **CN842399**

- The Motor Vehicle (Third Party Risk and Compensation) Act (Cap 169) - Republic of Singapore; or
- The Road Transport Act 1987 of Malaysia; or
- The Agreement between the Minister of Finance (Singapore) and the Motor Insurers' Bureau of Singapore dated 22 February 1975; or
- The Agreement between the Minister for Transport (Malaysia) and the Motor Insurers' Bureau of West Malaysia dated 30 March 1992;
- And any subsequent revisions to the above Acts and Agreements

The Insured mentioned in the Schedule, having proposed for insurance in respect of the Motor Vehicle described in the Schedule, is hereby **HELD COVERED** under the terms of the Company's usual form of Motor Policy applicable thereto for the period mentioned in the Schedule unless the cover be terminated by the Company by notice in writing in which case the insurance will thereupon cease and a proportionate part of the annual premium otherwise payable for such insurance will be charged for the time the Company has been on risk.

SCHEDULE

THE COMPANY	AXA INSURANCE PTE LTD
INSURED	MELVIN LEE YEN HAU
MAKE AND DESCRIPTION OF VEHICLE	BMW 216D ACTIVE TOURER
VEHICLE REGISTRATION NO.	SLS 6699C
YEAR OF MANUFACTURE	2017
ENGINE NO.	34979987B37C15A
CHASSIS NO.	WBA2B32000V925962
ENGINE CAPACITY/TONNAGE	1496
COVER TYPE	COMPREHENSIVE
HIRE PURCHASE	DBS BANK LTD
VALUE (S\$)	AS PER MARKET VALUE
PERIOD OF INSURANCE	FROM: 31/07/2017 TO: 30/07/2019
EXCESS (S\$)	700
AXA PREMIUM WORKSHOP?	NO



I/WE HEREBY CERTIFY THAT POLICY TO WHICH THIS CERTIFICATE RELATES IS ISSUED IN ACCORDANCE WITH THE PROVISIONS OF THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) ACT (CHAPTER 169) AND PART IV OF THE ROAD TRANSPORT ACT 1987 (MALAYSIA).



AXA INSURANCE PTE LTD

Issued by **SIME DARBY SINGAPORE LIMITED** on **31/07/2017 8:52am**

[Signature]

Authorised Signature

Note : This Cover Note is only valid for 60 days from the date of issue unless replaced by the Certificate of Insurance issued by the Company.

- Premium for time on risk will be charged subject to minimum of S\$53.50 (inclusive of GST), if the policy is cancelled after the inception date.
- An administrative fee of S\$26.75 (inclusive of GST) will be charged:
 - Cover note issued and cancelled before inception.
 - Retaining the old registration number for a new vehicle insuring with AXA.

PREMIUM WARRANTY

For Individual Customers:

Please note that the premium in full should be paid before inception date (unless above is made for the insurance cover to be valid).

For Motor Vehicle Customers:

Please note that where the period of cover is for more than 60 days, the premium in full should be paid within 60 days of inception (original + subsequent renewals). For all other cases, the premium in full should be paid before inception.

MTR/CNOTEV01/03

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S8375881C



Name

MELVIN LEE YEN HAU

李彦豪

Race

CHINESE

Date of birth

04-04-1983

Sex

M

Country of birth

MALAYSIA

S8375881C

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number: S8375881C

Name

MELVIN LEE YEN HAU

Birth Date: 04 Apr 1983

Issue Date: 09 Jul 2014



002222293C



NRIC No: S8375881C



Nationality

MALAYSIAN

Date of issue

01-12-2006

79 ANCHORVALE CRESCENT #14-20
SINGAPORE 544624

NRIC No: S8375881C

Date: 25/03/2018

8818307

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSIE

EFFECTIVE DATE

Class 3 Motor Cars \leq 3000kg with \leq 7 passengers, exclusive of the driver; and other motor vehicles \leq 2500kg 09 Jul 2014



Licence No: S8375881C

NP 428A



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC3/AIG18012783/wb3

18 July 2018

Kinetic Holdings Pte Ltd

9 Tagore Lane

#03-21

Singapore 787472

Dear Sir/Madam,

ACCIDENT INVOLVING SLK 1783S AND SJZ 8887A ON 08/07/2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd. to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Vivian Lau
Case Handler

DID: 6841 8625

FAX: 6741 4108

EMAIL: Vivianlau@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

AUTHORISATION TO ACT
(AIG Express Third Party Claim)

I, Melvin Lee Yau Hau (the third party claimant) of 472 Pasir
Ris Drive 6406-462 (510472) (address), owner of SLS 6699C (vehicle no.)
hereby authorize Performance Motors Ltd ("the workshop") to act for me
with respect to my claim for repair costs and/or rental and/or loss of use ("claim") for my vehicle
no. SLS 6699C that was damaged pursuant to the accident which occurred on 30.6.2018
(date) along BRIDGE AVE (location) involving vehicle no/s
SH3274X ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit
and the workshop is further authorized to receive payment further to settlement of my claim with
payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without
prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other
vehicle/s is concerned.

Dated this 24 (day) of July (month) 2018 (year)



Signed by "the third party claimant"
(with chop if applicable)



Signed by "the workshop"
(with chop)
Ingrid A. Thurensamy
303 Alexandra Road
Performance Centre
Singapore 159041

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, **PERFORMANCE MOTORS LIMITED** ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd **LKK AUTO CONSULTANTS PTE LTD** (name of surveyor) with respect to the amount claimed for **S\$10,468.77** (Repair Cost), **S\$524.30** (Loss of Use/Rental), **S\$77.60** (Disbursement) for vehicle no. **SLS 6699C** that was damaged pursuant to the accident which occurred on **30/06/2018** (date) along **BAYFRONT AVE** (location) involving vehicle no/s **SJH 3274X**.

This is pursuant to the inspection conducted on **18/07/2018** (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner **MELVIN LEE YEN HAU** ("the third party claimant") of vehicle no. **SLS 6699C** make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to **SLS 6699C** (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 17 (day) of 04 (month) **2019** (year)



MTH

Signed by appointed surveyor

PERFORMANCE MOTORS LIMITED

303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941
TEL: 63190100 (Sales)
63408111 (Parts/Service)

Signed by "the workshop" (with chop)



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747775

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190828 (AfterSales)
63190833/538 (Motorrad)
Fax. 64796601 (AfterSales)
64796824 (Motorrad)

SERVICE TAX INVOICE

Repair Order No. : B1 1284533

Date IN : 18/07/2018

Cust. Svc. Advisor: Inthiran A/L Thurasamy

Page No. : 1 of 2

Invoice Number : 2027254 / WSB

Invoice Date : 09/11/2018

Payment Terms : 30 Days From Invoice

Invoice By : Sharon Heng

- CUSTOMER INFORMATION -

Mr Melvin Lee Yen Hau
472 Pasir Ris Drive 6
#06-462

Singapore 510472

- INVOICE TO - 121

AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.
SLS6699C

CHASSIS NO.
V925962

REGN. DATE
31/07/2017

MODEL
216D CAT

MILEAGE
27913

- - - - LABOUR 1 - - - -

	NETT
To replace rear boot lid, rear bumper and attachments including to make good the tail end panel and knock out dented area caused by the accident. To remove and install body parts in order to carry out painting job.	2,550.00
To respray rear bumper and rear boot lid.	2,399.00
To check electrical wiring systems and lightings at the rear section for proper function.	150.00
To remove and install boot compartment carpet and garnish to facilitate repairs.	230.00
To transfer lock mechanism from old to new bootlid including conduct checks on new bootlid central locking system for proper function.	451.00
To carry out body cavity preservation.	100.00
To remove and install rear windscreen glass to facilitate the repair job.	574.00
To conduct water leak tests.	75.00
Sundries.	80.00
INS CLAIMS : ACCIDENT REPAIR. DIRECT SETTLEMENT.	0.00
DATE OF ACCIDENT : 30.6.2018. 3RD PARTY CAR : SJH3274X.	
YOUR REF NO : NIL.	
VEHICLE WAS SURVEYED BY MR TAUFIKH FROM LKK AUTO CONSULTANTS PTE LTD ON 18.7.2018. AUTHORISED REPAIR BY MS VIVIAN LAU FROM LKK ON 17.7.2018 VIA E-MAIL.	
PROPOSE CAR RENTAL = \$524.30. THE AMOUNT IS SUBJECTED TO INSURANCE COMPANY CONFIRMATION.	0.00
MEDICAL FEE = \$77.60.	0.00

Total Labour 1: 6,609.00

- - - - PARTS - - - -

	Qty	Retail Price	NETT
REAR BUMPER CARRIER	1	423.80	423.80
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	2	131.55	263.10
(DG/SL) GLASS PRIMER 30ML (VP206)	1	27.85	27.85
(DG) CLEANER R1 (100ML)	1	23.85	23.85

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401113W GST Reg. No. M2-0000001-x

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190086 (AfterSales)
Fax. 63449773

115, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64794601 (AfterSales)
64794624 (Motorrad)



SERVICE TAX INVOICE

Repair Order No. : B1 1284533	Page No. : 2 of 2
Date IN : 18/07/2018	Invoice Number : 2027254 / WSB
Cust. Svc. Advisor: Inthiran A/L Thurasamy	Invoice Date : 09/11/2018
	Payment Terms : 30 Days From Invoice
	Invoice By : Sharon Heng

PLAQUE 74MM	1	69.50	69.50
GROMMET	2	0.75	1.50
DECOUPING RING PDC TORQUE CONVERTER	4	5.05	20.20
BUMP STOP	10	3.25	32.50
REAR BUMPER PANEL PRIMED (PDC)	1	966.25	966.25
PLUG BLACK D=5MM	10	0.90	9.00
TRUNK LID	1	1,174.95	1,174.95
SUPPORT	1	45.30	45.30
RR BUMPER LH INNER SIDE GUIDE	1	58.55	58.55
RR BUMPER RH INNER SIDE GUIDE	1	58.55	58.55

Total Parts : 3,174.90

- - - - LABOUR 2 - - - -

NETT

0.00

Total Labour 2: 0.00

Labour Charges :	6,529.00	Total Labour & Parts Charges :	S\$ 9,783.90
Parts Charges :	3,174.90	Less Insurance Excess :	S\$ 0.00
Lubricant/Misc :	80.00	Invoice Total Amount Exclude GST :	S\$ 9,783.90
		GST @ 7% :	S\$ 684.87
		Invoice Total Amount Include GST :	S\$ 10,468.77

Computer generated invoice. No signature is required.

Amount Payable Include GST : S\$ 10,468.77

All amounts are in Singapore Dollars.

Work was carried out subject to the Company's Terms and Conditions of Service.

No complaints will be entertained unless reported within seven (7) days of the date of this invoice.

For credit purchases, interest @1% per month will be debited on overdue amounts.





TAX INVOICE

Invoice No. 55 - 511958

Page 1 of 1

MR MELVIN LEE YEN HAU

79 ANCHORVALE CRESCENT #14-20
544624 SINGAPORE

SIME DARBY SERVICES PTE LTD

Thrifty International Licensee

305 Alexandra Road, #03-01

Vantage Automotive Centre, Singapore 159942

p (65) 6447.3388 f (65) 6345.7247

Co. Reg. No. 197501065W GST Reg. No. M2-0021986-4

INVOICE DATE : 24-JUL 2018

R.A. No. 55004911 / Muhammad Lukman bin Mohamed Sidek

TITLE	: MR	KILOMETER OUT/IN	: 36945 / 37409
AUTHORIZED DRIVER	: MELVIN LEE YEN HAU	KILOMETER DRIVEN	: 464
NRIC/PASSPORT NO.	: S8375881C	PETROL LEVEL OUT/IN	: FULL / FULL
MAKE & MODEL	: MAZDA 3 1.5	DATE & TIME OUT	: 18-JUL 2018 09:00
CAR REGISTRATION NO.	: SLF6340E / UNIT #: 0002784	DATE & TIME IN	: 24-JUL 2018 11:27
CAR GROUP GIVEN	: G	CHECK IN LOCATION	: SHORT TERM-HQ (SIN55)-THRIFTY
CAR GROUP CHARGED	: F	NO. OF DAY(S) CHARGED	: 6 DAY(S) 3 HOUR(S)

DESCRIPTION	UNIT PRICE (SGD)	UNIT	AMOUNT BEFORE GST (SGD)	GST @ 7%	AMOUNT (SGD)
INSURANCE CLAIMS RATES 2017					
7 DAY(S) @ \$70.00 / DAY			490.00	34.30	524.30
SUB-TOTAL			490.00	34.30	524.30
REMARKS: BMW OWNER: SLS6699C \$100 / DAY 1.6CC PML CSA: INTHIRAN					
		TOTAL (SGD) :	490.00	34.30	524.30
* ITEMS NOT SUBJECT TO GST					
		MC XXXXXXXXXXXXX8531			-524.30
		BALANCE DUE			0.00

NOTE:

I/WE HEREBY AGREE TO THE TERMS AND CONDITIONS AND BE HELD LIABLE FOR ALL AMOUNT DUE UNDER THIS AGREEMENT; ALL TRAFFIC FINES INCLUDING ADMIN FEES INCURRED DURING PERIOD OF HIRE; ANY COSTS INCURRED BY SIME DARBY SERVICES PTE LTD FOR MY FAILURE TO REPORT ANY ACCIDENT WITHIN 24 HOURS. FINAL CHARGES IS SUBJECT TO FULL INSPECTION OF THE VEHICLE BY A COMPANY REPRESENTATIVE.

HIRER'S AND/OR ADDITIONAL DRIVER'S SIGNATURE

Printed on 24-Jul-2018 11:37

Entered by Benjamin Loo ZhiWei

**SIME DARBY SERVICES PTE LTD**

Thrifty International Licensee

305 Alexandra Road, #03-01

Vantage Automotive Centre, Singapore 159942

p (65) 6447.3388 f (65) 6345.7247

Co. Reg. No. 197501065W GST Reg. No. M2-0021985-4

TO BE PAID BY

PAYMENT MC - XXXXXXXXXX8531

HIRER'S DETAILS

TITLE : MR
 NAME : MELVIN LEE YEN HAU
 ADDRESS : 79 ANCHORVALE CRESCENT
 #14-20
 544624
 SINGAPORE

NRIC/PASSPORT NO : S8375881C ISSUE: 01/12/2008

ISSUED BY : SINGAPORE

LICENSE : S8375881C EXPIRY: 30/12/2999

ISSUED BY : SINGAPORE

NATIONALITY : D.O.B : 04/04/1983

FREQUENT FLYER NO.

LOCAL CONTACT : 9878 5041

HOTEL

COMPANY'S DETAILS

NAME

ADDRESS

IMPORTANT NOTICE

- Hirer is liable for all traffic fines including admin fees that are issued by Singapore or Malaysia authorities for a grace period of 12 months from the date of car return.
- A security deposit depending on the respective car group rented will be withheld on the Hirer's credit card.
- Any accident has to be reported within the next working day to Sime Darby Services Pte Ltd. In the event of failure to report, hirer shall be liable for any costs incurred by Sime Darby Services Pte Ltd or claims made by the other party.
- Smoking, durians and pets are not allowed in the vehicle. An additional 3 day's rental would be imposed if smoking and durian smell/pet's fur is detected upon car return.
- Hirer must inform Sime Darby Services Pte Ltd in advance for vehicle drop-off in Thrifty Malaysia renting location. A one-way rental fee and Malaysia surcharge are applicable as stated in our One Way Rental policy.
- Hirer is responsible for any missing items/car accessories or loss of keys will be charged accordingly.
- The excess do not cover i) Car accessories ii) Loss of key iii) Vandalism iv) Alcohol/intoxicants/drugs.
- Vehicles are prohibited to be driven into Thailand.
- Strictly no key-drop services allowed, security deposit will be forfeited.

The vehicle is rented subject to all terms and conditions on this page and on the reverse side whether printed or handwritten. Hirer represents that they have read, understand and agree with the conditions of the rental agreement. The hirer authorises all amounts due under the rental agreement to be charged to the hirer's credit card shown on this form.

x
 Hirer

x
 Additional Driver

ADDITIONAL DRIVERS:

RENTAL AGREEMENT NUMBER : 55004911
 RENTAL LOCATION : SHORT TERM-HQ (SIN55)-THRIFTY

CHECKOUT

UNIT # / REGN NO : 00002784 / SLF6340E
 MAKE & MODEL : MAZDA 3 1.5
 CAR GROUP GIVEN : G CHARGE: F
 KILOMETER OUT : 36,945
 PETROL LEVEL OUT : FULL
 DATE & TIME OUT : 18/07/2018 09:00
 DUE DATE & TIME IN : 26/07/2018 09:00
 CHECKIN LOCATION : SHORT TERM-HQ (SIN55)-THRIFTY

RENTAL RATES

AS: INSURANCE CLAIMS RATES 2017

DAILY @ S\$ 70.00

EXTRA DAY @ S\$ 70.00

EXTRA HOUR @ S\$ 14.00

TOTAL: S\$ 599.20**FOR RATES TO APPLY**

MINIMUM 24 HOURS
 CAR MUST BE RETURNED TO RENTING LOCATION
 ON THE DUE DATE

INSURANCE

BY INITIALS, THE HIRER

INCLUSIVE LDW

NON-WAIVERABLE DAMAGE EXCESS: S\$ 1,500.00 (SIN USE)

DECLINES PAI @ S\$ 5.00 PER DAY

DECLINES WSC @ S\$ 5.00 PER DAY

THIS CAR IS FOR SINGAPORE USE ONLY. THERE IS NO INSURANCE
 COVERAGE FOR USE OUTSIDE SINGAPORE

OTHER CHARGES

FUEL SERVICES @ S\$2.70 / LITRE

CASH & CHEQUE DEPOSIT**REMARKS**

BMW OWNER: SL58699C

\$100 / DAY 1.8CC

PML CSA: INTHIRAN

HI RESERVATION

RES ID# SD000004226

Muhammad Lukman bin Mohamed Sik

TACO#

REF SRC: INSCLAIMS

Printed on : 18-Jul-2018 8:53
 Entered by: Muhammad Lukman bin Mohamed

CENTRAL 24HR CLINIC (HOUGANG)
 BLOCK 681 HOUGANG AVE 8
 #01-831 SINGAPORE 530681

GST Reg No : 20-0206893-G

TAX INVOICE

TAN PUI KEAN
 472 PASIR RIS DRIVE 6
 #06-462
 S(510472)
 Patient : TAN PUI KEAN (S8373962B)

Invoice No. : 294103
 Our Reference : 213096
 Date : 02 Jul 2018

DESCRIPTION	QTY	FEE (S\$)
REPARIL-GEL N -40G	1.00 tube	14.00
NOROESIC	20.00 tabs	9.00
SPEDIFEN (NUROFEN) 400MG	12.00 tabs	9.60
KENHANCER PLASTER	2.00 pkts	12.00
CONSULTATION		28.00
Sub-Total		72.60
Add GST 7.0%		5.08
Rounding Adjustment		-0.08
Total Amount Payable		77.60
Receipt No. 686885 - CARD Payment Received		77.60
Outstanding Balance		0.00

This is a computer generated invoice which does not require a signature
 E. & O.E

For Health News and Updates : <http://news.centralclinic.com.sg>

24-Hour Clinics

SEBOK	200-113 Sebak Road #01-121 Sebak Road, Sebak	Tel: 6791 1122
SEKONG	200-113 Sebak Road #01-121 Sebak Road, Sebak	Tel: 6791 1122
SEKONG	200-113 Sebak Road #01-121 Sebak Road, Sebak	Tel: 6791 1122
SEKONG	200-113 Sebak Road #01-121 Sebak Road, Sebak	Tel: 6791 1122
SEKONG	200-113 Sebak Road #01-121 Sebak Road, Sebak	Tel: 6791 1122
SEKONG	200-113 Sebak Road #01-121 Sebak Road, Sebak	Tel: 6791 1122
SEKONG	200-113 Sebak Road #01-121 Sebak Road, Sebak	Tel: 6791 1122
SEKONG	200-113 Sebak Road #01-121 Sebak Road, Sebak	Tel: 6791 1122

CENTRAL 24HR CLINIC (HOUGANG)

BLOCK 681 HOUGANG AVE 8

#01-831 SINGAPORE 530681

Medical Certificate

Date : 02 Jul 2018

MC No. : 0000395437

This is to certify that :

Name : TAN PUI KEAN

NRIC : S8373962B

is Unfit for Duty for 3 days

from 02/07/2018 to 04/07/2018 inclusive.

Remarks : NECK STRAIN - FROM RTA ACCIDENT

LOCUM

For Health News and Updates : <http://news.centralclinic.com.sg>

24-Hour Clinics

**This certificate is not valid for absence from court or other judicial proceedings unless specifically stated.*

CLEMENTI	65 100 Clementi Ave 1 #01-100 Clementi Clinic	65 100 Clementi Ave 1 #01-100 Clementi Clinic
HOUGANG	65 100 Hougang Ave 8 #01-831 Central Clinic	65 100 Hougang Ave 8 #01-831 Central Clinic
JURONG WEST	65 100 Jurong West Street 61 #01-831 Jurong West Clinic	65 100 Jurong West Street 61 #01-831 Jurong West Clinic
PIONEER NORTH	65 100 Pioneer North Street 61 #01-831 Pioneer North Clinic	65 100 Pioneer North Street 61 #01-831 Pioneer North Clinic
RASER WIS	65 100 Raser Wis Street 61 #01-831 Raser Wis Clinic	65 100 Raser Wis Street 61 #01-831 Raser Wis Clinic
WOODLANDS	65 100 Woodlands Ave 5 #01-831 Woodlands Clinic	65 100 Woodlands Ave 5 #01-831 Woodlands Clinic
YISHUN	65 100 Yishun Ave 5 #01-831 Yishun Clinic	65 100 Yishun Ave 5 #01-831 Yishun Clinic

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Jul 2018 Edit Reg		18 Jul 2018 00:00 Edit Adj Rpt	S\$9,783.90 Edit Estimates	S\$9,783.90 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by adjuster]							
Insured:	Kinetic Holdings Pte Ltd , Co. Reg. No.: NA								
Main Claimant:	MELVIN LEE YEN HAU , ID: S8375881C								
Vehicle Reg. No.:	SLS6699C	Date of Loss:	30/06/2018 19:00 - :59 [11 Months From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 4384218973SG	Policy/Cover Note No.:	0999994563						
Vehicle Reg. No. (Insured):	SJH3274X	Policy No. (Claimant):							
		Excess:							
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha.Syed-Yusoff@aig.com								
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 24/07/2018]								
ASSOCIATED MAIL RECEIVED									
			View All	Compose Case Mail					
<ul style="list-style-type: none"> AIG_SG_EXPRESS (05/04/2019): Alert - Adj Mandate Approved (S\$11070.67) - SLS6699C - Claim Handler: Syed-Yusof... AIG_SG_EXPRESS (13/03/2019): Alert - Adj Mandate Revoked - SLS6699C - Claim Handler: Syed-Yusoff, Saliha 									
ALL ASSOCIATED TASKS									
			View All	Search Tasks					
			Create New Task	Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLS6699C (4384218973SG)
[SJH3274X]
TP
MELVIN LEE YEN HAU
Jun 30 2018 7:00PM
[Kinetic Holdings Pte Ltd]
Performance Motors Limited

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Letters/Correspondences															1 per page		<input checked="" type="checkbox"/>			
No	Finalized On		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print			
1	(Draft)		Third Party Express Settlement – Payment Breakdown												1		Edit			
Photos/Images															3 per page		<input checked="" type="checkbox"/>			
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print			
1	22/03/19 08:46		Odometer Reading												1		Load JPG <input checked="" type="checkbox"/>			
2	22/03/19 08:46		Chassis Number												1		Load JPG <input checked="" type="checkbox"/>			
3	22/03/19 08:46		General View												1		Load JPG <input checked="" type="checkbox"/>			
4	22/03/19 08:46		General View												1		Load JPG <input checked="" type="checkbox"/>			
5	22/03/19 08:46		General View												1		Load JPG <input checked="" type="checkbox"/>			
6	22/03/19 08:46		General View												1		Load JPG <input checked="" type="checkbox"/>			
7	22/03/19 08:46		General View												1		Load JPG <input checked="" type="checkbox"/>			
8	22/03/19 08:46		General View												1		Load JPG <input checked="" type="checkbox"/>			
9	22/03/19 08:46		General View												1		Load JPG <input checked="" type="checkbox"/>			
10	22/03/19 08:46		General View												1		Load JPG <input checked="" type="checkbox"/>			
11	22/03/19 08:46		General View												1		Load JPG <input checked="" type="checkbox"/>			
12	22/03/19 08:46		General View												1		Load JPG <input checked="" type="checkbox"/>			
13	22/03/19 08:46		General View												1		Load JPG <input checked="" type="checkbox"/>			
14	22/03/19 08:46		General View												1		Load JPG <input checked="" type="checkbox"/>			
15	22/03/19 08:46		General View												1		Load JPG <input checked="" type="checkbox"/>			
16	22/03/19 08:46		General View												1		Load JPG <input checked="" type="checkbox"/>			
17	22/03/19 08:46		General View												1		Load JPG <input checked="" type="checkbox"/>			
18	22/03/19 08:46		General View												1		Load JPG <input checked="" type="checkbox"/>			
19	22/03/19 08:46		General View												1		Load JPG <input checked="" type="checkbox"/>			
20	22/03/19 08:46		General View												1		Load JPG <input checked="" type="checkbox"/>			
21	22/03/19 08:46		General View												1		Load JPG <input checked="" type="checkbox"/>			
22	22/03/19 08:46		General View												1		Load JPG <input checked="" type="checkbox"/>			
23	22/03/19 08:46		General View												1		Load JPG <input checked="" type="checkbox"/>			
24	22/03/19 08:46		General View												1		Load JPG <input checked="" type="checkbox"/>			
25	22/03/19 08:46		General View												1		Load JPG <input checked="" type="checkbox"/>			
26	22/03/19 08:46		General View												1		Load JPG <input checked="" type="checkbox"/>			
27	22/03/19 08:46		General View												1		Load JPG <input checked="" type="checkbox"/>			
28	22/03/19 08:46		General View												1		Load JPG <input checked="" type="checkbox"/>			
29	22/03/19 08:46		General View												1		Load JPG <input checked="" type="checkbox"/>			
30	22/03/19 08:46		Reinspection Photo												1		Load JPG <input checked="" type="checkbox"/>			
31	22/03/19 08:46		Reinspection Photo												1		Load JPG <input checked="" type="checkbox"/>			
32	22/03/19 08:46		Reinspection Photo												1		Load JPG <input checked="" type="checkbox"/>			
33	22/03/19 08:46		Reinspection Photo												1		Load JPG <input checked="" type="checkbox"/>			
34	22/03/19 08:46		Reinspection Photo												1		Load JPG <input checked="" type="checkbox"/>			

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	22/03/19 08:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
36	22/03/19 08:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
37	22/03/19 08:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
38	22/03/19 08:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	22/03/19 08:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	22/03/19 08:46	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	13/07/18 16:42	TP ESTIMATE	 Load TIF	
2	13/07/18 16:42	TP GIA REPORT	 Load PDF	
3	23/07/18 09:15	TP ESTIMATE- MARKED	 Load PDF	
4	10/12/18 16:08	RENTAL RECEIPT	 Load PDF	
5	10/12/18 16:08	MEDICAL FEE	 Load PDF	
6	09/05/19 12:55	WORKSHOP INVOICE	 Load PDF	
7	09/05/19 12:55	AUTHORISATION TO ACT FORM	 Load PDF	
8	09/05/19 12:55	Release Voucher	 Load PDF	
9	09/05/19 12:55	LETTER TO OI	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	16/07/18 10:58	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SJH3274X (Insd veh)	Model:	BMW 216D 1.5 D ACTIVE
	SLS6699C (TP veh)		TOURER (F45) (A)
Date of Accident:	30/06/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	17,524.03
Final Repair Cost	:	\$	10,468.77
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	524.30 7 days
LTA / GIA Search Fee	:	\$	0.00
Others: Medical Fee	:	\$	77.60
	:	\$	
Final Settlement Sum	:	\$	11,070.67

Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)

A) For **Non GIA Registered Workshop**: Agreed Liability _____ (%)

B) For **GIA Registered Workshop**: BOLA Applicable: Yes/~~No~~—BOLA Scenario No: 27

BOLA Liability: _____ 100 _____ (%) Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Performance Motors Limited	:	\$ 11,070.67
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

09 May
2019

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co Reg No: 199807198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG18012783/T1EB3Q2

Date: 09/05/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No: 0999994563
Claimant Vehicle No : SLS6699C	Insured Vehicle No : SJH3274X
Date of Loss: 30/06/2018	Nature of Claim: TP Claim No: 4384218973SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLS6699C	Engine No:	34979987B37C15A
Make & Model:	BMW 216D, 1.5 D Active Tourer (F45) (A)	Chassis No:	WBA2B32000V925962
Reg. Date:	31/07/2017 (Man. Year: 2017)	Odometer:	27913 km
Colour:	Grey		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,953.60	3,254.90	1,698.70	34.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,424.00	6,529.00	4,895.00	42.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	16,377.60	9,783.90	6,593.70	40.26
+ GST 7.00/7.00% (S\$)	1,146.43	684.87	461.56	40.26
Nett Amount (S\$)	17,524.03	10,468.77	7,055.26	40.26
	+ Medical Costs (S\$)	77.60		
	+ Car Rental (7.0 x S\$70.00/day + 7.00% GST) (S\$)	524.30		
	Nett Liability (S\$)	11,070.67		

INSPECTION

Date of Assignment:	18/07/2018	
Date Inspected:	18/07/2018 Inspected At:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Singapore 159941
Estimated Period of Repair:	7.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*80.00 FS
2	1		*TRUNK LID	Bent	1,174.95 FS	*1,174.95 FS
3	1		*TAIL PANEL	Not Necessary	355.20 FS	*- FS
4	1		*REAR BUMPER PANEL PRIMED (PDC)	Deformed	966.25 FS	*966.25 FS
5	1		*RR BUMPER LH SIDE GUIDE	Not Necessary	47.85 FS	*- FS
6	1		*RR BUMPER RH SIDE GUIDE	Not Necessary	47.85 FS	*- FS
7	1		*REAR BUMPER CARRIER	Bent	423.80 FS	*423.80 FS
8	1		*SUPPORT	Necessary	45.30 FS	*45.30 FS
9	1		*RR BUMPER LH INNER SIDE GUIDE	Necessary	58.55 FS	*58.55 FS
10	1		*RR BUMPER RH INNER SIDE GUIDE	Necessary	58.55 FS	*58.55 FS
11	1		*SET MOUNTS PDC SENSOR REAR	Necessary	69.50 FS	*69.50 FS
12	2		*GROMMET	Necessary	1.50 FS	*1.50 FS
13	1		*PLAQUE 74MM	Not Necessary	69.50 FS	*- FS
14	1		*REAR FLAP TOWING EYE PRIMED	Not Necessary	41.80 FS	*- FS
15	4		*DECOUPLING RING PDC TORQUE CONVERTER	Necessary	20.20 FS	*20.20 FS
16	2		*PDC SENSOR MEDITERRANBLAU WC10	Not Necessary	761.30 FS	*- FS
17	19		*BLIND RIVET AVIBVLB	Not Necessary	10.45 FS	*- FS
18	5		*SCREWW (SF PLUS M5X15)	Not Necessary	2.75 FS	*- FS
19	1		*(DG/SL) BODY ADHESIVE K5B (195ML)	Not Necessary	281.55 FS	*- FS
20	1		*(DG) CLEANER R1 (100ML)	Necessary	23.85 FS	*23.85 FS
21	19		*PUNCH RIVET N4	Not Necessary	10.45 FS	*- FS
22	10		*BUMP STOP	Necessary	32.50 FS	*32.50 FS
23	10		*PLUG BLACK D=5MM	Necessary	9.00 FS	*9.00 FS
24	2		*(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	Necessary	263.10 FS	*263.10 FS
25	1		*(DG/SL) GLASS PRIMER 30ML (VP206)	Necessary	27.85 FS	*27.85 FS
Total Parts (\$\$)					4,953.60	3,254.90

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND INSTALL REAR WINDSCREEN GLASS TO FACILITATE REPAIRS	New	574.00	574.00
2	TO CONDUCT WATER LEAK TESTS	New	75.00	75.00
3	TO REPLACE REAR BUMPER ,TAILGATE ,TAIL PANEL AND ATTACHMENTS INCLUDING KNOCK OUT DENT AREA CAUSE BY ACCIDENT	New	5,950.00	2,550.00
4	PAINTING REAR BUMPER ,TAILGATE ,TAIL PANEL AND TRUNK FLOOR	New	3,197.00	2,399.00
5	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
6	TO REMOVE AND INSTALL BOOT COMPARTMENT CARPET AND GARNISH TO FACILITATE REPAIRS	New	271.00	230.00
7	TO TRANSFER LOCK MECHANISM FROM OLD TO NEW BOOTLID INCLUDING CONDUCT CHECKS ON NEW BOOTLID CENTRAL LOCKING SYSTEM FOR PROPER FUNCTION	New	531.00	451.00
8	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL)	New	118.00	100.00
9	TO CARRY OUT BODY CAVITY PRESERVATION (FOR CUT PANEL)	New	531.00	0.00
Gross Labour Cost (S\$)			11,424.00	6,529.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >