

SOON SAN MOTOR TRADING

Bik.3006,UBI ROAD 1,#01-390,SINGAPORE 408700,TEL:68414445 & FAX:67473546

To: Motor Claims Dept
 AIG ASIA PACIFIC PTE LTD
 78, Shenton way #09-16
 AIG Building
 Singapore 079120
 Accident date:06/07/18
 Date;09/07/18

*4 Days .
 lumpsum repair .
 After repair photos .
 Guo Qiang - 82880282
 10/7/18 .*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- PAI prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and subject to prior approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Estimate cost to repair vel: SJY 1288E (Mit Lancer) claims under vel:SLW1312E.

2pcs tail lamps@\$320	<i>4 - UA, RH X NN</i>	\$ 640.00	
1pce rear bumper	<i>- R</i>	815.00	
1pce rear bumper reflector	<i>- CRA</i>	135.00	
2pcs rear bumper side holders@\$18	<i>- LMC</i>	36.00	
10pcs rear bumper inner clips@\$5	<i>-</i>	50.00	
1set rear bumper reverse sensor	<i>R / DM</i>	450.00	<i>200 (SN)</i>
1pce rear reverse camera	<i>R - DM</i>	300.00	<i>200 (SN)</i>
1pce rear bumper reinforcement	<i>X NN</i>	210.00	
2pcs rear bumper inner brackets@\$65	<i>- BT</i>	130.00	<i>?</i>
1pce rear panel	<i>X repair</i>	506.00	
1pce rear panel lower lock cover	<i>R / R</i>	149.00	
1pce rear exhaust pipe	<i>X NN</i>	680.00	
		\$3,981.00	
Less 10%		398.10	
		\$3,582.90	
1pce rear number plate with cover	<i>- Mis</i>	100.00	<i>40</i>
To check wiring		50.00	<i>30</i>
To dismantle/renew reverse sensor		100.00	<i>30</i>
To dismantle/renew reverse camera		100.00	<i>30</i>
To remove/refit rear interior to effect repair		100.00	<i>60</i>
To dismantle/renew rear exhaust pipe		100.00	<i>X NN</i>
To dismantle/renew accident portion		1,000.00	<i>R Sao</i>
To spray paint		1,000.00	<i>600</i>
	Total;	\$6,132.90	
2pcs number plate lamp @845	<i>- CRA</i>	90.00	