

ASS. REC. BY: Rasul REF: CS/SMO18012786 / R1sd3n2 Special Instruction:

Surveyor: Grace Teo ASSIGNMENT (Office)

From (Person): Grace Teo of SMO Date/Time: 13/7/18 @ 4:36pm

Estimated Cost: _____ Bill to: _____

OD TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHB 695P Insured: GBF 6288S

at Workshop n/s: SMRT Tel: 6866 2672

of 60 woodlands Ind. park E4

Policy No: _____ Claim No: CMTD1802994 / THE

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A: 11/07/2018

(Client's Record) _____ H.O.D. Endorsement: 16/07/2018

CA / REV / REP. / REV 24 HRS ^{kup} Date/Time: 13/7/18 @ 4:37pm Person Contacted: shunji Vehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate
	SHB 695P - NS/INC18000199 / Svbe 2 GBF 6288S - X DOA: 28/12/2017
17/07/18	@ 16:26 p.m. revised PA to Grace via email.
	(\$ 3,215.29 Ret - 86%)

08/11/13 wef
ASS. REC. BY: *[Signature]*

REF: SMO

ASSIGNMENT

From: _____ Date: 16/07/18
Estimated Cost: _____
OD: WS / TP RES / OD RES / EVA / INV / MV
To inspect Vehicle No: SHB 695 P
at Workshop m/s: SMRT
of: 60 Woodlands Ind. Park E4
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

Veh No: SHB 695 P Yr Regn: 2014 / July
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____
Make: TOYOTA PRIUS c.c. 1798
Colour: MAROON A/C: Insured / Std / NI / NA
Sp. Reading: 455206 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: STDKN36 U805 747693
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or _____
Brake: In order / Jammed / Leaked / Burnt or _____
Modi: Nil / S/Rim / STD A/Rim or _____
Tyre Size: F: 195/65R15
R: _____

(Policy Condition)
Remark: The veh had commenced its repair at the time of inspection.
Bal. or Market Value: _____
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Sean: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS Wp
Date: _____ Person Contacted: _____ Vehicle: IN / OUT

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Falken
Front _____ Rear _____
R/Bal. 5 mm R/Bal. 5 mm
L/Bal. 5 mm L/Bal. 5 mm
D.O.A. 11/07/18 D.O.I. 16/07/18
Survey held at SMRT
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
O/S FR
The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>07/18/2018</u>
	<u>Sampu</u>
	<u>GRF 62885</u>
	RECEIVED 20 JUL 2018

Date/Time, File Pass to? 21/07/18
1) Zp'st
Date/Time, File Return to? _____
2) _____

Days Of Repair: 3
Resurvey No. of Trip: 1

Add Fee: Site Insp (\$ _____)
 Interview (\$ _____)
 Tech. Invs (\$ _____)
 Weekend (\$ _____)

Survey Fee:	
Transportation:	
\$ + RS \$ _____	
Photos	
Others	
250	
TOTAL	

Report Format :
Lump Sum / I.B.I: (\$ 500.00 L/S)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
SOMPO INSURANCE SINGAPORE PL		Ref : CS/SMO18012786/R1sd3	
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623		Date : 13-07-2018	
		Code : SMO	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBF 6288S	Veh. Inspected	SHB 695P
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1802994/THE	Excess (\$)	0.00
Assign From	MERIMEN (GRACE TEO)	Assign Date	13/07/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Waxes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
Front Tyre			mm
Front Tyre			mm
Rear Tyre			mm
Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	11/07/2018	Inspection Date	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		
5a. Remarks			
THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: CMTD1802994/THE

Date: 17 July 2018

Our Ref: CS/SMO18012786/R1sd3

The Motor Claims Department
Tenet Sampo Insurance Pte Ltd

Without Prejudice

Dear Sirs/Mdm


PRELIMINARY ADVICE OF VEHICLE NO. SHB 695P .

Please be informed that we had conducted the inspection of the above mentioned vehicle on 16-07-2018 at the premises of M/s SMRT Automotive Service Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$ <u>3,715.29</u> .
Revised Estimate Amount (Labour)	: S\$ <u>518.92</u> .
"Check" Items Amount	: S\$ <u>-</u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:

The vehicle sustained damages at the o/s front portion.



Comments/ Present Status:

Damages Consistent.
Repair days: 3 Days

Yours faithfully,
Mohammed Rasul
Automotive Assessor

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Thursday, 26 July 2018 1:15 PM
To: 'Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)'; 'Rasul (LKKAuto)'
Cc: 'SUR'; 'CS A Team'
Subject: RE: SHB695P

Dear Poh Suan,

Confirmed final fig of \$500 @ 3 working days under lump sum repair .

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25
| S(408933)

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) [mailto:YeoPohsuan@smrt.com.sg]
Sent: Tuesday, 24 July 2018 5:31 PM
To: Rasul (LKKAuto) <Rasul@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; CS A Team <cs-a@lkkauto.com>
Subject: SHB695P

Hi Rasul,

Attached herewith the repair estimate of SHB 695P having Case No:
TAX/07/18/2045.

There is no change to the approved amount of \$500 @ 3 working days under lump sum repair.

Cost of Repair invoice will be generated as approved.

Please finalize with me within 7 working day, thanks.

Thanks & Regards

Poh Suan

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)
Sent: Tuesday, 24 July 2018 5:17 PM
To: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)
Subject: Scan Data from FX-D421D6

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Tuesday, 17 July 2018 4:26 PM
To: 'Teo, Grace'
Cc: 'Choo, Thelma'; 'Ye, Yong Kang Melvin'; sur@lkkauto.com; 'Nivitha (LKK Auto)'; 'assignments'
Subject: RE: CMTD1802994/THE - SUV(LKK)/ GBF6288S & SHB695P ACC ON 11.07.18
Attachments: SHB 695P - Preli Advise.pdf

Dear Grace,

Enclosed preliminary revised for SHB 695P.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Nivitha (LKK Auto) [mailto:admin-d@lkkauto.com]
Sent: Friday, 13 July 2018 4:40 PM
To: 'Teo, Grace' <grace.teo@sompo.com.sg>; 'assignments' <assignments@lkkauto.com>
Cc: 'Choo, Thelma' <thelma.choo@sompo.com.sg>; 'Ye, Yong Kang Melvin' <melvin.ye@sompo.com.sg>; sur@lkkauto.com
Subject: RE: CMTD1802994/THE - SUV(LKK)/ GBF6288S & SHB695P ACC ON 11.07.18

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Teo, Grace [mailto:grace.teo@sompo.com.sg]
Sent: Friday, 13 July 2018 4:36 PM
To: Shanti B Thaiyal Nayagi (Auto Svcs/Ext Biz Svcs/Claims & IA/Taxis/Claims) <BThaiyalN@smrt.com.sg>; admin-d@lkkauto.com; assignments@lkkauto.com
Cc: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) <YeoPohsuan@smrt.com.sg>; Kok Tuck Foo (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) <TuckFoo@smrt.com.sg>; Koo Yew Chung (Auto Svcs/Ext Biz Svcs/AR & SC) <YewChung@smrt.com.sg>; Phua Zhi Yang (Auto Svcs/Ext Biz Svcs/AR & SC/ARC/AR) <ZhiYang.Phua@smrt.com.sg>; Grace Ng Siu Ching (Auto Svcs/Ext Biz Svcs/AR & SC/ARC/AR) <ngsiuching@smrt.com.sg>; Lim Kha Chiew (Auto Svcs/Ext Biz Svcs/AR & SC/ARC/AR) <limkhachiew@smrtlan.com.sg>; Lim Wei Siong (Auto Svcs/Ext Biz Svcs/Claims & IA/Taxis/Claims) <weisiong@smrt.com.sg>; Choo, Thelma <thelma.choo@sompo.com.sg>; Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>
Subject: CMTD1802994/THE - SUV(LKK)/ GBF6288S & SHB695P ACC ON 11.07.18

Nivitha (LKK Auto)

From: Teo, Grace <grace.teo@sompo.com.sg>
Sent: Friday, 13 July 2018 4:36 PM
To: Shanti B Thaiyal Nayagi (Auto Svcs/Ext Biz Svcs/Claims & IA/Taxis/Claims); admin-d@lkkauto.com; assignments@lkkauto.com
Cc: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC); Kok Tuck Foo (Auto Svcs/Ext Biz Svcs/AR & SC/ARC); Koo Yew Chung (Auto Svcs/Ext Biz Svcs/AR & SC); Phua Zhi Yang (Auto Svcs/Ext Biz Svcs/AR & SC/ARC/AR); Grace Ng Siu Ching (Auto Svcs/Ext Biz Svcs/AR & SC/ARC/AR); Lim Kha Chiew (Auto Svcs/Ext Biz Svcs/AR & SC/ARC/AR); Lim Wei Siong (Auto Svcs/Ext Biz Svcs/Claims & IA/Taxis/Claims); Choo, Thelma; Ye, Yong Kang Melvin
Subject: CMTD1802994/THE - SUV(LKK)/ GBF6288S & SHB695P ACC ON 11.07.18
Attachments: 2045 - 695.pdf; SHB695P.PDF

Our Reference : CMTD1802994/THE
Your Reference: SHB695P

Hi Shanti,

We acknowledged receipt of your claim documents.

Please be informed that Thelma Choo is the handler of this case.

Please be informed that we have appointed **LKK AUTO** to conduct the survey.

Aside to **LKK AUTO**,

Please make arrangement to conduct the survey for SHB695P.

Please be informed that Thelma Choo the handler of this case.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @



or



Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Shanti B Thaiyal Nayagi (Auto Svcs/Ext Biz Svcs/Claims & IA/Taxis/Claims) [mailto:BThaiyalN@smrt.com.sg]

Sent: Friday, July 13, 2018 2:57 PM

To: 'motorsurvey@sompo.com.sg'

Cc: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC); Kok Tuck Foo (Auto Svcs/Ext Biz Svcs/AR & SC/ARC); Koo Yew Chung (Auto Svcs/Ext Biz Svcs/AR & SC); Phua Zhi Yang (Auto Svcs/Ext Biz Svcs/AR & SC/ARC/AR); Grace Ng Siu Ching (Auto Svcs/Ext Biz Svcs/AR & SC/ARC/AR); Lim Kha Chiew (Auto Svcs/Ext Biz Svcs/AR & SC/ARC/AR); Lim Wei Siong (Auto Svcs/Ext Biz Svcs/Claims & IA/Taxis/Claims)

Subject: RE: SHB695P - Sompo Insurance

Dear Sir /Mdm

Kindly arrange to survey the vehicle **SHB695P** within 48 hours according to GIA guide line, involving your insured **GBF6288S**

Vehicle in Woodlands Depot

Regards

Shanti

SMRT Automotive Services PTE LTD

Accident Reporting Center (Claims Dept)

6866 2671/2 | bthaiyaln@smrt.com.sg



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	12/07/2018 13:17
Date Of Accident	11/07/2018 17:40
Exact Location Of Accident	CTE TOWARDS SLE (AFTER MERCHANT ROAD EXIT)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB695P
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18090213MFSH
Cover Note Number	

Driver

Name of Driver	JAMILAH BINTE JAAFAR
NRIC No	S7413224C
Date Of Birth	25/04/1974
Occupation	OUTDOOR
Date Of Driving Pass	19/11/1999
Driving Experience	18 YEARS AND 7 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	12
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : UNKNOWN GENDER: : MALE
Passenger 2	NAME: : UNKNOWN GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	BEDOK NEIGHBOURHOOD POLICE POST
Police Station Address	ROAD: BLK 15 BEDOK SOUTH ROAD #01-117 , POSTCODE: 460015 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-2419999 - FAX NO: 64431687
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT - T/20180711/2122 On the 11/07/2018 at about 1740hrs, I was travelling in my SMRT SHB695P along CTE towards SLE after the Merchant Rd exit. I was travelling on the left most lane of a three lane road when I suddenly felt an impact on the right front portion of my vehicle. From my view, I noticed that the rear portion of another vehicle, a white Toyota Lorry (GBF6288S) had collided with my vehicle. I then high beamed the vehicle to signal him to stop however he continued driving and eventually drove away. The driver looked to be in his 50s or 60s. At that point in time, I had 2 passengers on my vehicle (one seated at the front passenger seat, the other seated at the rear left passenger seat). One of my passenger managed to take a photo of the lorry. On the lorry, there seemed to have a company name which goes by 'Goh Nam Heng'. I did not feel any pains after the collision occurred and none of my passengers complained of any pains. I then continued driving and alighted my passengers at Lorong 6 Geylang. After they alighted, I made a check on my vehicle and noticed some scratches on the front right portion, near the wheels. I wish to state that I do have a front facing in-vehicle camera and that it was functioning properly when my vehicle got hit by the white lorry. I am lodging this report as required by SMRT Corporation Ltd.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE TOO LARGE
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBF6288S
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20180711/2122

Police Station Of Origin:
Bedok NPP
15 Bedok South Road #01-117 SINGAPORE
460015
Tel No: 1800-2419999

1 of 4

Report No. T/20180711/2122

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 11/07/2018 19:01		Vide Report No.:	Station Diary No.: 23
Informant's Particulars			
Name of Informant: JAMILAH BINTE JAAFAR		Address: APT BLK 12 YORK HILL #09-78 SINGAPORE 163012	
ID Type / ID No.: NRIC NO / S7413224C		Contact No.: Home/Office: Mobile: 98469653	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Female	Age: 44	Date of Birth: 25/04/1974	Type of Informant: Driver
Race: Malay		Language: English	Institution / School Name:
Occupation: Taxi driver		Driving Licence Information: Class: 3	Date of Expiry:

General Information of the Accident				
Type of Accident: Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 11/07/2018 17:40	Type of Location: Straight Road	
Location: Along Road 1 Traveling Toward Road 2 CENTRAL EXPRESSWAY SELETAR EXPRESSWAY AFTER MERCHANT ROAD EXIT				
Weather: Clear	Road Surface: Dry	Road Speed Limit:		
Traffic Flow: One Way	Traffic Control: Not Controlled	Traffic Volume: Moderate		
Type of Collision: Between Moving Vehicles - Side Swipe - Same Direction			Anyone conveyed by ambulance: No	

Details of Vehicle Involved						
Vehicle No	Type	Make	Model	Color	Condition	No of Passenger
GBF6288S	Lorry	TOYOTA		White	Slightly Damaged	0
SHB695P	Car	TOYOTA	PRIUS	Maroon	Slightly Damaged	2

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20180711/2122

Police Station Of Origin:
Bedok NPP
15 Bedok South Road #01-117 SINGAPORE
460015
Tel No: 1800-2419999

2 of 4

Report No. T/20180711/2122

CONTINUATION OF REPORT

Name	Unknown		ID No.	NIL
Related Vehicle	GBF6288S (Lorry)		Contact No.	NIL
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL
Driver:				
Name	JAMILAH BINTE JAAFAR		ID No.	S7413224C
Related Vehicle	SHB695P (Car)		Contact No.	98469653
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL

Brief Details.

On the 11/07/2018 at about 1740hrs, I was travelling in my SMRT Toyota Prius cab (SHB695P) along Central Expressway (CTE) towards Seletar Expressway (SLE) after the Merchant Rd exit. I was travelling on the left-most lane of a three lane road when I suddenly felt an impact on the right front portion of my vehicle.

From my view, I noticed that the rear portion of another vehicle, a white Toyota lorry (GBF6288S) had collided with my vehicle. I then high beamed the vehicle to signal him to stop however he continued driving and eventually drove away. The driver looked to be in his 50s or 60s.

At that point in time, I had 2 passengers in my vehicle (one seated at the front passenger seat, the other seated at the rear left passenger seat). One of my passenger managed to take a photo of the lorry. On the lorry, there seemed to have a company name which goes by 'Goh Nam Heng'. I did not feel any pains after the collision occurred and none of my passengers complained of any pains.

I then continued driving and alighted my passengers at Lorong 6 Geylang. After they alighted, I made a check on my vehicle and noticed some scratches on the front right portion, near the wheels.

I wish to state that I do have a front-facing in-vehicle camera and that it was functioning properly when my vehicle got hit by the white lorry.

I am lodging this report as required by SMRT Corporation Ltd.



**SINGAPORE
POLICE FORCE**



T/20180711/2122

Police Station Of Origin:
Bedok NPP
15 Bedok South Road #01-117 SINGAPORE
460015
Tel No: 1800-2419999

3 of 4

Report No. T/20180711/2122

CONTINUATION OF REPORT



**SINGAPORE
POLICE FORCE**



T/20180711/2122

Police Station Of Origin:
Bedok NPP
15 Bedok South Road #01-117 SINGAPORE
460015
Tel No: 1800-2419999

4 of 4


Report No. T/20180711/2122

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: G / Sgt 2 MUHAMMAD NURUL'OMARALI BIN SUPRAT	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 11/07/2018 19:01
Officer In Charge Of Case: TP / HRT / Sr Staff Sgt ESTHER CHONG Contact No. 65476368 SINGAPORE POLICE FORCE	Classification Of Case:
Authentication Stamp NP168  SIGNATURE	

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB695P
Ref. No : TAX/07/18/2045
Reg. Date : 20/08/2014
Vehicle Type : TAXI
Make : TOYOTA PRIUS
Model : PRIUS
Name of Driver : JAMILAH BINTE JAAFAR
Type of Accident : SIDE SWIPE
Date / Time of Accident : 11/07/2018 05:40:00 PM
Accident Reported Date / Time : 12/07/2018 12:00:00 AM
Surveyor is Required? : Yes
Survey by :
Vehicle is Towed Back? : No
Towed Back Date/Time :
Replacement Vehicle issued? : No
Accident Repair Job Card No : 000024096974
Special Instruction to ARC, if any :
TOS /GBF6288S - SOMPO / *Resy after repair*
Prepared Date : 13/07/2018 11:22:57 AM



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U805747693

Mileage :


0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 507.00	0.00
Total Spray Painting Charges	: 558.00	0.00
Total Material Charges	: 2,190.29	2,190.29
Other Charges	: 460.00	0.00
TOTAL	: 3,715.29	0.00
Lum Sum Total	: 3,700.00	0.00
No. of Repair Days	: 4.00	0.00 <i>3 days - Luperon</i>
Prepared / Adjusted By	:	
Arc / Surveyor Sign Off Date	: 13/07/2018 01:37:16 PM	01/01/1900 12:00:00 AM



Ref 16/07/18 @ 1555
[Signature]
17/7/18

Prepared / Adjusted Date :

Remarks :

Prepared Date : 13/07/2018 01:37:16 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount :

Prepared Date :

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
53801-47050		6505557	FENDER FRT/RH	1	723.40	25.00	542.55	Replace	Replace <i>Repair</i>	No
75374-47051			NAME PLATE (HYBRID)	1	51.90	25.00	38.92	Replace	Replace <i>nu</i>	No
52115-47040		6505515	BUMPER SUPPORT F/RH	1	76.40	25.00	57.30	Replace	Replace <i>X</i>	No <i>sw</i>
53875-47030		6505553	FENDER LINER FRT/RH	1	171.70	25.00	128.77	Replace	Replace <i>X</i>	No <i>sw</i>
879157-4010		6505598	COVER, OUTER MIRROR, RH	1	107.40	25.00	80.55	Replace	Replace <i>Repair</i>	No
81730-52090		6505466	MIRROR LAMP RH	1	65.30	10.00	58.77	Replace	Replace <i>X</i>	No <i>sw</i>
87910-47330		6505600	MIRROR ASSY, RH	1	1,307.10	25.00	980.32	Replace	Replace <i>X</i>	No <i>sw</i>
81130-47500		6505437	HEAD LAMP RH	1	945.20	10.00	850.68	Replace	Replace <i>X</i>	No <i>sw</i>
TOTAL MATERIALS							2,737.88	2,737.86		
TOTAL MATERIALS(Discounted)							2,190.29	2,190.29		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR RH FRONT PORTION	507.00	0.00 150 ✓
Total Labour	507.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT FENDER RH	378.00	0.00 200 ✓
TO RESPRAY VIEW MIRROR	180.00	0.00 70 ✓
Total Spray Painting & Panel Beating	558.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 40
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 20
TO REMOVE AND REFIX WING MIRROR	120.00	0.00 X 27
TO REPLACE SUNDRY PARTS	100.00	0.00 X 27
TO WASH AND VACUUM	60.00	0.00 X 27
Total Other Costs	460.00	0.00

19-7-18 / 12:33
 19-7-18 / 16:33

16-7-18 / 16:33


SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB695P
 Ref. No : TAX/07/18/2045
 Reg. Date : 20/08/2014
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS
 Name of Driver : JAMILAH BINTE JAAFAR
 Type of Accident : SIDE SWIPE
 Date / Time of Accident : 11/07/2018 05:40:00 PM
 Accident Reported Date / Time : 12/07/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by : Rasul
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024096974
 Special Instruction to ARC, if any :
 TOS /GBF6288S - SOMPO 4S
 Before paint photo, After repair photo FOR CHECK ITEM and REPLACE ITEM PLEASE CALL SURVEYOR RASUL / HP : 9001 0068. email: rasul@lkkauto.com
 LUMPSUM REPAIR
 Prepared Date : 13/07/2018 11:22:57 AM



QC 18/7/18 18,45 PTESS



Recording Camera
 Radio Antenna
 1st witness [Signature] Date 16.7.18
 2nd witness _____ Date _____

455274
 LEE SHENG AUTO PTE LTD
 Vehicle Return Date 18-7-2018
 Vehicle Return Time 10:35 am
 SMRT staff sign: _____

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U805747693

Mileage

0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 507.00	150.00
Total Spray Painting Charges	: 558.00	270.00
Total Material Charges	: 31.14	31.14
Other Charges	: 460.00	60.00
TOTAL	: 1,556.14	511.14
Lum Sum Total	: 1,550.00	500.00
No. of Repair Days	: 4.00	3.00
Prepared / Adjusted By	:	RASUL (LKK)
Arc / Surveyor Sing Off Date	: 13/07/2018 01:37:16 PM	16/07/2018 04:33:35 PM

M

LKK

Prepared / Adjusted Date :

Remarks :

Prepared Date : 13/07/2018 01:37:16 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : QN-1807-0505

Quotation Date : 22/7

Invoice Amount : 0.00

Invoice No :

Invoice Date :

Prepared Date : 7/16/2018 4:53:04 PM

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR RH FRONT PORTION	507.00 ✓	150.00 ✓
Total Labour	507.00	150.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT FENDER RH	378.00 ✓	200.00 ✓
TO RESPRAY VIEW MIRROR	180.00 ✓	70.00 ✓
Total Spray Painting & Panel Beating	558.00	270.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	40.00 ✓
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	20.00 ✓
TO REMOVE AND REFIX WING MIRROR	120.00	0.00
TO REPLACE SUNDRY PARTS	100.00	0.00
TO WASH AND VACUUM	60.00	0.00
Total Other Costs	460.00	60.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached	
53801-47050		6505557	FENDER FRT/RH	R 1	723.40	100.00	0.00	Replace	Repair	No	R
75374-47051			NAME PLATE (HYBRID)	V 1	51.90	25.00	38.92	Replace	Replace	No	✓
52115-47040		6505515	BUMPER SUPPORT F/RH	X 0	76.40	25.00	0.00	Replace	Not given	No	X
53875-47030		6505553	FENDER LINER FRT/RH	X 0	171.70	25.00	0.00	Replace	Not given	No	X
879157-4010		6505598	COVER, OUTER MIRROR, RH	R 1	107.40	100.00	0.00	Replace	Repair	No	R
81730-52090		6505466	MIRROR LAMP RH	X 0	65.30	10.00	0.00	Replace	Not given	No	X
87910-47330		6505600	MIRROR ASSY, RH	X 0	1,307.10	25.00	0.00	Replace	Not given	No	X
81130-47500		6505437	HEAD LAMP RH	X 0	945.20	10.00	0.00	Replace	Not given	No	X
TOTAL MATERIALS								38.93	38.92		
TOTAL MATERIALS(Discounted)								31.14	31.14		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

38.92
 - 20%
 31.14
 + 150.00
 + 330.00

 511.14
 LIS \$500/-

4973.40.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO18012786/R1sd3n2

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERSINGAPORE 048623

Date : 02-08-2018



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBF 6288S	Veh. Inspected	SHB 695P
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1802994/THE	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	13/07/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	JTDKN36U805747693	Colour	MAROON
Odometer	455206	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	FALKEN	5 mm
L/H Front Tyre	195/65 R15	FALKEN	5 mm
R/H Rear Tyre	195/65 R15	FALKEN	5 mm
L/H Rear Tyre	195/65 R15	FALKEN	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	11/07/2018	Inspection Date	16/07/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 695P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	NAME PLATE (HYBRID)(DISC 25%)	NECESSARY	51.90	38.92
1	BUMPER SUPPORT F/RH	SERVICEABLE	76.40	-
1	FENDER LINER FRT/RH	SERVICEABLE	171.70	-
1	MIRROR LAMP RH	SERVICEABLE	65.30	-
1	MIRROR ASSY, RH	SERVICEABLE	1,307.10	-
1	HEAD LAMP RH	SERVICEABLE	945.20	-
1	FENDER FRT/RH	TO REPAIR SEE LABOUR	723.40	-
1	COVER, OUTER MIRROR, RH	TO REPAIR SEE LABOUR	107.40	-
			3,448.40	38.92
LABOUR				
	PANEL BEATING & BODY WORK. INCLUSIVE OF THE REPAIR OF FENDER FRT/RH AND COVER, OUTER MIRROR, RH.		507.00	150.00
	SPRAY PAINT.		558.00	270.00
	TO CHECK WIRING AND SYSTEM FUNCTION.		80.00	40.00
	TO APPLY RUST-PROOFING ON AFFECTED AREA.		100.00	20.00
	TO REMOVE AND REFIX WING MIRROR.	NOT NECESSARY	120.00	-
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
			1,525.00	480.00
GRAND TOTAL			4,973.40	518.92
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				500.00

Report Ref No. CS/SMO18012786/R1sd3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.