From (Person): Hwary Shiang Vi of CTT Detertime 16 [4] 18 69-060	
Establica Cost Bill to	am
To Inspect Vehicle No. SIN 1543B Insured: GBC 5069E at Workshop m/s ZOOM Autowerks Tel: 9450 7920 of BIK 15 Kaki Bukit Rd 4 # 01-53	
Policy No DMCVSN 3047 641700 Claim No: SNM & D03452C02 Sum Insured. Excess:	
Make of Veh:	
CA / REV / REP. / REV 24 HRS W H.O.D. Endorsement: Date/Time: 9:28am @ 16 7118 Person Contacted: Elin Vehicle IN (OUT)	
Date/Time Action/Instruction () Estimate	
Vehicle will be In by 3pm. Requirer currency after 3pm. SJN 1543B-NA LINC 18012799/24 Obt. 13107 118 GBC 5060E-NA LINC 18012799/24 POA: 13107 118	

(08/11/13) wef	REF:	C7,1		
ASS. REC. BY: March	6			= Unico
,	AS	SSIGNMENT	,	
From:	Date:	Veh No: STNISK	33 Yr Regn: 5 7	09
Estimated Cost:		Type: M.Carl M.Cycle / Bus / Van /		
OD TP WS TP RES OD RES EV	A/INV/MV	Truck / Trailer or (A)	/	
To Inspect Vehicle No:	STN 15433	Make: Hong Str	legen ac	700
at Workshop m/s	From Su	Colour Iour	A/C: Insured / Std / N	IINA
of	(0 4	Sp.Reading 176414	T/Radio: Insured / Std / I	NI/NA
Insured:		Eng/No:		,
Policy No.		C/No: JHMRN	688095 2007	18
Claims No.		Gen. Cond: Good / Fair / Poor / But	nt	/
Sum Insured:	Excess:	Steering: Lorder / Jammed / Leake	d/Burnt or	
(Client's Record)		Brake: Interes / Jammed / Leake	d/Burnt or	
Make of Veh:		Modi: Nil / 8/Rim / STD A/Rim	or	
	10 <u>0</u>	Tyre Size: F:		
(Policy Condition)		R: 21	5-/502217	
Remark: The veh had commenced its		S DUN / EXNOVA / GY / FS / LIZ	A /MIC / OHTSU / PIR / SUMI	1
repair at the time of inspect	ion.	TOYO / YOKO or	Chanp, N	15
Bal. or Market Value:	7	Front 6	Rear	7
IDAC Accident Rport: Con:	sistent? : Yes or No	R/Bal. mm	R/Bal.	mm
GIA / PR Seen: Cons	sistent?: Yes or No	L/Bal. 6 mm	L/Bal. 6	mm
Est. Repairs: days	Res.: Yes or No	D.O.A. /3/7/18	D.O.I. 16/7	1.f
Lum Sum: %	3 Val.: Yes or No	Survey held at		_
CA / REV / REP. / 24 HRS		Des. of Damages : Frt / Rear / O/S		
Date: Person Contact	Vehicle: IN / O			- X-1
Date / Time Action / Instruction		The U/C / Chassis frame / Bo	dy Structure affected due to c	collision.
6 mlh plus	27A14870	19-7-11		
1 /				
23/1/18 1/5 \$320) Confin	wh Elin		
(\$6,211.48	Red - 66%))		111100-00
	DECE	IVED 2 4 JUL 2016		
	KLOL	116021002		
	823 (0			
74/04/18 ===	. Report	Days Of Repair:		
Date/Time, File Return to?	Report	Resurvey No. of Trip: 2	Survey Fee:	
	Add F	ee: : Site Insp (\$	Transportation:	
2)	Add F	ee: Site Insp (\$)S+RS,SI	
Report Format :		: Tech. Invs (\$) Photos) Others	
Lump Sum / I.B.I: (\$ 3, 200.	m 1/e	: Weekend (\$	7 0963	
0,200.0	—	Treenone 17	TOTAL 23	0.0
			20	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	NA TAIPING INS	URANCE (S) PTE LTD	Ref : CS/CTI180128	20/Usd3	
	NSON ROAD #16 RINGLEAF TOWE	-00 RSINGAPORE 079909	Date: 16-07-2018 Code: CTI		
		Policy Particulars	:- THIRD PARTY CLA	IM	
	ir wed ven.	GBC 5069E	Veh. Inspected	SJN 1543B	
	lay tio.	DMCVSN3047641700	Coverage (\$)	0.00	
	C in No.	SNM18D03452C02	Excess (\$)	0.00	
	Assign From	MERIMEN (HWANG SHIANG YI)	Assign Date	16/07/2018	
		Vehicle Part	culars & Condition		
	dol		c.c	0	
	· 4	HIDDEN	Year of Reg.		
	sis No.		Colour		
		16 20	Steering		
			Modification		
3.		Condit	ions of Tyres		
		Size	Make	Balance	
	yre			mm	
	1 re			mm	
	. 0			mm	
	/10			mm	
	4	Descripti	on of Damages		
		Genera	I Information		
	· **e	13/07/2018	Inspection Date	16/07/2018	
	, lat	BLK 15 KAKI BUKIT RD 4 # 01	-53	Committee of the programme	
	¥	ZOOM AUTOWERKS PTE LTD			
ā,		R	emarks		
	1	ON WAS CONDUCTED ON A"WIT	HOUT PREJUDICE" BAS	IS.	
	· ·	ICE TO YOUR INSTRUCTIONS, W	E HAVE NOT AUTHORIS	ED REPAIRS.	

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBF	OLDER TRA	CKING								
Case	Votified	Est Submitted	Adj Assigned	Adj Rpt	Adt Sut	amitted	Ins Authled	Status		
Main	13 Jul 2018		16 Jul 2018 09:06 Assign				THE POULSE	New	Assignme el Case	nt
М	tain	Re	ference		Claim Details		Documen	ts	7	Show All
CLAIM SUB	FOLDER DE	TAILS	#156 or 15 and 15 and 1			The state of the s	THE RESERVE	1000000	-	Silon Fall
Insured:						Create	d by insurer]			
Main Claimant:	JP SERVI	СЕ ТЕАМ								
Vehicle Reg. No.:	SJN1543	3B			Date of Loss:	13/07/20	18 00:00 - :59			
Claim Type:	TP / SNM	118D03452C02			Policy/Cover Note No.: DMCVSN3047641700					
Vehicle Reg, No. (Insured):	GBC50698				Policy No. (Claimant):					
Repairer:	7000 804		2424		Excess:	S\$0.00				
Handling Insurer:	China Talp	owerks Pte Ltd (ping Insurance (HQ) 15 Kaki Buk Singapore) Pte	it Road 4, #	01-53, 417808	Kaki Bukit	- Tel:		SARTING	
Adjuster:	LKK Auto	Consultante Pte	I to (MO) Tole		re: 0309 011	ı [manoi	led by Hwang Sh	iang Yi -	6389654	1]
Adj Asg. Remarks:	NO EST, AS	Consultants Pte SIGN MARCUS CH	UA AS SJE.	0256-3561,.	. [Final Rpt	due 25/0	7/2018]			
ASSOCIATE	D MAIL REG	CEIVED							1000	
There are no	mail for this	case.						lew All	Compose	Case Mail
ALL ASSOC	IATED TASE	KS⊟							V0.100-100-100-100	
Due Date	Priority	Type Task 0	iroup Subje	ort Drawer		View All	Search Tasks	Create N	ew Task	Complete
	ASSESSMENT OF THE PARTY OF THE	CONTRACTOR OF THE SECOND	a seals sample	ct Hand	er Assigne	ed By	Completed On	Cre	ated On	Done?

Lucas Lee

From:

Zoom Autowerks <zoomautowerks@gmail.com>

Sent:

Friday, 13 July, 2018 4:02 PM

To:

Claims Dept of CTI

Cc:

Lucas Lee

Subject:

Pre-Repair Inspection for SJN 1543 B // Accident on 13/07/2018 @ 08:30HR at along PIE(Changi) before Simei Avenue Exit involving Vehicle Number SJN 1543 B

& GBC 5069 F

Attachments:

New Doc 2018-07-13 (2).pdf

Dear Sir/Madam,

We are instructed by JP Service Team to notify you of a road traffic accident on 13/07/2018 at about 08:30HR at along PIE(Changi) before Simei Avenue involving our client's vehicle registration number SJN 1543 B and vehicle registration number GBC 5069 E driven by your insured at the material time.

A copy of the Singapore Accident Statement/Traffic Police Report filed is enclosed. As a result of the accident, out client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated time, our client shall proceed to repair the vehicle without further reference to you.

Please contact me @ 9450 7920, should you require more information.

Kindly arrange survey at Blk 15 Kaki Bukit Road 4, Bartley Biz Centre, #01-53, Singapore 417808.

Warmest Regards, Elin Cai

Zoom Autowerks Pte Ltd

130 Bedok Reservoir Road #08-1339 Singapore 470130 @9450 7920

12oomautowerks@gmail.com

Please note our change in mailing/registered address with effect from 1st July 2018 -

This email has been scanned by the Symantec Email Security.cloud service. For more information please visit http://www.symanteccloud.com

SGCARMART.COM

Login Sign up

New Cars -

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Submit (


Resources

DIRECT OWNER



CONNECTING CAR BUYERS & SELLERS. We'll handle your loans, insurance & other paperwork for FREE.



















Seller Information

Desmond
91070316
Contact Seller
» Sales agreement
» Hand-over form
now to complete a seller to end-
ng or selling, we'll handle ans & insurance for FREE.

Useful Services



Afraid of lemons? Request to have this car evaluated professionally.

Vehicle Evaluation



Find out the market value for your car. Get a free Car Valuation.

Free Valuation

\$6,450 (change)

Maximum 70% Loan

Down Payment

Compare

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	8667J
Vehicle Details	
Vehicle No.:	SJN1543B
Vehicle to be Exported:	No
ntended De-registration Date:	20 Jul 2018
Vehicle Make:	HONDA
Vehicle Model:	STREAM 1.8L SUNROOF ALLOY WHEEL
Primary Colour:	AT Grey
Manufacturing Year:	2008
Engine No.:	R18A13800779
Chassis No.:	JHMRN688095200769
Maximum Power Output:	103.0 kW (138 bhp)
Open Market Value:	\$28,722.00
Original Registration Date:	05 Feb 2009
First Registration Date:	05 Feb 2009
Transfer Count:	1
Actual ARF Paid:	\$28,722.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	04 Feb 2019
PARF Rebate Amount: Intended COE Rebate Details	\$14,361.00
COE Expiry Date:	04 Feb 2019
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$8,301.00
COE Rebate Amount:	\$449.00
Total Rebate Amount:	\$14,810.00

The information contained herein is correct as at 16 Jul 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

OR STATE	20	DEN	IT STA	T = 0	4ENT
m A	uu.	DEN	II SIA	ш-ц	

Date Of Report

13/07/2018 15:56

Date Of Accident

13/07/2018 08:30

Exact Location Of Accident

PIE (CHANGI) BEFORE SIMEI AVE EXIT

Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number

SJN1543B

Insured/Policyholder

Name Of Registered Owner

JP SERVICE TEAM

Co Reg No

53318667J

Email Address

NOEMAIL

Mobile Phone No

Alternative Phone No

OFFICE-89999999

Vehicle Particulars

Manufacturer

HONDA

Model

STREAM 1.8L SUNROOF ALLOY WHEEL AT

Exact Purpose for which vehicle was being used at

time of accident

WORKING

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

If No. Please state action to be taken

THIRD PARTY

Vehicle Category

PRIVATE HIRE

Insurance Company

Name of Insurance Company

NTUC INCOME INSURANCE CO-OPERATIVE LTD

Type Of Coverage

COMPREHENSIVE

Fleet Policy

NO

Policy Number

5096405921

Cover Note Number

Driver

Name of Driver LOW TECK HOE (LIU DEHE)

 NRIC No
 S7417377B

 Date Of Birth
 05/06/1974

 Occupation
 OUTDOOR

 Date Of Driving Pass
 08/12/1997

Driving Experience 20 YEARS AND 7 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-97999992

Fax Number

Contact Number OFFICE-97999992

EMail Address NOEMAIL

Address

BLK 328 HOUGANG AVENUE 5

#12-182

Postcode

530328

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OWNER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

SIDE SWIPE

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles involved in the accident

2

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

ambulance?

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

Passenger 1

NAME:

GENDER:

: MALE

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER TO STATEMENT.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

GBC5069E

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be an truthful and accurate as possible. Any widul misrepresentation or withholding of material. facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance. companies
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded for the insurers or the GIA Hezords Menagement Centre established by the General Insurance Association of Singapure (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8 Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agove and consent that:

- (a) My insurer, my workshop, and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or processing revisional data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal information to a course(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Sensacione and any relevant government agency/authority (such as the police), for the purposels)
 - (i) processing, handling and or dealing with my claims including the settlement of the claims and any necessary. investigations relating to the claims,
 - (ii) investigating the account and/or my darms.
 - (iii) carrying out would in the with my matructions or responding to any enquiries by me;
 - (iv) administering my Campunicluding the mailing of correspondence, statements, invoices, reports or notices to me, which could involve or counter of certain personal data about me to bring about delivery of the same as well as on the external cover of environmental packages); and/or
 - (v) complying with applicative law in administering, processing, handling and/or dealing with my claims [collectively the Purposes
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and or process my Personal Information for one or more of the above Purposes, and
- rey Personal Information intoly/care be disclosed by any of the insurers and/or GIA to their third party service providers or agents(including their live (at Lifux firms), which may be sized outside of Singapore, for one or more of the above Purposes.
- (d) my Personal information will also be collected and used to compile claims history for the purpose of fraud detection investigation and management in present and all future claims
- (e) the information to collect at under (d) above may be shared / disclosed
 - (i) to all insurers androwers, when their parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law serior, and or and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with repairments under any regulations, laws or court orders.

JP SERVICE TEA REG 533186871

> Policyhalder's Signaturs Date & Taren

Denier's Signatury (if dover is not the policyholder) Date & Town

Reporting Centre Port et's Signature NRXC/FIN No.

Accident Sketch Plan

SKETCH PLAN

VEHICLE A CONSUMB

PIE (CHONG), before comes bue test

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

	041	tine	stated	dant	T to	ne , I	16	hicle	X,	NTZ	15436	, was
aveling	alon	g tri	State	ed vi	21.18	L Slo	ulld	dov	M	and	lame	to
1 tombs	LYE !	Stop .	suclde	my. I	enu	6,60	6 51	hat,	14	ied	to ov	iviate
ir, and	Оус	ned	shitt.	ing vel	tille 's	isar	TV.	pat j	n/h	ou.		

DECLARATION

I/We declare the foregoing particles are true in every respect.

IP SERVICETEA

-

Oriver's Signature of driver is not the policyholder) Date & Time

Reporting Centre Personne & Signature Name NRIC/FIN No.



ZOOM AUTOWERKS PTE LTD

832 Sims Avenue, Eunosville #12-884 Singapore 400832 Tel: 9450 7920 * zoomautowerks@gmail.com

17 JULY 2018

REG NO. :

SJN 1543 B

MAKE/MODEL:

HONDA STREAM

ESTIMATED DEDAIL	COST FOR	THE VEHICLE	MENTIONED ABOVE
ESTIMATED REPAIR	t GOSI FOR	THE VEHICLE	MICHIONED ADOVE

QTY	DESCRIPTION	AMT(S\$)
	LIST ITEMS	.1 .
1	Rear taillamp -R/H	1/(\$)C/ 585.90 X
1	Rear bumper 65-4	Deus & Cu) 1,185.00
1	Rear bumper side retainer 23.60	(\$ 3cf 48.50
1	Rear fender -R/H	1/10 to 981.60
1	Rear fender air gate	/s 17 48.60 X
1	Rear fender inner trim board	\$ 1 628.50 \$
1	Rear fender quarter glass moulding 60	\$ M 182.60
1	Rear shock absorber	\$ 1 1 421.00 X
1	Rear knuckle arm	\$ 11 289.50 X
1	Rear top arm	\$ 47 105.00
1	Rear trailing arm	\$ 1つ 386.90 ナ
1	Rear wheel hup c/w bearing	\$ 9me 332.50
	The state of the state of the second state of the state o	\$ 5,195.60
	Less 20%	\$ 1,039.12
		\$ 415648

200/2 1/5 # 3200/2 (6/2/18

2051.6

	SPECIAL NETT ITEMS		2 -
1	Rear bumper clip (1 set)	\$ rec	45.00 50
1	Rear fender quarter glass sealant	\$ Lu	80.00
1	Rear tyre	\$ 8u	350.00 💢
1	Rear sport rim	\$00/sel	600.00 40D
		\$	1,075.00

S/N	LABOUR CHARGES		2
1	To remove, replaced damaged lamps and check up rear wiring.	\$	80.00 20
2	To remove and refit inner garnishes.	\$	180.00 80
3	To remove and refit rear reverse sensor.	\$	120.00
4	To remove and refit rear undercarriage.	\$	450.00 /00
5	To conduct wheel alignment.	\$	150.00
6	To remove and refit quarter glass to assist repair.	\$	150.00 82
7	To apply undercoating.	\$	150.00 3
8	Panel beating.	\$	1,500.00 800
9	To re-spray painting on the affected areas.	\$	1,400.00 6 8
	5.450 100%-15 0 (100%-150%-150%-150%-150%-150%-150%-150%-	S	4.180.00

GRAND TOTAL:

\$ 9,411.48

2390 4031.Y

• To resurvey be • To displie "so • Ports priore a • Third party so • No illegal more	autiants nence notify "The following: It after spray painting the arter spray painting the arter spray painting the arter spray painting the subject to confirmation tivey is on a "Without Prejudice" basis diffication(s) is allowed try (tem(s) must be resurveyed and inal approval from Insurance Company
Acknowledged	by Repairer
Signature:	
Date:	

PAGE 2 OF 2

LKK Auto Consultants Pte Ltd (Co.Reg. No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

DMCVSN3047641700

CS/CTI18012820/USD3N2

Date:

30/07/2018

REFERENCE

Handling Insurer: Claimant China Taiping Insurance

(Singapore) Pte. Ltd.

SJN1543B

Vehicle No:

13/07/2018

Policy No:

Insured Vehicle GBC5069E

No:

Nature of

Claim:

TP

Claim No:

SNM18D03452C02

R18A13800779

176414 km

JHMRN68809S200769

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

Colour:

Price:

SJN1543B

Make & Model: Reg. Date:

Date of Loss:

HONDA STREAM, 1.8 L RSZ (A)

05/02/2009 (Man. Year: 2008)

Brown

1799 cc

Engine Capacity: Market Value/New Car

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable): Yes Engine Modification:

Footbrake (Serviceable): Pre-accident Condition:

Engine No:

Chassis No:

Odometer:

Yes

Handbrake (Serviceable): CONDITION OF TYRES

Front Tyre Size: Front Left Side:

215/50ZR17 Champiro 6 mm Champiro 6 mm Rear Tyre Size: Rear Left Side: Rear Right Side: 215/50ZR17 Champiro 6 mm

Champiro 6 mm

Front Right Side: The above values represent the remaining tyre treads depth

COST OF CLAIMS Parts Miscellaneous Items	Repairer's 5,231.48 0.00	Adjuster's 2,111.28 0.00	3,120.20 0.00	Diff % 59.64
Labour Paintwork Labour	4,180.00 0.00	1,920.00 0.00	2,260.00 0.00	54.07
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$) Approved Total (Overridden) (S\$)	9,411.48	4,031.28 3,200.00	5,380.20	57.17
Nett Amount (S\$)	9,411.48	3,200.00	6,211.48	66.00

INSPECTION

Date of Assignment:

16/07/2018

Date Inspected:

16/07/2018 Inspected At: Zoom Autowerks Pte Ltd (HQ) 15 Kaki Bukit Road 4, #01-53

Singapore 417808

Estimated Period of Repair:

5.0 days

Adjuster: MARCUS CHUA

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 30 Jul 2018)

Parts: M1-MPV HONDA STREAM 1.8 L RSZ (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJN1543B)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deep Cut	1,185.00 FL	*654.00 FL
2	1		*REAR BUMPER SIDE RETAINER	Bent	48.50 FL	*23.50 FL
3	1		*REAR FENDER-R/H	Badly Dented/Cracked	981.60 FL	*981.60 FL
4	1		*REAR FENDER AIR GATE	Not Necessary	48.60 FL	*-FL
5	1		*REAR FENDER INNER TRIM BOARD	Not Necessary	628.50 FL	*-FL
6	1		*REAR FENDER QUARTER GLASS MOULDING	Necessary	182.60 FL	*60.00 FL
7	1		*REAR SHOCK ABSORBER	Not Necessary	421.00 FL	*-FL
8	1		*REAR KNUCKLE ARM	Not Necessary	289.50 FL	*-FL
9	1		*REAR TOP ARM	Not Necessary	105.00 FL	*-FL
10	1		*REAR TRAILING ARM	Not Necessary	386.90 FL	*-FL
11	1		*REAR WHEEL HUP C/W BEARING	Damaged	332.50 FL	*332.50 FL
12	1		*SET REAR BUMPER CLIP	Necessary	45.00 FS	*30.00 FS
13	1		*REAR FENDER QUARTER GLASS SEALANT	Necessary	80.00 FS	*40.00 FS
14	1		*REAR TYRE	Serviceable	350.00 FS	*-FS
15	1		*REAR SPORT RIM	Dented/Bent	600.00 FS	*400.00FS
16	1		*REAR TAILLAMP R/H (SCRATCHED)	Not Consistent With The Impact	585.90 FL	*-FL
F=Fra	anchise	part. S=S	pcNett. L=ListItemDisc.			
				Sub Total (S\$)	6,270.60	2,521.60
			- List Item Discoun	t on L Items 20.00/20.00% (S\$)	1,039.12	410.32
				Total Parts (S\$)	5,231.48	2,111.28

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labo	our Items			
1	TO REMOVE, REPLACED DAMAGED LAMPS AND CHECK UP REAR WIRING	New	80.00	20.00
2	TO REMOVE AND REFIT INNER GARNISHES	New	180.00	80.00
3	TO REMOVE AND REFIT REAR REVERSE SENSOR	New	120.00	50.00
4	TO REMOVE AND REFIT REAR UNDERCARRIAGE	New	450.00	100.00
5	TO CONDUCT WHEEL ALIGNMENT	New	150.00	80.00
6	TO APPLY UNDERCOATING	New	150.00	30.00
7	PANEL BEATING	New	1,500.00	800.00
8	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS	New	1,400.00	680.00
9	TO REMOVE AND REFIT QUARTER GLASS TO ASSIST REPAIR	New	150.00	80.00
	Gross Labou	r Cost (S\$)	4,180.00	1,920.00
	Report was unsubmitted during	g this print-out.		

< END OF ESTIMATES >