

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0798/2018/PH
Date : 12-Jul-18

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Hi Adrian

You recommend 8 days

We took 20 days exclude 1 PH 3 Sundays

Checked items replaced, parts order

jb ok 11 Sep 18

Owner's Name : Mr Tan Cher Teong
Address : 94 Watten Estate Road
Singapore 287635
Telephone : (HP) +65 92311333
Type of Claim : Own Damage Claim
Policy No. : 2100467474-02
Vehicle No : **SFY 3 P**
Model Code : Audi A4 1.4 TFSI
Model / Year : May-16
Engine No : CVN 009519
Chassis No : WAUZZZF4XGA076337
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 10-Jul-18
Place of Accident : Junction of Cecil Street

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SFY 3 P.

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To tow and recover vehicle from scene of accident	S/N \$	280.00	nil
2	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlight washer assy.	S/N \$	360.00	\$ 360.00
3	To dismantle and renew front bumper, lhs headlight, lhs front fender. Re-organise front crash management components.	\$	2,100.00	\$ 1,250.00
4	To dismantle lhs front door panel trim. To renew lhs wing mirror assy.	\$	600.00	\$ 300.00
5	To respray front bumper, lhs front fender, bonnet, lhs sill panel, lhs front door and lhs wing mirror cover.	\$	4,200.00	\$ 2,200.00
6	To suspend engine, dismantle front suspension assy. Inspect for damages and renew accordingly.	S/N \$	2,800.00	\$ 2,800.00
SUB - LABOUR CHARGES		:	<u>\$ 10,340.00</u>	<u>\$ 6,910.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SFY 3 P .

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
		<i>c/f</i>		\$ 6,910.00
7	To renew lhs front rim and carry out wheel alignment.	S/N	\$ 280.00	\$ 280.00
8	To carry out diagnostic check	S/N	\$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	<u>\$ 10,812.00</u>	<u>\$ 7,382.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFY 3 P.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	BUMPER COVER	\$ 1,849.00	\$ 1,479.20
2	FIXING PARTS FOR BUMPER	\$ 245.00	
3	GRILLE SATIN BLACK	\$ 171.00	
4	CLOSING ELEMENT - LOWER CENTRE	\$ 180.00	
5	SECURING STRIP	\$ 30.00	
6	AIR GUIDE - LH	\$ 73.00	\$ 57.84
7	RADIATOR GRILLE BLACK CHROME	\$ 972.00	\$ 777.20
8	AIR GUIDE GRILLE - LH	\$ 118.00	
9	GUIDE SECTION - LH	\$ 31.00	\$ 24.56
10	FENDER - LH	\$ 665.00	\$ 532.00
11	ATTACHMENT PARTS FOR FENDER	\$ 45.00	\$ 36.00
12	BRACKET FOR FENDER - LH	\$ 31.00	\$ 24.16
13	BRACKET FOR DEFORMATION ELEMENT - LH	\$ 43.00	\$ 34.56
14	BRACKET FOR FENDER - LH/RH	\$ 27.00	\$ 21.60
15	BRACKET	\$ 15.00	\$ 11.76
16	BRACE	\$ 103.00	\$ 82.40
17	CLOSING ELEMENT FOR FENDER - LH	\$ 30.00	
18	WHEEL HOUSING LINER - LH	\$ 215.00	\$ 171.60
19	ATTACHMENT PARTS FOR WHEEL HOUSING	\$ 78.00	
20	WHEEL SPOILER - LH	\$ 63.00	
SUB - TOTAL SPARE PARTS CHARGES :		\$ 4,984.00	\$ 3,252.88

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFY 3 P .

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
			\$ 3,252.88
21	STONE CHIP GUARD	\$ 44.00	\$ 34.56
22	LED HEADLIGHT - LH	\$ 6,973.00	\$ 5,578.40
23	LIFT CYLINER - LH	\$ 184.00	\$ 147.20
24	ALUMINIUM RIM	\$ 563.00	\$ 450.00
25	WING MIRROR ASSY - LH	\$ 959.00	
26	MIRROR CAP - LH	\$ 217.00	
27	ASSEMBLY CARRIER	\$ 1,657.00	
28	FRONT WISHBONE LINK	\$ 476.00	\$ 380.40
29	SUSPENSION GUIDE - LH FRONT	\$ 834.00	\$ 667.20
30	GUIDE - LH FRONT UPPER	\$ 452.00	\$ 361.20
31	HEXAGON FLANGE SCREW	\$ 10.00	\$ 8.00
32	GUIDE - LH REAR UPPER	\$ 452.00	\$ 361.20
33	HEXAGON FLANGE SCREW	\$ 10.00	\$ 8.00
34	WHEEL BEARINGN HOUSING - LH	\$ 848.00	\$ 678.40
35	HEXAGON FLANGE SCREW	\$ 10.00	\$ 8.00
36	SOCKET HEAD BOLT	\$ 24.00	\$ 18.88
37	SWIVEL JOINT	\$ 165.00	\$ 132.00
38	WHEEL HUB WITH BEARING	\$ 651.00	\$ 520.80
39	SOCKET HEAD BOLT	\$ 24.00	\$ 18.88
40	SUSPENSION FORK	\$ 225.00	\$ 180.00
SUB - TOTAL SPARE PARTS CHARGES		\$ 14,778.00	\$ 12,806.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFX 3 P .

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
			\$ 12,806.00
	c/f		
41	HEX. COLLAR BOLT	\$ 13.00	\$ 10.32
42	COUPLING ROD	2 \$ 247.00	\$ 98.80
43	DRIVESHAFT WITH CONSTANT VELOCITY	1 \$ 2,363.00	
44	SOCKET HEAD BOLT	\$ 24.00	\$ 18.88
45	GAS SHOCK ABSORBER	\$ 260.00	
46	HEX. COLLARED BOLT	\$ 13.00	\$ 10.32
47	STEERING GEAR WITH TRACK ROD JOINT	\$ 5,761.00	\$ 4,608.80
48	SUPPLEMENTARY	\$ 741.00	\$ 626.92
52	TIE ROD END	\$ 169.00	\$ 135.20
	TOTAL SPARE PARTS CHARGES	\$ 29,353.00	\$ 18,315.24
	TOTAL LABOUR CHARGES	\$ 21,152.00	\$ 7,382.00
	GRAND TOTAL	\$ 50,505.00	\$ 25,697.24

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SFY 3 P

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0798/2018/NH

5TH DEC 2019

Dear Sir,

RE: INSURANCE CLAIM FOR SFY 3 P, Audi A4 SEDAN 1.4 TFSI.

With reference to the above-mentioned vehicle, no. **SFY 3 P**, claimant, **Mr. Tan Cher Teong**, please find the related document per attached.

1. A copy of the Original invoice no. 85014542 – S\$ 23,965.05
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encl
AIG – SFY 3 P

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

total pages

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6536 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 1 14:47

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice No: 85014542	Account: A0006 (T 0)
	Date: 04/12/2019	AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
	Order: SFY0003P	
	Term: 30	

Regn No: SFY0003P (V 29762) Regn Date: 24/05/2016 Mileage: 39899 WIP No.: 17055
Model: A4 SEDAN 1.4 TFSI S tronic Chassis: WAUZZZF4XGA076337 Engine: CVN 009519 Dept: U

You have been assisted by :- UB-Tony Foong (33)

		Details	Qty	Unit Price	Amount
S	SUBLET	M: TO SUPPLY VEHICLE NUMBER PLATE	25.00	1.00	25.00
Q	EXC	M: 8888 Insurance Excess/Liability	-3300.00	1.00	-3,300.00
S	BODYWORK	M: TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	360.00	1.00	360.00
S	BODYWORK	M: TO DISMANTLE AND RENEW FRONT BUMPER, LHS HEADLIGHT, LHS FRONT FENDER, REORGANISE FRONT CRASH MANAGEMENT COMPONENTS.	1250.00	1.00	1,250.00
S	BODYWORK	M: TO DISMANTLE LHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL LHS WING MIRROR ASSY	300.00	1.00	300.00
S	BODYWORK	M: TO RESPRAY FRONT BUMPER, LHS FRONT FENDER, LHS FRONT DOOR AND LHS WING MIRROR COVER	2200.00	1.00	2,200.00
S	BODYWORK	M: TO SUSPEND ENGINE, DISMANTLE FRONT SUSPENSION ASSY, INSPECT FOR DAMAGES AND RENEW ACCORDINGLY	2800.00	1.00	2,800.00
S	BODYWORK	M: TO RENEW LHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT	280.00	1.00	280.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00
X	A8W0407151C	CONTR ARM (TECH) (V)	1.00	475.50	380.40
X	A8W0407693B	WISHBONE (TECH) (A)	1.00	834.00	667.20
X	A8W0407505C	UPPER LINK (TECH) (A)	1.00	451.50	361.20
X	A8W0407509B	UPPER LINK (TECH) (A)	1.00	451.50	361.20
X	A8W0413037G	SUSP FORK (TECH) (A)	1.00	225.00	180.00
X	A8W2423055AE	STEERING (TECH) (V)	1.00	5761.00	4,608.80
X	ZC205/60R16W	CONTIECO CONTACT 5	1.00	200.00	200.00

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 2 14:47

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120		Invoice No: 85014542	Account: A0006 (T 0)
		Date : 04/12/2019	AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
		Order : SFY0003P	
		Term : 30	

Regn No: SFY0003P (V 29762)	Regn Date: 24/05/2016	Mileage: 39899	WIP No.: 17055
Model: A4 SEDAN 1.4 TFSI S tronic	Chassis: WAUZZZF4XGA076337	Engine: CVN 009519	Dept: U
You have been assisted by :- UB-Tony Foong (33)			

		Details	Qty	Unit Price	Amount	
X	AN 10810701	SCREW (V)	Less 020%	1.00	2.80	2.24
X	A8W0611845S	BRACKET (V)	Less 020%	1.00	23.30	18.64
X	A8W0260759A	BRACKET	Less 020%	1.00	6.00	4.80
X	A8W0853651 3FZ	GRILLE	Less 020%	1.00	971.50	777.20
X	A8W0407253F	HOUSING (TECH)	Less 020%	1.00	848.00	678.40
X	A8W0941773A	HEADLIGHT	Less 020%	1.00	6973.00	5,578.40
X	A8W0821105A	FENDER	Less 020%	1.00	665.00	532.00
X	A8W0853887A	SPOILER	Less 020%	1.00	62.70	50.16
X	A8W0821171A	WHEEL HOUS	Less 020%	1.00	214.50	171.60
X	A8W0807081	COVER	Less 020%	1.00	109.00	87.20
X	A8W0807065C GRU	COVER	Less 020%	1.00	1849.00	1,479.20
X	A8W0601025B	RIM 16" C4M	Less 020%	1.00	562.50	450.00
X	AN 10197304	BOLT (TECH)	Less 020%	1.00	5.50	4.40
X	AWHT001949	SCREW (TECH)	Less 020%	1.00	7.70	6.16
X	AN 10272302	NUT (TECH)	Less 020%	5.00	2.60	10.40
X	A8E0407643A	SCREW (TECH)	Less 020%	3.00	23.60	56.64
X	A4M0411317	CONN LINK	Less 020%	1.00	123.50	98.80
X	A8W0821467	BRACKET	Less 020%	1.00	30.20	24.16
X	A8W0821471	BRACKET	Less 020%	1.00	27.00	21.60
X	A8W0821433B	BRACKET	Less 020%	1.00	14.70	11.76
X	A8W0821135C	SUPPORT	Less 020%	1.00	103.00	82.40
X	A8W0807283	GUIDE	Less 020%	1.00	30.70	24.56
X	A8W0121763	AIR DUCT	Less 020%	1.00	72.30	57.84
X	A8W0823745	COVER	Less 020%	1.00	19.20	15.36
X	A8W0821091	PLATE	Less 020%	1.00	43.20	34.56
X	A8W0821653	COVER	Less 020%	1.00	12.10	9.68
X	A8W0807277	STRIP	Less 020%	2.00	29.90	47.84
X	A8W0820581B	COVER	Less 020%	1.00	26.30	21.04
X	A8W0820769C	BRACKET	Less 020%	1.00	6.00	4.80
X	A8W0853823B 9B9	STONEGUARD	Less 020%	1.00	43.20	34.56
X	A8W0423811C	TIEROD END (TECH)	Less 020%	1.00	169.00	135.20
X	A8W0407689B	JOINT (TECH)	Less 020%	1.00	165.00	132.00
X	A8W0407607A	WHEEL HUB (TECH)	Less 020%	1.00	651.00	520.80
X	A191611715	CLIP (V)	Less 020%	1.00	1.90	1.52

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6386 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 3 14:47

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice No: 85014542 Date: 04/12/2019 Order: SFY0003P Term: 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No: SFY0003P (V 29762) Regn Date: 24/05/2016 Mileage: 39899 WIP No.: 17055

Model: A4 SEDAN 1.4 TFSI S tronic Chassis: WAUZZZF4XGA076337 Engine: CVN 009519 Dept: U

You have been assisted by :- UB-Tony Foong (33)

		Details	Qty	Unit Price	Amount
X	ABK0611715	SPRING (TECH)	Less 020%	1.00	1.50
X	A8W0955775	BRACKET	Less 020%	1.00	5.10
X	A8W0955101A	CYLINDER	Less 020%	1.00	184.00
X	A8W0010515A	STICKER	Less 020%	1.00	6.10
X	A8K0010520A	PLATE	Less 020%	1.00	11.60
X	AWHT001987	NUT (TECH)	Less 020%	3.00	4.60
X	AWHT006966	SCREW (TECH)	Less 020%	4.00	4.60
X	AWHT006542	SCREW (TECH)	Less 020%	3.00	10.00
X	AN 0161857	POP-RIVET	Less 020%	10.00	2.90
X	AN 0385053	RIVET	Less 020%	5.00	0.40
X	AN 0385012	RIVET	Less 020%	2.00	1.50
X	AN 105835019B9	RIVET	Less 020%	2.00	1.40
X	AWHT007061	SCREW (TECH)	Less 020%	1.00	4.60
X	AN 10640901	BOLT (REQ2) (TECH)	Less 020%	1.00	9.80
X	AN 01116417	NUT (TECH)	Less 020%	2.00	3.10
X	AWHT006151	NUT (REQ1) (TECH)	Less 020%	6.00	7.70
X	AN 10688301	BOLT (TECH)	Less 020%	2.00	12.90
X	AN 91221601	SCREW	Less 020%	2.00	7.70
X	AN 10784702	SCREW (TECH)	Less 020%	2.00	8.30
Parts 18,290.24					Sub-Total 22,397.24
Labour 0.00					7% GST 1,567.81
Sublet 7,407.00					Grand Total 23,965.05
Menus 0.00					
Lubricant 0.00					



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Premium Automobiles

Telefax

to AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SFY 3 P

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/0798/2018/KS
10 August 2018

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

total pages

RE : CLAIM - OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A4 SEDAN 1.4 TFSI
Vehicle Chassis No. : WAUZZZF4XGA076337
Vehicle Regn No. : SFY 3 P
Vehicle Mileage : 30765 KM
Vehicle Owner : Mr. Tan Cher Teong
Certificate No : 2100467474-02
Policy Excess : S\$3,531.00 (Inclusive GST)
Accident Date : 10 July 2018
Place : Junction of Cecil Street
Repair Cost : \$ 23965.05
WIP No. : 17055
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature : 
Time :
Date : 10/8/18

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	16 Jul 2018		16 Jul 2018 11:20 Edit Adj Rpt	S\$25,697.24 Edit Estimates	S\$25,697.24 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS			[Created by insurer]						
Insured:	TAN CHER TEONG , ID: S1356421C								
Vehicle Reg. No.:	SFY3P	Date of Loss:	10/07/2018 20:00 - :59 [25 Months and 16 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 4332673841SG	Policy/Cover Note No.:	2100467474-02 (Comprehensive)						
		Excess:	S\$3,300.00						
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Dally Amri, Mimi Zarina] MimiZarina.DallyAmri@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 25/07/2018]								
Driver/Custodian:	TAN YU HUAN TESSA (21 / Male) , NRIC: S9627456D, Tel: +6592311333 Email: RAYMONDTCT@HOTMAIL.COM								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG (02/12/2019): Alert - Adj Mandate Approved (S\$25697.24) - SFY3P - Claim Handler: Dally Amri, M... - AIG_SG (01/02/2019): Alert - Adj Mandate Maintained - SFY3P - Claim Handler: Dally Amri, Mimi Zarina - AIG_SG (17/07/2018): Alert - Adj Mandate Approved (S\$8304.00) - SFY3P - Claim Handler: Dally Amri, Mi... - AIG_SG (17/07/2018): SFY3P / OD / 10/07/2018 / Coverage & Excess update									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SFY3P (4332673841SG)**
OD
Jul 10 2018 8:50PM
[TAN CHER TEONG]
Premium Automobiles Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser		
Video			1 per page		
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	11/07/18 15:26	Video - Accident [Linked Accident Report Documents]		Load MP4	
Assessment Reports			1 per page		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	16/07/18 14:04	Adjuster Immediate Advice		Load HTM	
2	20/12/18 15:04	Adjuster Immediate Advice		Load HTM	
Photos/Images			3 per page		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	16/07/18 14:32	General View		Load JPG	
2	16/07/18 14:32	Chassis Number		Load JPG	
3	16/07/18 14:32	General View		Load JPG	
4	16/07/18 14:32	General View		Load JPG	
5	16/07/18 14:32	General View		Load JPG	
6	16/07/18 14:32	General View		Load JPG	
7	16/07/18 14:32	General View		Load JPG	
8	16/07/18 14:32	General View		Load JPG	
9	16/07/18 14:32	General View		Load JPG	
10	16/07/18 14:32	General View		Load JPG	
11	16/07/18 14:32	General View		Load JPG	
12	16/07/18 14:32	General View		Load JPG	
13	16/07/18 14:32	General View		Load JPG	
14	16/07/18 14:32	General View		Load JPG	
15	16/07/18 14:32	General View		Load JPG	
16	16/07/18 14:32	General View		Load JPG	
17	16/07/18 14:32	General View		Load JPG	
18	16/07/18 14:32	General View		Load JPG	
19	16/07/18 14:32	General View		Load JPG	
20	16/07/18 14:32	General View		Load JPG	
21	16/07/18 14:32	General View		Load JPG	
22	16/07/18 14:32	General View		Load JPG	
23	16/07/18 14:32	General View		Load JPG	
24	16/07/18 14:32	General View		Load JPG	
25	16/07/18 14:32	General View		Load JPG	
26	16/07/18 14:32	General View		Load JPG	
27	16/07/18 14:32	General View		Load JPG	
28	19/12/18 14:50	Reinspection Photo		Load JPG	
29	19/12/18 14:50	Reinspection Photo		Load JPG	
30	19/12/18 14:50	Reinspection Photo		Load JPG	
31	19/12/18 14:50	Reinspection Photo		Load JPG	
32	19/12/18 14:50	Reinspection Photo		Load JPG	
33	19/12/18 14:50	Reinspection Photo		Load JPG	
34	19/12/18 14:50	Reinspection Photo		Load JPG	

Video			1 per page ▾	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
35	19/12/18 14:50	Reinspection Photo	 Load JPG	☒
36	19/12/18 14:50	Reinspection Photo	 Load JPG	☒
37	19/12/18 14:50	Reinspection Photo	 Load JPG	☒
38	19/12/18 14:50	Reinspection Photo	 Load JPG	☒
39	19/12/18 14:50	Reinspection Photo	 Load JPG	☒
40	19/12/18 14:50	Reinspection Photo	 Load JPG	☒
41	19/12/18 14:50	Reinspection Photo	 Load JPG	☒
42	19/12/18 14:50	Reinspection Photo	 Load JPG	☒
43	19/12/18 14:50	Reinspection Photo	 Load JPG	☒
44	19/12/18 14:50	Reinspection Photo	 Load JPG	☒
45	19/12/18 14:50	Reinspection Photo	 Load JPG	☒
46	19/12/18 14:50	Reinspection Photo	 Load JPG	☒
47	19/12/18 14:50	Reinspection Photo	 Load JPG	☒
48	19/12/18 14:50	Reinspection Photo	 Load JPG	☒
49	19/12/18 14:50	Reinspection Photo	 Load JPG	☒
50	19/12/18 14:50	Reinspection Photo	 Load JPG	☒
51	19/12/18 14:50	Reinspection Photo	 Load JPG	☒
52	19/12/18 14:50	Reinspection Photo	 Load JPG	☒
53	19/12/18 14:50	Reinspection Photo	 Load JPG	☒
54	19/12/18 14:50	Reinspection Photo	 Load JPG	☒
55	19/12/18 14:50	Reinspection Photo	 Load JPG	☒
56	19/12/18 14:50	Reinspection Photo	 Load JPG	☒
57	19/12/18 14:50	Reinspection Photo	 Load JPG	☒
58	19/12/18 14:50	Reinspection Photo	 Load JPG	☒
59	19/12/18 14:50	Reinspection Photo	 Load JPG	☒
60	19/12/18 14:50	Reinspection Photo	 Load JPG	☒
61	19/12/18 14:50	Reinspection Photo	 Load JPG	☒
62	19/12/18 14:50	Reinspection Photo	 Load JPG	☒
63	19/12/18 14:50	Reinspection Photo	 Load JPG	☒
64	19/12/18 14:50	Reinspection Photo	 Load JPG	☒
65	19/12/18 14:50	Reinspection Photo	 Load JPG	☒
66	19/12/18 14:50	Reinspection Photo	 Load JPG	☒
67	19/12/18 14:50	Reinspection Photo	 Load JPG	☒
68	19/12/18 14:50	Reinspection Photo	 Load JPG	☒
69	19/12/18 14:50	Reinspection Photo	 Load JPG	☒
70	19/12/18 14:50	Reinspection Photo	 Load JPG	☒
71	19/12/18 14:50	Reinspection Photo	 Load JPG	☒
72	19/12/18 14:50	Reinspection Photo	 Load JPG	☒
73	19/12/18 14:50	Reinspection Photo	 Load JPG	☒
74	19/12/18 14:50	Reinspection Photo	 Load JPG	☒
75	19/12/18 14:50	Reinspection Photo	 Load JPG	☒
76	19/12/18 14:50	Reinspection Photo	 Load JPG	☒
77	19/12/18 14:50	Reinspection Photo	 Load JPG	☒
78	19/12/18 14:50	Reinspection Photo	 Load JPG	☒
79	19/12/18 14:50	Reinspection Photo	 Load JPG	☒
80	19/12/18 14:50	Reinspection Photo	 Load JPG	☒
81	19/12/18 14:50	Reinspection Photo	 Load JPG	☒
82	19/12/18 14:50	Reinspection Photo	Load JPG	☒
83	19/12/18 14:50	Reinspection Photo	Load JPG	☒
84	19/12/18 14:50	Reinspection Photo	Load JPG	☒
85	19/12/18 14:50	Reinspection Photo	Load JPG	☒
86	19/12/18 14:50	Reinspection Photo	Load JPG	☒
87	19/12/18 14:50	Reinspection Photo	Load JPG	☒

Video			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
88	19/12/18 14:50	Reinspection Photo	Load JPG	☒
89	19/12/18 14:50	Reinspection Photo	Load JPG	☒
90	19/12/18 14:50	Reinspection Photo	Load JPG	☒
91	19/12/18 14:50	Reinspection Photo	Load JPG	☒
92	19/12/18 14:50	Reinspection Photo	Load JPG	☒
93	19/12/18 14:50	Reinspection Photo	Load JPG	☒
94	19/12/18 14:50	Reinspection Photo	Load JPG	☒
95	19/12/18 14:50	Reinspection Photo	Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	16/07/18 13:40	DRIVING & IC	Load PDF	
2	16/07/18 13:40	ESTIMATE	Load PDF	
3	20/12/18 14:50	ESTIMATE MARKED & SUPPLEMENTARY.pdf	Load PDF	
4	11/12/19 14:34	DISCHARGE VOUCHER	Load PDF	
5	11/12/19 14:34	SUPPLEMENTARY	Load PDF	
6	11/12/19 14:34	WORKSHOP INVOICE	Load PDF	

Linked Accident Report Documents

Video			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	11/07/18 15:26	Video - Accident	Load MP4	
Assessment Reports			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	11/07/18 15:32	Accident Statement	Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	11/07/18 15:24	Accident Photo	Load JPG	☒
2	11/07/18 15:24	Accident Photo	Load JPG	☒
3	11/07/18 15:24	Accident Photo	Load JPG	☒
4	11/07/18 15:24	Accident Photo	Load JPG	☒
5	11/07/18 15:24	Accident Photo	Load JPG	☒
6	11/07/18 15:24	Accident Photo	Load JPG	☒
7	11/07/18 15:24	Accident Photo	Load JPG	☒
8	11/07/18 15:24	Accident Photo	Load JPG	☒
9	11/07/18 15:24	Accident Photo	Load JPG	☒
10	11/07/18 15:24	Accident Photo	Load JPG	☒
11	11/07/18 15:24	Accident Photo	Load JPG	☒
12	11/07/18 15:24	Accident Photo	Load JPG	☒
13	11/07/18 15:24	Accident Photo	Load JPG	☒
14	11/07/18 15:24	Accident Photo	Load JPG	☒
15	11/07/18 15:24	Accident Photo	Load JPG	☒
16	11/07/18 15:24	Accident Photo	Load JPG	☒
17	11/07/18 15:24	Accident Photo	Load JPG	☒
18	11/07/18 15:24	Accident Photo	Load JPG	☒
19	11/07/18 15:24	Accident Photo	Load JPG	☒
20	11/07/18 15:27	ACCIDENT SCENE PHOTO	Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	11/07/18 15:15	Sketch Plan	Load JPG	☒
2	11/07/18 15:15	Sketch Plan #2	Load JPG	☒

DOCUMENTS CHECKLIST

There are no document checklists configured.

Reset

Save

Print

Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG18012824/ASBS2

Date: 11/12/2019

REFERENCE

Insured/Claimant: TAN CHER TEONG Policy No: 2100467474-02
Date of Loss: 10/07/2018 Nature of Claim: OD Claim No: 4332673841SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SFY3P
Make & Model: AUDI A4, 1.4 T (A) Engine No: CVN009519
Reg. Date: 24/05/2016 (Man. Year: 2016) Chassis No: WAUZZZF4XGA076337
Colour: Black Odometer: 30764 km
Engine Capacity: 1395 cc
Market Value/New Car Price: S\$115,000.00
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16
Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	29,238.92	18,315.24	10,923.68	37.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,812.00	7,382.00	3,430.00	31.72
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	40,050.92	25,697.24	14,353.68	35.84
- Excess (S\$)	3,300.00	3,300.00	0.00	0.00
(S\$)	36,750.92	22,397.24	14,353.68	39.06
+ GST 7.00/7.00% (S\$)	2,572.56	1,567.81	1,004.75	39.06
Nett Amount (S\$)	39,323.48	23,965.05	15,358.43	39.06

INSPECTION

Date of Assignment: 16/07/2018
Date Inspected: 13/07/2018 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 12.0 days

Adjuster: ADRIAN LING

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER	Distorted	1,849.00 FS	*1,479.20 FS
2	1		*FIXING PARTS FOR BUMPER	Not Necessary	245.00 FS	*- FS
3	1		*GRILLE SATIN BLACK	Not Necessary	171.00 FS	*- FS
4	1		*CLOSING ELEMENT - LOWER CENTRE	Not Necessary	180.00 FS	*- FS
5	1		*SECURING STRIP	Not Necessary	30.00 FS	*- FS
6	1		*AIR GUIDE - LH	Deformed	73.00 FS	*57.84 FS
7	1		*RADIATOR GRILLE BLACK CHROME	Cracked	972.00 FS	*777.20 FS
8	1		*AIR GUIDE GRILLE - LH	Not Necessary	118.00 FS	*- FS
9	1		*GUIDE SECTION - LH	Damaged	31.00 FS	*24.56 FS
10	1		*FENDER - LH	Distorted	665.00 FS	*532.00 FS
11	1		*ATTACHMENT PARTS FOR FENDER	Necessary	45.00 FS	*36.00 FS
12	1		*BRACKET FOR FENDER - LH	Bent	31.00 FS	*24.16 FS
13	1		*BRACKET FOR DEFORMATION ELEMENT - LH	Necessary	43.00 FS	*34.56 FS
14	2		*BRACKET FOR FENDER - LH/RH	Bent	27.00 FS	*21.60 FS
15	1		*BRACKET	Bent	15.00 FS	*11.76 FS
16	1		*BRACE	Bent	103.00 FS	*82.40 FS
17	1		*CLOSING ELEMENT FOR FENDER - LH	Not Necessary	30.00 FS	*- FS
18	1		*WHEEL HOUSING LINER - LH	Deformed	215.00 FS	*171.60 FS
19	1		*ATTACHMENT PARTS FOR WHEEL HOUSING	Not Necessary	78.00 FS	*- FS
20	1		*WHEEL SPOILER - LH	Not Necessary	63.00 FS	*- FS
21	1		*STONE CHIP GUARD	Necessary	44.00 FS	*34.56 FS
22	1		*LED HEADLIGHT - LH	Cracked	6,973.00 FS	*5,578.40 FS
23	1		*LIFT CYLINDER - LH	Cracked	184.00 FS	*147.20 FS
24	1		*ALUMINIUM RIM	Cut	563.00 FS	*450.00 FS
25	1		*WING MIRROR ASSY - LH	Not Necessary	959.00 FS	*- FS
26	1		*MIRROR CAP - LH	Not Necessary	217.00 FS	*- FS
27	1		*ASSEMBLY CARRIER	Not Necessary	1,657.00 FS	*- FS
28	1		*FRONT WISHBONE LINK	Bent	476.00 FS	*380.40 FS
29	1		*SUSPENSION GUIDE - LH FRONT	Bent	834.00 FS	*667.20 FS
30	1		*GUIDE - LH FRONT UPPER	Bent	452.00 FS	*361.20 FS
31	1		*HEXAGON FLANGE SCREW	Necessary	10.00 FS	*8.00 FS
32	1		*GUIDE - LH REAR UPPER	Bent	452.00 FS	*361.20 FS
33	1		*HEXAGON FLANGE SCREW	Necessary	10.00 FS	*8.00 FS
34	1		*WHEEL BEARING HOUSING - LH	Damaged	848.00 FS	*678.40 FS
35	1		*HEXAGON FLANGE SCREW	Necessary	10.00 FS	*8.00 FS
36	1		*SOCKET HEAD BOLT	Damaged	24.00 FS	*18.88 FS
37	1		*SWIVEL JOINT	Bent	165.00 FS	*132.00 FS
38	1		*WHEEL HUB WITH BEARING	Damaged	651.00 FS	*520.80 FS
39	1		*SOCKET HEAD BOLT	Necessary	24.00 FS	*18.88 FS
40	1		*SUSPENSION FORK	Bent	225.00 FS	*180.00 FS
41	1		*HEX. COLLAR BOLT	Necessary	13.00 FS	*10.32 FS
42	1		*COUPLING ROD	O/s Bent	247.00 FS	*98.80 FS
43	1		*DRIVESHAFT WITH CONSTANT VELOCITY	Not Necessary	2,363.00 FS	*- FS
44	1		*SOCKET HEAD BOLT	Necessary	24.00 FS	*18.88 FS
45	1		*GAS SHOCK ABSORBER	Not Necessary	260.00 FS	*- FS
46	1		*HEX. COLLARED BOLT	Necessary	13.00 FS	*10.32 FS
47	1		*STEERING GEAR WITH TRACK ROD JOINT	Damaged	5,761.00 FS	*4,608.80 FS
48	1		*TIE ROD END	Bent	169.00 FS	*135.20 FS
49	2		*FRONT BUMPER SECURING STRIP	Damaged	47.84 FS	*47.84 FS
50	1		*FRONT BUMPER TOP COVER	Deformed	87.20 FS	*87.20 FS
51	1		*SIGN CAUTION STICKER	Necessary	9.28 FS	*9.28 FS
52	1		*WHEEL HOUSE LINER COVER - LH	Necessary	9.68 FS	*9.68 FS
53	1		*FRONT FENDER TRIM - LH UPPER	Necessary	21.04 FS	*21.04 FS
54	1		*HEADLIGHT TRIM - LH UPPER	Damaged	15.36 FS	*15.36 FS
55	1		*HEADLIGHT LIFT CYLINDER BRACKET - LH	Bent	4.08 FS	*4.08 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*STICKER FOR AIR CONDITIONER	Necessary	4.88 FS	*4.88 FS
57	2		*AIR-COND LINE BRACKET	Bent	9.60 FS	*9.60 FS
58	1		*TYRE - LHS FRT	Cut	200.00 FS	*200.00 FS
59	1		*FRT NO PLATE	Necessary	25.00 FS	*25.00 FS
60	1		*SUNDRIES	Necessary	192.96 FS	*192.96 FS
				Total Parts (S\$)	29,238.92	18,315.24

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO TOW AND RECOVER VEHICLE FROM SCENE OF ACCIDENT.	New	280.00	0.00
2	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	New	360.00	360.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, LHS HEADLIGHT, LHS FRONT FENDER. RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS.	New	2,100.00	1,250.00
4	TO DISMANTLE LHS FRONT DOOR PANEL TRIM. TO RENEW LHS WING MIRROR ASSY.	New	600.00	300.00
5	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER, BONNET, LHS SILL PANEL, LHS FRONT DOOR AND LHS WING MIRROR COVER.	New	4,200.00	2,200.00
6	TO SUSPEND ENGINE, DISMANTLE FRONT SUSPENSION ASSY, INSPECTION FOR DAMAGES AND RENEW ACCORDINGLY.	New	2,800.00	2,800.00
7	TO RENEW LHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT.	New	280.00	280.00
8	TO CARRY OUT DIAGNOSTIC CHECK.	New	192.00	192.00
Gross Labour Cost (S\$)			10,812.00	7,382.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >