

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 / 97761091 Fax : 67528669

Co. Reg No. 201202259N

Owner : Sahadevan Balamurugan

Accident Date : 26-Feb-18

Vehicle No : FBB 1805 D

Vehicle Model : Bajaj Chetak

Estimated Repair Costs

Qty	Description <u>List Items</u>	Amount S(\$)
1	Front fender	\$ 340 75.00 —
2	Fork inner tubes	\$ 24/1m 290.00 —
1	Fork under bracket	\$ 34 185.00 —
2	Fork outer tubes	\$ 117 250.00 x
1	Front rim shaft	\$ 122 45.00 —
1	Front rim bearing	\$ 122 38.00 —
1	Front wheel rim	\$ 20/21 280.00 —
1	Top cowling	\$ 12 135.00 x
1	Windshield	\$ 72 68.00 x
1	Headlamp	\$ 512 145.00 —
2	Front signals	\$ 11 120.00 x
1	Meter assy	\$ CM 388.00 —
1	Lampstay	\$ 34 75.00 —
2	Front side cowlings	N/S \$ CM 360.00 120
1	Handle bar	\$ 34 95.00 —
2	Handle bar ends	N/S \$ 512 50.00 120
1	Brake lever	11 \$ 28.00 x
1	Clutch lever	\$ 512 28.00 —
2	Side mirrors	N/S \$ CM 110.00 120
1	Exhaust assy	\$ 20/21 485.00 —
1	Front footrest -L/H	\$ (11) 35.00 —
1	Front footrest bracket	\$ 34 50.00 —
1	Gear pedal	\$ 34 38.00 —
1	Rear tailboard	\$ 12 145.00 x
1	Rear signal -L/H	\$ 11 65.00 —
1	Side board -L/H	\$ 612 60.00 —
1	Rear footrest -L/H	\$ 11 25.00 —
1	Rear footrest bracket -L/H	\$ 11 48.00 x
1	Side stand	\$ 12 75.00 x
1	Main stand	\$ 12 90.00 x
		\$ 3,881.00
		\$ 388.10
		\$ 3,492.90

front Disc plate 90 sat —

Fuel tank 200 cc Respray 805.00

Less 10%

2662
2395.8

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 / 97761091 Fax : 67528669

Co. Reg No. 201202259N

Owner : Sahadevan Balamurugan

Accident Date : 26-Feb-18

Vehicle No : FBB 1805 D

Vehicle Model : Bajaj Chetak

Estimated Repair Costs

Special Nett Items

1	Number plate (1 set)	\$	34	28.00	10
2	Fork oils	\$	24	30.00	—
2	Fork oil seals	\$	24	56.00	—
1	Steering cone (1 set)	\$	24	75.00	—
1	Rear box	\$	24	180.00	60
1	Rear box bracket	\$	24	100.00	x
				\$	469.00

LR 605.N 147

S/No.

Labour

1	To provide towing service.	\$	50.00	35
2	To check wiring and reset headlamp focusing.	\$	17 80.00	2
3	To provide labour.	\$	380.00	300
4	To repair body frame.	\$	350.00	250
		\$	<u>860.00</u>	

Grand Total

\$ 4,821.90

Dollars: Four Thousand Eight Hundred Twenty-One And Nine Cents Only.

EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

PAGE 2 OF 2
Signature:

Date:

3211-8
2809