

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 / 97761091 Fax : 67528669

Co. Reg No. 201202259N

Owner : Sahadevan Balamurugan

Accident Date : 26-Feb-18

Vehicle No : FBB 1805 D

Vehicle Model : Bajaj Chetak

Estimated Repair Costs

Qty	Description	Amount S(\$)
	<u>List Items</u>	
1	Front fender	\$ 310 75.00
2	Fork inner tubes	\$ 241/m 290.00
1	Fork under bracket	\$ 51 185.00
2	Fork outer tubes	\$ 11 250.00
1	Front rim shaft	\$ 22 45.00
1	Front rim bearing	\$ 22 38.00
1	Front wheel rim	\$ 22 280.00
1	Top cowling	\$ 2 135.00
1	Windshield	\$ 2 68.00
1	Headlamp	\$ 51 145.00
2	Front signals	\$ 11 120.00
1	Meter assy	\$ 22 388.00
1	Lampstay	\$ 51 75.00
2	Front side cowlings	N/S \$ 22 360.00
1	Handle bar	\$ 22 95.00
2	Handle bar ends	N/S \$ 51 50.00
1	Brake lever	\$ 11 28.00
1	Clutch lever	\$ 51 28.00
2	Side mirrors	N/S \$ 22 110.00
1	Exhaust assy	\$ 22 485.00
1	Front footrest -L/H	\$ 11 35.00
1	Front footrest bracket	\$ 51 50.00
1	Gear pedal	\$ 51 38.00
1	Rear tailboard	\$ 2 145.00
1	Rear signal -L/H	\$ 11 65.00
1	Side board -L/H	\$ 51 60.00
1	Rear footrest -L/H	\$ 11 25.00
1	Rear footrest bracket -L/H	\$ 11 48.00
1	Side stand	\$ 2 75.00
1	Main stand	\$ 2 90.00
		\$ 3,881.00
		\$ 388.10
		\$ 3,492.90

front Disc plate 90 sat

Less 10%

Fuel tank 200 cc Respray 805.00

2662
2396.8

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 / 97761091 Fax : 67528669

Co. Reg No. 201202259N

Owner : Sahadevan Balamurugan

Accident Date : 26-Feb-18

Vehicle No : FBB 1805 D

Vehicle Model : Bajaj Chetak

Estimated Repair Costs

Special Nett Items

1	Number plate (1 set)	\$	34	28.00	10
2	Fork oils	\$	24	30.00	—
2	Fork oil seals	\$	24	56.00	—
1	Steering cone (1 set)	\$	24	75.00	—
1	Rear box	\$	24	180.00	60
1	Rear box bracket	\$	2	100.00	α
		\$		469.00	

LR 605.2 147

S/No. Labour

1	To provide towing service.	\$	50.00	35
2	To check wiring and reset headlamp focusing.	\$	11	80.00 α
3	To provide labour.	\$		380.00 300
4	To repair body frame.	\$		350.00 250
		\$		860.00

Grand Total

\$ 4,821.90

Dollars: Four Thousand Eight Hundred Twenty-One And Nine Cents Only.



EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

3211-8
2809