

Registered in Merimes.

Place of Accident:

Final ? Yes / No

RMKS.

D (TE/PIC)

Post-Repair Photos

Others:	
---------	--

Sample 2
Sample 3

C/P.
\$450.00

ASSIGNMENT

Front: Date: 16/7/2018

Estimated Cost:

ON ☒ TP ☐ WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SHD 97594

at Workshop m/s Trans Carb

of No. 2 AMK sf-63

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh.

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 01 days Res.: Yes or No

Lum Sum: 1-B1% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{hup}

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SHD 97594 Regn: 03, 14

Type: M,Car / M,Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Peravit Latitude cc 1995

Colour: M. White / Red A/C: Insured / Std / NI / NA

Sp. Reading: 473277 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: VF1ABL15AUC 276883

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ Inorder / Jammed / Leaked / Burnt or

Brake: ☒ Inorder / Jammed / Leaked / Burnt or

Modi: ☒ Nil / S/Rim / STD A/Rim or

Tyre Size: F: Conti 215/60R16

R: Felken

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 8 mm

R/Bal. 6 mm

L/Bal. 8 mm

L/Bal. 6 mm

D.O.A. 8/7/18

D.O.I. 16/7/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

17/7 File pass to Carborne
8/22/18 with 1 working day

(L.I. = \$42074.61
99%)

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

___ S + RS ___ \$

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$))

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9759U**AAD1807-070***Not Authored
8/22/01*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 9759U

VF1ABL15AUC276883

RENAULT

LATITUDE

8.7.2018

III**PART****LIST**

1	1 BUMPER COVER REAR	\$	11,108.46
2	1 BUMPER LOWER REAR	\$	768.84
3	1 BUMPER BRACKET CTR REAR	\$	113.47
4	1 BUMEP R BRACKET SIDE RH REAR	\$	135.97
5	1 BUMEP R RETAINER RH REAR	\$	44.99
6	1 BUMPER REFLECTOR RH	\$	43.61
7	1 BUMEP R BRACKET SIDE LH REAR	\$	135.97
8	1 BUMEP R RETAINER LH REAR	\$	44.99
9	1 BUMPER REFLECTOR LH	\$	43.61
10	1 BUMPER BEAM REAR	\$	777.52
11	1 BUMPER BEAM BRACKET LH REAR	\$	225.95
12	1 BUMPER BEAM BRACKET RH REAR	\$	225.95
13	1 BOOT REAR	\$	2,872.68
14	1 BOOT FINISHER	\$	470.06
15	1 BOOT WHEATERSTRIP	\$	323.05
16	1 BOOT REFLECTOR LAMP LH	\$	493.35
17	1 BOOT REFLECTOR LAMP RH	\$	493.35
18	1 BOOT BADGE 'RENAULT'	\$	225.36
19	1 BOOT BADGE	\$	225.36
20	1 BOOT STRUT LH	\$	276.08
21	1 BOOT STRUT RH	\$	276.08
22	1 BOOT HINGE LH	\$	367.84
23	1 BOOT HINGE RH	\$	367.84
24	1 BOOT INNER TRIM	\$	586.45
25	1 BOOT SWITCH	\$	168.13
26	1 BOOT LOCK	\$	202.67
27	1 BOOT LOCK CATCH	\$	74.40
28	2 LICENCE PLATE LAMP	\$	50.52
29	2 BOOT RUBBER PLUG	\$	221.81

X

Trans-cab Auto Services Pte Ltd

AAD1807-070

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9759U

30	1 DOOR PANEL REAR RH	\$	R	2,844.66	}	X
30	1 FENDER PANEL INNER TRIM REAR RH	\$	SL	671.45		
30	1 FENDER PANEL REAR RH	\$	R	3,299.13		
31	1 WHEELARCH REAR RH	\$	SL	543.47		
32	1 TAILLAMP RH	\$	SL	552.55		
33	1 TAILLAMP PANEL RH	\$	R	986.70		
34	1 TAILLAMP LH	\$	SL	552.55		
35	1 TAILLAMP PANEL LH	\$	R	986.70		
36	1 OUTER PANEL REAR (End Panel)	\$	R	1,471.77		
37	1 OUTER PANEL REAR (End Panel)TRIM	\$	SL	404.56		
38	1 SPARE WHEEL PANEL (Luggage Floor Panel)	\$	R	2,189.88		
39	1 SPARE WHEEL PANEL TRIM	\$	SL	612.21		
40	1 EXHAUST REAR	\$	R	7,489.05		
41	1 EXHAUST CAP REAR	\$	R	230.49		

TOTAL	\$	34,199.54
10%	\$	3,419.95
	\$	30,779.59

Special Nett

1	1SET PARKING AID	\$	SL	700.00	}	X
2	1SET REAR BUMPER CLIP	\$	na	66.00		
3	1SET BUMPER BRACKET CTR CLIP	\$	na	33.00		
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	na	10.00		
5	1SET BUMPR RETAINER RH CLIP RR	\$	na	20.00		
6	1SET BUMPR BRACKET SIDE CLIP LH RR	\$	na	10.00		
7	1SET BUMPR RETAINER CLIP LH RR	\$	na	20.00		
8	1SET BUMPER LOWER REAR RIVET	\$	na	22.00		
9	1SET BUMPER LOWER REAR CLIP	\$	na	66.00		
10	1 EXHAUST MOUNTING REAR	\$	SL	17.82		
11	1SET BOOT FINISHER CLIP	\$	na	24.20		
12	1 BOOT STICKER "Trans-cab"	\$	na	30.00		
13	1 BOOT STICKER "6555-3333"	\$	na	30.00		
14	1 BOOT INNER TRIM CLIP	\$	na	45.00		
15	1SET FENDER WHEELARCH REAR RH CLIP	\$	na	35.00		
16	1SET FENDER WHEELARCH REAR LH CLIP	\$	na	35.00		
17	1 FENDER INNER TRIM CLIP LH	\$	na	28.00		
18	1 FENDER INNER TRIM CLIP LH	\$	na	28.00		

Trans-cab Auto Services Pte Ltd**AAD1807-070**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9759U

19	1 TAILLAMP CLIP RH	\$	nn	5.00	} X
20	1 TAILLAMP CLIP LH	\$	nn	5.00	
21	2 REAR WINDSCREEN SELANT	\$	nn	80.00	
22	1 WINDSCREEN MOULDING	\$	nn	100.00	
23	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	nn	100.00	
24	1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	nn	385.00	
25	1 SPARE TYRE	\$	nn	330.00	

TOTAL \$ 2,225.02**TOTAL PARTS \$ 33,004.61****LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	3,750.00	229
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	nn	3,200.00 X
To Rust-Proofing Of The Affected Areas.	\$	nn	170.00 X
To reinstall rear bumper parking sensor.	\$	nn	170.00 X
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	nn	170.00 X
To repair and realign rear exhaust pipe.	\$	nn	170.00 X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	nn	170.00 X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	nn	170.00 X
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	nn	170.00 X

Trans-cab Auto Services Pte Ltd**AAD1807-070**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9759U

To supply and re-do rear luggage floor panel insulation padding.

\$ 380.00 X

To transfer of rear fender fittings, attachment and perform water seepage test.

\$ 380.00 X

To transfer of rear windscreen fittings and conduct water seepage test.

\$ 170.00 X

To check steering geometry and computer wheel alignment

\$ 220.00 X

To transfer of rear door fittings, attachment and perform water seepage test.

\$ 380.00 X

TOTAL \$ 9,290.00**Over All Total \$ 42,294.61****(LUMP SUM)****Repair Days****15 days***1 day***LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

[-> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	3878K

Vehicle Details

Vehicle No.:	SHD9759U
Vehicle to be Exported:	Yes
Intended De-registration Date:	16 Jul 2018
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2013
Engine No.:	M9R8839C000948
Chassis No.:	VF1ABL15AUC276883
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	31 Mar 2014
First Registration Date:	31 Mar 2014
Transfer Count:	0
Actual ARF Paid:	\$12,498.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Mar 2022
PARF Rebate Amount:	\$9,373.00

Intended COE Rebate Details

COE Expiry Date:	30 Mar 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$58,745.00
COE Rebate Amount:	\$27,201.00
Total Rebate Amount:	\$36,574.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 16 Jul 2018

OK

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Friday, 13 July 2018 2:51 PM
To: 'sur@lkkauto.com'; Catherine Chong (LKK Auto)
Cc: C Meenachi - III; Candy Kong; jasminetan@transcab.com.sg
Subject: FW: ARRANGE FOR SURVEY FOR SHD9759U
Attachments: SHD9759U.PDF; img-712132225-0001.pdf; SHD9759U.PDF

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SHD9759U and let us have your report urgently.

This claim will be handled by Ms Sherini.

*Kindly upload this survey request email to merimen.

Thank You.

16072018

Best Regards,
ANDREW LIM
Motor Claims Dept.
India International Insurance Pte Ltd
64 Cecil Street | #05 IOB Building | Singapore 049711
Tel: 6347 6100, Ext - 227
S&P 'A-' (stable) rated Company

-----Original Message-----

From: Candy Kong [mailto:candy.kong@transcab.com.sg]
Sent: Friday, 13 July, 2018 2:46 PM
To: Motor Claim - III <motorclaim@iii.com.sg>
Cc: jasminetan@transcab.com.sg
Subject: ARRANGE FOR SURVEY FOR SHD9759U

Hi Andrew,

Kindly assign to LKK Auto Consultants Pte Ltd

Thks & Rdgs
Candy Kong
Claims Service Assistant

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you

may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet

-----Original Message-----

From: Motor Claim - III [mailto:motorclaim@iii.com.sg]
Sent: Friday, 13 July, 2018 2:42 PM
To: Candy Kong <candy.kong@transcab.com.sg>
Cc: jasminetan@transcab.com.sg
Subject: RE: ARRANGE FOR SURVEY FOR SHD9759U

Dear Candy,

Sorry for the delay.

We propose using one of the following motor surveyors:

- * Automobile Inspection Services Pte Ltd
- * Autoprobe Consultants
- * VP Appraisal
- * Quantum Risk Management
- * Ajax Inspection Services Pte Ltd
- * Form Team Adjusters Pte Ltd
- * Infiniti Appraisal Service
- * JP Knights Adjusters
- * LBS Auto Consultants Pte Ltd
- * Premier Appraisers Services
- * Priority Services
- * RT Appraisal
- * LKK Auto Consultants Pte Ltd
- * Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,
ANDREW LIM
Motor Claims Dept.
India International Insurance Pte Ltd
64 Cecil Street | #05 IOB Building | Singapore 049711
Tel: 6347 6100, Ext - 227
S&P 'A-' (stable) rated Company

-----Original Message-----

From: Candy Kong [mailto:candy.kong@transcab.com.sg]
Sent: Friday, 13 July, 2018 10:59 AM
To: Motor Claim - III <motorclaim@iii.com.sg>
Cc: jasminetan@transcab.com.sg
Subject: ARRANGE FOR SURVEY FOR SHD9759U

Hi Andrew

Kindly see attach LTA search result.

Thks & Rdgs
Candy Kong
Claims Service Assistant

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet

-----Original Message-----

From: Motor Claim - III [mailto:motorclaim@iii.com.sg]
Sent: Friday, 13 July, 2018 10:53 AM
To: Candy Kong <candy.kong@transcab.com.sg>
Cc: jasminetan@transcab.com.sg
Subject: RE: ARRANGE FOR SURVEY FOR SHD9759U

Dear Candy,

Please hold on as we are trying to find information about the driver.

We can't find any records of this vehicle in our system.

Kindly provide us extra information, if any please.

Best Regards,
ANDREW LIM
Motor Claims Dept.
India International Insurance Pte Ltd
64 Cecil Street | #05 IOB Building | Singapore 049711
Tel: 6347 6100, Ext - 227
S&P 'A-' (stable) rated Company

-----Original Message-----

From: Candy Kong [mailto:candy.kong@transcab.com.sg]
Sent: Friday, 13 July, 2018 10:46 AM
To: Motor Claim - III <motorclaim@iii.com.sg>
Cc: jasminetan@transcab.com.sg
Subject: ARRANGE FOR SURVEY FOR SHD9759U

Dear all,

Resend.

Kindly arrange to survey urgently

Thks & Rdgs
Candy Kong
Claims Service Assistant

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet

-----Original Message-----

From: Candy Kong [mailto:candy.kong@transcab.com.sg]

Sent: Thursday, 12 July, 2018 1:27 PM

To: 'motorclaim@iii.com.sg' <motorclaim@iii.com.sg>

Subject: ARRANGE FOR SURVEY FOR SHD9759U

DEAR ALL,

KINDLY SEE ATTACH LTA SEARCH

Please arrange for survey as below :

SLT8112K - 08.07.2018 at 2045Hrs - SHD9759U

Lunch time : 12pm - 1pm.

Kindly pls dun arrange survey during lunch time.

"We Agree to let your In-house surveyor assess/ survey our vehicle with estimate

Thks & Rdgs
Candy Kong
Claims Service Assistant

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and

outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful.

Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful.

Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission,

printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful.

Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Shu Pei (LKKAuto)

From: Pooi Chin Han Daniel <danielpooi@iii.com.sg>
Sent: Tuesday, 20 August 2019 2:41 PM
To: Shu Pei (LKKAuto)
Subject: FW: IIIRef: MTS2018D0000013 - ACCDT INVLT8112K (BK Auto Motortrade)(III) & SHD9759U ON 08/07/2018 ALONG NEWTON CIRCUS

Dear Shu Pei,

We refer to our earlier telephone conversation.

Please refer to the email below.

Daniel Pooi

**Motor Claims Department
India International Insurance Pte Ltd**

64 Cecil Street #04-02 IOB Building
Singapore 049711
Tel: 6347 6100 Ext 202 Fax: 6224 4174
S&P 'A-' rated Company



From: Pooi Chin Han Daniel
Sent: Wednesday, 25 July, 2018 2:15 PM
To: 'Jasmine Tan' <jasminetan@transcab.com.sg>; 'Candy Kong' <candy.kong@transcab.com.sg>; TKB <Kim.bock.tay@gmail.com>
Cc: 'Catherine Chong (LKK Auto)' <admin-d@lkkauto.com>; sur@lkkauto.com; C Meenachi - III <Meenachi@iii.com.sg>; 'ken.loh@vehicleowners.com' <ken.loh@vehicleowners.com>
Subject: IIIRef: MTS2018D0000013 - ACCDT INVLT8112K (BK Auto Motortrade)(III) & SHD9759U ON 08/07/2018 ALONG NEWTON CIRCUS

Dear Sir/Madam,

Our insured has informed us that they do not wish to seek indemnity under the policy.

Kindly take up the matter directly with the insured/driver concerned.

Thank you.

Daniel Pooi

**Motor Claims Department
India International Insurance Pte Ltd**

64 Cecil Street #04-02 IOB Building
Singapore 049711

Tel: 6347 6100 Ext 202 Fax: 6224 4174

S&P 'A-' (stable) rated Company



CC: BK Auto

23 JALAN NOVENA SELATAN

Singapore 308578

This email is intended solely for the person to whom it has been addressed. It may contain confidential and/or legally privileged information. If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses. Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

...CLAIM SUBFOLDER...(Pending for Survey Report)

WF

CLAIM SUBFOLDER TRACKING

Case:	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	17 Jul 2018 Edit Reg		16 Jul 2018 00:00 Edit Adj Rpt	\$5220.00 Edit Estimates	\$5220.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	BK AUTO , Co. Reg. No.: -								
Main Claimant:	TRANS-CAB SERVICES PTE LTD , Co. Reg. No.: 200303878K								
Vehicle Reg. No.:	SHD9759U	Date of Loss:	08/07/2018 20:00 - :59 [51 Months and 8 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MTS2018D0000013	Policy/Cover Note No.:	D18MTS0000253						
Vehicle Reg. No. (Insured):	SLT8112K	Policy No. (Claimant):	VPX/P1680520						
		Excess:							
Repairer:	Trans-cab Auto Services Pte Ltd (Ang Mo Kio) 2, Ang Mo Kio Street 63, 569111 Ang Mo Kio - Tel: 62876666								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by C. Meenachi - 6347 6073]								
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 25/07/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SHD9759U (MTS2018D0000013)
[SLT8112K]
TP
TRANS-CAB SERVICES PTE LTD
Jul 8 2018 8:00PM
[BK AUTO]
Trans-cab Auto Services Pte Ltd

Upload Documents

Upload Photos











Compose New Letter

View

View in Browser







Photos/Images


3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	20/08/19 15:39	General View	 Load JPG	<input checked="" type="checkbox"/>
2	20/08/19 15:39	General View	 Load JPG	<input checked="" type="checkbox"/>
3	20/08/19 15:39	General View	 Load JPG	<input checked="" type="checkbox"/>
4	20/08/19 15:39	General View	 Load JPG	<input checked="" type="checkbox"/>
5	20/08/19 15:39	General View	 Load JPG	<input checked="" type="checkbox"/>
6	20/08/19 15:39	General View	 Load JPG	<input checked="" type="checkbox"/>
7	20/08/19 15:39	General View	 Load JPG	<input checked="" type="checkbox"/>
8	20/08/19 15:39	General View	 Load JPG	<input checked="" type="checkbox"/>
9	20/08/19 15:39	General View	 Load JPG	<input checked="" type="checkbox"/>
10	20/08/19 15:39	General View	 Load JPG	<input checked="" type="checkbox"/>

Documentation

1 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	16/07/18 14:52	EMAIL FROM III DD 13072018	 Load PDF	
2	16/07/18 14:52	TP EST & GIA REPORT	 Load PDF	
3	17/07/18 18:25	TP ESTIMATE- MARKED	 Load PDF	
4	20/08/19 15:55	FOLLOW UP NR	 Load PDF	
5	20/08/19 15:55	FOLLOW UP NR-REMINDER	 Load PDF	
6	20/08/19 15:57	REQUEST EMAIL FROM DANIEL	 Load PDF	

No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	23/08/18 11:39	Letter of Demand from Third Party STERLING LAW	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III18012836/KWB3Q2

Date: 21/08/2019

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D18MTS0000253
Claimant Vehicle No :	SHD9759U	Insured Vehicle No :	SLT8112K
Date of Loss:	08/07/2018	Nature of Claim:	TP
		Claim No:	MTS2018D0000013

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD9759U	Engine No:	M9R8839C000948
Make & Model:	RENAULT LATITUDE, 2.0 L (A)	Chassis No:	VF1ABL15AUC276883
Reg. Date:	31/03/2014 (Man. Year: 2013)	Odometer:	473277 km
Colour:	Metallic White/Red		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Giti 8 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Giti 8 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	33,004.60	0.00	33,004.60	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,670.00	220.00	9,450.00	97.72
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	42,674.60	220.00	42,454.60	99.48
+ GST 7.00/7.00% (S\$)	2,987.22	15.40	2,971.82	99.48
Nett Amount (S\$)	45,661.82	235.40	45,426.42	99.48

INSPECTION

Date of Assignment:	16/07/2018	
Date Inspected:	16/07/2018 Inspected At:	Trans-cab Auto Services Pte Ltd (Ang Mo Kio) 2, Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	1.0 days	

Adjuster: KENNETH KONG

Manager: VIVIAN LAU PEI FENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 21 Aug 2019)
Parts: 143	RENAULT LATITUDE 2.0 L (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SHD9759U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER REAR	Repair	1,108.46 FL	*-FL
2	1		*BUMPER LOWER REAR	Serviceable	768.84 FL	*-FL
3	1		*BUMPER BRACKET CTR REAR	Serviceable	113.47 FL	*-FL
4	1		*BUMPER BRACKET SIDE RH REAR	Serviceable	135.97 FL	*-FL
5	1		*BUMPER RETAINER RH REAR	Serviceable	44.99 FL	*-FL
6	1		*BUMPER REFLECTOR RH	Serviceable	43.61 FL	*-FL
7	1		*BUMPER BRACKET SIDE LH REAR	Serviceable	135.97 FL	*-FL
8	1		*BUMPER RETAINER LH REAR	Serviceable	44.99 FL	*-FL
9	1		*BUMPER REFLECTOR LH	Serviceable	43.61 FL	*-FL
10	1		*BUMPER BEAM REAR	Repair	777.52 FL	*-FL
11	1		*BUMPER BEAM BRACKET LH REAR	Repair	225.95 FL	*-FL
12	1		*BUMPER BEAM BRACKET RH REAR	Repair	225.95 FL	*-FL
13	1		*BOOT REAR	Repair	2,872.68 FL	*-FL
14	1		*BOOT FINISHER	Serviceable	470.06 FL	*-FL
15	1		*BOOT WEATHERSTRIP	Serviceable	323.05 FL	*-FL
16	1		*BOOT REFLECTOR LAMP LH	Serviceable	493.35 FL	*-FL
17	1		*BOOT REFLECTOR LAMP RH	Serviceable	493.35 FL	*-FL
18	1		*BOOT BADGE RENAULT	Not Necessary	225.36 FL	*-FL
19	1		*BOOT BADGE	Not Necessary	225.36 FL	*-FL
20	1		*BOOT STRUT LH	Serviceable	276.08 FL	*-FL
21	1		*BOOT STRUT RH	Serviceable	276.08 FL	*-FL
22	1		*BOOT HINGE LH	Repair	367.84 FL	*-FL
23	1		*BOOT HINGE RH	Repair	367.84 FL	*-FL
24	1		*BOOT INNER TRIM	Serviceable	586.45 FL	*-FL
25	1		*BOOT SWITCH	Serviceable	168.13 FL	*-FL
26	1		*BOOT LOCK	Repair	202.67 FL	*-FL
27	1		*BOOT LOCK CATCH	Repair	74.40 FL	*-FL
28	2		*LICENCE PLATE LAMP	Serviceable	50.52 FL	*-FL
29	2		*BOOT RUBBER PLUG	Serviceable	221.81 FL	*-FL
30	1		*DOOR PANEL REAR RH	Repair	2,844.66 FL	*-FL
31	1		*FENDER PANEL INNER TRIM REAR RH	Serviceable	671.45 FL	*-FL
32	1		*FENDER PANEL REAR RH	Repair	3,299.13 FL	*-FL
33	1		*WHEELARCH REAR RH	Serviceable	543.47 FL	*-FL
34	1		*TAILLAMP RH	Serviceable	552.55 FL	*-FL
35	1		*TAILLAMP PANEL RH	Repair	986.70 FL	*-FL
36	1		*TAILLAMP LH	Serviceable	552.55 FL	*-FL
37	1		*TAILLAMP PANEL LH	Repair	986.70 FL	*-FL
38	1		*OUTER PANEL REAR (END PANEL)	Repair	1,471.77 FL	*-FL
39	1		*OUTER PANEL REAR (END PANEL)TRIM	Serviceable	404.56 FL	*-FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL)	Repair	2,189.88 FL	*- FL
41	1		*SPARE WHEEL PANEL TRIM	Serviceable	612.21 FL	*- FL
42	1		*EXHAUST REAR	Repair	7,489.05 FL	*- FL
43	1		*EXHAUST CAP REAR	Repair	230.49 FL	*- FL
44	1		*SET PARKING AID	Serviceable	700.00 FS	*- FS
45	1		*SET REAR BUMPER CLIP	Not Necessary	66.00 FS	*- FS
46	1		*SET BUMPER BRACKET CTR CLIP	Not Necessary	33.00 FS	*- FS
47	1		*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	*- FS
48	1		*SET BUMPER RETAINER RH CLIP RR	Not Necessary	20.00 FS	*- FS
49	1		*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	*- FS
50	1		*SET BUMPER RETAINER CLIP LH RR	Not Necessary	20.00 FS	*- FS
51	1		*SET BUMPER LOWER REAR RIVET	Not Necessary	22.00 FS	*- FS
52	1		*SET BUMPER LOWER REAR CLIP	Not Necessary	66.00 FS	*- FS
53	1		*EXHAUST MOUTING REAR	Serviceable	17.82 FS	*- FS
54	1		*SET BOOT FINISHER CLIP	Not Necessary	24.20 FS	*- FS
55	1		*BOOT STICKER TRANS-CAB	Not Necessary	30.00 FS	*- FS
56	1		*BOOT STICKER 6555-3333	Not Necessary	30.00 FS	*- FS
57	1		*BOOT INNER TRIM CLIP	Not Necessary	45.00 FS	*- FS
58	1		*SET FENDER WHEELARCH REAR RH CLIP	Not Necessary	35.00 FS	*- FS
59	1		*SET FENDER WHEELARCH REAR LH CLIP	Not Necessary	35.00 FS	*- FS
60	1		*FENDER INNER TRIM CLIP LH	Not Necessary	28.00 FS	*- FS
61	1		*FENDER INNER TRIM CLIP LH	Not Necessary	28.00 FS	*- FS
62	1		*TAILLAMP CLIP RH	Not Necessary	5.00 FS	*- FS
63	1		*TAILLAMP CLIP LH	Not Necessary	5.00 FS	*- FS
64	2		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
65	1		*WINDSCREEN MOULDING	Not Necessary	100.00 FS	*- FS
66	1		*REAR WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	*- FS
67	1		*SPARE TYRE RIM (ROUE 7J 16H 2547)	Serviceable	385.00 FS	*- FS
68	1		*SPARE TYRE	Serviceable	330.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	36,424.55	0.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	3,419.95	0.00
Total Parts (\$\$)	33,004.60	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	3,750.00	220.00
2	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	3,200.00	0.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	0.00
4	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	0.00
5	TO TRANSFER OF BOOTLID FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
6	TO REPAIR AND REALIGN REAR EXHAUST PIPE	New	170.00	0.00
7	TO DROP REAR EXHAUST BOX ,RENEW THE SAME ,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE	New	170.00	0.00
8	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
9	TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
10	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING	New	380.00	0.00
11	TO TRANSFER OF REAR FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
12	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	0.00
13	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
14	TO TRANSFER OF REAR DOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
Gross Labour Cost (S\$)			9,670.00	220.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >