

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9759U**AAD1807-070***Not Authored
82201*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 9759U

VF1ABL15AUC276883

RENAULT

LATITUDE

8.7.2018

III

PART		LIST	
1	1 BUMPER COVER REAR	\$	<i>N</i> 1,108.46
2	1 BUMPER LOWER REAR	\$	<i>Sn</i> 768.84
3	1 BUMPER BRACKET CTR REAR	\$	<i>Sn</i> 113.47
4	1 BUMEP R BRACKET SIDE RH REAR	\$	<i>Sn</i> 135.97
5	1 BUMEP R RETAINER RH REAR	\$	<i>Sn</i> 44.99
6	1 BUMPER REFLECTOR RH	\$	<i>Sn</i> 43.61
7	1 BUMEP R BRACKET SIDE LH REAR	\$	<i>Sn</i> 135.97
8	1 BUMEP R RETAINER LH REAR	\$	<i>Sn</i> 44.99
9	1 BUMPER REFLECTOR LH	\$	<i>Sn</i> 43.61
10	1 BUMPER BEAM REAR	\$	<i>N</i> 777.52
11	1 BUMPER BEAM BRACKET LH REAR	\$	<i>N</i> 225.95
12	1 BUMPER BEAM BRACKET RH REAR	\$	<i>N</i> 225.95
13	1 BOOT REAR	\$	<i>N</i> 2,872.68
14	1 BOOT FINISHER	\$	<i>Sn</i> 470.06
15	1 BOOT WHEATERSTRIP	\$	<i>Sn</i> 323.05
16	1 BOOT REFLECTOR LAMP LH	\$	<i>Sn</i> 493.35
17	1 BOOT REFLECTOR LAMP RH	\$	<i>Sn</i> 493.35
18	1 BOOT BADGE 'RENAULT'	\$	<i>Up</i> 225.36
19	1 BOOT BADGE	\$	<i>nn</i> 225.36
20	1 BOOT STRUT LH	\$	<i>Sn</i> 276.08
21	1 BOOT STRUT RH	\$	<i>Sn</i> 276.08
22	1 BOOT HINGE LH	\$	<i>N</i> 367.84
23	1 BOOT HINGE RH	\$	<i>N</i> 367.84
24	1 BOOT INNER TRIM	\$	<i>Sn</i> 586.45
25	1 BOOT SWITCH	\$	<i>Sn</i> 168.13
26	1 BOOT LOCK	\$	<i>N</i> 202.67
27	1 BOOT LOCK CATCH	\$	<i>N</i> 74.40
28	2 LICENCE PLATE LAMP	\$	<i>Sn</i> 50.52
29	2 BOOT RUBBER PLUG	\$	<i>Sn</i> 221.81

Trans-cab Auto Services Pte Ltd**AAD1807-070**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9759U

30	1 DOOR PANEL REAR RH	\$	R	2,844.66	}	X
30	1 FENDER PANEL INNER TRIM REAR RH	\$	SL	671.45		
30	1 FENDER PANEL REAR RH	\$	R	3,299.13		
31	1 WHEELARCH REAR RH	\$	SL	543.47		
32	1 TAILLAMP RH	\$	SL	552.55		
33	1 TAILLAMP PANEL RH	\$	R	986.70		
34	1 TAILLAMP LH	\$	SL	552.55		
35	1 TAILLAMP PANEL LH	\$	R	986.70		
36	1 OUTER PANEL REAR (End Panel)	\$	R	1,471.77		
37	1 OUTER PANEL REAR (End Panel)TRIM	\$	SL	404.56		
38	1 SPARE WHEEL PANEL (Luggage Floor Panel)	\$	R	2,189.88		
39	1 SPARE WHEEL PANEL TRIM	\$	SL	612.21		
40	1 EXHAUST REAR	\$	R	7,489.05		
41	1 EXHAUST CAP REAR	\$	R	230.49		

TOTAL	\$	34,199.54
10%	\$	3,419.95
	\$	30,779.59

Specical Nett

1	1SET PARKING AID	\$	SL	700.00	}	X
2	1SET REAR BUMPER CLIP	\$	na	66.00		
3	1SET BUMPER BRACKET CTR CLIP	\$	na	33.00		
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	na	10.00		
5	1SET BUMPER RETAINER RH CLIP RR	\$	na	20.00		
6	1SET BUMPER BRACKET SIDE CLIP LH RR	\$	na	10.00		
7	1SET BUMPER RETAINER CLIP LH RR	\$	na	20.00		
8	1SET BUMPER LOWER REAR RIVET	\$	na	22.00		
9	1SET BUMPER LOWER REAR CLIP	\$	na	66.00		
10	1 EXHAUST MOUNTING REAR	\$	SL	17.82		
11	1SET BOOT FINISHER CLIP	\$	na	24.20		
12	1 BOOT STICKER "Trans-cab"	\$	na	30.00		
13	1 BOOT STICKER "6555-3333"	\$	na	30.00		
14	1 BOOT INNER TRIM CLIP	\$	na	45.00		
15	1SET FENDER WHEELARCH REAR RH CLIP	\$	na	35.00		
16	1SET FENDER WHEELARCH REAR LH CLIP	\$	na	35.00		
17	1 FENDER INNER TRIM CLIP LH	\$	na	28.00		
18	1 FENDER INNER TRIM CLIP LH	\$	na	28.00		

Trans-cab Auto Services Pte Ltd**AAD1807-070**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9759U

19	1 TAILLAMP CLIP RH	\$	<i>na</i> 5.00	} X
20	1 TAILLAMP CLIP LH	\$	<i>na</i> 5.00	
21	2 REAR WINDSCREEN SELANT	\$	<i>na</i> 80.00	
22	1 WINDSCREEN MOULDING	\$	<i>na</i> 100.00	
23	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>na</i> 100.00	
24	1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	<i>sh</i> 385.00	
25	1 SPARE TYRE	\$	<i>sh</i> 330.00	

TOTAL \$ 2,225.02**TOTAL PARTS \$ 33,004.61****LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	3,750.00	<i>229</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	<i>na</i> 3,200.00	X
To Rust-Proofing Of The Affected Areas.	\$	<i>na</i> 170.00	X
To reinstall rear bumper parking sensor.	\$	<i>na</i> 170.00	X
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	<i>na</i> 170.00	X
To repair and realign rear exhaust pipe.	\$	<i>na</i> 170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<i>na</i> 170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>na</i> 170.00	X
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	<i>na</i> 170.00	X

Trans-cab Auto Services Pte Ltd**AAD1807-070**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9759U

To supply and re-do rear luggage floor panel
insulation padding.

\$ *na* 380.00 X

To transfer of rear fender fittings, attachment and
perform water seepage test.

\$ 380.00 X

To transfer of rear windscreen fittings and conduct
water seepage test.

\$ 170.00 X

To check steering geometry and computer wheel
alignment

\$ 220.00 X

To transfer of rear door fittings, attachment and
perform water seepage test.

\$ 380.00 X

TOTAL \$ 9,290.00**Over All Total \$ 42,294.61****(LUMP SUM)****Repair Days***15 days**1 day*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: