

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

WBAPG56040

MOHAMMAD FAIZAL BIN FADIL
BLK334 UBI AVE 1
#02-805
S 400334

TPAXA
Parker

Date : 20.07.2018
Vehicle no : SJS 7646 Y
Make/Model : BMW 320 I
Accident date : 02.07.2018

No	DESCRIPTION	Qty	Amount (\$\$)
<u>List Items</u>			
1	Front LH door <i>Dented</i>	1	\$ 1292.3 ✓
2	Front LH door glass outer moulding <i>He m</i>	1	\$ 86 x
3	Front LH door glass outer handle <i>lit</i>	1	\$ 77.8 ✓
4	Front LH door inner board <i>He m</i>	1	\$ 1235.9 x
5	Front LH door inner weather strip <i>over</i>	1	\$ 179.9 ✓
6	Front LH door inner lock <i>He m</i>	1	\$ 312.9 x
7	Front LH door side mirror assy <i>Damaged</i>	1	\$ 1068.8 ✓
8	Front LH door top hinge	1	\$ 62.9 x
9	Front LH door lower hinge <i>2 set</i>	1	\$ 62.9 x
10	Front LH door stopper	1	\$ 79.5 x
11	Rear LH door <i>Repair</i>	1	\$ 1292.3 x
12	Rear LH door inner weather strip <i>Not</i>	1	\$ 179.9 x
			\$ 5931.1
Less 5% Disc			\$ 296.6
Total			\$ 5634.5

Labour Cost

- 1 Remove & reinstall door glass *fittings*
- 2 Remove ,replace & repair consistent to the accident
- 3 Respray painting

1250	\$ 200 <i>100</i>
	\$ 1000 <i>450</i>
	\$ 1100 <i>700</i>
Total	\$ 2300

Grand Total \$ 7934.5

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

total: 3737.86

L/S: 3K

04 Days

3K