

# Ryder Auto Pte Ltd

1 Kaki Bukit Ave 6, #01-56, Autobay @ Kaki Bukit, Singapore 417883

Email: [ryderautoworkshop@gmail.com](mailto:ryderautoworkshop@gmail.com)

Fax: 64815390

## ESTIMATE OF REPAIR

(Without Prejudice)

Veh # : YN3930B  
FM65FM1RDEA

Model : MITSUBISHI

Date Of Accident: 13/7/2018

Location : AYE TWDS TUAS (BEFORE CLEMENTI ROAD)

| Qty  | Description                                   | Surveyor<br>Remarks | Surveyor<br>Adj | Amount \$ |         |
|------|-----------------------------------------------|---------------------|-----------------|-----------|---------|
|      | <u>Special Nett Items</u>                     |                     |                 |           |         |
| 1pc  | Rear power gate                               |                     | 10200           | 12,000.00 | 6500    |
| 4pcs | Rear power gate pump                          |                     | 9350            | 11,000.00 | 5000    |
| 1pc  | Rear power gate hinges                        |                     |                 | 3,000.00  | 1500    |
| 4pcs | Rear power gate pump dust cover               |                     |                 | 800.00    | tu✓ 500 |
| 4pcs | Rear power gate hydraulic fluid               |                     |                 | 200.00    | ne✓     |
| 1pc  | Rear power gate 60KMPH emblem                 |                     |                 | 20.00     | ne✓     |
| 1set | Rear power gate sticker                       |                     |                 | 120.00    | ne✓     |
| 1pc  | Rear power gate advertisement                 |                     |                 | 120.00    | ne✓     |
| 1pc  | Rear power gate 45PAX emblem                  |                     |                 | 20.00     | ne✓     |
| 2pcs | Rear power gate ZEPRO FLAP                    |                     |                 | 360.00    | X       |
|      | Sub-Total                                     |                     |                 | 27,640.00 | 13980   |
|      | <u>Labour</u>                                 |                     |                 |           |         |
| 1    | To remove & replace rear power tail-gate pump |                     |                 | 3,000.00  | 2100    |
|      | Sub-Total                                     |                     |                 | 3,000.00  |         |
|      | Total                                         |                     |                 | 30,640.00 |         |

16080  
2/24 12,900  
8 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: @ BOK SENG

(heavy vehicles, marine vessels)

@ Bluwei 2088

(motorbike, cars, light vehicles)



Authorised Workshop  
Authorised Reporting Centre

8778 1999

24 hr accident call