

ESTIMATE OF REPAIR

(Without Prejudice)

Veh # : YN3930B
FM65FM1RDEA

Model : MITSUBISHI

Date Of Accident: 13/7/2018

Location : AYE TWDS TUAS (BEFORE CLEMENTI ROAD)

Qty	Description	Surveyor Remarks	Surveyor Adj	Amount \$	
	<u>Special Nett Items</u>				
1pc	Rear power gate		10200	12,000.00	10500 bt
4pcs	Rear power gate pump @1500 each		9350	11,000.00	6000 jm
1pc	Rear power gate hinges			X 3,000.00	1800 bt
4pcs	Rear power gate pump dust cover			800.00	400 500 out
4pcs	Rear power gate hydraulic fluid			200.00	ne
1pc	Rear power gate 60KMPH emblem			20.00	ne
1set	Rear power gate sticker			120.00	ne
1pc	Rear power gate advertisement			120.00	ne
1pc	Rear power gate 45PAX emblem			20.00	ne
2pcs	Rear power gate ZEPRO FLAP			360.00	X nm
	Sub-Total			27,640.00	19280
	<u>Labour</u>				
1	To remove & replace rear power tail-gate pump			3,000.00	2000
	Sub-Total			3,000.00	
	Total			30,640.00	

21,280
4/8 17,000
8 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: [Signature]

@ Blurwell 2088